

Joel

6 EQ1 100 20293, 21 fa 52

LKK:

UAC:

ASSIGNMENT

phk

9-11-18

Insured: Rusal

DO: 16/11/2018

Date/Time: 9-11-18

Registered in Merimen: -

Pre-assign / CCU / FTE



Insured Vehicle No. : SKX 9891D
 Name of Insured : VIP Mary Fai
 Insured Tel No. : _____ HP: _____
 Excess Sec II :SS _____ D.O.A : 1-11-18
 Is driver the owner? (YES / NO) _____ Nature of Accident : _____

Claim No. : _____
 Policy No. : _____
 Make / Model : _____
 Place of Accident : _____

If NO, Driver Name / Age :

Driver Tel No. : _____ (V/L) YES / NO

OI GIA REPORT YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SKS 5130 U



INSRS: _____
 WSP: BH Auto
 Tel: _____
 Liability: _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____

Date/Time	STAGE	DATE / PIC
12/11	SKS 5130 U - X;	
12/11	SKX 9891D - 06/11/2018 19887/AY0302; VOA: 14/10/17	Non-Reporting ltr (1st):
12/11	04/08/17 04364/Anub352; VOA: 9/6/18	Non-Reporting ltr (2nd):
		Non-Reporting ltr (Final):
		Notification ltr (if non-pickup):
		Call Of: 21/11/2018
		After call ltr to OI:
		Documentation Check List: Handler Typist
		Notification ltr (if non-pickup) <input type="checkbox"/>
		After call ltr to OI: <input type="checkbox"/>
		Authorisation To Act: <input type="checkbox"/>
		Release Voucher: <input type="checkbox"/>
		Final Repair Bill: <input type="checkbox"/>
		Car Rental Invoice: <input type="checkbox"/>
		Towing Invoice: <input type="checkbox"/>
		LTA / GIA: <input type="checkbox"/>
		Medical Bill: <input type="checkbox"/>
		PIR: <input type="checkbox"/>
		Mandate/Reject Instruction: <input checked="" type="checkbox"/>
		LOD: <input type="checkbox"/>
		Payment Breakdown Form: <input type="checkbox"/>
		Post-Repair Photos: <input type="checkbox"/>
		Others: <input type="checkbox"/>

→ To check if TP has any evidence.
 pending Estimate, KIV TP rewater our email date 9/10/18
 TP video / OI video in drive
 Hua Meng helping OI doing TP claim
 email to reject TP claim, pending finalise LOR

25-01-14 T/P WAS AT FAULT BY SWERVING OUT FROM THE QUEUE
 AND COLLIDED WITH CAR OI TO REJECT & CLOSE THE FILE

After repair photo X

Reject Case
 By (staff) Paul Kim
 Approved by Y.

PRELIMINARY ADVICE	Date/Time: 19/11/2018	Sent By: PHMK	25/01/19
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	SS	(days) Reduction:	% Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time:	Confirm with	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	%	(Agreed / Assessed) BOLA S/N No.:	If NO or B 28, Ass. Lia :
Repair Cost:	SS		
Loss of Rental (LOR):	SS	(days)	
Loss of Use (LOU):	SS	(\$ x days)	
Loss of Income (LOI):	SS	(\$ x days)	
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]	
GIA/LTA Search	SS		
Medical:	SS		
Disbursement	SS	(e.g. Tow/Independent)	1) Claim status: Normal/Reject/Private Settle
Legal Cost	SS		2) Report Format:
Total:	SS	Global Sum SS:	3) Survey fee: \$160.00
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	SS	Name 1:	
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

13/3/19

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

ATTN : MOTOR CLAIMS DEPARTMENT
EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX SINGAPORE 069110
TEL : 6223 9433

DATE : 14/11/2018
PAGE : 1 OF 2

ACCIDENT REPAIR ON : SKS5130U
MODEL : MAZDA 5 5-DOOR WAGON 2.0L
POLICY NO : 18-MV002940-R02
CHASSIS NO : JM6CW1071F0121223
YEAR OF MANUFACTURE : 2015
DATE / TIME OF ACCIDENT : 01/11/2018@14:00HRS
LOCATION : ALONG AMK AVE 8 OPEN CAR PARK
THIRD PARTY VEHICLE NO : SKX9891D

REPLACEMENT OF PARTS		QUANTITY	UNIT PRICE	AMOUNT
1	FRONT HEADLAMP RH ? X nn	1		\$ 1,481.90
2	FRONT HEADLAMP LOWER BRACKET RH ? X nn	1		\$ 42.30
3	FRONT BUMPER DE ✓	1		\$ 1,108.20
4	FRONT BUMPER SIDE RETAINER RH ne ✓	1		\$ 21.60
5	FRONT BUMPER "LOGO" EMBLEM ne ✓	1		\$ 45.60
6	FRONT BUMPER FOG LAMP RH X nn	1		\$ 315.70
7	FRONT BUMPER FOG LAMP GARNISH RH sc ✓	1		\$ 78.20
8	FRONT FENDER RH repair	1		\$ 322.40
9	FRONT FENDER INNER SHIELD RH cut ✓	1		\$ 210.50
10	FRONT SPORT RIM RH sc ✓ price?	1		\$ 1,156.00
11	FRONT SUSPENSION WHEEL BEARING RH ?	1		\$ 171.20
12	FRONT SUSPENSION KNUCKLE ARM RH ?	1		\$ 366.50
13	FRONT SUSPENSION STEERING TIE ROD END RH X } nn	1		\$ 141.50
14	FRONT SUSPENSION STABILIZER BAR LINKAGE RH X }	1		\$ 97.80
SUB TOTAL				\$ 5,559.40
LESS 20%				\$ (1,111.88)
PARTS TOTAL				\$ 4,447.52

SPECIAL NETT ITEMS		QUANTITY	UNIT PRICE	AMOUNT
1	FRONT HEADLAMP CLIPS RH ne ✓	3	\$ 5.00	\$ 15.00
2	FRONT BUMPER CLIPS ne ✓	10	\$ 5.00	\$ 50.00
3	FRONT FENDER INNER SHIELD CLIPS RH ne ✓	4	\$ 5.00	\$ 20.00
4	FRONT TYRE RH- 205/55R16 X nn	1		\$ 380.00
PARTS TOTAL				\$ 465.00

ACCIDENT REPAIR ON : SKS5130U
 MODEL : MAZDA 5 5-DOOR WAGON 2.0L
 POLICY NO : 18-MV002940-R02
 CHASSIS NO : JM6CW1071F0121223
 YEAR OF MANUFACTURE : 2015
 DATE / TIME OF ACCIDENT : 01/11/2018@14:00HRS
 LOCATION : ALONG AMK AVE 8 OPEN CAR PARK
THIRD PARTY VEHICLE NO : SKX9891D

DATE : 14/11/2018
PAGE : 2 OF 2

LABOUR CHARGES FOR RIGHT FRONT PORTION		AMOUNT
1	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT, CUT AND WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS.	\$ 600.00 300
2	PROVIDE SKILL LABOUR AND MATERIAL TO PUTTY ALL DAMAGED PARTS AND PANEL AND TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES.	\$ 500.00 400
3	REMOVE AND REPLACE/REFIT FRONT SUSPENSION AND UNDERCARRIAGE TO FACILITATE REPAIRS.	\$ 150.00 100.80
4	CHECK AND READJUST FRONT WHEEL ALIGNMENT AND BALANCING.	\$ 80.00 60
5	TUFF KOTE AND ANTI RUST COATING ALL REPLACE AND REPAIR PARTS.	\$ 50.00 30
6	DISCONNECT, CHECK, RESET AND DIAGNOSTIC ELECTRICAL SYSTEM WIRING, HARNESS, WIRE SOCKETS AND ETC. REMOVE AND REINSTALL DAMAGED PARTS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	\$ 100.00 30
LABOUR TOTAL		\$ 1,480.00

TOTAL PARTS & LABOUR	\$ 6,392.52
GST 7%	\$ 447.48
GRAND TOTAL	\$ 6,840.00
ESTIMATE REPAIR DURATION	5 DAYS

YOURS SINCERELY,



ESTIMATOR : KIT
 TEL : 8405 4058
 FAX : 6269 2404
 EMAIL : karkit.ngai@bhauto.com.sg

SURVEY ATTENDED BY :

NAME	Rasul
COMPANY	LKK
DATE	16/11/18 @ 1630
TIME	@ 1630
TEL	90010068
EMAIL	rasul@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

 Acknowledged by Repairer
 Signature:
 Date:

4 days
 4/5



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: DM18HO02988-JG

Our ref: CC6/EQI18020293/R1fa3

Date: 19/11/2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

PRELIMINARY ADVICE OF VEHICLE NO.

SKS 5130U


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 16/11/2018 at the premises of M/s BH Auto Services Pte Ltd (Sin Ming) have the following to report:-

Workshop Estimate Amount	: S\$	<u>6,392.52</u>
Revised Estimate Amount	: S\$	<u>3,081.08</u>
"Check" Items Amount	: S\$	<u>1,649.52</u>
Total (Including Check Items)	: S\$	<u>4,730.60</u>
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
O/S Front portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4.0 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

Mei Kwan (LKKAuto)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Friday, 9 November, 2018 2:59 PM
To: Mei Kwan (LKKAuto)
Cc: Poh Kin (LKKAuto); CS A Team; Admin A
Subject: RE: Direct Settlement - Accident Involving SKX9891D (OI : EQI - DM18HO02988-JG) AND SKS5130U (TP : LKK REF - CC6/EQI18020293/fa3) on 01/11/2018

Attachments: SKX9891D.pdf

Follow Up Flag: Follow up
Flag Status: Completed

Categories: HMK

Dear Mei Kwan

Attached insured's accident report for you attention.

Based on insured's statement, he was travelling straight when third party turn right and hit into OI vehicle.

Please assist to check if third party has any video footage

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]
Sent: Friday, November 9, 2018 9:34 AM
To: Joel Goh
Cc: Poh Kin (LKKAuto); CS A Team; Admin A
Subject: Direct Settlement - Accident Involving SKX9891D (OI : EQI - TBA) AND SKS5130U (TP : LKK REF - CC6/EQI18020293/fa3) on 01/11/2018

EQI ref: TBA
LKK REF: CC6/EQI18020293/fa3

Dear Sir / Madam,

We refer to the above matter.

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Wednesday, 12 December 2018 2:37 PM
To: 'BHAS - Jacelyn Loh'
Cc: BHAS - Moo Wen Zheng; BHAS - Bernard Kee; BHAS - Chan Yun Shi
Subject: RE: checking liability (OUR VEHICLE - SKS5130U / YOUR VEHICLE - SKX9891D) ***
LKK REF: CC6/EQ118020293/fa3
Attachments: OI video footage-SKX 9891D.mp4
Importance: High

WITHOUT PREJUDICE
SAVE AS TO COSTS

Our Ref: CC6/EQ118020293/fa3
Your Ref: SKS 5130U

Dear Sir/Madam,

We refer to the above matter.

We have reviewed the circumstances of the incident and we are of the opinion that your driver is more liable by driver is more liable by moving out from Queue when our Insured moving straight along said lane. Vehicle moving out should exercise Greater Caution. This is evidenced of video footage from our Insured. Attached herewith of our insured video footage for your kind attention.

In view of this, we regret to inform you that we are unable to look into your claim.

We will now close the matter in our end.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."


Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

 *Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not

Poh Kin (LKKAuto)

From: BHAS - Jacelyn Loh <jacelyn.loh@bhauto.com.sg>
Sent: Wednesday, 12 December 2018 11:56 AM
To: Poh Kin (LKKAuto)
Cc: BHAS - Moo Wen Zheng; BHAS - Bernard Kee; BHAS - Chan Yun Shi
Subject: RE: checking liability (OUR VEHICLE - SKS5130U / YOUR VEHICLE - SKX9891D) ***
LKK REF: CC6/EQI18020293/fa3

Dear Sir,

Received and thanks

My client asking on liability urgently this case is unclear or 50%. Thanks

Thank You & Best Regards,

Jacelyn Loh

 **BH AUTO SERVICES PTE LTD**

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singaopre:575636

(T) +65-6559 8944 /8940 (F) +65-6515 3144 / +65-6269 2404

Email: Jacelyn.loh@bhauto.com.sg

Website: <http://www.bhauto.com.sg>

From: BHAS - Chan Yun Shi
Sent: Friday, 7 December 2018 4:34 PM
To: 'Poh Kin (LKKAuto)' <pohkin@lkkauto.com>
Cc: BHAS - Jacelyn Loh <jacelyn.loh@bhauto.com.sg>; BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>; BHAS - Bernard Kee <bernard.kee@bhauto.com.sg>
Subject: RE: checking liability (OUR VEHICLE - SKS5130U / YOUR VEHICLE - SKX9891D) *** LKK REF: CC6/EQI18020293/fa3

Dear Poh Kin,

Thanks for your video.

Can you amend this liability status on your end , I can answer to my client.

Appreciate can you revert email to us by today.

Thank you.

Thank You & Best Regards,

Yun Shi

 **BH AUTO SERVICES PTE LTD**

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singaopre:575636

(T) +65-6559 8944 /8940 (F) +65-6515 3144 / +65-6269 2404

Email: yunshi.chan@bhauto.com.sg

Website: <http://www.bhauto.com.sg>

Poh Kin (LKKAUTO)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Tuesday, 11 December 2018 1:48 PM
To: Poh Kin (LKKAUTO)
Cc: Admin A
Subject: RE: Direct Settlement - Accident Involving SKX9891D (OI : EQI - DM18HO02988-JG) AND SKS5130U (TP : LKK REF - CC6/EQI18020293/fa3) on 01/11/2018

Categories: clear

Dear Poh Kin

Please proceed to reject third party's claim as per your proposal.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Poh Kin (LKKAUTO) [mailto:pohkin@lkkauto.com]
Sent: Friday, December 7, 2018 5:02 PM
To: Joel Goh
Cc: Admin A
Subject: RE: Direct Settlement - Accident Involving SKX9891D (OI : EQI - DM18HO02988-JG) AND SKS5130U (TP : LKK REF - CC6/EQI18020293/fa3) on 01/11/2018
Importance: High

WITHOUT PREJUDICE

Your Ref: **DM18HO02988-JG**
Our Ref: **CC6/EQI18020293/fa3**

Dear Joel,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SKX 9891D (OI) & SKS 5130U (TP) ON 01/11/2018

We refer to the above matter and below.

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Friday, 7 December 2018 5:02 PM
To: Joel Goh
Cc: Admin A
Subject: RE: Direct Settlement - Accident Involving SKX9891D (OI : EQI - DM18HO02988-JG) AND SKS5130U (TP : LKK REF - CC6/EQI18020293/fa3) on 01/11/2018

Importance: High

WITHOUT PREJUDICE

Your Ref: **DM18HO02988-JG**
Our Ref: **CC6/EQI18020293/fa3**

Dear Joel,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SKX 9891D (OI) & SKS 5130U (TP) ON 01/11/2018

We refer to the above matter and below.

Third party reported that he was queue in the lane, he decided shift into right lane, while do so, suddenly our insured side swipe into his vehicle from the right side.

OID reported that he was driven straight along the said road, suddenly third party change lane from left side and collided to his vehicle left rear portion.

Based on OI's video footage shows OI was driven within his lane (against traffic flow) and Third Party encroached into OI lane by moving off from the queue.

<https://drive.google.com/open?id=1HYou3M7VVgfabYzF1JBIAAg4yKy5cMOe>

In view of this, we are intending to reject third party claim as vehicle moving out should exercise Greater Caution.

For your approval/comments/instruction.


Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



AUTO
CONSULTANTS
PTE LTD

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Friday, 7 December 2018 4:21 PM
To: 'BHAS - Chan Yun Shi'
Cc: BHAS - Jacelyn Loh; BHAS - Moo Wen Zheng; BHAS - Bernard Kee
Subject: RE: checking liability (OUR VEHICLE - SKS5130U / YOUR VEHICLE - SKX9891D) ***
LKK REF: CC6/EQI18020293/fa3
Attachments: OI video footage-SKX 9891D.mp4
Importance: High

WITHOUT PREJUDICE

Our Ref: CC6/EQI18020293/fa3
Your Ref:

Dear Yun Shi/ Jaclyn,

We refer to the above matter and our tele-conversation.

Apologies for late reply.

We have reviewed the circumstances of the incident and we are of the opinion that your driver is more liable by moving out from Queue when our Insured moving straight along said lane. Vehicle moving out should exercise Greater Caution.

We attached herewith a copy of Video footage for your kind attention.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC6/EQ118020293/R1fa3s2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 15-03-2019	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKX 9891D	Veh. Inspected	SKS 5130U
Policy No.	DMPPHQ18-000134	Coverage (\$)	0.00
Claim No.	DM18HO02988-JG	Excess (\$)	0.00
Assign From		Assign Date	16/11/2018
2. Vehicle Particulars & Condition			
Make & Model	MAZDA 5-DOOR WAGON 2.0L	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JM6CW1071F0121223	Colour	BLUE
Odometer	105653	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55R16	MICHELIN	6 mm
L/H Front Tyre	205/55R16	MICHELIN	6 mm
R/H Rear Tyre	205/55R16	MICHELIN	6 mm
L/H Rear Tyre	205/55R16	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	01/11/2018	Inspection Date	16/11/2018
Survey held at	BH AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 5130U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT HEADLAMP RH	NOT NECESSARY	1,481.90	-
1	FRONT HEADLAMP LOWER BRACKET RH	NOT NECESSARY	42.30	-
1	FRONT BUMPER	DEFORMED	1,108.20	1,108.20
1	FRONT BUMPER SIDE RETAINER RH	NECESSARY	21.60	21.60
1	FRONT BUMPER "LOGO" EMBLEM	NECESSARY	45.60	45.60
1	FRONT BUMPER FOG LAMP RH	NOT NECESSARY	315.70	-
1	FRONT BUMPER FOG LAMP GARNISH RH	SCRATCHED	78.20	78.20
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	322.40	-
1	FRONT FENDER INNER SHIELD RH	CUT	210.50	210.50
1	FRONT SPORT RIM RH	SCRATCHED	1,156.00	1,156.00
1	FRONT SUSPENSION WHEEL BEARING RH	NOT NECESSARY	171.20	-
1	FRONT SUSPENSION KNUCKLE ARM RH	NOT NECESSARY	366.50	-
1	FRONT SUSPENSION STEERING TIE ROD END RH	NOT NECESSARY	141.50	-
1	FRONT SUSPENSION STABILIZER BAR LINKAGE RH	NOT NECESSARY	97.80	-
	LESS 20% DISCOUNT		-1,111.88	-524.02
			4,447.52	2,096.08
<u>SPECIAL NETT ITEMS</u>				
3	FRONT HEADLAMP CLIPS RH @ \$5.00 (SN)	NECESSARY	15.00	15.00
10	FRONT BUMPER CLIPS @ \$5.00 (SN)	NECESSARY	50.00	50.00
4	FRONT FENDER INNER SHIELD CLIPS RH @ \$5.00 (SN)	NECESSARY	20.00	20.00
1	FRONT TYRE RH - 205/55R16 (SN)	NOT NECESSARY	380.00	-
			465.00	85.00
<u>LABOUR</u>				
	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT, CUT AND WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER RH.		600.00	300.00
	PROVIDE SKILL LABOUR AND MATERIAL TO PUTTY ALL DAMAGED PARTS AND PANEL AND TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITATES.		500.00	400.00

Report Ref No. CC6/EQ18020293/R1fa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND REPLACEMENT / REFIT FRONT SUSPENSION AND UNDERCARRIAGE TO FACILITATE REPAIRS.		150.00	80.00
	CHECK AND READJUST FRONT WHEEL ALIGNMENT AND BALANCING.		80.00	60.00
	TUFF KOTE AND ANTI RUST COATING ALL REPLACE AND REPAIR PARTS.		50.00	30.00
	DISCONNECT, CHECK, RESET AND DIAGNOSTIC ELECTRICAL SYSTEM WIRING, HARNESS, WIRE SOCKETS AND ETC. REMOVE AND REINSTALL DAMAGED PARTS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		100.00	30.00
			1,480.00	900.00
GRAND TOTAL			6,392.52	3,081.08
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,450.00

Report Ref No. CC6/EQ118020293/R1fa3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.