

# BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636  
Tel: 6559 8944 / Fax: 6269 2404

ATTN : MOTOR CLAIMS DEPARTMENT  
EQ INSURANCE COMPANY LTD  
5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEX SINGAPORE 069110  
TEL : 6223 9433

DATE : 14/11/2018  
PAGE : 1 OF 2

ACCIDENT REPAIR ON : SKS5130U  
MODEL : MAZDA 5 5-DOOR WAGON 2.0L  
POLICY NO : 18-MV002940-R02  
CHASSIS NO : JM6CW1071F0121223  
YEAR OF MANUFACTURE : 2015  
DATE / TIME OF ACCIDENT : 01/11/2018@14:00HRS  
LOCATION : ALONG AMK AVE 8 OPEN CAR PARK  
THIRD PARTY VEHICLE NO : SKX9891D

REPLACEMENT OF PARTS		QUANTITY	UNIT PRICE	AMOUNT
1	FRONT HEADLAMP RH ?	1		\$ 1,481.90
2	FRONT HEADLAMP LOWER BRACKET RH ?	1		\$ 42.30
3	FRONT BUMPER DE ✓	1		\$ 1,108.20
4	FRONT BUMPER SIDE RETAINER RH NA ✓	1		\$ 21.60
5	FRONT BUMPER "LOGO" EMBLEM NA ✓	1		\$ 45.60
6	FRONT BUMPER FOG LAMP RH X	1		\$ 315.70
7	FRONT BUMPER FOG LAMP GARNISH RH SCR ✓	1		\$ 78.20
8	FRONT FENDER RH repair	1		\$ 322.40
9	FRONT FENDER INNER SHIELD RH cut ✓	1		\$ 210.50
10	FRONT SPORT RIM RH SCR ✓	1		\$ 1,156.00
11	FRONT SUSPENSION WHEEL BEARING RH ? price?	1		\$ 171.20
12	FRONT SUSPENSION KNUCKLE ARM RH ?	1		\$ 366.50
13	FRONT SUSPENSION STEERING TIE ROD END RH X	1		\$ 141.50
14	FRONT SUSPENSION STABILIZER BAR LINKAGE RH X	1		\$ 97.80
SUB TOTAL				\$ 5,559.40
LESS 20%				\$ (1,111.88)
PARTS TOTAL				\$ 4,447.52

SPECIAL NETT ITEMS		QUANTITY	UNIT PRICE	AMOUNT
1	FRONT HEADLAMP CLIPS RH NA ✓	3	\$ 5.00	\$ 15.00
2	FRONT BUMPER CLIPS NA ✓	10	\$ 5.00	\$ 50.00
3	FRONT FENDER INNER SHIELD CLIPS RH NA ✓	4	\$ 5.00	\$ 20.00
4	FRONT TYRE RH- 205/55R16 X	1		\$ 380.00
PARTS TOTAL				\$ 465.00

**ACCIDENT REPAIR ON : SKS5130U**  
 MODEL : MAZDA 5 5-DOOR WAGON 2.0L  
 POLICY NO : 18-MV002940-R02  
 CHASSIS NO : JM6CW1071F0121223  
 YEAR OF MANUFACTURE : 2015  
 DATE / TIME OF ACCIDENT : 01/11/2018@14:00HRS  
 LOCATION : ALONG AMK AVE 8 OPEN CAR PARK  
**THIRD PARTY VEHICLE NO : SKX9891D**

**DATE : 14/11/2018**  
**PAGE : 2 OF 2**

LABOUR CHARGES FOR RIGHT FRONT PORTION		AMOUNT	
1	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT, CUT AND WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS.	\$ <del>600.00</del>	300
2	PROVIDE SKILL LABOUR AND MATERIAL TO PUTTY ALL DAMAGED PARTS AND PANEL AND TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES.	\$ <del>500.00</del>	400
3	REMOVE AND REPLACE/REFIT FRONT SUSPENSION AND UNDERCARRIAGE TO FACILITATE REPAIRS.	\$ <del>150.00</del>	100.80
4	CHECK AND READJUST FRONT WHEEL ALIGNMENT AND BALANCING.	\$ <del>80.00</del>	60
5	TUFF KOTE AND ANTI RUST COATING ALL REPLACE AND REPAIR PARTS.	\$ <del>50.00</del>	30
6	DISCONNECT, CHECK, RESET AND DIAGNOSTIC ELECTRICAL SYSTEM WIRING, HARNESS, WIRE SOCKETS AND ETC. REMOVE AND REINSTALL DAMAGED PARTS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	\$ <del>100.00</del>	30
<b>LABOUR TOTAL</b>		\$ 1,480.00	

TOTAL PARTS & LABOUR	\$ 6,392.52
GST 7%	\$ 447.48
<b>GRAND TOTAL</b>	<b>\$ 6,840.00</b>
<b>ESTIMATE REPAIR DURATION</b>	<b>5 DAYS</b>

YOURS SINCERELY,



ESTIMATOR : KIT  
 TEL : 8405 4058  
 FAX : 6269 2404  
 EMAIL : karkit.ngai@bhauto.com.sg

**SURVEY ATTENDED BY :**

NAME	Rasul
COMPANY	LKK
DATE	16/11/18 @ 1630
TIME	@ 1630
TEL	90010068
EMAIL	rasul@lkkauto.com

4 days  
 45