

SERVICE ESTIMATE

93811 - C00001
Mr Carl Skadiang
52E Elite Terrace

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date. : 09/11/2018

WIP No. : 37318

Veh.In/Out:

*Tel.No. : Mobile: 96180359

Reg.No. : SKV8897E

Reg.date : 13/06/2018

Mileage : 0

Chassis No: SAJAB4AX2JCP35128

Singapore 458816

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Mr Carl Skadiang

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRT BUMPER, FRT RH HEADLAMP, GRILLE, ETC		0	1800.00	0		1,800.00 S	900.
800	TO PUTTY SPRAYPAINT ON FRT BUMPER, ETC		0	1600.00	0		1,600.00 S	800
R06	FRT NUMBER PLATE & HOLDER		0	60.00	0		60.00 S	X
280	TO FOCUS HEADLAMP		0	162.00	0		162.00 S	✓
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES		0	486.00	0		486.00 S	✓
	COVER-BUMPER	1.0	EA	1720.80			1,720.80 S	de
	TOWING COVER FRT XE	1.0	EA	30.00			30.00 S	af
	HEADLAMP RH	1.0	EA	3322.10			3,322.10 S	ut
	BRACKET-FEND RH	1.0	EA	34.30			34.30 S	?
	MESH-GRILLE	1.0	EA	257.10			257.10 S	?

Labour Total 4,108.00
Parts Total 5,364.30
Package Total 0.00

Gross Total. 9,472.30

Net..... 9,472.30

GST @ 7.0% 663.06

Total..... 10,135.35

Paid..... 0.00

Please Pay.. 10,135.35

GST: S=StdRated; 0=OutOfScope
Supplemental Rate of resurvey is subject to final approval from Insurance Company

LKK Auto Consultants - we notify
the Repairer of the following:

- To resurvey before any spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental Rate of resurvey is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanfu 97495749
WP
14/11/18 C 210 / m
Resny before paint
sure lkk auto.wm.