

REF: CS3/MSA18013169/B.tb<sup>02</sup>-1

Checked by: **Meimien**

T.G. Lim

ASSIGNMENT (Office)

From (Person):

Christina Wong

MSIG

Date/Time:

09.11.2018

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

FBK 5961 L

Insured:

FBD 82875

at Workshop m/s:

Hiap Lek Automobile

Tel:

9660 1347

of:

160 Sin Ming Drive # 05-17

Policy No:

MSD/VMT/17-368834

Claim No:

MSC/v/18-000976

Sum Insured:

Excess:

Make of Veh.  
(Client's Record)

D.O.A.

12/07/2018

CA / REV / REP. / REV 24 HRS

1up

20/07/2018

R.O.D. Endorsement

Date/Time:

4:47pm @ 19/7/18

Person Contacted:

Mr. Ong

Vehicle:

IN OUT

Date/Time	Action/Instruction (X) Estimate	Do Not Finalize
	FBK 5961 L - NA / INC / 0014295 / r3	DOA 1/8/2016
	FBD 82875 - X	
23/7/18	Disassembled Est. 3K - 3.5K Repair days 3	Estimate range 2 Repair days 1
	Lump Sum Summit #2700 (Red. 500; 15%)	

14/11/2018.

Repair days 3

RECEIVED 15 NOV 2018

TGum Lim

9/11/18



**...CLAIM SUBFOLDER...(Pending for Payment)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Jul 2018		19 Jul 2018 16:23		25 Jul 2018 10:42 <b>S\$0.00</b> (S\$192.60)		<b>Pending for Payment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	CHEU YOON HIONG, ID: S7476410Z		
Main Claimant:	JEFFREY BIN SENIN, ID: S7048646F		
Vehicle Reg. No.:	FBK5961L	Date of Loss:	12/07/2018 00:00 - :59 [104 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/18-000976	Policy/Cover Note No.:	MSD/VMT/17-368834 Coverage: 07/08/2017 - 06/08/2018
Vehicle Reg. No. (Insured):	FBDB2875	Policy No. (Claimant):	
		Excess:	
Repairer:	Hiap Lek Automobile Trading (HQ) 160 Sin Ming Drive, #05-17 Sin Ming Autocity, 575722 Sin Ming - Tel: 64531743		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 20/07/2018]		
Adj Asg. Remarks:	Liability unclear. Contact Person: Mr Han Wei / 9660 1347. TP disagree with our SJE. Proceed to appoint LKK as the SJE.		
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
<ul style="list-style-type: none"> <li>MSIG_SG (09/11/2018): PAPER SURVEY - FBK 5961L</li> </ul>			
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a>	<a href="#">Search Tasks</a>
		<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

## OH APPRAISAL SERVICES

BLK 34, #02-309, TOA PAYOH, LORONG 5  
SINGAPORE (310034)  
Mobile : 97982959 Fax : 63975857 email : [oh3434@yahoo.com.sg](mailto:oh3434@yahoo.com.sg)  
Business Regn No 53214975X

### VEHICLE DAMAGE INSPECTION REPORT

Mr. Jeffrey Bin Senin  
Blk 202 Yishun Street 21  
#09-79  
Singapore 760202

Our Ref : FBK5961L/TP5083  
Date : 02 August 2018

#### REFERENCES

Claim Type	: Third Party	Date of Accident	: 12 July 2018
Vehicle No.	: FBK5961L	Date of Assignment	: 18 July 2018
Make	: Sym	Date of Inspection	: 18 July 2018
Model	: Gts 200	Date of Re-inspn.	: 23 July 2018
Reg. Date	: 11 November 2009	Chassis No	: RFGLM18WX95000923
Color	: Grey	Engine No	: Blocked
Odometer	: Nil		

#### TYRE CONDITION

	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
<u>Front</u>	Michelin	110/90-13	3
<u>Rear</u>	Michelin	130/70-12	4

#### GENERAL DESCRIPTION OF DAMAGE (PHOTOGRAPHS ATTACHED)

Front, Rh and Rear Portion

#### INSPECTION AND ADJUSTMENT

Original Quotation : \$5,784.40 Revised Assessment \$3,200.00 Lump sum

In accordance to your instruction, we have not authorized repairs.

In normal circumstances, repairs to the vehicle would take approximately ( 5 ) days to complete. (Survey at Hiap Lek Automobile Trading.)

This survey was conducted on a "WITHOUT PREJUDICE" basis.

### OH APPRAISAL SERVICES

BLK 34,#02-309,TOA PAYOH,LORONG 5

SINGAPORE (310034)

Mobile : 97982959 Fax : 63975857 email : [oh3434@yahoo.com.sg](mailto:oh3434@yahoo.com.sg)

Business Regn No 53214975X


### INVOICE

Mr. Jeffrey Bin Senin  
Blk 202 Yishun Street 21  
#09-79  
Singapore 760202

Invoice No :2018/0083  
Our Ref :FBK5961L/TP5083  
Date :02 August 2018

Claim Type	Third Party	Date of Accident	12-07-2018
Vehicle No.	FBK5961L	Date of Inspection	18-07-2018
No	Description		Amount (S\$)
1	Survey fees inclusive of Transportation and Photographs ( 100 ) copies		
		Total	<u>540.00</u>
Singapore Dollar: Five Hundred and Forty Dollars			
All payments made payable to : Oh Appraisal Services			



  
For Oh Appraisal Services

S/N	Description	Qty	Condition	Original Quotation	Revised Quotation	
	<u>Material</u>					
1	Handle bar	1 pc	Bent	90.00	90.00	BTV
2	Handle balancer	1 set	Grazed	32.00	32.00	CUTV
3	Brake lever	1 pc	Bent Rh	22.00	22.00	BTV
4	Mirror	1 pc	Grazed Rh	65.00	65.00	CUTV
5	Front cowling	1 pc	Cut/grazed	360.00	360.00	CUTV
6	Cowling screen	1 pc	Scratches	220.00	220.00	CUTV
7	Meter assy	1 pc	Usable	320.00	0.00	
8	Counter shield	1 pc	Cut/grazed	312.00	312.00	
9	Headlamp top garnish	1 pc	Grazed	55.00	55.00	CUTV
10	Headlamp	1 pc	Usable	380.00	0.00	
11	Front signal	1 pc	Grazed Rh	280.00	140.00	CUTV
12	Front mudguard	1 pc	Grazed	95.00	95.00	CUTV
13	Front fork assy @ \$300/-	2pcs	Align	600.00	S.N.150.00	NECV
14	Side cover (Grey)	1 pc	Grazed	35.00	35.00	CUTV
15	Lower fairing @\$175/-	2 pcs	Grazed	350.00	350.00	CUTV
16	Under cover tray	1 pc	Deformed	80.00	80.00	BTV
17	Rear footrest	1 pc	Bent Rh	30.00	30.00	BTV
18	Rear rim	1 pc	Bent	350.00	350.00	BTV
19	Rear swing arm	1 pc	Distorted	470.00	470.00	RX
20	Tail board	1 pc	Grazed	180.00	180.00	CUTV
21	Exhaust protector (Rear)	1 pc	Dented	80.00	80.00	SCRV
22	Exhaust muffler assy	1 pc	Dented-repair	680.00	S.N.200.00	SCRV
				5086.00	2966.00	
			Less 10% discount	508.60	296.60	
				4577.40	2669.40	
	<u>Special nett items from above</u>				350.00	
23	Front number plate	1 pc	Necessary	12.00	10.00	
24	Steering bearing & cone	1 pc	Necessary	55.00	27.50	NECV
	Towing fee (Two ways)			60.00	50.00	
	Check electrical			80.00	60.00	40.00
	Spraying painting			600.00	600.00	300.00
	Labour charges			400.00	350.00	
				5784.40	4016.90	
	Lump sum repair adjustment				3200.00	

Repair days 3

TTCM lim

9/11/18

OH APPRAISAL SERVICES


Vehicle No: FBK5961L

Our Ref :FBK5961L/TP5083

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

The information contained in this document is privileged and confidential and is intended for the exclusive use of the addressee designation. If you are not the addressee; any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for it to return.



  
\_\_\_\_\_  
For Oh Appraisal Services

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Jul 2018		19 Jul 2018 16:23 <a href="#">Edit Adj Rpt</a>	<b>S\$2,700.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,700.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	CHEU YOON HIONG, ID: S7476410Z		
Main Claimant:	JEFFREY BIN SENIN, ID: S7048646F		
Vehicle Reg. No.:	FBK5961L	Date of Loss:	12/07/2018 00:00 - :59 [104 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/18-000976	Policy/Cover Note No.:	MSD/VMT/17-368834 Coverage: 07/08/2017 - 06/08/2018
Vehicle Reg. No. (Insured):	FBD8287S	Policy No. (Claimant):	
		Excess:	
Repairer:	Hiap Lek Automobile Trading (HQ) 160 Sin Ming Drive, #05-17 Sin Ming Autocity, 575722 Sin Ming - Tel: 64531743		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Koh Ming Shao - 6594 2546]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 13/11/2018]		
Adj Asg. Remarks:	Liability unclear. Contact Person: Mr Han Wei / 9660 1347. TP disagree with our SJE. Proceed to appoint LKK as the SJE.		
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
<ul style="list-style-type: none"> <li>MSIG_SG (09/11/2018): Report Send Back Alerts - FBK5961L (TP)</li> <li>MSIG_SG (09/11/2018): PAPER SURVEY - FBK 5961L</li> </ul>			
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a>	<a href="#">Search Tasks</a>
		<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			



## Claim Documents

**\*FBK5961L (MSC/V/18-000976)**  
**[FBD8287S]**

TP

**JEFFREY BIN SENIN**

**Jul 12 2018 12:00AM**

**[CHEU YOON HIONG]**

**Hiap Lek Automobile Trading**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			View	View in Browser ▼
<b>Photos/Images</b>			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/07/18 10:31	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
2	23/07/18 10:31	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
3	23/07/18 10:31	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
4	23/07/18 10:31	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
5	23/07/18 10:31	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
6	23/07/18 10:31	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
7	23/07/18 10:31	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
8	23/07/18 10:31	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
9	23/07/18 10:31	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
10	23/07/18 10:31	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
11	23/07/18 10:31	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
12	23/07/18 10:31	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
13	23/07/18 10:31	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
14	23/07/18 10:31	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
15	23/07/18 10:31	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
16	23/07/18 10:31	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
17	23/07/18 10:31	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
18	23/07/18 10:31	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
19	23/07/18 10:31	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
20	23/07/18 10:31	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
21	23/07/18 10:31	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
22	23/07/18 10:31	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
23	23/07/18 10:31	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
24	23/07/18 10:31	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
25	23/07/18 10:31	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
26	23/07/18 10:31	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
27	23/07/18 10:31	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
28	23/07/18 10:31	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
29	23/07/18 10:31	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
30	23/07/18 10:31	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
31	24/07/18 10:39	<b>Dismantled Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
32	24/07/18 10:39	<b>Dismantled Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
33	24/07/18 10:39	<b>Dismantled Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
34	24/07/18 10:39	<b>Dismantled Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
35	24/07/18 10:39	<b>Dismantled Parts</b>	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
37	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
38	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
70	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
71	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
72	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
73	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
74	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
75	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
76	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
77	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
78	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
79	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
80	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
81	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
82	24/07/18 10:39	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
83	24/07/18 10:39	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	24/07/18 10:39	<b>Dismantled Parts</b>	Load JPG	<input checked="" type="checkbox"/>
85	24/07/18 10:39	<b>Dismantled Parts</b>	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/07/18 10:20	<b>FBK5961L GIA Rpt</b>	Load PDF	
2	19/07/18 10:22	<b>FBD8287S GIA Rpt</b>	Load PDF	
3	19/07/18 10:24	<b>Email frm TP - PRI</b>	Load PDF	
4	03/09/18 10:30	<b>TP Survey Rpt Part 1</b>	Load PDF	
5	03/09/18 10:30	<b>TP Survey Rpt Part 2</b>	Load PDF	

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/11/18 10:17	<b>PRS INVOICE</b>	Load PDF	

## Documents Checklist

### DOCUMENTS CHECKLIST




There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:  Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/MSG18013169/BTBS2-1  
**Date:** 21/11/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VMT/17-368834  
**Claimant Vehicle No :** FBK5961L **Insured Vehicle No :** FBD8287S  
 Date of Loss: 12/07/2018 Nature of Claim: TP Claim No: MSC/V/18-000976

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBK5961L**  
 Make & Model: SYM GTS 200, 172cc Engine No: KB602389  
 Reg. Date: 11/11/2009 (Man. Year: 2009) Chassis No: RFGLM18WX9S000923  
 Colour: Silver Odometer: 2529 km  
 Engine Capacity: 172 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/90-13 Rear Tyre Size: 130/70-12  
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,644.40	2,633.90	2,010.50	43.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,140.00	740.00	400.00	35.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,784.40</b>	<b>3,373.90</b>	<b>2,410.50</b>	<b>41.67</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,700.00</b>		
<b>Nett Amount (S\$)</b>	<b>5,784.40</b>	<b>2,700.00</b>	<b>3,084.40</b>	<b>53.32</b>

INSPECTION

Date of Assignment: 19/07/2018  
 Date Inspected: 20/07/2018 Inspected At: Hiap Lek Automobile Trading (HQ)  
 160 Sin Ming Drive, #05-17 Sin Ming Autocity  
 Singapore 575722  
 Estimated Period of Repair: 3.0 days

**Adjuster:** Lim Teow Guan

**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

**REPAIR DETAILS****Reference**

<b>Part Source:</b>	(Last Synchronised: 21 Nov 2018)	
<b>Parts:</b>	N/A	SYM GTS 200 172cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBK5961L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Bent	90.00 FL	*90.00 FL
2	1		*SET HANDLE BALANCER	Cut	32.00 FL	*32.00 FL
3	1		*BRAKE LEVER	Bent	22.00 FL	*22.00 FL
4	1		*MIRROR	Cut	65.00 FL	*65.00 FL
5	1		*FRONT COWLING	Cut	360.00 FL	*360.00 FL
6	1		*COWLING SCREEN	Cut	220.00 FL	*220.00 FL
7	1		*METER ASSY	Usable	320.00 FL	*- FL
8	1		*COUNTER SHIELD	Cut	312.00 FL	*312.00 FL
9	1		*HEADLAMP TOP GARNISH	Cut	55.00 FL	*55.00 FL
10	1		*HEADLAMP	Usable	380.00 FL	*- FL
11	1		*FRONT SIGNAL	Cut	280.00 FL	*140.00 FL
12	1		*FRONT MUDGUARD	Cut	95.00 FL	*95.00 FL
13	1		*SIDE COVER (GREY)	Cut	35.00 FL	*35.00 FL
14	2		*LOWER FAIRING	Cut	350.00 FL	*350.00 FL
15	1		*UNDER COVER TRAY	Bent	80.00 FL	*80.00 FL
16	1		*REAR FOOTREST	Bent	30.00 FL	*30.00 FL
17	1		*REAR RIM	Bent	350.00 FL	*350.00 FL
18	1		*REAR SWING ARM	Repair	470.00 FL	*- FL
19	1		*TAIL BOARD	Cut	180.00 FL	*180.00 FL
20	1		*EXHAUST PROTECTOR (REAR)	Scratched	80.00 FL	*80.00 FL
21	1		*FRONT FORK ASSY	Necessary	540.00 FS	*150.00 FS
22	1		*EXHAUST MUFFLER ASSY	Scratched	612.00 FS	*200.00 FS
23	1		*FRONT NUMBER PLATE	Necessary	12.00 FS	*10.00 FS
24	1		*STEERING BEARING & CONE	Necessary	55.00 FS	*27.50 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,025.00</b>	<b>2,883.50</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	380.60	249.60
<b>Total Parts (\$\$)</b>	<b>4,644.40</b>	<b>2,633.90</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOWING FEE (TWO WAYS)	New	60.00	50.00
2	CHECK ELECTRICAL.	New	80.00	40.00
3	SPRAY PAINTING.	New	600.00	300.00
4	LABOUR CHARGES.	New	400.00	350.00
<b>Gross Labour Cost (S\$)</b>			<b>1,140.00</b>	<b>740.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >