

ASSIGNED BY

Meninon

Guo Agency
Monica chung

REF CS3/MSG18012601/G96⁵⁷1

ASSIGNMENT (Office)

of MSIG

Date/Time

07/12/18

Estimated Cost:

Bill to

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: SKX 7067E

Insured: SFA 718C

at Workshop: 898 Car Servicing

Tel: 96621885

of 10 Kaki Bukit Rd 2 #03-34

Policy No: 27724091QMY

Claim No: 563822

Sum Insured

Excess:

Make of Veh:
(Client's Record)

D.O.A 06/07/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement

Date/Time: 9:39am @ 11/7/18

Person Contacted: Mr. Cashin

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

Do Not Proceed

SKX 7067E - X

SFA 718C - CS/MSG15018733/Rvbc2

D.O.A: 23/04/2015

Range 4500/- - 5500/-

Repair days 4

Est Range of repair days.

15/11/18 Submit US 62350, 4 days.
(Red \$ 3250, 58%)

Repair days 4

14/11/2018.

RECEIVED 15 NOV 2018

TC Lim

Min

12/11/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Jul 2018		10 Jul 2018 16:17 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]
Insured:	Choo Geok Lan Theresa, ID: S0009628H			
Main Claimant:	CROSS NORMAN FRANCIS, ID: S8339086G			
Vehicle Reg. No.:	SKX7067E	Date of Loss:	06/07/2018 16:00 - :59 [61 Months and 6 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 563822	Policy/Cover Note No.:	27724091QMY (Comprehensive) Coverage: 21/06/2018 - 20/06/2019	
Vehicle Reg. No. (Insured):	SFQ718C	Policy No. (Claimant):		
		Excess:		
Repairer:	889 Car Servicing Pte Ltd () 10 Kaki Bukit Road 2, #03-34 First East Centre, 417868 Kaki Bukit - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 09/11/2018]			
Adj Asg. Remarks:	SJE Disagree Please appoint LKK and contact Mr. Cashin Terng @ 96621885 / 64445889 Liability (Non-reporting)			


ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
<ul style="list-style-type: none"> MSIG_SG (07/11/2018): Report Send Back Alerts - SKX7067E (TP) 		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Our Ref : CY.10053.18(889CS)AC/hh

Your Ref : 563822

31st July 2018



The Motor Claims Department
MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way #21-01
SGX Centre 2
Singapore 068807

mc

WITHOUT PREJUDICE

BY HAND

Madam Choo Geok Lan Theresa
10 Mount Rosie Terrace
Singapore 308012
(Documents were enclosed to your insurers)

YQ, -upload to M

Dear Sirs

PROPERTY DAMAGE CLAIM
ACCIDENT INVOLVING SKX7067E AND SFQ718C ON 05/07/2018 @ 16:30 HRS
ALONG YOTEL SINGAPORE ORCHARD ROAD MSCP LEVEL 3

We are instructed by **Mr. Cross Norman Francis** to claim damages and losses against you in connection with the above-captioned road traffic accident which our client's vehicle **SKX7067E** was damaged by vehicle **SFQ718C** driven by your insured's driver at the material time.

We are instructed that the said accident was caused by your insured's driver's negligent driving and/or management of the vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

1) Repair costs inclusive of GST	\$5,992.00
2) Loss of rental	\$1,400.00
3) Survey fee	\$ 562.00
4) Accident report search fees	\$ 15.00
5) Costs & Incidental inclusive of GST	<u>\$ 856.00</u>
	<u>\$8,825.00</u>

.../2

mic
1/8/18

Page 2
CY.10053.18(889CS)AC/hh

A copy each of the following supporting documents is enclosed:-

- 1) Accident report and Police report of SKX7067E;
- 2) 2 scene photographs;
- 3) Survey report and survey invoice together with 42 coloured photographs;
- 4) Final repair bill;
- 5) Vehicle Rental Agreement;
- 6) LTA search of SFQ718C and transaction history.

We had on **9th July 2017** notified MSIG Insurance (Singapore) Pte Ltd of the above accident and pre-repair inspection of our client's vehicle was carried out by your appointed surveyor .

Please let us know within the next seven (7) days upon receipt of this letter whether you intend to re-inspect our client's vehicle failing which the said vehicle will no longer be available for the same.

Please note that you should send to us an acknowledgment of receipt of this letter within fourteen (14) days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against your insured without further notice to you.

Please note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

Yours faithfully



C. YOGARAJAH LLC

Encs



CAR SERVICING PTE LTD

10 KAKI BUKIT ROAD 2 #03-34 FIRST EAST CENTRE SINGAPORE 417868

TEL : 6444 5889 FAX: 6538 2180

Email: carservicing889@singet.com.sg

Co Reg No./ GST Reg No. / UEN : 201306774G

Name: Cross Norman Francis Date: 26-Jul-18

Address: C/o: 889 Car Servicing Pte Ltd Date of accident: 5-Jul-18
10 Kaki Bukit Road 2 #03-34
First East Centre, Singapore 417868

Final repair bill for SKX 7067 E

Description	Amount (S\$)
Lump Sum Repair Costs	\$ 5,600.00
Plus 7% GST	\$392.00
	<u>\$ 5,992.00</u>



10 Kaki Bukit Road 2, #03-15 First East Centre,
Singapore 417868
Email: info@revpowercarleasing.com.sg
Tel: 62510150 Rev Power Car Leasing

Rental Agreement No: 04106
ROC: 201540824Z

Date: 13/7/2018

HIRER'S DRIVER (1st Driver Name)

Name: ROSS NORMAN FRANCIS
Address: BLK 4 TOH YI DRIVE #13-213 (Sg0004)
I/C or Passport No: S83390866 Nationality: SG
Date of Birth: 03/12/1983 Occupation: -
Driving License No: S83390866 Pass Date: 05/10/2007
Contact No (H): _____ (HP): 98483230

RELIEF DRIVER (if any)

Name: _____
Address: _____
I/C or Passport No: _____ Nationality: _____
Date of Birth: _____ Occupation: _____
Driving License No: _____ Pass Date: _____
Contact No (H): _____ (HP): _____

VEHICLE INFORMATION AND CHECK LIST

Number	Description
1	Scratch
2	Dent
3	Break

Vehicle No. SLT 5979X.
Vehicle Make And Model Toyota CHR Hybrid.

RENTAL CHARGES			
<u>70</u> Weekday/s	@ \$ <u>200</u>	/ per day	\$ <u>1400</u>
Weekend/s	@ \$	/ per day	\$
Month/s	@ \$	/ per day	\$
Additional to JB / KL	*1 day	for (day)	\$
Total Amount			
CASH / NETS / CHEQUE:			\$
Deposit (Refundable)			\$
Petrol Top Up			\$
Delivery / Collection Fee			\$
MISC			\$
Extension			\$
Day/s	@ \$	/ per day	
Total (Balance Payment / To Refund)			\$ <u>1400</u>
CASH / NETS / CHEQUE:			\$ <u>1400</u>

FUEL AMOUNT	1/8	5/8
<u>20%</u>	1/4	3/4
	3/8	7/8
	1/2	FULL

*Every 1/8 of petrol used is chargeable @\$20 nett

REMARKS

OUT		IN	
Date	Mileage	Date	Mileage
<u>13/7/2018</u>		<u>20/7/2018</u>	
Time <u>12.13pm.</u>	Petrol <u>()</u>	Time <u>11am.</u>	Petrol <u>()</u>
Parking / Traffic Fine		Signature of Hirer / Driver	


When Return

- IMPORTANT NOTES**
- Rental vehicle is strictly for Singapore use only and may not be driven out of Singapore without Prior consent of the owner.
 - Only person/s authorized by RPCL Pte Ltd may drive the vehicle.
 - All parking and traffic violation are the responsibility of the Hirer. Administrative charge will be levied on any traffic violations redirected.
 - The Hirer shall be liable for excess charges for any late return at the rate showb hour per of per day.
 - In the event of accident, the Hirer shall report to the rental office immediately.
 - The Hirer is liable for punctures, damage tyres, wheel rims and windscreens.

We have read and agreed to the terms and conditions as set out on both sides of the agreement and certify that the information given is true and correct. If I / we opt to pay by edit / charge card, I / we agreed that all amounts payable under this agreement may be billed to the same account and my signature here will be deemed to have mad on a applicable card charge slip.

Hirer's Signature

Add. Driver



RPCL Pte Ltd

Enquire Vehicle & Owner Information (Vehicle No. SFQ718C As At 05 Jul 2018 / 16:30:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: CY(889CS)SKX7067E

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: S0009628H

Owner Name: CHOO GEOK LAN THERESA

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 10

Registered Street Name: MOUNT ROSIE TERRACE

Registered Unit No.: -

Registered Building Name: -

Registered Postal Code: 308012

Current Vehicle Details

Vehicle No.: SFQ718C

Make Description/Model: MERCEDES BENZ / E 200CGI

Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD



Thank you

Phee Lay San has successfully logged out.

Your last login date and time was 09 Jul 2018, 16:31:13.

To return to ONE.MOTORING, please [click here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount (\$)	Log Date/Time
1	Vehicle	SFQ718C	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	09 Jul 2018 / 16:33:10

CL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

INVOICE

Cross Norman Francis
C/o: 889 Car Servicing Pte Ltd
10 Kaki Bukit Road 2 #03-34
First East Centre, Singapore 417868

Invoice No: CL/18647
Ref No: 889/07/1801/TP
Date: 26 July 2018

DESCRIPTION	AMOUNT
OUR SERVICE FEE CHARGES:	
<ul style="list-style-type: none">SURVEY INSPECTION FOR VEHICLE NO. <u>SKX 7067 E</u>RESURVEY INSPECTIONDIGITAL PHOTOGRAPHS SERVICES <i>(INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS)</i>TRANSPORTATION	
GRAND TOTAL	S\$ 562.00

E & O. E

All cheque payment should be "Crossed" and made payable to " C L APPRAISER PTE LTD "

We shall be grateful if you could forward our payment at your early convenience.



CL Appraiser Pte Ltd

SLC L APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Cross Norman Francis
C/o: 889 Car Servicing Pte Ltd
10 Kaki Bukit Road 2 #03-34
First East Centre, Singapore 417868

Date : 26 July 2018
Our ref : 889/07/1801/TP

Accident Date : 05 July 2018
Inspection Date : 12 July 2018
Repairer Name : 889 Car Servicing Pte Ltd
10 Kaki Bukit Road 2 #03-34
First East Centre, Singapore 417868

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : SKX 7067 E
Make / Model : BMW 316i
Chassis No : WBA3A12080J720411
Engine No : A968J463N13B16A

Year / Capacity : 2013 / 1598 cc
Colour : Black
Mileage : 96463

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: Bridgestone	225/50 R17	5 mm	Sport
Front Offside	: Bridgestone	225/50 R17	5 mm	Sport
Rear Nearside	: Bridgestone	225/50 R17	5 mm	Sport
Rear Offside	: Bridgestone	225/50 R17	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the n/s portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 42 copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis
and we have not given authorization and instruction to the repairer to proceed with the repair

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$ 5,600.00** on a contractual basis.

Under normal circumstances, the repair period would be about 6 (Six) working days.

SCL APPRAISER PTE LTD

Vehicle Registration No: SKX 7067 E

Our Ref No: 889/07/1801/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Front n/s door	Damage	\$ 1,605.00	\$ 1,605.00 R X
1	Front n/s door lock	Damage	\$ 285.00	\$ 285.00 NN X
1	Front n/s door rubber	Necessary	\$ 197.00	\$ 197.00 NEC X NN
1	Rear n/s door	Damage	\$ 1,655.00	\$ 1,655.00 DD ✓
1	Rear n/s door inner lock	Damage	\$ 393.00	\$ 393.00 NN X
1	Rear n/s door regulator	Damage	\$ 345.00	\$ 345.00 NN X
1	Rear n/s door regulator motor	Damage	\$ 305.00	\$ 305.00 NN X
1	Rear n/s door rubber	Necessary	\$ 197.00	\$ 197.00 NEC ✓
1	Rear n/s fender	Repair	\$ 1,550.00	
			\$ 6,532.00	\$ 4,982.00
		Less 5%	\$ 326.60	\$ 249.10
	Total Cost - List Items		\$ 6,205.40	\$ 4,732.90

Total cost of parts

\$ 6,205.40	\$ 4,732.90
-------------	-------------

S&C L APPRAISER PTE LTD

Vehicle Registration No: SKX 7067 E

Our Ref No: 889/07/1801/TP

S/No	Description	Repairer's Estimate	Revised Amount
	Total cost of parts c/f	\$ 6,205.40	\$ 4,732.90
<u>LABOUR</u>			
1	To remove and refit doors complete fittings and replace damaged parts, transfer all fittings to new door.	\$ 300.00	\$ 240.00 ⁵⁰ 150.00
2	To apply undercoating on repaired and replaced panel.	\$ 150.00	\$ 90.00 ^{60.00}
3	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,400.00	\$ 1,000.00 ^{600.00}
4	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,200.00	\$ 880.00 ⁶⁰⁰ 480.00
	GRAND TOTAL	\$ 9,255.40	\$ 6,942.90

Repair days 4

Taim 

9/11/18

CL APPRAISER PTE LTD

Vehicle Registration No: SKX 7067 E

Our Ref No: 889/07/1801/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 5,600.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

CL APPRAISER PTE LTD



Cheong K. H
Automotive Appraiser



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	06 Jul 2018		10 Jul 2018 16:17 Edit Adj Rpt	S\$2,350.00 Edit Estimates	S\$2,350.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	Choo Geok Lan Theresa, ID: S0009628H								
Main Claimant:	CROSS NORMAN FRANCIS, ID: S8339086G								
Vehicle Reg. No.:	SKX7067E	Date of Loss:	06/07/2018 16:00 - :59 [61 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 563822	Policy/Cover Note No.:	27724091QMY (Comprehensive) Coverage: 21/06/2018 - 20/06/2019						
Vehicle Reg. No. (Insured):	SFQ718C	Policy No. (Claimant):							
		Excess:							
Repairer:	889 Car Servicing Pte Ltd () 10 Kaki Bukit Road 2, #03-34 First East Centre, 417868 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 09/11/2018]								
Adj. Asg. Remarks:	SJE Disagree Please appoint LKK and contact Mr. Cashin Terng @ 96621885 / 64445889 Liability (Non-reporting)								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
<ul style="list-style-type: none"> MSIG_SG (07/11/2018): Report Send Back Alerts - SKX7067E (TP) 									
ALL ASSOCIATED TASKS <input type="checkbox"/>				View All	Search Tasks	Create New Task	Complete		
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKX7067E (563822)**
[SFQ718C]
TP
CROSS NORMAN FRANCIS
Jul 6 2018 4:00PM
[Choo Geok Lan Theresa]
889 Car Servicing Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser ▼		
Video			1 per page ▼	<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	06/08/18 16:52	Video - AccidentTPCCTV1		Load MP4	<input type="checkbox"/>
2	06/08/18 16:52	Video - AccidentTPCCTVLIFT1		Load MP4	<input type="checkbox"/>
3	06/08/18 16:52	Video - AccidentTPCCTVLIFT2		Load MP4	<input type="checkbox"/>
Letters/Correspondences			1 per page ▼	<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	10/07/18 14:43	Non Reporting Letter to OI		Load HTM	<input type="checkbox"/>
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/07/18 11:36	General View		Load JPG	<input checked="" type="checkbox"/>
2	23/07/18 11:36	General View		Load JPG	<input checked="" type="checkbox"/>
3	23/07/18 11:36	General View		Load JPG	<input checked="" type="checkbox"/>
4	23/07/18 11:36	General View		Load JPG	<input checked="" type="checkbox"/>
5	23/07/18 11:36	General View		Load JPG	<input checked="" type="checkbox"/>
6	23/07/18 11:36	General View		Load JPG	<input checked="" type="checkbox"/>
7	23/07/18 11:36	General View		Load JPG	<input checked="" type="checkbox"/>
8	23/07/18 11:36	General View		Load JPG	<input checked="" type="checkbox"/>
9	23/07/18 11:36	General View		Load JPG	<input checked="" type="checkbox"/>
10	23/07/18 11:36	General View		Load JPG	<input checked="" type="checkbox"/>
11	23/07/18 11:36	General View		Load JPG	<input checked="" type="checkbox"/>
12	23/07/18 11:36	General View		Load JPG	<input checked="" type="checkbox"/>
13	23/07/18 11:36	General View		Load JPG	<input checked="" type="checkbox"/>
14	23/07/18 11:36	General View		Load JPG	<input checked="" type="checkbox"/>
15	23/07/18 11:36	General View		Load JPG	<input checked="" type="checkbox"/>
16	23/07/18 11:36	General View		Load JPG	<input checked="" type="checkbox"/>
17	23/07/18 11:36	General View		Load JPG	<input checked="" type="checkbox"/>
18	23/07/18 11:36	General View		Load JPG	<input checked="" type="checkbox"/>
19	23/07/18 11:36	General View		Load JPG	<input checked="" type="checkbox"/>
20	23/07/18 11:36	General View		Load JPG	<input checked="" type="checkbox"/>
21	23/07/18 11:36	General View		Load JPG	<input checked="" type="checkbox"/>
22	23/07/18 11:36	General View		Load JPG	<input checked="" type="checkbox"/>
23	23/07/18 11:36	General View		Load JPG	<input checked="" type="checkbox"/>
24	23/07/18 11:36	General View		Load JPG	<input checked="" type="checkbox"/>
25	23/07/18 11:36	General View		Load JPG	<input checked="" type="checkbox"/>
26	23/07/18 11:36	General View		Load JPG	<input checked="" type="checkbox"/>
27	23/07/18 11:36	General View		Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
28	23/07/18 11:36	General View	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/07/18 14:38	PRI & THIRD PARTY ACCIDENT REPORT	Load PDF	
2	10/07/18 14:47	Email to Workshop	Load PDF	
3	27/07/18 15:32	traffice police report	Load PDF	
4	06/08/18 15:40	SFQ718C	Load PDF	
5	06/08/18 15:40	SKX7067E	Load PDF	
6	17/08/18 18:50	LOD,REPAIR BILL, RENTAL AGREEMENT & LTA SEARCH	Load PDF	
7	17/08/18 18:50	COLOURED IMAGES	Load PDF	
8	17/08/18 18:50	SURVERY FEE & REPORT	Load PDF	

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/11/18 15:32	PRS INVOICE	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/> <input type="button" value="Save"/> <input type="button" value="Print"/>
----------------------------	---

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18012601/GQBS2-1
Date: 21/11/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 27724091QMY
Claimant Vehicle No : SKX7067E **Insured Vehicle No :** SFQ718C
 Date of Loss: 06/07/2018 Nature of Claim: TP Claim No: 563822

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX7067E**
 Make & Model: BMW 316I, 1.6 AT D/AB 4DR ABS HID (A) Engine No: A968J463N13B16A
 Reg. Date: 31/05/2013 (Man. Year: 2013) Chassis No: WBA3A12080J720411
 Colour: Black Odometer: 96463 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50R17 Rear Tyre Size: 225/50R17
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,205.40	1,759.40	4,446.00	71.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,050.00	1,220.00	1,830.00	60.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,255.40	2,979.40	6,276.00	67.81
Approved Total (Overridden) (S\$)		2,350.00		
Nett Amount (S\$)	9,255.40	2,350.00	6,905.40	74.61

INSPECTION

Date of Assignment: 10/07/2018
 Date Inspected: 12/07/2018 Inspected At: 889 Car Servicing Pte Ltd
 10 Kaki Bukit Road 2, #03-34 First East Centre
 Singapore 417868
 Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Nov 2018)
Parts: 143	BMW 316I 1.6 AT D/AB 4DR ABS HID (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKX7067E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT N/S DOOR	Repair	1,605.00 FL	*- FL
2	1		*FRONT N/S DOOR LOCK	Not Necessary	285.00 FL	*- FL
3	1		*FRONT N/S DOOR RUBBER	Not Necessary	197.00 FL	*- FL
4	1		*REAR N/S DOOR	Dented	1,655.00 FL	*1,655.00 FL
5	1		*REAR N/S DOOR INNER LOCK	Not Necessary	393.00 FL	*- FL
6	1		*REAR N/S DOOR REGULATOR	Not Necessary	345.00 FL	*- FL
7	1		*REAR N/S DOOR REGULATOR MOTOR	Not Necessary	305.00 FL	*- FL
8	1		*REAR N/S DOOR RUBBER	Necessary	197.00 FL	*197.00 FL
9	1		*REAR N/S FENDER	Repair	1,550.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	6,532.00	1,852.00
- List Item Discount on L Items 5.00/5.00% (\$\$)	326.60	92.60
Total Parts (\$\$)	6,205.40	1,759.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT DOORS COMPLETE FITTINGS AND REPLACE DAMAGED PARTS, TRANSFER ALL FITTINGS TO NEW DOOR.	New	300.00	60.00
2	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.	New	150.00	60.00
3	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT.	New	1,400.00	500.00
4	TO RESPRAY PAINTING INCLUDING POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT.	New	1,200.00	600.00
Gross Labour Cost (S\$)			3,050.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >