

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD

143 Cecil Street #01-01 GB Building
 069542

Attention : Motor Claim Department

Contact : 338 7288 Fax No. : 880 4838

Estimate : ES000381

Date : 08/11/2018

Vehicle Num. : SLK 7535C (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 01/11/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|--------------|-----|---------------------------------|--|--|
| LIST ITEMS : | | | | |
| 1. | 1 | REAR BOOT LID | | |
| 2. | 1 | REAR BOOT INNER TRIM BOARD | | |
| 3. | 1 | REAR WINDSCREEN GLASS MOULDING | | |
| 4. | 1 | REAR BOOT HYBRID EMBLEM (VEZEL) | | |
| 5. | 1 | REAR BOOT VEZEL EMBLEM (VEZEL) | | |
| 6. | 1 | REAR BUMPER | | |
| 7. | 1 | REAR END PANEL | | |
| 8. | 1 | REAR END PANEL TOP GARNISH | | |
| 9. | 1 | REAR BOOT WEATHER STRIP | | |
| 10. | 1RH | REAR BOOT REFLECTOR LAMP | | |
| 11. | 1RH | REAR TAIL LAMP | | |
| 12. | 1 | REAR BUMPER REFLECTOR LENS RH | | |
| 13. | 1 | REAR ANTENNA SENSOR | | |
| 14. | 1 | SMART BUZZER SENSOR | | |
| 15. | 1 | REAR COMPARTMENT BOX | | |
| 16. | 1 | REAR BOOT HAND GRIP COVER | | |
| 17. | 1 | REAR NUMBER PLATE LAMP GARNISH | | |
| 18. | 1 | REAR BOOT LOCK ASSY | | |
| 19. | 1 | REAR EXHAUST MUFFLER | | |

List TotalS\$:

25.00% Discount S\$:

DEF

1,200.00	MA
345.00	X SVC
250.00	X NN
89.00	NEC
89.00	NEC
900.00	CRK
755.00	PAR
245.00	PAR X SVC
188.00	X SVC
580.00	X SVC
580.00	X SVC
170.00	X SVC
188.00	X SVC
188.00	X SVC
280.00	X SVC
68.00	X SVC
290.00	X SVC
300.00	X SVC
750.00	X SVC
7,455.00	
1,863.75	
5,591.25	

- | | | | | |
|----------------------|---|---------------------------------|--|--|
| SPECIAL NETT ITEMS : | | | | |
| 1. | 1 | REAR BOOT INNER TRIM BOARD CLIP | | |
| 2. | 1 | REAR WINDSCREEN SEALANT | | |
| 3. | 1 | REAR BUMPER CLIP | | |

40.00	X NN
100.00	NEC
40.00	NEC

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
 143 Cecil Street #01-01 GB Building
 069542

Attention : Motor Claim Department
 Contact : 338 7288 Fax No. : 880 4838

Estimate : ES000381

Date : 08/11/2018
 Vehicle Num. : SLK 7535C (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 01/11/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
4.	1	REVERSE SENSOR		280.00 280.00 <i>ERK</i>
5.	1	REAR END PANEL TOP GARNISH CLIPS		40.00 40.00 <i>SVL (Airtel)</i>
6.	1	REAR TAILLAMP CLIPS		40.00 40.00 <i>XXX</i>
7.	1	REAR NUMBER PLATE LAMP GARNISH CLIP		40.00 40.00 <i>XXX</i>
Special Nett Total S\$:				580.00
LABOUR :				
TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES				180.00 180.00 <i>70</i>
REMOVE & REFIT REAR WINDSCREEN GLASS				180.00 180.00 <i>120</i>
TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT TO REPLACED PARTS.				180.00 180.00 <i>40</i>
TO DISMANTLE REAR DAMAGE PARTS, CUT AND WELD REAR SUPPORT PANEL, KNOCK, STRAIGHTEN AND RESHAPE O/S REAR CHASSIS FRAME AND REPLACE RECOMMENDED PARTS.				1,200.00 1,200.00 <i>400 500</i>
TO PUTTY & SPRAY PAINTING ON REAR AFFECTED AREAS				1,400.00 1,400.00 <i>400 600</i>
TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS AND REVERSE SENSORS				180.00 180.00 <i>30</i>
DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME. (HV HYBRID SYSTEM SAFETY PROCEDURES)				450.00 450.00 <i>XXX</i>
PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINITIALISING HV HYBRID SYSTEM FOR POST REPAIRS. (HV HYBRID SYSTEM SAFETY PROCEDURES)				450.00 450.00 <i>XXX</i>

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
 143 Cecil Street #01-01 GB Building
 069542

Attention : Motor Claim Department
 Contact : 338 7288 Fax No. : 880 4838

Estimate : ES000381

Date : 08/11/2018
 Vehicle Num. : SLK 7535C (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 01/11/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

REMOVE REAR EXHAUST MUFFLER IN ORDER TO FACILITATE
 REPAIRS AND REFIT BACK SAME

180.00 x 2

Labour Total S\$:

4,400.00

NA2 LKK

9/11/18

P/P

3 DAYS 4 DAYS

CHECK ITEM & PHOTOS
 BEFORE PAINT PHOTOS

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

E. & O.E.

Total S\$: 10,571.25

=====

for WORLD AUTO PTE LTD