

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5749E****AAD1811-041***Not Authorised*  
*LLP &*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

**SHC 5749E**

VF1ABL15AUC281560

RENAULT

LATITUDE

6.11.2018

**AIG**

| PART |                                      | LIST |          |
|------|--------------------------------------|------|----------|
| 1    | DOOR PANEL REAR LH                   | \$   | 2,844.66 |
| 1    | DOOR GUIDE REAR LH                   | \$   | 176.82   |
| 1    | DOOR HINGE UPPER LH                  | \$   | 274.50   |
| 1    | DOOR HINGE LOWER LH                  | \$   | 300.55   |
| 1    | DOOR CHECK REAR LH                   | \$   | 203.06   |
| 1    | DOOR LOCK REAR LH                    | \$   | 908.75   |
| 1    | DOOR HANDLE OUTER REAR LH            | \$   | 126.49   |
| 1    | DOOR HANDLE CAP REAR LH              | \$   | 35.52    |
| 1    | DOOR HANDLE SEAL REAR LH             | \$   | 7.89     |
| 1    | DOOR HANDLE COVER REAR LH            | \$   | 13.22    |
| 1    | DOOR HANDLE MODULE REAR LH           | \$   | 133.60   |
| 1    | DOOR REGULATOR REAR LH               | \$   | 1,135.10 |
| 1    | DOOR REGULATOR MOTOR REAR LH         | \$   | 893.75   |
| 1    | DOOR REGULATOR NUT REAR LH           | \$   | 12.43    |
| 1    | DOOR REGULATOR MOTOR SCREW REAR L70Y | \$   | 6.31     |
| 1    | DOOR FINISHER REAR LH                | \$   | 423.10   |
| 1    | DOOR MOULDING REAR LH                | \$   | 176.82   |
| 1    | DOOR MOULDING CLIP L70Y              | \$   | 5.92     |
| 1    | DOOR MOULDING SCREW L70Y             | \$   | 6.91     |
| 1    | DOOR CASING REAR LH                  | \$   | 1,509.06 |
| 1    | DOOR WATER SHIELD REAR LH            | \$   | 30.39    |
| 1    | DOOR CASING CLIP                     | \$   | 12.63    |
| 1    | DOOR CASING LIGHT L70Y               | \$   | 48.74    |
| 1    | DOOR FINISHER INNER REAR LH          | \$   | 323.44   |
| 1    | DOOR FINISHER BRACKET INNER REAR LH  | \$   | 46.97    |
| 1    | DOOR FINISHER BRACKET INNER REAR LH  | \$   | 20.33    |
| 1    | DOOR FINISHER BRACKET INNER REAR LH  | \$   | 20.33    |
| 1    | DOOR FINISHER BRACKET INNER REAR LH  | \$   | 20.33    |
| 1    | DOOR GRAB HANDLE REAR LH             | \$   | 210.96   |

*X22*

**Trans-cab Auto Services Pte Ltd****AAD1811-041**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5749E**

|   |                                |        |                  |   |
|---|--------------------------------|--------|------------------|---|
| 1 | DOOR BLIND REAR LH             | \$     | 741.80           |   |
| 1 | DOOR WHEATHESTRIIP REAR LH     | \$     | 410.66           |   |
| 1 | DOOR SEAL REAR LH              | \$     | 162.02           |   |
| 1 | DOOR GLASS RUNNER SEAL REAR LH | \$     | 229.31           |   |
| 1 | DOOR WAIST SEAL OUTER REAR LH  | \$     | 334.69           |   |
| 1 | DOOR WAIST SEAL INNER REAR LH  | \$     | 115.64           |   |
| 1 | FENDER PANEL REAR LH           | \$     | 3,299.13         | ✓ |
| 1 | FENDER PANEL INNER TRIM REAR   | \$     | 671.45           | X |
| 1 | WHEELARCH REAR LH              | \$     | 543.47           | ✓ |
| 1 | ROCKER PANEL INNER GARNISH LH  | \$     | 466.51           | X |
| 1 | ROCKER PANEL INNER LH          | \$     | 1,024.79         | X |
| 1 | ROCKER PANEL CENTER LH         | \$     | 990.25           | X |
| 1 | WHEEL HOUSING PANEL REAR LH    | \$     | 4,682.09         | X |
| 1 | CHASSIS PANEL REAR LH L70Y     | \$     | 3,766.43         | X |
| 1 | HEADLAMP RH                    | \$     | 1,184.43         | ✓ |
| 1 | BUMPER COVER REAR              | \$     | 1,108.46         | ✓ |
| 1 | BUMPER LOWER REAR              | \$     | 768.84           | X |
| 1 | BUMPER BRACKET CTR REAR        | \$     | 113.47           | X |
| 1 | BUMPER BRACKET SIDE LH REAR    | \$     | 135.97           | X |
| 1 | BUMPER RETAINER LH REAR        | \$     | 44.99            | ✓ |
| 1 | FUEL FLAP L70Y                 | \$     | 343.57           | X |
| 1 | DOOR PANEL FRT LH              | \$     | 2,844.66         | X |
|   |                                | \$     | <b>33,911.20</b> |   |
|   |                                | 10% \$ | <b>3,391.12</b>  |   |
|   |                                | \$     | <b>30,520.08</b> |   |

**Specical Nett**

|   |                               |    |        |       |
|---|-------------------------------|----|--------|-------|
| 1 | REAR DOOR STICKER '6555 3333' | \$ | 80.00  |       |
| 1 | DOOR CHECK BOLT               | \$ | 22.69  |       |
| 1 | DOOR GUIDE SCREW              | \$ | 10.85  |       |
| 1 | DOOR HINGE BOLT               | \$ | 10.85  |       |
| 1 | DOOR HINGE NUT RH             | \$ | 14.60  |       |
| 1 | DOOR CHECK BOLT               | \$ | 22.69  |       |
| 1 | DOOR CHECK NUT                | \$ | 3.75   |       |
| 1 | DOOR LOCK SCREW L70Y          | \$ | 6.12   |       |
| 1 | DOOR CATCH SCREW L70Y         | \$ | 10.06  |       |
| 1 | LEFT REAR TYRE                | \$ | 330.00 | 70% ✓ |

**Trans-cab Auto Services Pte Ltd**

AAD1811-041

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5749E

1 LEFT REAR TYRE RIM

\$

B1 380.00 ✓

**TOTAL \$****891.63****TOTAL PARTS \$****31,411.71****LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$

1200  
4,500.00

Putty and spray painting of the affected portion.

\$

1320  
4,500.00

To rust-proofing of the affected areas.

\$

170.00 300

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$

380.00 1000

To check steering geometry and computer wheel alignment

\$

220.00 600

To transfer of tire, rim and on wheel balancing.

\$

170.00 400

To Check Electrical Lighting Concerned.

\$

170.00 400

To transfer of Rear fender fittings, attachment and perform water seepage test.

\$

na 380.00 X

To transfer of Rear bumper fittings, attachment and perform water seepage test.

\$

na 380.00 X

LKK Auto Consultants hence notify the Repairer of the following:

To transfer of Rear door fittings, attachment and perform water seepage test.

\$

na 380.00 X

- To resurvey before and after spray painting
- To display damaged parts to be replaced
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**TOTAL \$****11,250.00****Over All Total \$****42,661.71****LUMP SUM (REPAIR DAY)****15 DAYS**

8 days

Acknowledged by Repairer

Signature:

Date: