

INSURANCE

INS. CASE OWNER:

CC 6 /AIG1802 ONLY, A e b h y

LKK

IDAC

Surveyor:

emp

DOI:

10/1/18

Date / Time:

11/1/18

Registered in Merimen:

10/1/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLK 67466

Name of Insured:

MIE JIANPUN

Insured Tel No.:

HP: 95161119

Excess Sec II :SS

D.O.A.: 8/11/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

17748965554

Policy No.:

120004795-01

Make / Model:

MAYON

Place of Accident:

YISHAN AVE 1

If NO, Driver Name / Age:

Driver Tel No.:

(VA- YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SLK 507472

INSRS:
WSP:
Tel:
Liability:
RMKS:

modern

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

15/1/18
15/1/18

SLK 507472 - R

SLK 67466 - R

STAGE

DATE / PIC

Non-Reporting hr (1st):

Non-Reporting hr (2nd):

Non-Reporting hr (Final):

Notification hr (if non-pickup):

Call Of:

After call hr to OI:

Documentation Check List: Handler Typist

Notification hr (if non-pickup)

After call hr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by: LKK

FINALIZATION

Date/Time:

Confirm with:

Confirm by: LKK

Repair Cost:

US \$53,880

(5 days) Reduction:

54

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%100

(Agreed / Assessed) BOLA S/N No.:

27

Repair Cost:

US \$4,119.30

OI: RMR ENDED TP

Loss of Rental (LOR):

US \$60.00

(5 days) x 1200

Loss of Use (LOU):

US -

(5 days) x

Loss of Income (LOI):

US -

(5 days) x

LOR only

LOU only

LOR + LOU

LOR + LOU

(Tick only one)

GIA/LTA Search

US \$2.00

Medical:

US -

Disbursement:

US -

(e.g. Tow/ Independent)

Legal Cost:

US -

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: 9320 + 1220

Total:

US \$4,121.30

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

US \$4,121.30

Name 1: MODERN AUTOMOTIVE PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % J Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLX5035 Z Yr Regn: 2018 MarchType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Wish c.c. 1798Colour: White A/C: Insured / Std / NI / NASp. Reading 21146 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTD6620W40J029501Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 195/65R15BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 19/11/18Sunray held at ModernDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP ALG.45: +3820 (RED: +4449.43 54%)

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, Si

Photos

Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG18020314/eb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 09-11-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLQ 6746K	Veh. Inspected	SLX 5035Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	09/11/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	08/11/2018	Inspection Date
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
78 Shenton Way #07-16
Singapore 079120
Tel : 6419 - 3000
Fax : 6835 - 7416

Quotation
DATE : 19.11.2018
VEH NO : SLX5035Z
MODEL : Toyota Wish
D O A : 08.11.2018
YR REF : SLQ6794K

Attn : Motor Claim Dept (P's arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLX5035Z (TOYOTA WISH)

Item	Description	Qty	Am't
NO	LIST ITEMS		
1	Rear Bumper <i>Deformed</i>	1	498.30 ✓
2	Rear Bumper Clips <i>new</i>	1 set	30.00 ✓
3	Rear Bumper Side Holder - LH & RH <i>RH Dmgd</i>	2	90.20 45.10 ✓
4	Rear Bumper Reflector - RH <i>lt</i>	1	81.70 ✓
5	Rear Bumper Impact Bracket - LH & RH <i>RH Dented</i>	2	431.40 65.70 ✓
6	Rear End Panel <i>Dented</i>	1	477.20 ✓
7	Rear End Panel Top Garnish <i>new</i>	1	253.60 X
8	Taillamp - RH <i>lt</i>	1	387.60 ✓
9	Tailgate <i>Dented</i>	1	1,248.60 ✓
10	Tailgate Lock <i>new</i>	1	361.10 X
11	Tailgate Weatherstrips <i>new</i>	1	304.70 X
12	Tailgate Reflector - RH <i>lt</i>	1	304.60 ✓
13	Tailgate Inner Trim Board <i>new</i>	1	345.20 X
14	Tailgate Inner Trim Board Clips <i>new</i>	1 set	30.00 X
15	Tailgate Glass Moulding <i>new</i>	1	132.40 ✓
16	Toyota Logo <i>new</i>	1	75.10 ✓
17	Valvematic Emblem <i>new</i>	1	35.70 ✓
18	Rear Fender Inner Trim Board - RH <i>new</i>	1	599.00 X
19	Rear Fender Inner Trim Board Clips <i>new</i>	1 set	30.00 X
20	Rear Exhaust Pipe <i>new</i>	1	780.20 X
21	Rear Exhaust Mounting <i>new</i>	1	39.40 X
			6,225.90
Less 25%			(1,556.48)
			\$ 4,669.43

S/NETT ITEMS

1	Reverse Sensor <i>Damaged</i>	1	280.00 <i>200</i>
2	Rear End Panel Sealant <i>new</i>	1	60.00 ✓

RE: ESTIMATE FOR ACCIDENT REPAIR SLX5035Z (TOYOTA WISH)

3	Tailgate Glass Sealant	1	60.00
			400.00
	Total Parts		5,069.43

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$	1,200.00	800
2	To putty & spray up paint works	\$	1,100.00	800
3	To check wiring	\$	50.00	30
4	To underseal	\$	150.00	50
5	To remove upholstery	\$	150.00	60
6	To remove reverse sensor	\$	100.00	50
7	To remove exhaust pipe	\$	150.00	X
8	To remove tailgate glass	\$	180.00	120
9	To transfer tailgate fittings	\$	150.00	80
Total Labour		\$	3,230.00	
Grand Total		\$	8,299.43	

NOTE : •

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 484642.
w/c: 3850.

MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 # 01 - 61

SINGAPORE 408717

GST REG. NO : 200501102H

TEL : 6748-4422 / 6744-4422 FAX : 6-747- 6720

Email: chin@modernautomotive.com.sg

Your Ref : SLQ6794K

Our Ref : SLX5035Z

Date : 20.12.2018

The Claims Manager

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78, Shenton Way #07-16

Singapore 079120

Tel : 6-419-300 Fax : 6-415-3727

Attn : The Motor Claim Dept

RE : ACCIDENT INVOLVING SLX5035Z & SLQ6794K ON 08.11.2018
AT CROSS JUNCTION OF SEMBAWANG ROAD & YISHUN AVENUE 1

We refer to the above matter.

We have been authorized by our client M/s Hitachi Capital Asia Pacific Pte Ltd to make claim against your insured vehicle No.SLQ6794K in respect of the above accident for the following:

Repair Cost	\$ 4,119.50 (Incl GST)
Loss of rental (\$200 x 5 days)	\$ 1,000.00
Search fee	\$ 2.00
Total :	\$ 5,121.50

Enclosed herewith a copy each of the supporting documents for your perusal.
Kindly process the above and remit the payment to us asap

Yours faithfully



Modern Automotive Pte Ltd

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Thursday, 15 November 2018 2:04 PM
To: 'NIEJIANJUN74@GMAIL.COM'
Subject: ACCIDENT INVOLVING SLQ 6746K AND SLX 5035Z ON 08/11/2018

Our Ref: CC6/AIG18020314/eb3

15 NOV 2018

NIE JIANJUN

Dear Sir/Madam,

ACCIDENT INVOLVING SLQ 6746K AND SLX 5035Z ON 08/11/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: Ashersng@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

LETTER OF AUTHORIZATION

Date: 08/11/2018

TO WHOM IT MAY CONCERN

Dear Sir,

RE: ACCIDENT INVOLVING VEHICLE

SLX 5035Z / SLQ 6746K

ON 08/11/18 ALONG Cross Junction of Sembawang
Road & Yishun Ave 1.

This letter is to authorize MODERN AUTOMOTIVE PTE LTD at Block 3023A, Ubi Road 1,
#01-61, Singapore 408717 to resolve the above matter.

In respect of this authorization, MODERN AUTOMOTIVE PTE LTD has my/our authority to
decide on my/our behalf whether to accept any offer of settlement from the third party
insurers. I/we also agreed that all payments include Loss of Use to make in favour of
MODERN AUTOMOTIVE PTE LTD.

MODERN AUTOMOTIVE PTE LTD is also authorized to sign all the required documents
include Discharge Voucher from the third party insurers on my/our behalf.

Yours Faithfully

Signature of Owner

Name / NRIC

HITACHI CAPITAL ASIA PACIFIC PTE. LTD.

HIROYUKI WASHISHITA (MR)
Senior Manager
Total Vehicle Solutions Department

THAT SENG WEE / 882241026

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **MODERN AUTOMOTIVE PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$4,119.50** (Repair Cost), **S\$600.00** (Loss of Use/Rental), **S\$2.00** (Disbursement) for vehicle no. **SLX 5035Z** that was damaged pursuant to the accident which occurred on **08/11/2018** (date) along **CROSS JUNCT OF SEMBWANG D & YISHUN AVE 1** (location) involving vehicle no/s **SLO 6746K**.

This is pursuant to the inspection conducted on **19/11/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **HITACHI CAPITAL ASIA PACIFIC PTE LTD** ("the third party claimant") of vehicle no. **SLX 5035Z** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SLX 5035Z** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 14 (day) of Jan (month) 2019 (year)



LWP

Signed by appointed surveyor



Signed by "the workshop" (with chop)

MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 # 01-58 / 61 SINGAPORE 408717
TEL : 67474422, 67454422 FAX : 67476720
GST REG. NO : 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
SINGAPORE 079120

Attention : Motor Claim Department
Contact : 6415-3727 6419-3000

Tax Invoice : TP001297

Date : 19/12/2018
Vehicle Num. : SLX 5035Z
Make/Model : TOYOTA WISH-2018
Chassis/Eng# :
Accident Date : 08/11/2018
Claim No. :
Reference :
Policy No. : 1800038735

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
		ACCIDENT REPAIR (LUMPSUM)		3,850.00
		Labour Total S\$:		3,850.00

Total S\$:	3,850.00
GST @ 7% S\$:	289.50
Amount Due S\$:	4,119.50



MODERN AUTOMOTIVE PTE LTD



DAWN ENTERPRISES

21 SELETAR WEST FARMWAY 1
SINGAPORE 798125
TEL: 6383 2661 FAX: 6484 2836
REG. NO. 430058/000

No. 19695

OFFICIAL RECEIPT

Received from

Hitachi Capital Asia Pacific P. L

Date

24/11/18

the sum of Dollars

One thousand only

being Payment Of

SDX 2437D

(19/11/18 - 24/11/18)

DAWN ENTERPRISES

\$

1000/-

Cash/Cheque No.



DAWN ENTERPRISES

21 Seletar West Farmway 1
Singapore 798125
Tel: 63832661 Fax: 64842836
Reg No.430058/00D

TP SLX 50352

Nº 35921

RENTAL AGREEMENT

DATE 19/11/18

HIRER'S PARTICULARS

Name Hitachi Capital Asia Pacific P. L.

Address _____

I/C or Passport No. _____ Country _____

Occupation _____

Date of Birth _____ Age _____

Driving Licence No. _____ Date Passed _____

Tel: (HP) _____ (Residence) _____

DRIVER'S PARTICULARS

Name RAY SENIG WEE.

Address BLK 315A YISHUAN AVE
9# 12-206 S 761315.

I/C or Passport No. S82241026 Country S'PORE.

Occupation SALES.

Date of Birth 29/07/82 Age 36+

Driving Licence No. _____ Date Passed _____

Tel: (Office) _____ (Residence) _____

IMPORTANT NOTES:

1. No Insurance Coverage if the driver is below 24yrs old or less than 2 years driving licence.
2. This vehicle is licensed to carry 2000 passengers only.
3. Hirer is liable to pay first \$ 2000 as excess all claims any accident plus loss of earning while damaged vehicle is under repair.
4. For usage to Malaysia subject to higher excess all claims of S\$5,000.00 and different rental rate.
5. Please notify our office should there be any accident involving this hired vehicle within 24 hrs.
6. No refund will be given for vehicle return early.
7. No refund will be given for petrol left in vehicle.
8. Hirer is liable to pay all parking fee and traffic summonses.
9. Vehicles to be return during office hour only.
10. No Service on Public Holiday and Sunday.

SCHEDULE

MODEL

8x 2437 D

Toyota Picnic

Date	Time	Mileage
<u>19/11/18</u>	<u>1.35pm</u>	
<u>24/11/18</u>		

CHARGES

Day at \$ <u>200.00</u>	per days	<u>\$1000.00</u>
Day at \$ _____	per week	
Day at \$ _____	per month	
TOTAL AMOUNT		<u>\$1000.00</u>
AMOUNT PAID		<u>\$1000.00</u>
BALANCE DUE		
Days Extension From _____	To _____	
Amount Deposit (refundable) \$ _____		

FROM

19/11/18

TO

24/11/18

I/we have read and understood the terms and conditions above and hereby agreed to abide

Hirer's Signature

Driver/Guarantor's Signature

DAWN ENTERPRISES



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-173848
Date of Request: 09/11/2018

Your Ref No: Online Purchase

Modern Automotive Pte Ltd
Blk 3023A Ubi Road 1
#01-61 & #01-58
Singapore 408717

Dear Sir/Madam,

Enquiry Date 09/11/2018
Enquiry By Chin Sol Shong
TP Vehicle No. SLQ6746K
Accident Date 08/11/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLQ6746K	AIG Asia Pacific Insurance Pte. Ltd.	19/07/2018-18/07/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-173648

Date of Request: 09/11/2018

Your Ref No: Online Purchase

Modern Automotive Pte Ltd
Blk 3023A Ubi Road 1
#01-61 & #01-58
Singapore 408717

Dear Sir/Madam,

Enquiry Date 09/11/2018
Enquiry By Chin Sol Shong
TP Vehicle No. SLQ6746K
Accident Date 08/11/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)
Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Nov 2018 Edit Reg		19 Nov 2018 00:00 Edit Adj Rpt	S\$3,850.00 Edit Estimates	S\$3,850.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS				[Created by adjuster]	
Insured:	NIE JIANJUN, ID: S74610423				
Main Claimant:	HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N				
Vehicle Reg. No.:	SLX5035Z	Date of Loss:	08/11/2018 07:00 - :59 [7 Months and 10 Days From LTA Reg Date (Man Yr)]		
Claim Type:	TP / 2175989655SG	Policy/Cover Note No.:	1700043525 (Comprehensive)		
Vehicle Reg. No. (Insured):	SLQ6746K	Policy No. (Claimant):	1800038735		
		Excess:			
Repairer:	Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58, 408717 Ubi - Tel: 6748 4422 / 6747 4422				
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M]				
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 20/11/2018]				

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLX5035Z (2175989655SG)
[SLQ6746K]
TP
HITACHI CAPITAL ASIA PACIFIC PTE LTD
Nov 8 2018 7:00AM
[NIE JIANJUN]
Modern Automotive Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Letters/Correspondences

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	<div><div></div><div>Edit</div></div>	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/01/19 11:16	General View	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
2	28/01/19 11:16	General View	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
3	28/01/19 11:16	General View	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
4	28/01/19 11:16	General View	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
5	28/01/19 11:16	General View	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
6	28/01/19 11:16	General View	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
7	28/01/19 11:16	General View	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
8	28/01/19 11:16	General View	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
9	28/01/19 11:16	General View	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
10	28/01/19 11:16	General View	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
11	28/01/19 11:16	General View	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
12	28/01/19 11:16	General View	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
13	28/01/19 11:16	General View	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
14	28/01/19 11:16	General View	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
15	28/01/19 11:16	General View	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
16	28/01/19 11:16	General View	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
17	28/01/19 11:16	General View	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
18	28/01/19 11:16	General View	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
19	28/01/19 11:16	General View	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
20	28/01/19 11:16	General View	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
21	28/01/19 11:16	General View	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
22	28/01/19 11:16	General View	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
23	28/01/19 11:16	General View	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
24	28/01/19 11:16	General View	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
25	28/01/19 11:17	Chassis Number	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
26	28/01/19 11:17	Reinspection Photo	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
27	28/01/19 11:17	Reinspection Photo	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
28	28/01/19 11:17	Reinspection Photo	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
29	28/01/19 11:17	Reinspection Photo	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
30	28/01/19 11:17	Reinspection Photo	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
31	28/01/19 11:17	Reinspection Photo	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
32	28/01/19 11:17	Reinspection Photo	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
33	28/01/19 11:17	Reinspection Photo	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>
34	28/01/19 11:17	Reinspection Photo	<div><div></div><div>Load JPG</div></div>	<div><div></div></div>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	28/01/19 11:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	28/01/19 11:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/11/18 14:11	TP GIA REPORT	Load PDF	
2	30/01/19 09:06	WORKSHOP INVOICE	Load PDF	
3	30/01/19 09:06	AUTHORISATION TO ACT FORM	Load PDF	
4	30/01/19 09:06	Release Voucher	Load PDF	
5	30/01/19 09:06	RENTAL RECEIPT	Load PDF	
6	30/01/19 09:06	GIA SEARCH	Load PDF	
7	30/01/19 09:06	LETTER TO OI	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte, Ltd. (SG)	Thumbnail	Print
1	13/11/18 08:59	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLQ6746K (Insd veh)	Model:	TOYOTA WISH 1.8 (A)
	SLX5035Z (TP veh)		
Date of Accident:	08/11/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	: \$	8,880.38		
Final Repair Cost	: \$	4,119.50		
Loss of Use	: \$	days at \$0.00 per day		
Rental (if any)	: \$	600.00	5	days
LTA / GIA Search Fee	: \$	2.00		
Others:	: \$	0.00		
	: \$			
Final Settlement Sum	: \$	4,721.50		

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Modern Automotive Pte Ltd	: \$	4,721.50
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

30 Jan
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18020314/AEB3Q2

Date: 30/01/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700043525
Claimant Vehicle No : SLX5035Z **Insured Vehicle No :** SLQ6746K
 Date of Loss: 08/11/2018 Nature of Claim: TP Claim No: 2175989655SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLX5035Z**
 Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 2ZR0A79671
 Reg. Date: 29/03/2018 (Man. Year: 2017) Chassis No: JTDGG20W40J009501
 Colour: White Odometer: 21146 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,069.42	2,856.42	2,213.00	43.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,230.00	1,990.00	1,240.00	38.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,299.42	4,846.42	3,453.00	41.61
Approved Total (Overridden) (S\$)		3,850.00		
(S\$)	8,299.42	3,850.00	4,449.42	53.61
+ GST 7.00/7.00% (S\$)	580.96	269.50	311.46	53.61
Nett Amount (S\$)	8,880.38	4,119.50	4,760.88	53.61
+ Car Rental (5.0 x S\$120.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,721.50		

INSPECTION

Date of Assignment: 19/11/2018
 Date Inspected: 19/11/2018 Inspected At: Modern Automotive Pte Ltd (HQ)
 Blk 3023A Ubi Road 1, #01-61 & #01-58
 Singapore 408717

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	498.30 FL	*498.30 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
3	1		*REAR BUMPER SIDE HOLDER -LH & RH	O/S Damaged	90.20 FL	*45.10 FL
4	1		*REAR BUMPER REFLECTOR -RH	Cut	81.70 FL	*81.70 FL
5	1		*REAR BUMPER IMPACT BRACKET -LH & RH	O/S Dented	131.40 FL	*65.70 FL
6	1		*REAR END PANEL	Dented	477.20 FL	*477.20 FL
7	1		*REAR END PANEL TOP GARNISH	Not Necessary	253.60 FL	*- FL
8	1		*TAILLAMP -RH	Cut	387.50 FL	*387.50 FL
9	1		*TAILGATE	Dented	1,248.60 FL	*1,248.60 FL
10	1		*TAILGATE LOCK	Not Necessary	361.10 FL	*- FL
11	1		*TAILGATE WEATHERSTRIPE	Not Necessary	304.70 FL	*- FL
12	1		*TAILGATE REFLECTOR -RH	Cut	304.60 FL	*304.60 FL
13	1		*TAILGATE INNER TRIM BOARD	Not Necessary	345.20 FL	*- FL
14	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	30.00 FL	*- FL
15	1		*TAILGATE GLASS MOULDING	Necessary	132.40 FL	*132.40 FL
16	1		*TOYOTA LOGO	Necessary	75.10 FL	*75.10 FL
17	1		*VALVEMATIC EMBLEM	Necessary	35.70 FL	*35.70 FL
18	1		*REAR FENDER INNER TRIM BOARD -RH	Not Necessary	589.00 FL	*- FL
19	1		*SET REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	30.00 FL	*- FL
20	1		*REAR EXHAUST PIPE	Not Necessary	780.20 FL	*- FL
21	1		*REAR EXHAUST MOUNTING	Not Necessary	39.40 FL	*- FL
22	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
23	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
24	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,625.90	3,701.90
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,556.48	845.48
Total Parts (\$\$)	5,069.42	2,856.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	1,200.00	800.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	1,100.00	800.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO UNDERSEAL	New	150.00	50.00
5	TO REMOVE UPHOLSTERY	New	150.00	60.00
6	TO REMOVE REVERSE SENSOR	New	100.00	50.00
7	TO REMOVE EXHAUST PIPE	New	150.00	0.00
8	TO REMOVE TAILGATE GLASS	New	180.00	120.00
9	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
Gross Labour Cost (S\$)			3,230.00	1,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >