

ASS. REC. BY:

REF: CS/SMO18020315 / Rlvbn2 | Special Instruction:

Surveyor: Rasul ASSIGNMENT (Office)From (Person): Gnroh Pau Luong of SMO Date/Time: 06/11/2018 5:10pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: GBH 4798P Insured: \_\_\_\_\_at Workshop m/s Ethnoz Tel: 6654 7617of 30 Bukit Batok CrescentPolicy No: D18MTPCVE001804 Claim No: CMTD1804847Sum Insured: \_\_\_\_\_ Excess: IBH 500Make of Veh: \_\_\_\_\_ D.O.A. 06/11/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 22 Tampines St 92 H.O.D. Endorsement: \_\_\_\_\_Date/Time: 09-11-2018 9:25am Person Contacted: Boon Kai Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	GBH 4798P - X
9/11/18	Revert via merimen
15/11/18	Rece approved \$6594 from Pau Luong, ex \$500 via merimen
15/11/18	Informal Boon Kai c/A ex \$500 by email
23/11/18	final fig \$6156 confirmed by email (Reel 3309, 3575)

Surveyor: Fahar

REF:

CG/SM01 8020315 /R1vb

8003K

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: GBH 4798Pat Workshop m/s ETHOZof 22, TAMPINES ST 92Insured: SMO

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: TBA

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 67K

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: GBH 4798P Yr Regn: 2018 / MAYType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: TOYOTA DYNA 150 SMT c.c. 2982Colour: Green A/C: Insured / Std / NI / NASp. Reading: 29752 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTEAT35490K210216Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/75R15R: 155R15C D10BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front

Rear

R/Bal. 7 mmR/Bal. 6/6 mmL/Bal. 7 mmL/Bal. 6/6 mmD.O.A. 06/11/18D.O.I. 09/11/18Survey held at ETHOZ TAMPINES

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRT N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 23 NOV 2018

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 23/11 - typistReport Format: merimenLump Sum / I.B.I: (\$) 6156 pDays Of Repair: 8Resurvey No. of Trip: 1Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

TOTAL

250

10

260

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: GNOH PAU LOONG

Date: 09 Nov 2018

**Preliminary Advice**

Vehicle No	: GBH4798P	Accident Date	: 06/11/2018
Make	: TOYOTA DYNA	Policy No.	: D18MTPCVE001804
Assignment Date	: 08/11/2018	Excess	: S\$500.00
Date of Inspection	: 09/11/2018	Est. Duration of Repair	: 8.00
Inspection At	: ETHOZ PROTECT PTE LTD (BUKIT BATOK) 30 BUKIT BATOK CRESCENT SINGAPORE 658075		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,335.00
Revised Amount	:S\$	6,126.00
Check Items (Estimated)	:S\$	468.00
Total	:S\$	6,594.00

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	67,000.00
COE / PARF Rebate	:S\$	28,000.00
Salvage Value	:S\$	
Margin for Repair	:S\$	39,000.00

**Remarks**

( X )

The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( )

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( )

Other comments :

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Nov 2018 15:36 Sendback Est	08 Nov 2018 15:03 S\$9,335.00	08 Nov 2018 17:20 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
<b>CLAIM SUBFOLDER DETAILS</b>				
Insured:	WILLY DESIGN & ENGINEERING PTE. LTD., Co. Reg. No.: 200808003K			
Vehicle Reg. No.:	GBH4798P	Date of Loss:	06/11/2018 00:00 - :59 [5 Months and 20 Days From LTA Reg Date (Man Yr)]	
Claim Type:	OD / CMTD1804847	Policy/Cover Note No.:	D18MTPCVE001804 (Comprehensive)	
		Excess:		
Repairer:	ETHOZ Protect Pte Ltd (Bukit Batok) 30 Bukit Batok Crescent, 658075 Bukit Batok - Tel: 66547750/51			
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/11/2018]			
Driver/Custodian:	MALATCHAMY PRABHU (39 / Male), NRIC: G7286291R, Tel: +6598227784			
<b>ASSOCIATED MAIL RECEIVED</b>			View All	Compose Case Mail
There are no mail for this case.				
<b>ALL ASSOCIATED TASKS</b>				
View All Search Tasks Create New Task Complete				
Due Date	Priority	Type	Task Group	Subject
			Handler	Assigned By
			Completed On	Created On
			Done?	
No results.				

## Veron Chen (LKKAuto)

---

**From:** Ng Boon Kai <BoonKai.Ng@ethozgroup.com>  
**Sent:** Thursday, 15 November 2018 1:50 PM  
**To:** Veron Chen (LKKAuto); SUR  
**Cc:** Suhelmi Bin Suharman  
**Subject:** RE: GBH 4798P-DOA: 6/11/2018 (SOMPO OD)

Hi Veron,

Message noted.

Thanks,  
Regards,  
Boon Kai

---

**From:** Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]  
**Sent:** Thursday, November 15, 2018 1:46 PM  
**To:** Ng Boon Kai <BoonKai.Ng@ethozgroup.com>; SUR <sur@lkkauto.com>  
**Subject:** GBH 4798P-DOA: 6/11/2018 (SOMPO OD)

Dear Boon Kai,

As instructed by our client , please proceed to repair the **insured vehicle GBH 4798P (Excess \$500-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Disclaimer: This message may contain confidential information intended only for the use of the addressee named above. If you are not the intended recipient of this message you are hereby notified that any use, dissemination, distribution or reproduction of this message is prohibited. If you received this message by mistake, please notify the sender by reply email immediately. Please conduct your own virus checks before opening any attachment as ETHOZ Group does not guarantee the integrity of this email or attached files has been maintained nor this communication is free of viruses, interceptions or interference. Any views expressed in this message are those of the individual sender and may not necessarily reflect the views of ETHOZ Group. ETHOZ Group shall not be responsible nor liable for the improper and incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system.

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Thursday, 15 November 2018 1:46 PM  
**To:** 'Ng Boon Kai'; SUR  
**Subject:** GBH 4798P-DOA: 6/11/2018 (SOMPO OD)

Dear Boon Kai,

As instructed by our client , please proceed to repair the **insured vehicle GBH 4798P (Excess \$500-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## View Received Message

This mail is associated with :

**GBH4798P (CMTD1804847)**

OD

Nov 6 2018 12:00AM

[WILLY DESIGN & ENGINEERING PTE. LTD.]

ETHOZ Protect Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** Sompo Insurance Singapore Pte. Ltd. (SOMPO\_SG), sent on 15/11/2018 12:17 PM.

**To** LKK\_HQ

**Subject** Alert - Adj Mandate Approved (S\$6594.00) - GBH4798P - Claim Handler: GNOH PAU LOONG

Approved:6594.00:Please proceed to authorise OD repair and Excess \$ 500 applies, thank you

### DOCUMENTS SUMMARY

There are no documents.

## View Received Message

This mail is associated with :

**GBH4798P (CMTD1804847)**

OD

Nov 6 2018 12:00AM

[WILLY DESIGN & ENGINEERING PTE. LTD.]

ETHOZ Protect Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** Sompo Insurance Singapore Pte. Ltd. (SOMPO\_SG), sent on 09/11/2018 15:38 PM.

**To** LKK\_HQ

**Subject** CMTD1804847 ; Re: Alert: Im. Report (GBH4798P)

Dear M/s LKK,

We are unable to authorise OD as driver has work permit issues, thank you.

<-- Original Message -->

From: LKK\_HQ

To: SOMPO\_SG

Sent On: 09/11/2018 03:16 PM

Subject: Alert: Im. Report (GBH4798P)

Im. Report has been submitted on 2018/11/09

### DOCUMENTS SUMMARY

There are no documents.



## Veron Chen (LKKAUTO)

---

**From:** Ng Boon Kai <BoonKai.Ng@ethozgroup.com>  
**Sent:** Friday, 23 November 2018 9:44 AM  
**To:** Veron Chen (LKKAUTO); SUR  
**Subject:** RE: Finalization report for GBH4798P

Hi Veron,

Receive with thank.

Regards,  
Boon Kai

---

**From:** Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]  
**Sent:** Friday, November 23, 2018 9:41 AM  
**To:** Ng Boon Kai <BoonKai.Ng@ethozgroup.com>; SUR <sur@lkkauto.com>  
**Subject:** RE: Finalization report for GBH4798P

Dear Boon Kai,

Confirmed COR \$6156 before excess \$500 and GST @ 8 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Ng Boon Kai <BoonKai.Ng@ethozgroup.com>  
**Sent:** Friday, 23 November 2018 8:33 AM  
**To:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Cc:** Admin-D (LKKAUTO) <admin-d@lkkauto.com>  
**Subject:** Finalization report for GBH4798P

Hi Veron,

Attached is finalization report & supplier bill for the above mentioned vehicle.

Please endorse and fax or e-mail back once the COR confirm.

COR =\$6156.00  
Repair days =08  
Excess=\$500.00

Please revert

Thanks,

Best regards,

Boon Kai  
Executive  
Motor Claims Operation



ETHOZ GROUP LTD

22 Tampines Street 92 Singapore 528876

DID: 6654 7617 | Fax: 6654 7648

Website: [www.ethozgroup.com](http://www.ethozgroup.com)



---

**From:** Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]  
**Sent:** Thursday, November 15, 2018 1:46 PM  
**To:** Ng Boon Kai <[BoonKai.Ng@ethozgroup.com](mailto:BoonKai.Ng@ethozgroup.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** GBH 4798P-DOA: 6/11/2018 (SOMPO OD)

Dear Boon Kai,

As instructed by our client , please proceed to repair the **insured vehicle GBH 4798P (Excess S500-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :[sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Disclaimer: This message may contain confidential information intended only for the use of the addressee named above. If you are not the intended recipient of this message you are hereby notified that any use, dissemination, distribution or reproduction of this message is prohibited. If you received this message by mistake, please notify the sender by reply email immediately. Please conduct your own virus checks before opening any attachment as ETHOZ Group does not guarantee the integrity of this email or attached files has been maintained nor this communication is free of viruses, interceptions or interference. Any views expressed in this message are those of the individual sender and may not necessarily reflect the views of ETHOZ Group. ETHOZ Group shall not be responsible nor liable for the improper and incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system.

Disclaimer: This message may contain confidential information intended only for the use of the addressee named above. If you are not the intended recipient of this message you are hereby notified that any use, dissemination, distribution or reproduction of this message is prohibited. If you received this message by mistake, please notify the

## Veron Chen (LKKAUTO)

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Friday, 23 November 2018 9:41 AM  
**To:** 'Ng Boon Kai'; SUR  
**Subject:** RE: Finalization report for GBH4798P

Dear Boon Kai,

Confirmed COR \$6156 before excess \$500 and GST @ 8 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Ng Boon Kai <BoonKai.Ng@ethozgroup.com>  
**Sent:** Friday, 23 November 2018 8:33 AM  
**To:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Cc:** Admin-D (LKKAUTO) <admin-d@lkkauto.com>  
**Subject:** Finalization report for GBH4798P

Hi Veron,

Attached is finalization report & supplier bill for the above mentioned vehicle.

Please endorse and fax or e-mail back once the COR confirm.

COR =\$6156.00  
Repair days =08  
Excess=\$500.00

Please revert

Thanks,

Best regards,

Boon Kai  
Executive  
Motor Claims Operation

**ETHOZ**  
ETHOZ GROUP LTD

22 Tampines Street 92 Singapore 528876  
DID: 6654 7617 | Fax: 6654 7648  
Website: [www.ethozgroup.com](http://www.ethozgroup.com)



**From:** Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]  
**Sent:** Thursday, November 15, 2018 1:46 PM  
**To:** Ng Boon Kai <BoonKai.Ng@ethozgroup.com>; SUR <sur@lkkauto.com>  
**Subject:** GBH 4798P-DOA: 6/11/2018 (SOMPO OD)

Dear Boon Kai,

As instructed by our client, please proceed to repair the **insured vehicle GBH 4798P (Excess S500-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Disclaimer: This message may contain confidential information intended only for the use of the addressee named above. If you are not the intended recipient of this message you are hereby notified that any use, dissemination, distribution or reproduction of this message is prohibited. If you received this message by mistake, please notify the sender by reply email immediately. Please conduct your own virus checks before opening any attachment as ETHOZ Group does not guarantee the integrity of this email or attached files has been maintained nor this communication is free of viruses, interceptions or interference. Any views expressed in this message are those of the individual sender and may not necessarily reflect the views of ETHOZ Group. ETHOZ Group shall not be responsible nor liable for the improper and incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	8003K

### Vehicle Details

Vehicle No.:	GBH4798P
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	1KD2795133
Chassis No.:	JTFAT35Y90K210216
Maximum Power Output:	-
Open Market Value:	\$27,084.00
Original Registration Date:	17 May 2018
First Registration Date:	17 May 2018
Transfer Count:	0
Actual ARF Paid:	\$1,355.00

### Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

### Intended COE Rebate Details

COE Expiry Date:	16 May 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$29,416.00
COE Rebate Amount:	\$28,000.00
<b>Total Rebate Amount:</b>	<b>\$28,000.00</b>

The information contained herein is correct as at 09 Nov 2018

OK

&gt; Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

## Vehicle Owner Particulars

Owner ID Type:

Owner ID:

## Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

## Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

## Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

PQP Paid:

COE Rebate Amount:

Total Rebate Amount:

Company

8003K

GBH4798P

Yes

15 Nov 2018

TOYOTA

DYNA 150 5MT

Silver

2018

1KD2795133

JTFAT35Y90K210216

\$27,084.00

17 May 2018

17 May 2018

0

\$1,355.00

No

\$0.00

16 May 2028

C - Goods Vehicle &amp; Bus

10

\$29,416.00

\$23,532.00

\$23,532.00

The information contained herein is correct as at 07 Nov 2018

OK

## Certificate of Insurance

**MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)**  
**MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960**  
**ROAD TRANSPORT ACT, 1987 (MALAYSIA)**  
**MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)**

Cert No./Policy No. : D18MTPCVE001804  
 1. Registration No. : GBH4798P  
 2. Insured Name : WILLY DESIGN & ENGINEERING PTE. LTD.  
 3. Commencement Date : 17 MAY 2018 00:00  
 4. Expiry Date : 16 MAY 2019 23:59  
 5. Coverage : Market value at time of loss - Comprehensive  
 6. Excess : \$500 - Section I  
 7. Persons or Classes of Persons entitled to drive\*

b) Any person who is driving on the Insured's order or with their permission.  
 Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.  
 And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

8. Limitations as to use\*

- 1) Use in connection with the Insured's business.
- 2) Use for the carriage of passengers (other than for hire or reward) in connection with the policyholder's business.
- 3) Use for social, domestic or pleasure purposes.

The Policy does not cover

- 1) Use for hire or reward or racing, pacemaking, reliability trial or speed-testing.
- 2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

9. ExcelDrive Workshops & Accident Reporting

It is a condition precedent to liability that the Policyholder shall, together with the Motor Vehicle, call at the Company's Accident Reporting Center and report the accident within 24 hours of the accident or by the next working day thereof.


It is compulsory to have the accident repairs to the insured vehicle carried out at ExcelDrive Workshops, otherwise claim is not payable.

In an emergency and for directions to the Company's Accident Reporting Centers, please contact our Emergency Hotline : (65) 6461 6555

Visit [www.sompo.com.sg](http://www.sompo.com.sg) for list of ExcelDrive Workshops and Accident Reporting Centers.

I/We HEREBY CERTIFY that the policy to which this certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Sompo Insurance Singapore Pte. Ltd.



Date/Time of Issue : 21 MAY 2018 11:22

\*Limitation rendered inoperative by section 8 of the Motor Vehicles(Third-Party Risks and Compensation)Act (Chapter 189 and section 95 of the Road Transport Act, 1987(Malaysia), are not to be included under these headings.

**IMPORTANT NOTICE**

1. Insureds are hereby warned that under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap.189), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicles without a valid policy of insurance under the Act.
2. Insureds are further warned that on the sale of a motor vehicle or if for any reason the Insurance is terminated during its currency, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap.189)
3. The Policy will cease to be valid once the motor vehicle has been sold to another person. It is not transferable to a new owner of the Vehicle.
4. Please note that this insurance is subject to the premium being paid and received in full by the Company (a) before the inception date where the Policy is to be issued to an Individual; or (b) within the period specified in the Premium Payment Warranty applied to the Policy in all other instances.
5. Insurance coverage under this Policy is subject to the terms and conditions as stipulated in the Motor Insurance Policy

WORK PERMIT  
Employment of Foreign Manpower Act (Chapter 91A)  
Republic of Singapore

Employer  
WILLY DESIGN & ENGINEERING PTE. LTD.

Sector: CONSTRUCTION



Name  
MALAICHAMY PRABHU  
Occupation  
CONSTRUCTION WORKER

Work Permit No.  
D 32529860



Date of Application  
29-08-2014  
Date of Issue  
09-11-2016  
Date of Expiry  
29-12-2018



L7370305



REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: G7286291R

Name: MALAICHAMY PRABHU

Date of Birth: 15 Feb 1979


Issue Date: 19 Nov 2013

Valid Till: 16 Nov 2018



VISIT PASS  
Immigration Regulations

Name  
MALAICHAMY PRABHU



Date of Birth	Sex	Nationality
15-02-1979	M	INDIAN
FIN	Date of Issue	Date of Expiry
G7286291R	09-11-2016	29-12-2018

MULTIPLE JOURNEY VISA ISSUED

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED  
OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 2B Motorcycles <= 200 cc  
Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg

EFFECTIVE DATE

19 Nov 2013  
19 Nov 2013



Licence No: G7286291R

NP 428A



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	07/11/2018 15:00
Date Of Accident	06/11/2018 23:50
Exact Location Of Accident	LOYANG AVE AFTER PASIR RIS DR 1 EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH4798P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	WILLY DESIGN & ENGINEERING PTE. LTD.
Co Reg No	200808003K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67878928

### Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150 5MT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

### Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPVE001804
Cover Note Number	17/05/2018-16/05/2019

### Driver

Name of Driver	MALAICHAMY PRABHU
Passport No/FIN	G7286291R
Date Of Birth	15/02/1979
Occupation	OUTDOOR
Date Of Driving Pass	19/11/2013
Driving Experience	4 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98227784
Fax Number	
Contact Number	

Address

9003 TAMPINES STREET 93 #--#01-132 SINGAPORE 528837

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
Weather Conditions CLEAR  
Road Surface DRY

### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

### Circumstances of Accident

REFER TO SKETCH PLAN

### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SH8832X

Vehicle Make/Model/Colour TOYOTA

### Details Of Properties

Vehicle Category TAXI

Name of Driver LIM LEE KIM

NRIC/Passport Number S7300152H

Contact Number 98340761

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



A: GBH47981

B: SH8832X

# DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My vehicle left lane, the taxi suddenly swayed in to my lane in front and stop to alight his passenger. I brake hard and sway to my right to avoid collision with the taxi, but unfortunately my left corner hit the taxi bonnet (Pearl). The taxi did not make any squalling at that time when he sway into my left lane.

You had been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a **Fourteen (14) days clause** whereby the claim must be made within the stipulated timeframe from the day of occurrence.

Reporting Only

☒ Claim OD

Claim TP

Claim OD / TP at other workshop

## DECLARATION

I/We declare that the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



INSURER: **Sompo Insurance Singapore Pte. Ltd. (HQ)**

### PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	D18MTPCVE001804	Date of Loss:	06/11/2018
Vehicle Reg. No.:	<b>GBH4798P</b>	Driveable?	
Driver Age/Info:	39 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	WILLY DESIGN & ENGINEERING PTE. LTD.		
Driver:	MALAICHAMY PRABHU		
Make/Model:	TOYOTA DYNA, 3.0 D (M)	Vehicle Reg. Date:	17/05/2018
Vehicle Colour:	SILVER	Chassis No:	JTFAT35Y90K210216
Engine No:	1KD2795133		
Odometer:	1 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Description of Accident/Loss	REFER TO SKETCH PLAN		
Remarks:	VEHICLE WITH OWNER		
Present Location:	ETHOZ PROTECT PTE LTD (TAMPINES)		

### COST OF CLAIMS

	Amount
Parts	6,745.00
Miscellaneous Items	110.00
Labour	2,480.00
Paintwork Labour	0.00
Towing	0.00
	<b>9465</b>
<b>Gross Total (S\$)</b>	<b>9,335.00</b>
<b>+ GST 7.00% (S\$)</b>	<b>653.45</b>
<b>Nett Amount (S\$)</b>	<b>9,988.45</b>

This claim is handled by: **SUHELMI BIN SUHARMAN/**

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

## REPAIR DETAILS

## Reference

Part Source: (Last Synchronised: 08 Nov 2018)  
 Parts: N/A TOYOTA DYNA 3.0 D (M) (Model not available in database)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: ETHOZ Protect Pte Ltd/GBH4798P/08/11/2018 15:03  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*WIPER PANEL <i>BT</i>	0.00	0.00	*220.00 F	✓
2	1		*WIPER NOZZLE RH <i>X 3 an</i>	0.00	0.00	*58.00 F	
3	1		*WIPER NOZZLE LH <i>X 3 an</i>	0.00	0.00	*58.00 F	
4	1		*WIPER LINK <i>? X suc X</i>	0.00	0.00	*150.00 F	
5	1		*WIPER TANK <i>? X suc X</i>	0.00	0.00	*165.00 F	
6	1		*FRONT PANEL OUTER <i>BT</i>	0.00	0.00	*630.00 F	✓
7	1		*FRONT PANEL INNER REPAIR	0.00	0.00	-	
8	1		*FRONT PANEL EMBLEM(DYNA) <i>nee</i>	0.00	0.00	*58.00 F	✓
9	1		*CORNEL PANEL LH <i>DE</i>	0.00	0.00	*220.00 F	✓
10	1		*CORNEL PANEL INNER BRACKET LH <i>? X suc</i>	0.00	0.00	*68.00 F	
11	1		*FRONT GRILLE <i>suc</i>	0.00	0.00	*310.00 F	✓
12	1		*FRONT GRILLE LOGO <i>nee</i>	0.00	0.00	*58.00 F	✓
13	1		*FRONT GRILLE BRACKET <i>? X suc X</i>	0.00	0.00	*85.00 F	
14	10		*FRONT GRILLE CLIPS <i>nee</i>	0.00	0.00	*45.00 F	✓
15	1		*FRONT HEADLAMP LH(LED) <i>suc</i>	0.00	0.00	*850.00 F	✓
16	1		*FRONT BUMPER <i>DE</i>	0.00	0.00	*520.00 F	✓
17	1		*FRONT BUMPER BRACKER RH <i>X suc</i>	0.00	0.00	*185.00 F	
18	1		*FRONT BUMPER BRACKER LH <i>BT</i>	0.00	0.00	*185.00 F	✓
19	1		*FRONT WINDSCREEN MOULDING <i>nee</i>	0.00	0.00	*190.00 F	✓
20	1		*FOG LAMP COVER LH <i>suc</i>	0.00	0.00	*75.00 F	✓
21	1		*FRONT DOOR LH <i>Repair</i>	0.00	0.00	*880.00 F	
22	1		*FRONT DOOR LOWER STEP GARNISH LH <i>suc</i>	0.00	0.00	*225.00 F	✓
23	1		*FRONT DOOR HINGE LH(UPPER) <i>X 3 an</i>	0.00	0.00	*85.00 F	
24	1		*FRONT DOOR HINGE LH(LOWER) <i>X 3 an</i>	0.00	0.00	*85.00 F	
25	1		*FRONT DOOR CHECKER LH	0.00	0.00	*110.00 F	
26	1		*FRONT DOOR GLASS OUTER MOULDING LH <i>X an</i>	0.00	0.00	*120.00 F	
27	1		*A/C FAN ASSY COMPLETE SET <i>BT</i>	0.00	0.00	*680.00 F	✓
28	1		*FRONT WIPER MOTOR <i>X an</i>	0.00	0.00	*430.00 F	

F=Franchise part.

Total Parts (S\$)

6,745.00

ETHOZ Protect Pte Ltd/GBH4798P/08/11/2018 15:03. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS



## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT NUMBER PLATE	30.00
2	1	FRONT WINDSCREEN SEALANT	80.00
Sub Total (S\$)			110.00

110 X 30.00  
 110 X 80.00

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	LABOUR TO FACILITATE REPAIR	New	750 1,200.00
2	LABOUR TO SPRAY PAINT AFFECTED AREAS	New	700 800.00
3	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	30.00
4	TO REMOVE & REFIT FRONT WINDSCREEN	New	120 150.00
5	TO REMOVE & REFIT FRONT DASHBOARD	New	100 180.00
6	TO REMOVE & REFIT A/C CONDENSOR INCLUDING A/C GAS	New	100 120.00
Gross Labour Cost (S\$)			2,480.00

110 X 750  
 110 X 700  
 110 X 30  
 110 X 120  
 110 X 100  
 110 X 100

ETHOZ Protect Pte Ltd/GBH4798P/08/11/2018 15:03. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

ETHOZ PROTECT PTE LTD

Company Registration No. 199005791M

30 Bukit Batok Crescent, SINGAPORE 658075. Website : <http://www.orix.com.sg>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

14/11/18  
 4p 90010068  
 8 days  
 P/P  
 09/11/18 @ 1420  
 EXCESS: TBA  
 Repair  
 Resurvey by part



Date : 22/11/2018

To : SOMPO INSURANCE SINGAPORE PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : WILLY DESIGN & ENGINEERING PTE. LTD.

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTPVE001804 Accident Date : 06/11/2018

Vehicle No : GBH-4798-P Make & Model : TOYOTA DYNA 150 3.0 DIESEL G (M)

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 500.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
<b>List Item</b>			
1	A/C PIPE(LIQUID)	130.00	130.00
1	WIPER PANEL	220.00	220.00
1	WIPER NOZZLE RH	58.00	0.00
1	WIPER NOZZLE LH	58.00	0.00
1	WIPER LINK	150.00	0.00
1	WIPER TANK	165.00	0.00
1	WIPER MOTOR	430.00	0.00
1	FRONT PANEL	630.00	630.00
1	FRONT PANEL EMBLEM(DYNA)	58.00	58.00
1	CORNEL PANEL LH	220.00	220.00
1	CORNEL PANEL INNER BRACKET LH	68.00	0.00
1	FRONT GRILLE	310.00	310.00
1	FRONT GRILLE LOGO	58.00	58.00
1	FRONT GRILLE BRACKET	85.00	0.00

P = \$436.00

STAR = \$60.00

L = \$1700.00

COR = \$6156/-

Repair days: 08

Excess: \$500/-

PAGE: 1





Date : 22/11/2018

To : SOMPO INSURANCE SINGAPORE PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : WILLY DESIGN & ENGINEERING PTE. LTD.

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTPVE001804 Accident Date : 06/11/2018

Vehicle No : GBH-4798-P Make & Model : TOYOTA DYNA 150 3.0 DIESEL G (M)

FINAL ESTIMATED REPAIR COST DETAIL Excess : 0.00 Add Excess : 500.00

QTY	DESCRIPTION	REPAIRER AMT (\$)		SURVEYOR AMT (\$)	
		45.00		45.00	
10	FRONT GRILLE CLIPS	850.00		850.00	
1	FRONT HEADLAMP LH(LED)	520.00		520.00	
1	FRONT BUMPER	185.00		0.00	
1	FRONT BUMPER BRACKET RH	185.00		185.00	
1	FRONT BUMPER BRACKET LH	190.00		190.00	
1	FRONT WINDSCREEN MOULDING	75.00		75.00	
1	FOG LAMP COVER LH	880.00		0.00	
1	FRONT DOOR L/H	225.00		225.00	
1	FRONT DOOR LOWER STEP GARNISH LH	85.00		0.00	
1	FRONT DOOR HINGE LH(UPPER)	85.00		0.00	
1	FRONT DOOR HINGE LH(LOWER)	110.00		0.00	
1	FRONT DOOR CHECKER LH	120.00		0.00	
1	FRONT DOOR GLASS OUTER MOULDING LH	680.00		680.00	
1	A/C FAN ASSY COMPLETE SET				

PAGE : 2

# ETHOZ

Date : 22/11/2018

To : SOMPO INSURANCE SINGAPORE PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : WILLY DESIGN & ENGINEERING PTE. LTD.

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTPVE001804 Accident Date : 06/11/2018

Vehicle No : GBH-4798-P Make & Model : TOYOTA DYNA 150 3.0 DIESEL G (M)

FINAL ESTIMATED REPAIR COST DETAIL Excess : 0.00 Add Excess : 500.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	Sub Total	6875.00	4396.00
	Discount % On Parts	(0.00)	(13.00)
		(13.00)	(13.00)
	<u>Special Nett Item</u>		
1	FRONT WINDSCREEN SEALANT	80.00	60.00
1	FRONT NUMBER PLATE	30.00	0.00
	Sub Total	110.00	60.00
	<u>Labour &amp; Misc</u>		
	LABOUR TO FACILITATE REPAIR	1200.00	750.00
	LABOUR TO SPRAY PAINT AFFECTED AREAS	800.00	700.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30.00	30.00
	TO REMOVE & REFIT FRONT	150.00	120.00

PAGE : 3



Date : 22/11/2018

To : SOMPO INSURANCE SINGAPORE PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : WILLY DESIGN & ENGINEERING PTE. LTD.

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTPVE001804 Accident Date : 06/11/2018

Vehicle No : GBH-4798-P Make & Model : TOYOTA DYNA 150 3.0 DIESEL G (M)

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 500.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	WINDSCREEN	180.00	0.00
	TO REMOVE & REFIT FRONT DASHBOARD	120.00	100.00
	TO REMOVE & REFIT A/C COMPONENT AND TOP UP GAS	2480.00	1700.00
	Sub Total		
		9,452.00	6,143.00
	Sub Total		
	GST 7.0 %	661.64	430.01
	Total	10,113.	6,573.01

Surveyor Name : RASUL - LKK

Date & Time : 09/11/2018 2:20:00 PM

Ng Boon Kai

CLAIM DEPARTMENT

DID : 6654 7617

FAX :

PAGE : 4

# EURO AUTOPART TRADE

YOUR ONE STOP AUTOPARTS SOLUTION

## TAX INVOICE

To COMPANY: ETHOZ PROTECT PTE LTD

INV NO: PF201811-10561

ATTENTION TO SALES PERSON:

KAI

DATE: 15-Nov-18

P/O

164694

30 DAYS

VEHICLE NO: GBH4798P TY DYNA KDY231

SEND TO: 30 BUKIT BATOK CRES

S/NO.	PART NO.	PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
1		WIPER PANEL	1	\$ 220.00	\$ 220.00
2		FRT PANAL	1	\$ 630.00	\$ 630.00
3		FRT PANEL EMBLE DYNA	1	\$ 58.00	\$ 58.00
4		CORNEL PANEL LH	1	\$ 220.00	\$ 220.00
5		FRT GRILLE	1	\$ 310.00	\$ 310.00
6		FRT GRILLE LOGO	1	\$ 58.00	\$ 58.00
7		FRT GRILLE CLIPS	10	\$ 4.50	\$ 45.00
8		HEADLAMP LH	1	\$ 850.00	\$ 850.00
9		FRT BUMPER	1	\$ 520.00	\$ 520.00
10		FRT BUMPER BRACKET LH	1	\$ 185.00	\$ 185.00
11		FRT WINDSCREEN MOULDING	1	\$ 190.00	\$ 190.00
12		FOGLAMP COVER LH	1	\$ 75.00	\$ 75.00
13		FRT DOOR LOWER STEP GARNISH LH	1	\$ 225.00	\$ 225.00
14		AIRCON FAN W CONDENSER ASSY	1	\$ 680.00	\$ 680.00
15					\$ -
16					\$ -
17					\$ -
18					\$ -
19					\$ -
20					\$ -
21					\$ -
22					\$ -
23					\$ -
24		DELIVERY ST92 TAMPINES			\$ -
25					\$ -
SUB-TOTAL					\$ 4,266.00
GST @ 7%					\$ 298.62
GRAND TOTAL					\$ 4,564.62

NOTE: GOODS SOLD ARE NON RETURNABLE

RECEIVED BY:

AUTHORISED BY:

NO. 50 PLAYFAIR ROAD #03-02F

NOEL BUILDING S(367995)

BRN:53225532A / GST REG NO: M90370620L

TEL: 6635 8238 FAX: 6280 5805 HP: 9451 5113 / 9457 4513

# EURO AUTOPART TRADE

YOUR ONE STOP AUTOPARTS SOLUTION

## TAX INVOICE

To COMPANY: ETHOZ PROTECT PTE LTD

INV NO: PF201811-10575

ATTENTION TO SALES PERSON: KAI

DATE: 19-Nov-18

P/O 164694

30 DAYS

VEHICLE NO: GBH4798P TY DYNA KDY231

SEND TO: 30 BUKIT BATOK CRES

S/NO.	PART NO.	PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
1		AIRCON LIQUAR PIPE	1	\$ 130.00	\$ 130.00
2					\$ -
3					\$ -
4					\$ -
5					\$ -
6					\$ -
7					\$ -
8					\$ -
9					\$ -
10					\$ -
11					\$ -
12					\$ -
13					\$ -
14					\$ -
15					\$ -
16					\$ -
17					\$ -
18					\$ -
19					\$ -
20					\$ -
21					\$ -
22					\$ -
23					\$ -
24		DELIVERY ST92 TAMPINES			\$ -
25					\$ -
SUB-TOTAL					\$ 130.00
GST @ 7%					\$ 9.10
GRAND TOTAL					\$ 139.10

NOTE: GOODS SOLD ARE NON RETURNABLE

RECEIVED BY:

AUTHORISED BY:



NO. 50 PLAYFAIR ROAD #03-02F  
NOEL BUILDING S(367995)

BRN:53225532A / GST REG NO: M90370620L

TEL: 6635 8238 FAX: 6280 5805 HP: 9451 5113 / 9457 4513

# LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Sompo Insurance Singapore Pte. Ltd.  
50 Raffles Place, #05-01/06, Singapore Land Tower  
Singapore 048623

Our File No: CS/SMO18020315/R1VBN2

Date: 29/11/2018

### REFERENCE

Insured/Claimant: WILLY DESIGN & ENGINEERING PTE. LTD.

Policy No: D18MTPCVE001804

Date of Loss: 06/11/2018

Nature of Claim: OD

Claim No: CMTD1804847

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBH4798P

Make & Model: TOYOTA DYNA, 3.0 D (M)

Reg. Date: 17/05/2018 (Man. Year: 2018)

Colour: Grey

Engine Capacity: 2982 cc

Market Value/New Car Price: S\$67,000.00

Price:

Sum Insured (S\$): Market Value/New Car Price

Engine No: 1KD2795133

Chassis No: JTFAT35Y90K210216

Odometer: 29752 km

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/75 R15

Rear Tyre Size: 155 R12C (D)

Front Left Side: Bridgestone 7 mm

Rear Left Side: Bridgestone 6/6 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side: Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,875.00	4,396.00	2,479.00	36.06
Miscellaneous Items	110.00	60.00	50.00	45.45
Labour	2,480.00	1,700.00	780.00	31.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,465.00</b>	<b>6,156.00</b>	<b>3,309.00</b>	<b>34.96</b>
<b>- Excess (S\$)</b>	<b>0.00</b>	<b>500.00</b>	<b>-500.00</b>	
<b>(S\$)</b>	<b>9,465.00</b>	<b>5,656.00</b>	<b>3,809.00</b>	<b>40.24</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>662.55</b>	<b>395.92</b>	<b>266.63</b>	<b>40.24</b>
<b>Nett Amount (S\$)</b>	<b>10,127.55</b>	<b>6,051.92</b>	<b>4,075.63</b>	<b>40.24</b>

### INSPECTION

Date of Assignment: 08/11/2018

Date Inspected: 09/11/2018 Inspected At:

22 TAMPINES STREET 92  
REPAIRER: ETHOZ GROUP LTD  
30 BUKIT BATOK CRESCENT  
SINGAPORE 658075

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.





## REPAIR DETAILS

## Reference

Part Source:	(Last Synchronised: 29 Nov 2018)
Parts:	N/A TOYOTA DYNA 3.0 D (M) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH4798P)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WIPER PANEL	Bent	220.00 F	*220.00 F
2	1		*WIPER NOZZLE RH	Not Necessary	58.00 F	*- F
3	1		*WIPER NOZZLE LH	Not Necessary	58.00 F	*- F
4	1		*WIPER LINK	Serviceable	150.00 F	*- F
5	1		*WIPER TANK	Serviceable	165.00 F	*- F
6	1		*FRONT PANEL OUTER	Bent	630.00 F	*630.00 F
7	1		*FRONT PANEL INNER (NPA)	Repair	-	-
8	1		*FRONT PANEL EMBLEM(DYNA)	Necessary	58.00 F	*58.00 F
9	1		*CORNEL PANEL LH	Deformed	220.00 F	*220.00 F
10	1		*CORNEL PANEL INNER BRACKET LH	Serviceable	68.00 F	*- F
11	1		*FRONT GRILLE	Scratched	310.00 F	*310.00 F
12	1		*FRONT GRILLE LOGO	Necessary	58.00 F	*58.00 F
13	1		*FRONT GRILLE BRACKET	Serviceable	85.00 F	*- F
14	10		*FRONT GRILLE CLIPS	Necessary	45.00 F	*45.00 F
15	1		*FRONT HEADLAMP LH(LED)	Scratched	850.00 F	*850.00 F
16	1		*FRONT BUMPER	Deformed	520.00 F	*520.00 F
17	1		*FRONT BUMPER BRACKER RH	Serviceable	185.00 F	*- F
18	1		*FRONT BUMPER BRACKER LH	Bent	185.00 F	*185.00 F
19	1		*FRONT WINDSCREEN MOULDING	Necessary	190.00 F	*190.00 F
20	1		*FOG LAMP COVER LH	Scratched	75.00 F	*75.00 F
21	1		*FRONT DOOR LH	Repair	880.00 F	*- F
22	1		*FRONT DOOR LOWER STEP GARNISH LH	Scratched	225.00 F	*225.00 F
23	1		*FRONT DOOR HINGE LH(UPPER)	Not Necessary	85.00 F	*- F
24	1		*FRONT DOOR HINGE LH(LOWER)	Not Necessary	85.00 F	*- F
25	1		*FRONT DOOR CHECKER LH	Not Necessary	110.00 F	*- F
26	1		*FRONT DOOR GLASS OUTER MOULDING LH	Not Necessary	120.00 F	*- F
27	1		*A/C FAN ASSY COMPLATE SET	Bent	680.00 F	*680.00 F
28	1		*FRONT WIPER MOTOR	Not Necessary	430.00 F	*- F
<b>Supplementary #1</b>						
29	1		*A/C PIPE(LIQUID)	Bent	130.00 F	*130.00 F
F=Franchise part.						
<b>Total Parts (\$\$)</b>					<b>6,875.00</b>	<b>4,396.00</b>

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	FRONT NUMBER PLATE (NOT NECESSARY)	30.00	0.00
2	1	FRONT WINDSCREEN SEALANT (NECESSARY)	80.00	60.00
Sub Total (\$\$)			110.00	60.00

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO FACILIATE REPAIR	New	1,200.00	750.00
2	LABOUR TO SPRAY PAINT AFFECTED AREAS	New	800.00	700.00
3	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	30.00	30.00
4	TO REMOVE & REFIT FRONT WINDSCREEN	New	150.00	120.00
5	TO REMOVE & REFIT FRONT DASHBOARD	New	180.00	-
6	TO REMOVE & REFIT A/C CONDENSOR INCLUDING A/C GAS	New	120.00	100.00
Gross Labour Cost (\$\$)			2,480.00	1,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >