

Surveyor: ASSIGNMENT (Office)From (Person): (WS) Lawrence Jau of FCL Date/Time: 09/12/18 12.48pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJF 4466M Insured: SHC 7294Lat Workshop m/s MOWA Tel: 6272 3892of Bik 1008 Bukit Merdu Lot 3 #01-04Policy No: _____ Claim No: D18007964 MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 04.11.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS' 12/12/18 @ after 12pm H.O.D. Endorsement: _____Date/Time: 09.11.2018 1:12pm Person Contacted: Nabilah Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJF 4466M - x
	QIC TOTAL - CS/FCU1703559 / R1qbn2 DA: 11/11/17
16/11/18 @ 4.21a	revised to FCL by email.
24/12/18 @ 5.46pm	Paru finalised final fig @ 2860 then email. Cled to 1033.50, 27%.
	no lump sum.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007964MFSH

Date: 16 November 2018

Our Ref: CS/FCI18020316/R1qb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJF 4466M.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 12/11/2018 at the premises of M/s MOVA, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,763.00</u> .
Revised Estimate Amount	: S\$ <u>2,479.50</u> .
"Check" Items Amount	: S\$ <u>150.00</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the o/s front portion.



Yours faithfully

Rasul
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	07-11-2018	Our Ref No. D18007964MFSH
Accident Date	04-11-2018	Claim Type. Third Party
Insured Vehicle	SHC7294L	Third Party Vehicle. SJF4466M
Survey Location	BLOCK 1008 BUKIT MERAH LANE 3 #01-04/06/08	
Contact Person.	NITHA	
Contact No.	62723892/ 0	Fax No. 62708314
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MOVA AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Rasul (LKKAuto)

From: Rasul (LKKAuto)
Sent: Monday, 24 December, 2018 5:46 PM
To: 'Jacelyn'
Subject: RE: FINALIZATION: SJF4466M - TP/FCI - TOYOTA LEXUS NX200 (DOA 04.11.2018)

Hi Jacelyn,

Finalised amount confirmed


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



ALSO
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Jacelyn [<mailto:jacelyn@moval.com.sg>]
Sent: Monday, 3 December, 2018 4:00 PM
To: Rasul (LKKAuto)
Subject: FINALIZATION: SJF4466M - TP/FCI - TOYOTA LEXUS NX200 (DOA 04.11.2018)

Dear Rasul,

Please find the attached 'Marking Estimate', & 'After-Paint' photographs for your reference.

We propose the finalize amount at Part-By-Part \$ 2,860.00. Kindly revert.

Best Regards,

Jacelyn Ooi

Estimator

Mova Automotive Pte Ltd

Tel: 6272 3892 Fax: 6270 8314



MOVA

Automotive Pte Ltd



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 16 November 2018 11:21 AM
To: 'CWS Motor Claims'; assignments
Cc: SUR
Subject: RE: SURVEY ASSESSMENT - D18007964MFSH/1
Attachments: CSFCI18020316R1qb.pdf

Dear Sir/Madam,

Enclosed herewith preliminary advice of SJF 4466M.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 9 November 2018 1:14 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Lurene Jaw' <LureneJaw@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007964MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 9 November, 2018 12:48 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Lurene Jaw <LureneJaw@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18007964MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Main Office:

 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:

 Block 100B,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

 Tel: (65) 6272 3892
 Fax: (65) 6270 8314

 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

Estimate

08/11/2018

MS FIRST CAPITAL INSURANCE LIMITED
36 Robinson Road
#16-01 City House
Singapore 068877.

 Attention :- **XA026**

Page # :- 1

Veh # :- SJF4466M

Veh Model :- TOYOTA LEXUS

Estimate# :- CK418239

Claim # :- TP/CK 133154

ACC. Date :- 04/11/18

Terms :- C.O.D Days

Remarks :- MFG 10 JUL 2015 (2015)

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :

1.	FRONT FENDER RH <i>repair</i>	1	PC	730.00	730.00
2.	FRONT FENDER ARCH GARNISH RH <i>sch /</i>	1	PC	261.00	261.00
3.	FRONT FENDER ARCH GARNISH CLIPS <i>new /</i>	10	PC	5.00	50.00
4.	FRONT FENDER COWLING CLIPS <i>new /</i>	10	PC	5.00	50.00
5.	FRONT FENDER LOWER GARNISH RH <i>X</i>	1	PC	90.00	90.00 <i>X PVC</i>
6.	FRONT FENDER LOWER GARNISH CLIPS <i>X</i>	4	PC	5.00	20.00 <i>X PVC</i>
7.	FRONT DOOR RH <i>new</i>	1	PC	980.00	980.00
8.	FRONT DOOR LOWER GARNISH RH <i>DE /</i>	1	PC	267.00	267.00
9.	FRONT DOOR LOWER GARNISH CLIPS <i>new /</i>	10	PC	5.00	50.00
10.	FRONT DOOR HINGE UPPER RH <i>X</i>	1	PC	98.00	98.00 <i>X PVC</i>
11.	FRONT DOOR HINGE LOWER RH <i>PA /</i>	1	PC	98.00	98.00
12.	FRONT DOOR REGULATOR RH <i>?</i>	1	PC	200.00	200.00 <i>X PVC</i>
13.	FRONT DOOR RIVET <i>new</i>	14	PC	5.00	70.00
14.	FRONT A-PILLAR - REPAIR	1	PC		
15.	ROCKER PANEL RH - REPAIR	1	PC		

LIST TOTAL S\$

2,964.00

25% DISCOUNT S\$

-741.00

2,223.00

LABOUR :

TO DIAGNOSE LOCKING SYSTEM & SETTING

 60 ~~80.00~~

 TO KNOCK & STRAIGHTEN ON FRONT A-PILLAR &
 ROCKER PANEL RH. TO REPLACE DAMAGED ITEMS.
 REALIGN CONNECTION

 550 450 ~~600.00~~

TO TRANSFER ITEMS INTO NEW DOOR RH

 60 ~~80.00~~

TO RUST PROOF ON REPAIR AREAS

 40 ~~80.00~~

TOSPRAY PAINT ON REPAIRED AREAS

 650 500 ~~700.00~~

LABOUR TOTAL S\$

1,540.00

Estimate

08/11/2018

MS FIRST CAPITAL INSURANCE LIMITED
 36 Robinson Road
 #16-01 City House
 Singapore 068877.

Attention :- **XA026**

Page # :- 1 133154

Veh # :- SJF4466M

Veh Model :- TOYOTA LEXUS

Estimate# :- CK418239

Claim # :-

ACC. Date :- 04/11/18

Terms :- C.O.D Days

Remarks :-

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: **(65) 6476 3333**
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722
 Tel: **(65) 6272 3892**
 Fax: (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S	
AMOUNT S\$	3,763.00
GST @ 7 %	263.41
AMOUNT DUE S\$	4,026.41

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Resue
Hp 90010068
5 days
#3 P/P
12/11/18 @ 1230
60 part
Resury after report

3993.50

SHIM C (dam)

Estimate

08/11/2018

MS FIRST CAPITAL INSURANCE LIMITED
36 Robinson Road
#16-01 City House
Singapore 068877.

Attention :- XA026

Page # :- 1

Veh # :- SJF4466M

Veh Model :- TOYOTA LEXUS

Estimate# :- CK418239

Claim # :- TP/CK 133154

ACC. Date :- 04/11/18

Terms :- C.O.D Days

Remarks :- MFG 10 JUL 2015 (2015)

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088884-2

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	FRONT FENDER RH <i>repair</i>	1 PC	730.00	730.00
2.	FRONT FENDER ARCH GARNISH RH <i>SC1</i>	1 PC	261.00	261.00
3.	FRONT FENDER ARCH GARNISH CLIPS <i>new</i>	10 PC	5.00	50.00
4.	FRONT FENDER COWLING CLIPS <i>new</i>	10 PC	5.00	50.00
5.	FRONT FENDER LOWER GARNISH RH <i>X</i>	1 PC	90.00	90.00 <i>scux</i>
6.	FRONT FENDER LOWER GARNISH CLIPS <i>X</i>	4 PC	5.00	20.00 <i>xan</i>
7.	FRONT DOOR RH <i>new</i>	1 PC	980.00	980.00
8.	FRONT DOOR LOWER GARNISH RH <i>DE</i>	1 PC	267.00	267.00
9.	FRONT DOOR LOWER GARNISH CLIPS <i>new</i>	10 PC	5.00	50.00
10.	FRONT DOOR HINGE UPPER RH <i>X</i>	1 PC	98.00	98.00 <i>xscv</i>
11.	FRONT DOOR HINGE LOWER RH <i>PA</i>	1 PC	98.00	98.00
12.	FRONT DOOR REGULATOR RH <i>?</i>	1 PC	200.00	200.00 <i>xscv</i>
13.	FRONT DOOR RIVET <i>new</i>	14 PC	5.00	70.00
14.	FRONT A-PILLAR - REPAIR	1 PC		
15.	ROCKER PANEL RH - REPAIR	1 PC		
LIST TOTAL S\$			1826.00	2,964.00
25% DISCOUNT S\$			- 25%	-741.00
<i>Supp = Front Door Black Tape 58 x 3pcs.</i>			1369.50	2,223.00
LABOUR :				
TO DIAGNOSE LOCKING SYSTEM & SETTING				
TO KNOCK & STRAIGHTEN ON FRONT A-PILLAR & ROCKER PANEL RH. TO REPLACE DAMAGED ITEMS. REALIGN CONNECTION				
TO TRANSFER ITEMS INTO NEW DOOR RH				
TO RUST PROOF ON REPAIR AREAS				
TOSPRAY PAINT ON REPAIRED AREAS				
LABOUR TOTAL S\$			650?	1,540.00

550? 480 600.00
60 80.00
40 80.00
650? 500 700.00
1360.00 1,540.00

Estimate

08/11/2018

MS FIRST CAPITAL INSURANCE LIMITED
36 Robinson Road
#16-01 City House
Singapore 068877.

Attention :- XA026

Page # :- 1 133154

Veh # :- SJF4466M

Veh Model :- TOYOTA LEXUS

Estimate# :- CK418239

Claim # :-

ACC. Date :- 04/11/18

Terms :- C.O.D Days

Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel : (65) 6272 3892
Fax : (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 3,763.00

GST @ 7 % 263.41

AMOUNT DUE S\$ 4,026.41

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resue
Hp 90010068
5 days
P/P
12/11/18 @ 1230
64 part
Resurvey also repair

Part = \$ 1369.50

Lab = \$ 1360.00

\$ 2729.50

Supp : \$ 130.50

\$ 2860.00



Automotive Pte Ltd

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/05/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

SUPPLEMENTARY

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Page : 1
Veh No : SJF4466M
Model : TOYOTA LEXUS
Acc Date : 04-Nov-18
Incharge : JACELYN

No	Description	Qty	U.Price	Amt \$
1	<u>LIST ITEMS :</u> FRONT DOOR BLACK TAPE	3	\$ 58.00	\$174.00 <i>re</i>
LIST TOTAL S\$				\$174.00
25% DISCOUNT S\$				\$43.50
				\$130.50

NON-TAX AMOUNTS	\$130.50
GST @ 7%	\$9.14
AMOUNT DUE	\$139.64

Customer's Signature/Co.Stamp

MOVA AUTOMOTIVE PTE LTD



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18020316/R1qbn2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 28-12-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7294L	Veh. Inspected	SJF 4466M
Policy No.		Coverage (\$)	0.00
Claim No.	D18007964MFSH	Excess (\$)	0.00
Assign From	LURENE	Assign Date	09/11/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA LEXUS NX200T	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JTJBARBZ902026880	Colour	GREY
Odometer	34217	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/60 R18	BRIDGESTONE	6 mm
L/H Front Tyre	225/60 R18	BRIDGESTONE	6 mm
R/H Rear Tyre	225/60 R18	BRIDGESTONE	6 mm
L/H Rear Tyre	225/60 R18	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/11/2018	Inspection Date	12/11/2018
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJF 4466M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	730.00	-
1	FRONT FENDER ARCH GARNISH RH	SCRATCHED	261.00	261.00
10	FRONT FENDER ARCH GARNISH CLIPS @\$5.00	NECESSARY	50.00	50.00
10	FRONT FENDER COWLING CLIPS @\$5.00	NECESSARY	50.00	50.00
1	FRONT FENDER LOWER GARNISH RH	SERVICEABLE	90.00	-
4	FRONT FENDER LOWER GARNISH CLIPS @\$5.00	NOT NECESSARY	20.00	-
1	FRONT DOOR RH	BUCKLED	980.00	980.00
1	FRONT DOOR LOWER GARNISH RH	DEFORMED	267.00	267.00
10	FRONT DOOR LOWER GARNISH CLIPS @\$5.00	NECESSARY	50.00	50.00
1	FRONT DOOR HINGE UPPER RH	SERVICEABLE	98.00	-
1	FRONT DOOR HINGE LOWER RH	BENT	98.00	98.00
1	FRONT DOOR REGULATOR RH	SERVICEABLE	200.00	-
14	FRONT DOOR RIVET @\$5.00	NECESSARY	70.00	70.00
1	FRONT A-PILLAR (NPA)	TO REPAIR SEE LABOUR	-	-
1	ROCKER PANEL RH (NPA)	TO REPAIR SEE LABOUR	-	-
3	FRONT DOOR BLACK TAPE @\$58.00 (ADDITIONAL)	NECESSARY	174.00	174.00
	LESS 25% DISCOUNT		-784.50	-500.00
			2,353.50	1,500.00
LABOUR				
	TO DIAGNOSE LOCKING SYSTEM & SETTING.		80.00	60.00
	TO KNOCK & STRAIGHTEN FRONT A-PILLAR & ROCKER PANEL RH. TO REPLACE DAMAGED ITEMS. REALIGN CONNECTION. INCLUSIVE OF THE REPAIR OF FRONT FENDER RH.		600.00	550.00
	TO TRANSFER ITEMS INTO NEW DOOR RH.		80.00	60.00
	TO RUST PROOF ON REPAIR AREAS.		80.00	40.00
	TO SPRAY PAINT ON REPAIRED AREAS.		700.00	650.00
			1,540.00	1,360.00
GRAND TOTAL			3,893.50	2,860.00

Report Ref No. CS/FCI18020316/R1qbn2



RECOMMENDED COST OF REPAIRS			2,860.00
-----------------------------	--	--	----------

Report Ref No. CS/FCI18020316/R1qbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.