

ASS. REC. BY:

REF: CS/SMD18020322 / Atbnz | Special Instruction:

Survivor

Adrian

ASSIGNMENT (Office)

From (Person): Merimen Shawn Ngo of SMD Date/Time: 09/11/2018 2:02pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLA 6307D Insured: SKC 8661T

at Workshop m/s Hiap Hong Tel: 67459633

of 2 Kaki Bukit Ave 2 #02-13

Policy No: DISMTPV01017118 Claim No: CMTD1804890

Sum Insured: Excess:

Make of Veh: D.O.A. 07/11/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time: 09/11/2018 2:06pm Person Contacted: Ah Kiat Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLA 6307D - x
	SKC 8661T - x
11/11/16:02	Revert via Merimen pending estimate
	lump sum \$7500/- (Red: 6534.90, 46%)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Nov 2018		09 Nov 2018 14:02 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	MUTHU KUMAAR K KARUPPIAH, ID: S1553314E, Tel: +6597700755, Email: kmkumaar@gmail.com								
Main Claimant:	HO AIK SENG, ID: S8104034F								
Vehicle Reg. No.:	SLA6307D	Date of Loss:	07/11/2018 20:00 - :59						
Claim Type:	TP / CMTD1804890	Policy/Cover Note No.:	D18MTPV01017118 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKC8661T	Policy No. (Claimant):							
		Excess:							
Repairer:	Hiap Hong Motor Repair () 2 Kaki Bykit Avenue 2, #02-13, 417921 Kaki Bukit - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by NGO SAU WEI SHAWN - 6329 5202]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/11/2018]								
Driver/Custodian (Insured):	MUTHU KUMAAR K KARUPPIAH (56 / Male), NRIC: S1553314E, Tel: +6597700755								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***SLA6307D (CMTD1804890)**
[SKC8661T]

TP
HO AIK SENG
Nov 7 2018 8:00PM
[MUTHU KUMAAR K KARUPPIAH]
Hiap Hong Motor Repair

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 12/11/2018 16:02 PM.
To Shawn.Ngo@sompo.com.sg
Subject SLA6307D (CMTD1804890) [SKC8661T]

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SLA 6307D on 09/11/2018
We are pending estimate from repairer.

Regards,

Denise
LKK Auto

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/11/2018 09:38
Date Of Accident	07/11/2018 20:25
Exact Location Of Accident	UPPER CHANGI RD NORTH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA6307D
Insured Policyholder	
Name Of Registered Owner	HO AIK SENG
NRIC No	S8104034F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91762948
Alternative Phone No	OFFICE-91762948

Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A28757811 QMY
Cover Note Number	

Driver

Name of Driver	HO AIK SENG
NRIC No	S8104034F
Date Of Birth	10/02/1981
Occupation	INDOOR
Date Of Driving Pass	20/07/2001
Driving Experience	17 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91762948
Fax Number	
Contact Number	OFFICE-91762948
Email Address	NOEMAIL

Address BLK 231 JURONG EAST ST 21 #04-665
Postcode
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions DRIZZLING
Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 3
Passenger 1 NAME: : --
GENDER: : MALE
Passenger 2 NAME: : --
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLS REFER ATTACHED ACCIDENT REPORT FROM THE DRIVER. NO CI AT POINT OF REPORTING, RECEIVED EMAIL AT 11AM.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKC8661T
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC BUKIT BATOK (VAC)
51-11-11

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 07/11/18 at about 2024hrs, I was driving SLA6307D along Upper Changi Road North heading towards Tanah Merah Besar Road to drop off my friends. I was at traffic light junction waiting for green arrow to turn right into Tanah Merah Besar Road. Traffic was in Red and when the green arrow for turning right appear, I proceed to turn right. While I was turning right, I received an oncoming vehicle SKC8661T moving towards my direction. I immediate stopped my car but ~~SKC8661T~~ SKC8661T did not stop and proceed and collided into my car right hand front. There are huge damage to my right hand front vehicle and my vehicle door have problem opening.

There are one female and a boy in my vehicle. There is only a driver in SKC8661T.

The other party is Mr Muthu Kumar K Karupiah, NRIC J1553314E. My NRIC IC 98104025EE, HO AIK BENG DENNIS.

Video footage is available.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

REPORTING CENTRE PERSONNEL'S SIGNATURE

Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4034F
Vehicle Details	
Vehicle No.:	SLA6307D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	09 Nov 2018
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.3L MT
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	L13Z11042462
Chassis No.:	JHMGE67509S242426
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$19,200.00
Original Registration Date:	30 Jun 2010
First Registration Date:	30 Jun 2010
Transfer Count:	3
Actual ARF Paid:	\$19,200.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jun 2020
PARF Rebate Amount:	\$10,560.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jun 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$31,510.00
COE Rebate Amount:	\$5,164.00
Total Rebate Amount:	\$15,724.00

The information contained herein is correct as at 09 Nov 2018

OK



FREE SERVICE & TYRE CREDITS
WHEN YOU PURCHASE A CAR FROM INCHCAPE-PREOWNED

PIT & GO

FREE SERVICE & TYRE CREDITS

VALUE \$1,500

FOR PURCHASER BELOW \$10K

PIT & GO

FREE SERVICE & TYRE CREDITS

VALUE \$3,000

FOR PURCHASER ABOVE \$10K



LEARN MORE



SEARCH

jazz

Price Range

Depreciation

2010

Vehicle Type

Search

View All

Advanced Search

Used Car Comparison

--- Comparing 4 Vehicles ---

Honda Jazz 1.3A L

Honda Jazz 1.3A L

Honda Jazz 1.3A L

Honda Jazz 1.3A L



Clear All

Add all to Shortlist

Add to Shortlist

Add to Shortlist

Add to Shortlist

Add to Shortlist

Back to search result

CAR DETAILS

Price	\$21,800	\$23,800	\$23,800	\$24,800
Instalment	\$1,128	\$967	\$967	\$832
Registration Date	05-Feb-2010	02-Jun-2010	04-Jun-2010	28-Sep-2010
Manufactured	2008	2008	2008	2009
Mileage	88,000 km	97,899 km	200,000 km	88,000 km
Transmission	Auto	Auto	Auto	Auto
Engine Cap	1,339 cc	1,339 cc	1,339 cc	1,339 cc
Road Tax	\$590 /yr	\$590 /yr	\$590 /yr	\$590 /yr
Power	73.0 kW (97 bhp)	73.0 kW (97 bhp)	73.0 kW (97 bhp)	73.0 kW (97 bhp)
Curb Weight	1,060 kg	1,060 kg	1,060 kg	1,110 kg
Features	Responsive And Fuel Efficient 1.3L 16 Valves I-DSI Engine, CVT Auto Transmission, ABS, SRS Airbags, Rear Knockdown Seats Immobilizer Key.	1.3L I-VTEC Engine, 5 Speed Auto Transmission, SRS Airbags, Reverse Sensors, Multi Function Steering Control W/ Paddle Shifter, Knockdown Rear Seats.	Responsive And Fuel Efficient 1.3L 16 Valves I-DSI Engine, CVT Auto Transmission, ABS, SRS Airbags, Rear Knockdown Seats Immobilizer Key	1.3L I-VTEC Engine Transmission, SRS Sensors, Multi Fun With Paddle Shifters Seat.
Accessories	Sports Rims, Black Leather Seats, Factory Fitted MP3/CD Sound System, Auto Retractable Side Mirrors, Solar Films, Reverse Sensors, New Gearbox.	ALPINE Audio System, Electrical Retractable Side Mirror With Indicator, Door Visor, Sun Shade, 2 Tone Upholstery.	Sports Rims, Black Leather Seats, Factory Fitted MP3/CD Sound System, Auto Retractable Side Mirrors, Solar Films, Reverse Sensors, New Gearbox.	Factory Fitted Audi Retractable Side M
Description	The Car That Doesnt Need An Introduction. Perfect Short Term Drive And Also Good For COE Renewal. Low Mileage Done Due To OWhner Being Overseas Most Of The Time. Fully Stock Interior And Exterior Thats Impressive For Its Age. Reliable And Economical Car For Point A To Point B. No Repairs Needed Buy With Peace Of Mind. Come On Down Today To View! Do Contact Us For Appointment. Cheers	Full Agent Maintained,Extended Warranty Available!Extremely Low Fuel Consumption! Low Cost Of Maintenance, Road Tax 2nd Insurance! Reliable L13 Engine With I-VTEC! A Stylish Hatchback That Simply Tops The Fuel Economy Yet Comes With Spacious Interior For Your Comfort. Buy It From Us With A Peace Of Mind. Professional After Sales Service Assured. Appreciate It In Mint Condition At Our Showroom Now!	Enjoy Interest Rate As Low As 1.98%! Well Maintained By Previous Owners. Low Fuel Consumption And Maintenance. Loan And Trade In All Welcome. Call Now To Arrange For A Viewing!	Interest Rate From Loan, Very Well M Free. Tip Top Conc For Viewing.
COE	\$19,989	\$27,389	\$27,389	\$33,089
OMV	\$19,047	\$18,025	\$19,038	\$16,739
ARF	\$19,047	\$18,025	\$19,038	\$16,739
Depreciation	\$9,910 /yr	\$9,470 /yr	\$9,110 /yr	\$8,720 /yr
No. of Owners	2	1	3	1
Type of Vehicle	Hatchback	Hatchback	Hatchback	Hatchback
Category	PARF Car, Premium Ad Car	PARF Car	PARF Car, Premium Ad Car	PARF Car
Availability	Available	Available	Available	Available

TPSamps
Denise.

SLA6307D

Honda Jazz

JHMGE6750SS242426

Front Number Plate crunched	30(SN) ✓
Front Number Plate Holder Deformed	30(SN) ✓
Front Bumper Distorted	523.40 ✓
Front Bumper Clips new	30 ✓
Front Bumper Side Holder x 02 new	$24.1 \times 2 = 48.20$ ✓
Front Bumper Reinforcement Bent	231.20 ✓
Front Bumper Lower Grille Deformed	124.30 ✓
Front Grille Lt	183.60 ✓
Front Grille Logo new	32.80 ✓
Front Grille Clips new	15 ✓
Headlamp x 02 crunched	$412.9 \times 2 = 825.80$ ✓
Headlamp Lower Bracket x 02 ^{RH} crunched	$27.5 \times 2 = 55$ 27.50 ✓
Front Support Panel Brunched	447.90 ✓
Bonnet Distorted	579.40 ✓
Bonnet Lock Damaged	90.60 ✓
Bonnet Hinge x 02 Bent	$40.3 \times 2 = 80.60$ ✓
Wiper Washer Tank Distorted	75.90 ✓
Wiper Washer Tank Motor Damaged	65.60 ✓

3469.3

SLAG307D.

Air Can Condenser	Bent	762.80 ✓
Air Can Fan Cowling	cracked	93.30 ✓
Air Can Fan Blade	cut	68.50 ✓
Air Can Fan Motor	Distorted m	223.60 249.50 X
Air Can Condenser Bracket x 02	Bent	25.1 x 2 = 50.20 ✓
Radiator	Dented	1137.20 ✓
Radiator Fan Cowling		116.30 X
Radiator Fan Blade		68.50 X
Radiator Fan Motor	not new	277.50 342.50 X
Radiator Spare Tank		44.80 X
Front Fender RH	Distorted	398 ✓
Front Fender Inner Panel RH	Distorted	46.5 ✓
Front Fender Inner Shield RH	torn	138.60 ✓
Front Fender Inner Shield Clips RH	new	30 ✓
Front Fender Inner ^{Inner} Garnish RH	dented	45.80 ✓
Engine Mounting RH	not new	215.60 X
Front Driver Seat Belt	Activated	541.60 ✓
Front Passenger Seat Belt		541.60 ✓
Air Bag ECU	Activated	892.90 ✓

62027

SLA 6307D.

Panel Beating
Spray Painting.
Wiring.
To undersoil.

To remove condenser, radiator and to re-gas. ~~1600~~ 1100
~~1500~~ 1000
~~50~~ 30
~~180~~ 60.

To remove engine mountings.

To remove seat belts.

To perform diagnostic test.

Towing Fee.

4440

List: 8547.30

Len 20/: 6837.84

S.N: 60

Labour: 2730.

total: 9627.84.

2/s: 7.5k

09 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

14/12

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18020322/ATBN2

Date: 13/12/2018

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01017118
Claimant Vehicle No :	SLA6307D	Insured Vehicle No :	SKC8661T
Date of Loss:	07/11/2018	Nature of Claim:	TP
		Claim No:	CMTD1804890

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA6307D	Engine No:	L13Z11042462
Make & Model:	HONDA JAZZ, 1.3 (A)	Chassis No:	JHMGE67509S242426
Reg. Date:	30/06/2010 (Man. Year: 2009)	Odometer:	165966 km
Colour:	Blue		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50R16	Rear Tyre Size:	195/50R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,672.00	6,897.84	2,774.16	28.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,440.00	2,730.00	1,710.00	38.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,112.00	9,627.84	4,484.16	31.78
Approved Total (Overridden) (S\$)		7,500.00		
Nett Amount (S\$)	14,112.00	7,500.00	6,612.00	46.85

INSPECTION

Date of Assignment:	09/11/2018	
Date Inspected:	09/11/2018	Inspected At: Hiap Hong Motor Repair 2 Kaki Bykit Avenue 2, #02-13 Singapore 417921
Estimated Period of Repair:	9.0 days	

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 Dec 2018)
Parts: 144	HONDA JAZZ 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLA6307D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	523.40 F	*523.40 FL
2	1		*FRONT BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
3	2		*FRONT BUMPER SIDE HOLDER	Necessary	48.20 F	*48.20 FL
4	1		*FRONT BUMPER REINFORCEMENT	Bent	231.20 F	*231.20 FL
5	1		*FRONT BUMPER LOWER GRILLE	Deformed	124.30 F	*124.30 FL
6	1		*FRONT GRILLE	Cut	183.60 F	*183.60 FL
7	1		*FRONT GRILLE LOGO	Necessary	32.80 F	*32.80 FL
8	1		*FRONT GRILLE CLIPS	Necessary	15.00 F	*15.00 FL
9	2		*HEADLAMP	Cracked	825.80 F	*825.80 FL
10	1		*HEADLAMP LOWER BRACKET	O/s Cracked	55.00 F	*27.50 FL
11	1		*FRONT SUPPORT PANEL	Buckled	447.90 F	*447.90 FL
12	1		*BONNET	Distorted	579.40 F	*579.40 FL
13	1		*BONNET LOCK	Damaged	90.60 F	*90.60 FL
14	2		*BONNET HINGE	Bent	80.60 F	*80.60 FL
15	1		*WIPER WASHER TANK	Distorted	75.90 F	*75.90 FL
16	1		*WIPER WASHER TANK MOTOR	Damaged	65.60 F	*65.60 FL
17	1		*AIR CON CONDENSER	Bent	762.80 F	*762.80 FL
18	1		*AIR CON FAN COWLING	Cracked	93.30 F	*93.30 FL
19	1		*AIR CON FAN BLADE	Cut	68.50 F	*68.50 FL
20	1		*AIR CON FAN MOTOR	Not Necessary	249.50 F	*- FL
21	2		*AIR CON CONDENSER BRACKET	Bent	50.20 F	*50.20 FL
22	1		*RADIATOR	Dented	1,137.20 F	*1,137.20 FL
23	1		*RADIATOR FAN COWLING	Not Necessary	116.30 F	*- FL
24	1		*RADIATOR FAN BLADE	Not Necessary	68.50 F	*- FL
25	1		*RADIATOR FAN MOTOR	Not Necessary	342.50 F	*- FL
26	1		*RADIATOR SPARE TANK	Not Necessary	44.80 F	*- FL
27	1		*FRONT FENDER RH	Distorted	398.00 F	*398.00 FL
28	1		*FRONT FENDER INNER PANEL RH	Distorted	465.00 F	*465.00 FL
29	1		*FRONT FENDER INNER SHIELD RH	Torn	138.60 F	*138.60 FL
30	1		*FRONT FENDER INNER SHIELD CLIPS RH	Necessary	30.00 F	*30.00 FL
31	1		*FRONT FENDER INNER GARNISH RH	Deformed	45.80 F	*45.80 FL
32	1		*ENGINE MOUNTING RH	Not Necessary	215.60 F	*- FL
33	1		*FRONT DRIVER SEAT BELT	Activated	541.60 F	*541.60 FL
34	1		*FRONT PASSENGER SEAT BELT	Activated	541.60 F	*541.60 FL
35	1		*AIR BAG ECU	Activated	892.90 F	*892.90 FL
36	1		*FRONT NUMBER PLATE	Cracked	30.00 FS	*30.00 FS
37	1		*FRONT NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,672.00	8,607.30
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	1,709.46
Total Parts (\$\$)	9,672.00	6,897.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,600.00	1,100.00
2	SPRAY PAINTING	New	1,500.00	1,000.00
3	WIRING	New	50.00	30.00
4	TO UNDERSEAL	New	150.00	60.00
5	TO REMOVE CONDENSER,RADIATOR AND TO RE-GAS	New	180.00	120.00
6	TO REMOVE ENGINE MOUNTINGS	New	250.00	-
7	TO REMOVE SEAT BELTS	New	450.00	280.00
8	TO PERFORM DIAGNOTIC TEST	New	200.00	80.00
9	TOWING FEES	New	60.00	60.00
Gross Labour Cost (S\$)			4,440.00	2,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >