

ASS. REC. BY:

REF: CS/FCL18020227/R19bn2 | Special Instruction:

Surveyor: ASSIGNMENT (Office)

From (Person): W3 Sithara of FCL Date/Time: 09/12/08 12:50pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKS 8083C Insured: SHC 7133T

at Workshop m/s Auto Wheels Tel: 912 3963

of No. 1 Bukit Bukit Crescent #02-40

Policy No: _____ Claim No: D18008007MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 07/12/08

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Ds' #-13-11-20-8 @ 12pm H.O.D. Endorsement: _____

Date/Time: 09.11.2018 1:24pm Person Contacted: Louis Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKS 8083C - X
	SHC 7133T - CS/EQT/17015389 / R19bn2 (copy) D.O.A: 07/12/08
15/11/08	@ 16:04 p.m. revised PA to Sithara via email.
23/11/08	Confirmed HS \$ 3,300/- @ 3 days with Resul. (\$ 12,181.68 Ad - 79%)

Surveyor: P. Ram

REF:

6429H

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKS 8083C

at Workshop m/s Auton Wheels

of HC, Port Curran Rd, GSI #04-142

Insured: FCU

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : **Yes** or No

GIA / PR Seen: _____ Consistent? : **Yes** or No

Est. Repairs: _____ days Res.: **Yes** or No

Lum Sum: _____ % 3 Val.: **Yes** or No

CA / REV / REP. / 24 HRS JS

Vehicle: **IN / OUT**

Date: _____ Person Contacted: _____

Veh No: SKS 8083C Yr Regn: 2011 Jan

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Audi TT Coupe 2-0TFSI c.c. 1984

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 114439 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: TRU 222855B / 009617

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 245/40R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front 6 mm Rear 6 mm

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 07/11/18 D.O.I. 14/11/18

Survey held at AutonWheels

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 28 NOV 2018

Date/Time, File Pass to?

28/11/18

1) _____

Typist

Date/Time, File Return to?

2) _____

: Preli. Report

: Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I: (\$ 3,300/- H/S)

5x15 = 75

170 + 75

50

50

40

385

MOTOR SURVEY ASSIGNMENT

Date 08-11-2018 **Our Ref No.** D18008007MFSH

Accident Date 07-11-2018 **Claim Type.** Third Party

Insured Vehicle SHC7133T **Third Party Vehicle.** SKS8083C

Survey Location NO 1 BUKIT BATOK CRESCENT #02-40 WCEGA PLAZA
Contact Person. LOUIS ONG

Contact No. 91928963/ 91928963 **Fax No.** 0

Survey Type WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person NA **Fax No.** 68416315

Contact Number. NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop AUTO WHEELS **Attention.** NIL
MOTORWORKS

Cc : TP Solicitor NA **TP Solicitor Fax No.** NA

Officer Incharge SITHARA

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Louis Ong <louisongautowheels@yahoo.com>
Sent: Wednesday, 28 November 2018 11:15 AM
To: ShirleyHiew@lkkauto.com
Cc: Rasul (LKKAuto); SUR
Subject: RE: Finalize for vehicle SKS8083C lumpsum \$3,300.00 for 3 repair days before GST.

Noted with thanks

Auto Wheels Motorworks PTE LTD
Louis Ong
91928963

On Wed, 28 Nov 2018 at 11:14, Shirley Hiew (LKK Auto)
<ShirleyHiew@lkkauto.com> wrote:

RE-SEND

Hi Louis,

Confirmed final fig of \$ 3,300.00 (lump sum) @ 3 days of repairs before GST.

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Apologize for making mistake.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Louis Ong [mailto:louisongautowheels@yahoo.com]
Sent: Wednesday, 28 November 2018 10:34 AM
To: ShirleyHiew@lkkauto.com
Cc: Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Finalize for vehicle SKS8083C lumpsum \$3,300.00 for 3 repair days before GST.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 28 November 2018 10:25 AM
To: 'Louis Ong'
Cc: Rasul (LKKAuto); SUR
Subject: RE: Finalize for vehicle SKS8083C lumpsum \$3,300.00 for 3 repair days before GST.

Hi Louis,

Confirmed final fig of \$ 3,300.00 (part by part) @ 3 days of repairs before GST.

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Louis Ong [mailto:louisongautowheels@yahoo.com]
Sent: Friday, 23 November 2018 8:44 PM
To: Rasul (LKKAuto) <rasul@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: Finalize for vehicle SKS8083C lumpsum \$3,300.00 for 3 repair days before GST.

Hi,

The above attachment is the after paint photo and finalize.

Can help to finalize for vehicle SKS8083C lumpsum \$3,300.00 for 3 repair days before GST.

No Supplementary.

Just for your info, the airbag warning light is on when accident. We had change the airbag control unit.

See you can adjust on the labour for reset the warning light only.

Thanks

Auto Wheels Motorworks PTE LTD
Louis Ong
91928963

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 15 November 2018 4:04 PM
To: 'Sithara'; 'CWS Motor Claims'
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: SURVEY ASSESSMENT - D18008007MFSH/1
Attachments: SKS 8083C - Preli Advise.pdf

Dear Sithara,

Enclosed preliminary revised of vehicle SKS 8083C.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 9 November 2018 1:28 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008007MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Friday, 9 November, 2018 12:50 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008007MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE I, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008007MFSH

Date: 15 November 2018

Our Ref: CS/FCI18020327/R1sb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKS 8083C

Please be informed that we had conducted the inspection of the abovementioned vehicle on 14/11/2018 at the premises of M/s Auto Wheels Motorworks Pte Ltd and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 15,481.68</u>
Revised Estimate Amount	: <u>S\$ 4,103.71</u>
"Check" Items Amount	: <u>S\$ 2,412.24</u>
Market Value	: <u>S\$</u>
LTA Reimbursement Value	: <u>S\$</u>
Nett Value	: <u>S\$</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 3 Days

Yours faithfully,
Mohammed Rasul
Automotive Assessor

AUTO WHEELS

MOTORWORKS PTE LTD

48 TOH GUAN ROAD EAST ENTERPRISE

#04-142 SINGAPORE 608586

ATTN: FIRST CAPITAL INSURANCE

DATE: 8/11/2018
 VEHICLE NO: SKS8083C
 MODEL: AUDI TT
 YEAR: 2011
 ACCIDENT DATE: 7/11/2018
 TYPE OF CLAIM: TP
 CLAIM ADVISOR: LOUIS (91928963)
 EMAIL: louisongautowheels@yahoo.com

ESTIMATION

DESCRIPTION	QTY	LIST PRICE
PARTS		
BOOTLID	1	REPAIR
REAR BUMPER <i>cut ✓</i>	1	\$ 2,021.40
REAR BUMPER CLIPS <i>na ✓</i>	10	\$ 50.00
REAR BUMPER RETAINER <i>X suc</i>	2	\$ 394.80
REAR BUMPER CENTRE BRACKET <i>? X suc</i>	1	\$ 786.40
REAR BUMPER DIFFUSER <i>de ✓</i>	1	\$ 1,034.30
REAR BUMPER LOWER REFLECTOR <i>? } suc X</i>	1	\$ 587.10
REAR BUMPER REINFORCEMENT <i>? } suc X</i>	1	\$ 1,165.70
END PANEL	1	REPAIR
TAILLAMP <i>X suc</i>	2	\$ 2,586.80
REVERSE SENSOR <i>na ✓</i>	<i>X IPC</i>	\$ 1,024.40 <i>256.10</i>
AIRBAG CONTROL UNIT <i>X suc</i>	1	\$ 3,245.60
TOTAL:		\$ 12,896.50
DISCOUNT 5%:		\$ 644.83
		\$ 12,251.68

LABOUR	PRICE
LABOUR FOR FACILITATE REPAIR - REAR PORTION	\$ 1,000.00 <i>400</i>
TO RESPRAY AFFECTED AREAS - BOOTLID	\$ 300.00 <i>200</i>
TO RESPRAY AFFECTED AREAS - REAR BUMPER	\$ 300.00 <i>200</i>
TO RESPRAY AFFECTED AREAS - END PANEL	\$ 300.00 <i>X na</i>

AUTO WHEELS

MOTORWORKS PTE LTD

48 TOH GUAN ROAD EAST ENTERPRISE

#04-142 SINGAPORE 608586

ATTN: FIRST CAPITAL INSURANCE

DATE: 8/11/2018
 VEHICLE NO: SKS8083C
 MODEL: AUDI TT
 YEAR: 2011
 ACCIDENT DATE: 7/11/2018
 TYPE OF CLAIM: TP
 CLAIM ADVISOR: LOUIS (91928963)
 EMAIL: louisongautowheels@yahoo.com

ESTIMATION

TO CHECK AND RECONNECT ALL NECESSARY WIRING
 TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR
 TO REMOVE AND REFIT REVERSE SENSOR
 TO REMOVE AND REFIT AIRBAG
 TO DIAGNOSE AND RESET AIRBAG WARNING LIGHT
 SUNDARIES
 RUST PROOFING

\$ 50.00 X 11
 \$ 200.00 X 11
 \$ 100.00 60
 \$ 350.00 X 11
 \$ 450.00 X 11
 \$ nrc 80.00 30
 \$ 100.00 20

TOTAL: \$ 3,230.00

TOTAL: \$ 15,481.68
 7% GST: \$ 1,083.72
 \$ 16,565.39

[Signature]
 16/11/18
 Resul
 Hp 900/10068
 3 days
 L/S
 14/11/18 @ 1050
 Resuy after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

AUTO WHEELS

MOTORWORKS PTE LTD

88 TOH GUAN ROAD EAST ENTERPRISE
 #03-147 SINGAPORE 608586

ATTN: FIRST CAPITAL INSURANCE

DATE: 8/11/2018
 VEHICLE NO: SKS8083C
 MODEL: AUDI TT
 YEAR: 2011
 ACCIDENT DATE: 7/11/2018
 TYPE OF CLAIM: TP
 CLAIM ADVISOR: LOUIS (91928963)
 EMAIL: louisong@utowheels@yahoo.com

ESTIMATION

DESCRIPTION	QTY	LIST PRICE
PARTS		
BOOTLID	1	REPAIR
REAR BUMPER <i>cut</i>	1	\$ - 2,021.40
REAR BUMPER CLIPS <i>no</i>	10	\$ - 50.00
REAR BUMPER RETAINER <i>X</i>	2	\$ X 394.80
REAR BUMPER CENTRE BRACKET <i>?</i>	1	\$ X 786.40
REAR BUMPER DIFFUSER <i>no</i>	1	\$ - 1,034.30
REAR BUMPER LOWER REFLECTOR <i>?</i>	1	\$ X 587.10
REAR BUMPER REINFORCEMENT <i>?</i>	1	\$ X 1,165.70
END PANEL	1	REPAIR
TAILLAMP <i>X</i>	2	\$ X 2,586.80
REVERSE SENSOR <i>no</i>	<i>X IPC</i>	\$ - 1,024.00 256.1
AIRBAG CONTROL UNIT <i>X</i>	1	\$ X 3,245.60
TOTAL:	\$	12,896.50 <i>3,361.8</i>
DISCOUNT 5%:	\$	644.83 <i>168.09</i>
	\$	<u>12,251.68</u> <i>3,193.71</i>

LABOUR	PRICE
LABOUR FOR FACILITATE REPAIR - REAR PORTION	\$ <i>1000.00 400</i>
TO RESPRAY AFFECTED AREAS - BOOTLID	\$ <i>300.00 200</i>
TO RESPRAY AFFECTED AREAS - REAR BUMPER	\$ <i>300.00 200</i>
TO RESPRAY AFFECTED AREAS - END PANEL	\$ <i>300.00 X</i>

AUTO WHEELS

MOTORWORKS PTE LTD

48 TOH GUAN ROAD EAST ENTERPRISE

#04 142 SINGAPORE 608566

ATTN: FIRST CAPITAL INSURANCE

DATE: 8/11/2018
 VEHICLE NO: SKS8083C
 MODEL: AUDI TT
 YEAR: 2011
 ACCIDENT DATE: 7/11/2018
 TYPE OF CLAIM: TP
 CLAIM ADVISOR: LOUIS (91928963)
 EMAIL: louis@autowheels@yahoo.com

ESTIMATION

TO CHECK AND RECONNECT ALL NECESSARY WIRING
 TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR
 TO REMOVE AND REFIT REVERSE SENSOR
 TO REMOVE AND REFIT AIRBAG
 TO DIAGNOSE AND RESET AIRBAG WARNING LIGHT
 SUNDARIES
 RUST PROOFING

\$	50.00	X
\$	200.00	X
\$	100.00 60	
\$	350.00	X
\$	450.00	X
\$	800.00 30	
\$	100.00 20	910
TOTAL: \$	<u>3,230.00</u>	

TOTAL: \$	15,481.68
7% GST: \$	1,083.72
\$	<u>16,565.39</u>

4,103.71

LS: \$3,300

Resul
 Hp 900/10068

3 days

L/S

14/11/18 @ 1050

Resul after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before and after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18020327/R1sbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 29-11-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 7133T	Veh. Inspected	SKS 8083C
Policy No.		Coverage (\$)	0.00
Claim No.	D18008007MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	09/11/2018
2. Vehicle Particulars & Condition			
Make & Model	AUDI TT COUPE 2.0 TFSI	c.c	1984
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	TRUZZZ8J5B1009617	Colour	WHITE
Odometer	114439	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/40 R18	CONTINENTAL	6 mm
L/H Front Tyre	245/40 R18	CONTINENTAL	6 mm
R/H Rear Tyre	245/40 R18	CONTINENTAL	6 mm
L/H Rear Tyre	245/40 R18	CONTINENTAL	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	07/11/2018	Inspection Date	14/11/2018
Survey held at	48 TOH GUAN ROAD EAST #04-142		
Repairer	AUTO WHEELS MOTORWORKS PTE LTD		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 8083C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR BUMPER	CUT	2,021.40	2,021.40
10	REAR BUMPER CLIPS	NECESSARY	50.00	50.00
2	REAR BUMPER RETAINER	SERVICEABLE	394.80	-
1	REAR BUMPER CENTRE BRACKET	SERVICEABLE	786.40	-
1	REAR BUMPER DIFFUSER	DEFORMED	1,034.30	1,034.30
1	REAR BUMPER LOWER REFLECTOR	SERVICEABLE	587.10	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	1,165.70	-
1	END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
2	TAILLAMP	SERVICEABLE	2,586.80	-
4	REVERSE SENSOR	NOT WORKING (1 PC ONLY)	1,024.40	256.10
1	AIRBAG CONTROL UNIT	NOT NECESSARY	3,245.60	-
	LESS 5% DISCOUNT		-644.82	-168.09
			12,251.68	3,193.71
SPECIAL NETT ITEMS				
1	SUNDARIES (SN)	NECESSARY	80.00	30.00
			80.00	30.00
LABOUR				
	LABOUR FOR FACILITATE REPAIR-REAR PORTION.INCLUSIVE OF THE REPAIR OF BOOTLID AND END PANEL.		1,000.00	400.00
	TO RESPRAY AFFECTED AREAS-BOOTLID.		300.00	200.00
	TO RESPRAY AFFECTED AREAS-REAR BUMPER.		300.00	200.00
	TO RESPRAY AFFECTED AREAS-END PANEL.	NOT NECESSARY	300.00	-
	TO CHECK AND RECONNECT ALL NECESSARY WIRING.	NOT NECESSARY	50.00	-
	TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR.	NOT NECESSARY	200.00	-
	TO REMOVE AND REFIT REVERSE SENSOR.		100.00	60.00
	TO REMOVE AND REFIT AIRBAG.	NOT NECESSARY	350.00	-

Report Ref No. CS/FCI18020327/R1sbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DIAGNOSE AND RESET AIRBAG WARNING LIGHT. RUST PROOFING.	NOT NECESSARY	450.00 100.00 3,150.00	- 20.00 880.00
GRAND TOTAL			15,481.68	4,103.71
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,300.00

Report Ref No. CS/FCI18020327/R1sbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.