

ASS. REC. BY:

REF: CS / FCL18020328 / Rlsbnz

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): CUBS Sarene Ler of FCL Date/Time: 09-11-2018 11:38am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKL 3665T Insured: SH 9299D

at Workshop m/s Sng Ah Tee Motor Tel:

of Blk 3 Pioneer Rd North #01-18

Policy No: Claim No: D18007840 MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 30-10-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

12/11/2018 @ before 1pm

H.O.D. Endorsement:

Date/Time: 09/11/2018 12:04pm Person Contacted: Janlu Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKL 3665T - X
	SH 9299D - CUBS / FCL14021007 / K16b63 DCA: 08/03/13
15/11/18 @ 16:04 p.m.	rev'd RA to Sarene Ler via email.

Signature: *[Signature]*

REF: TCI

78842

ASSIGNMENT

From: Date: 12/12/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKL 3665T

at Workshop m/s: Sng Ah Tee Motor
of: Blk 3 Pioneer Rd North #01-18

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'Ds'

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKL 3665T Yr Regn: 2013 OUT

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAZDA 6 4DR 2-OL c.c. 1998

Colour: BLACK A/C: Insured / Std / NI / NA

Sp. Reading: 47870 T/Ratio: Insured / Std / NI / NA

Eng/No:

C/No: JM66J1071E0121832

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R17
R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: R/Bal. 6 mm L/Bal. 6 mm
Rear: R/Bal. 6 mm L/Bal. 6 mm

D.O.A. 30/10/18 D.O.I. 12/10/18

Survey held at: Sng Ah Tee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
09/04/19	Confirmed P/P \$ 2,045.60 @ 4 days with Resul (C \$ 1,079.20 Red - 35%)

RECEIVED 09 APR 2019

Date/Time, File Pass to? ☐ : Preli. Report

1) 09/04/19 ☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip:

Survey Fee:

Transportation

\$ - RS \$

Photos

Others

TOTAL

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$ 2,045.60 P/P

130
50
50
29

259



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007840MFSH

Date: 15 November 2018

Our Ref: CS/FCI18020328/R1sb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKL 3665T

Please be informed that we had conducted the inspection of the abovementioned vehicle on 12/11/2018 at the premises of M/s Sng Ah Tee Motor & Panel Service Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,124.80</u>
Revised Estimate Amount	: S\$ <u>1,976.24</u>
"Check" Items Amount	: S\$ <u>453.76</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the rear o/s portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 4 Days

Yours faithfully,
Mohammed Rasul
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	31-10-2018	Our Ref No. D18007840MFSH
Accident Date	30-10-2018	Claim Type. Third Party
Insured Vehicle	SH9299D	Third Party Vehicle. SKL3665T
Survey Location	BLK 3 PIONEER ROAD NORTH #01-18	
Contact Person.	SAMANTHA TAN	
Contact No.	62686183/ 0	Fax No. 62681429
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 9 April 2019 12:02 PM
To: 'Sharon Sng'
Cc: SUR
Subject: RE: SKL3665T - FINALISE & BEFORE PAINT

Dear Sharon,

Confirmed final fig \$2,045.60 @ 4 day of repairs before GST.

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sharon Sng [mailto:sharon@sngahtee.com]
Sent: Monday, 8 April 2019 5:22 PM
To: 'SUR' <sur@lkkauto.com>
Subject: FW: SKL3665T - FINALISE & BEFORE PAINT

From: Sharon Sng <sharon@sngahtee.com>
Sent: Monday, April 8, 2019 4:01 PM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Subject: SKL3665T - FINALISE & BEFORE PAINT

Best Regards

Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



-Please note that all offer/acceptance is made without prejudice.-

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 15 November 2018 4:04 PM
To: 'Serene Ler'; 'CWS Motor Claims'
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: SURVEY ASSESSMENT - D18007840MFSH/1
Attachments: SKL 3665T - Preli Advise -.pdf

Dear Serene,

Enclosed preliminary revised of vehicle SKL 3665T.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 9 November 2018 12:11 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Serener@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007840MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Friday, 9 November, 2018 11:38 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Serener@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18007840MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	7884Z

Vehicle Details

Vehicle No.:	SKL3665T
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Nov 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 4-DOOR SEDAN 2.0L SP6EAT
Primary Colour:	Black
Manufacturing Year:	2013
Engine No.:	PE20340878
Chassis No.:	JM6GJ1071E0121832
Maximum Power Output:	114.0 kW (152 bhp)
Open Market Value:	\$19,378.00
Original Registration Date:	30 Oct 2013
First Registration Date:	30 Oct 2013
Transfer Count:	0
Actual ARF Paid:	\$9,378.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Oct 2023
PARF Rebate Amount:	\$6,564.00

Intended COE Rebate Details

COE Expiry Date:	29 Oct 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$87,910.00
COE Rebate Amount:	\$43,884.00
Total Rebate Amount:	\$50,448.00

The information contained herein is correct as at 31 Oct 2018

OK

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com EST/QUOTE NO. SQ004348

RCB, Reg. / GST Reg. No: 200810440N

FIRST CAPITAL INSURANCE LIMITED
MOTOR CLAIMS DEPT

36 ROBINSON ROAD #16-01
CITY HOUSE SINGAPORE 068877

ATTENTION:

CONTACT: 6222 2311

FAX NO: 6507 3849

DATE: 08/11/2018
ACCIDENT DATE: 30/10/2018
VEHICLE NO: SKL3665T
CHASSIS/ENG.NO: JM6GJ1071E0121832
VEHICLE MODEL: MAZDA 6
CLAIM NO: D18007840MFSH
POLICY NO:
REMARK: 3665FIRST TP AGST SH9299D

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	REAR BUMPER RE	1,172.00	20	937.60	937.60
2	10	PC	REAR BUMPER CLIPS RM	4.80	20	3.84	38.40
3	1pc	PC	REAR BUMPER SIDE RETAINER RH-RE	39.60	20	31.68	63.36
4	2	PC	REAR BUMPER TOWING COVER MS	23.70	20	18.96	37.92
5	1	PC	REAR BUMPER REINFORCEMENT ? x 80	516.00	20	412.80	412.80
6	1	PC	REAR BUMPER REFLECTOR(RH) ? x 50	51.20	20	40.96	40.96
7	1	PC	REAR BOOT WEATHERSTRIPE ? x RM	129.70	20	103.76	103.76
SUB-TOTAL:							1,634.80
** SPECIAL NETT PRICE **							
1	1	PC	REAR BUMPER REVERSE SENSOR ✓	280.00		280.00	280.00
SUB-TOTAL							280.00
** WORK LABOUR **							
TO CHECK WIRING						30.00	30.00
TO APPLY ANTI RUST COATING						80.00	80.00
TO KNOCK, WELD, REMOVE & FIX ON ABOVE PARTS						550.00	550.00
TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS						550.00	550.00

SAM

PAGE: 1 of 2

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.

Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com EST/QUOTE NO. SQ004348

RCB. Reg. / GST Reg. No: 200810440N

FIRST CAPITAL INSURANCE LIMITED
MOTOR CLAIMS DEPT

36 ROBINSON ROAD #16-01
CITY HOUSE SINGAPORE 068877

ATTENTION :

CONTACT : 6222 2311

FAX NO: 6507 3849

DATE : 08/11/2018
ACCIDENT DATE : 30/10/2018
VEHICLE NO : SKL3665T
CHASSIS/ENG.NO : JM6GJ1071E0121832
VEHICLE MODEL : MAZDA 6
CLAIM NO : D18007840MFSH
POLICY NO :
REMARK : 3665FIRST TP AGST
SH9299D

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
SUB-TOTAL							1,210.00

Repair
IP 90010068
4 days
16/11/18
12/11/18 @ 1340
Reg after or SP part

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SAM

PAGE: 2 of 2

SUB-TOTAL : S\$ 3,124.80

ADD 7% GST. S\$ 218.74

GRAND TOTAL : S\$ 3,343.54

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O.E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.

Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com EST/QUOTE NO. SQ004348

RCB. Reg. / GST Reg. No: 200810440N

FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIMS DEPT

36 ROBINSON ROAD #16-01

CITY HOUSE SINGAPORE 068877

ATTENTION :

CONTACT : 6222 2311

FAX NO: 6507 3849

DATE 08/11/2018

ACCIDENT DATE : 30/10/2018

VEHICLE NO : SKL3665T

CHASSIS/ENG.NO : JM6GJ1071E0121832

VEHICLE MODEL : MAZDA 6

CLAIM NO : D18007840MFSH

POLICY NO :

REMARK : 3665FIRST TP AGST
SH9299D

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
SUB-TOTAL							1,210.00

Resue

1p 90010068

4 days

P/P or 4/S

12/11/18 @ 1340

Res after or 5p part

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*total \$7045.60
part by part
ok? pls resurvey.
Sham
21/4/2019.*

SAM

PAGE: 2 of 2

SUB-TOTAL : S\$ 3,124.80

ADD 7% GST. S\$ 218.74

GRAND TOTAL : S\$ 3,343.54

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O.E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com EST/QUOTE NO. SQ004348

RCB. Reg. / GST Reg. No: 200810440N

FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIMS DEPT

36 ROBINSON ROAD #16-01

CITY HOUSE SINGAPORE 068877

ATTENTION :

CONTACT : 6222 2311

FAX NO: 6507 3849

DATE 08/11/2018

ACCIDENT DATE : 30/10/2018

VEHICLE NO : SKL3665T

CHASSIS/ENG.NO : JM6GJ1071E0121832

VEHICLE MODEL : MAZDA 6

CLAIM NO : D18007840MFSH

POLICY NO :

REMARK 3665FIRST TP AGST
SH9299D

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	REAR BUMPER DE	1,172.00	20	937.60	937.60✓
2	10	PC	REAR BUMPER CLIPS mu	4.80	20	3.84	38.40✓
3	1pc	PC	REAR BUMPER SIDE RETAINER RH-mu	39.60	20	31.68	(1pc) 63.36
4	2	PC	REAR BUMPER TOWING COVER mu	23.70	20	18.96	37.92✓
5	1	PC	REAR BUMPER REINFORCEMENT ?	516.00	20	412.80	412.80X
6	1	PC	REAR BUMPER REFLECTOR(RH) ?	51.20	20	40.96	40.96X
7	1	PC	REAR BOOT WEATHERSTRIPE X	129.70	20	103.76	103.76X

SUB-TOTAL: 1,634.80

~~\$1045.60~~

** SPECIAL NETT PRICE **

1	1	PC	REAR BUMPER REVERSE SENSOR at	280.00
---	---	----	--	--------

220 ~~280.00~~ 280.00

SUB-TOTAL 280.00

~~\$779~~

** WORK LABOUR **

TO CHECK WIRING

TO APPLY ANTI RUST COATING

TO KNOCK, WELD, REMOVE & FIX ON ABOVE PARTS

TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS

~~X~~ 30.00 30.00

30 ~~80.00~~ 80.00

350 ~~550.00~~ 550.00

400 ~~550.00~~ 550.00

~~\$780~~

SAM

PAGE: 1 of 2

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18020328/R1sbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 10-04-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9299D	Veh. Inspected	SKL 3665T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007840MFSH	Excess (\$)	0.00	
Assign From	SERENE LER	Assign Date	09/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 6 4DR 2.0L	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	JM6GJ1071E0121832	Colour	BLACK	
Odometer	47870	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	TOYO	6 mm	
L/H Front Tyre	225/55 R17	TOYO	6 mm	
R/H Rear Tyre	225/55 R17	TOYO	6 mm	
L/H Rear Tyre	225/55 R17	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/10/2018	Inspection Date	12/11/2018	
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKL 3665T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	1,172.00	1,172.00
10	REAR BUMPER CLIPS @\$4.80	NECESSARY	48.00	48.00
2	REAR BUMPER SIDE RETAINER @\$39.60	O/S NECESSARY	79.20	39.60
2	REAR BUMPER TOWING COVER @\$23.70	MISSING	47.40	47.40
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	516.00	-
1	REAR BUMPER REFLECTOR (RH)	SERVICEABLE	51.20	-
1	REAR BOOT WEATHERSTRIPE	NOT NECESSARY	129.70	-
	LESS 20% DISCOUNT		-408.70	-261.40
			1,634.80	1,045.60
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER REVERSE SENSOR (SN)	NOT WORKING	280.00	220.00
			280.00	220.00
	<u>LABOUR</u>			
	TO CHECK WIRING.	NOT NECESSARY	30.00	-
	TO APPLY ANTI RUST COATING.		80.00	30.00
	TO KNOCK,WELD,REMOVE & FIX ON ABOVE PARTS.		550.00	350.00
	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS.		550.00	400.00
			1,210.00	780.00
	GRAND TOTAL		3,124.80	2,045.60
	RECOMMENDED COST OF REPAIRS			2,045.60

Report Ref No. CS/FC118020328/R1sbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.