

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBF1037H181101

Estimate

Customer

Name: India International Insurance Pte Ltd

Date: 08-11-18

Address: Motor Claims Department

Vehicle No: GBF1037H

64 Cecil Street #04-00 & #05-00

Model/Make: Fiat Doblo Cargo

IOB Building Singapore 049711

Maxi 1.6 MTJ AMT D/AB Panel

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Bumper	\$ 745.00	X
2	Bumper Clips 1 set	\$ 65.00	SN X
3	Bumper Side Holder	\$ 65.00	X
4	Bumper Side Holder 2 pcs (@ S\$10.50)	\$ 21.00	SN X
	Remove and refix rear bumper reverse sensor	\$ 60.00	- 40
	To check all wiring & electrical component for proper function	\$ 50.00	- X
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 600.00	- 200
	To putty & spray painting & including touch up paint on accident affe	\$ 700.00	- 260

Total Parts & Labour of estimate for damaged vehicle

\$ 2,306.00

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

not Allocial
LKR
P/P & SWP.
3dy.
9/11/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: