

COMFORTDELGRO ENGINEERING PTE LTD

(Fri)

Date: 09.11.2018

Time: 08:35:15

REPAIR ESTIMATE

AXA

CHS

1/4

TS

Page: 1

0900

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305236456
REGN NO : SHD4386U
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : SONATA
DATE OF REGN : 12.07.2012
DATE/TIME IN : 08.11.2018 15:00
ACCIDENT DATE : 07.11.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT	Notes
0001	04-01-0101-0001-G	REAR BUMPER	1 L	578.40 20.00 462.72	Advised
0002	03-01-0101-0003-G	REAR BUMPER SPONGE	1	137.40 20.00 109.92	Xsu
0003	04-01-0101-0005-U	REAR BUMPER REINFORCEMENT	1	483.30 20.00 386.64	con
0004	04-01-0101-0014-G	REAR BUMPER UNDER COVER	1 L	47.00 20.00 37.60	Xsu
0005	04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00 20.00 17.60	rec
0006	04-01-0101-0033-G	REAR BUMPER MOULDING LH	1	38.00 20.00 30.40	Xsu
0007	04-01-0101-0034-G	REAR BUMPER MOULDING RH	1	38.00 20.00 30.40	Xsu
0008	04-01-0101-0020-U	BOOTLID	1 L	1,935.90 20.00 1,548.72	Boyl
0009	04-01-0101-0031-G	BOOTLID UPR LOCK	1 L	132.10 20.00 105.68	X su
0010	04-01-0101-0079-G	BOOTLID LWR LOCK	1 L	30.30 20.00 24.24	X su
0011	04-01-0101-0008-G	BOOTLID EMBLEM HYUNDAI	1 L	24.20 20.00 19.36	rec
0012	04-01-0101-0570-G	BOOTLID EMBLEM SONATA	1 L	43.60 20.00 34.88	rec
0013	04-01-0101-0002-G	BOOTLID EMBLEM CRDI	1 L	22.70 20.00 18.16	rec

AXA

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305236456
 REGN NO : SHD4386U
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : SONATA
 DATE OF REGN : 12.07.2012
 DATE/TIME IN : 08.11.2018 15:00
 ACCIDENT DATE : 07.11.2018

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT	
0014 04-01-0101-0007-G BOOTLID EMBLEM H	1	L	26.10	20.00	20.88	✓ see
0015 04-01-0101-0158-G BOOTLID KEY LOCK	1	L	78.20	20.00	62.56	X see
0016 04-01-0101-0046-G TRIM-TRANSVERSE	1	L	55.30	20.00	44.24	X see
0017 04-01-0101-0048-U TAIL LAMP RH	1		344.00	20.00	275.20	X see
0018 04-01-0101-0050-U TAIL LAMP LH	1		344.00	20.00	275.20	X see
0019 04-01-0101-0057-G BOOTLID LAMP RH	1	L	230.20	20.00	184.16	X see
0020 04-01-0101-0056-G BOOTLID LAMP LH	1	L	230.20	20.00	184.16	X see
0021 04-01-0101-0136-G REAR TOWING HOOK	1		77.60	20.00	62.08	X see
0022 04-01-0101-0049-G REAR END PANEL	1	L	391.80	20.00	313.44	X repair
0023 04-01-0101-0132-G SPARE TYRE PANEL	1		863.00	20.00	690.40	X see
0024 04-01-0101-0076-G TAIL LAMP PANEL RH	1	L	217.40	20.00	173.92	X see
0025 04-01-0101-0083-G TAIL LAMP PANEL LH	1	L	217.40	20.00	173.92	X see

AXA

14 TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305236456
 REGN NO : SHD4386U
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : SONATA
 DATE OF REGN : 12.07.2012
 DATE/TIME IN : 08.11.2018 15:00
 ACCIDENT DATE : 07.11.2018

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT	
0026 04-01-0101-0080-G FENDER REAR RH	1	L	1,935.90	20.00	1,548.72	<i>hat X dp Range</i>
0027 04-01-0101-0052-G REAR WINDSCREEN MOULDING	1	L	60.00	20.00	48.00	<i>X "</i>
0028 05-01-0199-0032-A WINDSCREEN AHESIVE-310MLC	2		92.00	2.00	92.00	<i>X "</i>
0029 28-01-0101-0002-A BOOTLID 'COMFORT'	1		20.00	0.20	20.00	<i>- "</i>
0030 28-01-0199-0012-A BOOTLID '65521111'	1		10.00	0.02	10.00	<i>- "</i>
0031 09-01-9999-0068-A REVERSE SENSOR	1		135.70	0.00	135.70	<i>- 5 Ltr</i>
					SUB-TOTAL	: 7,140.90

JOB NATURE

0000 L	PANEL BEATING	1100.00	<i>600</i>
0001 23-502	SPRAYPAINT ON AFFECTED AREA	1100.00	<i>600</i>
0002 17-01	CHECK ALL LIGHTING	80.00	<i>70</i>

AXA

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305236456
REGN NO : SHD4386U
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : SONATA
DATE OF REGN : 12.07.2012
DATE/TIME IN : 08.11.2018 15:00
ACCIDENT DATE : 07.11.2018

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0003 20-00 TUFF COAT ON AFFECTED PARTS.	200		50		10000
0004 L R/I UPHOSTERY ETC	150	X	77		11550
0005 L R/I REAR WINDSCREEN	120	X	77		9240
0006 L R/I REVERSE SENSOR	120		30		3600
SUB-TOTAL :					2,870.00
TOTAL :					10,010.90

Limf

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Kahr 1/11/18
M 9/11/18 1040 hrs
3 Pys
4/2
Alta Reg photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Co. Staff

Acknowledged by Repairer
Signature:
Date: