

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5156R**AAD1810-310***Not Insured*
11 Sep @ 1550h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5156R

VF1ABL15AUC276551

RENAULT

LATITUDE

31.10.2018

AIG

PART		LIST	
1	BUMPER COVER FRT	\$	Su 1,259.42
1	BUMPER SPOILER FRT	\$	Su 181.75
1	BUMPER ABSORBER FRT	\$	Su 394.68
1	BUMPER RETAINER FRT RH	\$	Su 150.77
1	BUMPER SUPPORT FRT	\$	Su 123.88
1	BUMPER UNDERTRAY FRT	\$	Su 472.83
1	BUMPER GRILLE LOWER FRT	\$	Su 266.80
1	BUMPER FOG LAMP GRILLE RH	\$	Su 207.21
1	BUMPER BEAM FRT	\$	N 914.08
1	HEADLAMP RH	\$	Su 1,184.43
1	HEADLAMP PANEL FRT RH	\$	N 152.15
1	FENDER PANEL FRT RH	\$	N 783.83
1	WHEELARCH FRT RH	\$	Su 278.84
1	FENDER BRACKET LOWER RH	\$	Su 15.79
1	FENDER INSULATOR RH	\$	Su 130.84
1	SUBFRAME OUTER FRT	\$	Su 2,652.45
1	SUBFRAME BRACKET OUTER RH	\$	Su 92.36
1	DOOR PANEL FRT RH	\$	N 2,844.66
1	DOOR HINGE UPPER RH	\$	N 261.28
1	DOOR HINGE LOWER RH	\$	N 300.55
1	DOOR CHECK FRT RH	\$	Su 194.77
1	DOOR LOCK FRT RH	\$	N 908.75
1	DOOR CATCH FRT RH	\$	Su 131.23
1	DOOR HANDLE OUTER FRT RH	\$	Su 477.76
1	DOOR HANDLE COVER FRT RH	\$	Su 13.22
1	DOOR HANDLE MODULE FRT RH	\$	Su 133.60
1	DOOR REGULATOR FRT RH	\$	N 505.19
1	DOOR REGULATOR MOTOR FRT RH	\$	N 796.46
1	DOOR REGULATOR GUIDE FRT RH	\$	Su 120.97

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 51568

AAD1810- 310

1	DOOR MIRROR ASSY RH	\$	<i>Mydits / Del</i> 1,483.40 ✓
1	FRONT DOOR HARNESS WIRE	\$	<i>Sn</i> 2,670.00 X
1	WIPER RESERVOIR	\$	<i>Sn</i> 348.25 X
1	WIPER RESERVOIR NECK	\$	<i>Sn</i> 136.11 X
1	WIPER RESERVOIR MOTOR	\$	<i>Sn</i> 270.06 X

	\$	20,858.39
10%	\$	2,085.84
	\$	18,772.55

Special Nett

1SET	BUMPER CLIP FRT	\$	<i>na</i> 66.00	} X
1	BUMPER BRACKET CLIP FRT LH	\$	<i>na</i> 12.00	
1	BUMPER SUPPORT CLIP FRT LH	\$	<i>na</i> 10.50	
1SET	BUMPER GRILLE LOWER CLIP	\$	<i>na</i> 69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>na</i> 70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	<i>na</i> 20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	<i>na</i> 30.00	}
2	WINDSCREEN SEALANT	\$	<i>na</i> 253.80	
1SET	WHEELARCH CLIP FRT LH	\$	<i>na</i> 30.50	
1	FRONT DOOR STICKER 'Trans-cab'	\$	<i>na</i> 80.00 <i>60na</i>	} X
1	FRONT DOOR STICKER 'Chassis'	\$	<i>na</i> 50.00 <i>15na</i>	
2	ABSORBER BOLT L70Y	\$	<i>Sn</i> 44.01	
2	ABSORBER NUT L70Y	\$	<i>Sn</i> 17.56	
1	DOOR CHECK BOLT	\$	<i>Sn</i> 22.69	
1	DOOR GUIDE SCREW	\$	<i>Sn</i> 10.85	
1	DOOR HINGE BOLT	\$	<i>Sn</i> 10.85	
1	DOOR HINGE NUT RH	\$	<i>Sn</i> 14.60	
1	DOOR CHECK BOLT	\$	<i>Sn</i> 22.69	
1	DOOR CHECK NUT	\$	<i>Sn</i> 3.75	
1	DOOR LOCK SCREW L70Y	\$	<i>Sn</i> 6.12	
1	DOOR CATCH SCREW L70Y	\$	<i>Sn</i> 10.06	
1	FRONT RIGHT TYRE	\$	<i>Sn</i> 330.00	
1	FRONT RIGHT TYRE RIM	\$	<i>Sn</i> 380.00	

TOTAL	\$	1,565.00
--------------	----	-----------------

Trans-cab Auto Services Pte Ltd

AAD1810- 310

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 51562

TOTAL PARTS	\$	20,337.55
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00	2820d
Putty and spray painting of the affected portion.	\$	3,000.00	287
To rust-proofing of the affected areas.	\$	170.00	22 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	22 X
To check steering geometry and computer wheel alignment	\$	220.00	22 X
To transfer of tire, rim and on wheel balancing.	\$	170.00	22 X
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00	22 X
To transfer of windscreen fittings, attachment and perform water seepage test.	\$	380.00	22 X
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00	22 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	22 X
To vacuum, replace, refix and recharge air condenser	\$	380.00	22 X
To replace, refix and top up coolant for radiator	\$	170.00	22 X

Trans-cab Auto Services Pte Ltd

AAD1810- 310

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5156R

To vacuum, replace, refix and recharge Air Intercooler \$ *na* 170.00 X**TOTAL** \$ 9,350.00**Over All Total** \$ 29,687.55**LUMP SUM (REPAIR DAY)**~~10 DAYS~~

2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: