

Insurance: Jaimie CC: 3/601 20340 Kga392 LKK: D/D

Surveyor: KSC DOB: 8/11/2018 Date / Time: 8/11/2018

Pre-assign / CCU / FTE: _____ Registered in Meritmen: _____



Insured Vehicle No.: GBH 5021 R
Name of Insured: A Sfrat PLC
Insured Tel No.: _____ HP: _____
Excess Sec II : \$5 _____ D.O.A: 7/11/2018
Is driver the owner? (YES / NO) (NO) Nature of Accident: _____
If NO, Driver Name / Age: Lu SHAN
Driver Tel No.: 97213997 /L: YES / NO (NO)

Claim No.: _____
Policy No.: _____
Make / Model: _____
Place of Accident: _____
OI GIA REPORT: YES / NO (YES) ; TP GIA REPORT: YES / NO (YES)
Insured Liability: _____ % Final? Yes / No (YES)

SH0882 E



INSRS: _____
WSP: Trans Lab.
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____

Date/ Time		STAGE	DATE / PIC
	SH0882 E - NA/HP 17/11/2018/104 ; DPA: 24/8/17	Non-Reporting hr (1st):	
	NA/HP 17/11/2018. X	Non-Reporting hr (2nd):	
9/10	Email LOA. (Pending LOA) ✓	Non-Reporting hr (Final):	
11/10	TO pass file to RT type report off to RT type report	Notification hr (if non-pickup):	
26/11	Pending mandate approval of \$8953.66 ✓	Call OI:	7/10/19
4/12	offer to settle to \$8953.66 as per TP LOD	After call hr to OI:	
	NO DV required. File pass me to close.	Documentation Check List:	Handler Typist
		Notification hr (if non-pickup)	☒
		After call hr to OI:	☒
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☒
		Towing Invoice	☒
		LTA / GIA :	☒
		Medical Bill:	☒
		FIR:	☒
		Mandate/Reject Instruction:	☒
		LOD	☒

PRELIMINARY ADVICE		Date/Time: _____	Sent By: _____
FINALIZATION		Date/Time: _____	Confirm with: _____
Repair Cost:	<u>P/R</u>	<u>\$37499.50</u>	(3 days) Reduction: <u>\$32434.19%</u> <u>81</u>
FINAL SETTLEMENT		Date/Time: <u>4/12/18</u>	Confirm with: <u>Wai Yim</u>
Final Liability:	% <u>100</u>	(Agreed / Assessed) BOLA S/N No.: <u>31</u>	Email ☒ Call ☐
Repair Cost:	<u>(W/437)</u>	<u>\$8034.47</u>	If NO or B 28, Ass. Lia: _____
Loss of Rental (LOR):	<u>\$5</u>	<u>621.60</u>	(6 days) x \$103.60
Loss of Use (LOU):	<u>\$5</u>	<u>-</u>	(3 x days)
Loss of Income (LOI):	<u>\$5</u>	<u>300.00</u>	(\$ 50 x 6 days)
LOR only ☐ LOU only ☐	☒ LOR + LOU ☐ LOR + LOI ☐	[Tick only one]	
GIA/LTA Search	<u>\$5</u>	<u>7.49</u>	
Medical:	<u>\$5</u>	<u>-</u>	
Disbursement:	<u>\$5</u>	<u>-</u>	(e.g. Tow/ Independent)
Legal Cost	<u>\$5</u>	<u>-</u>	
Total:	<u>\$5</u>	<u>8953.66</u>	Global Sum \$5: <u>-</u>
FINAL PAYMENT		Date/Time: _____	Confirm with: _____
Payer 1:	<u>\$5</u>	<u>8953.66</u>	Name 1: <u>Trans - Cab Auto Services Pte Ltd</u>
Payer 2: (Strike if N.A.)	<u>\$5</u>	<u>-</u>	Name 2: _____
Payer 3: (Strike if N.A.)	<u>\$5</u>	<u>-</u>	Name 3: _____

COPY SENT

1) Claim status: Normal/Reject/Private Settle
2) Report Format: TP
3) Survey fee: \$4001-

ASS. REC. BY:

REF: 891

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs: 0324 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

9/11 File pass to Carhenge

PIP = \$7499.50 - (Red = \$32,434.19 / 817.7)

* 3 repair days + 1 Sunday + 2 PRS = 6 days.

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) :

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ - RS. \$

Fixtures

Others

TOTAL

Veh No:

S110 882E

Yr Regn:

03, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Longitude

c.c.

1.895

Colour:

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

325445

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

V11AB15AUC 282624

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: M / S / R / STD A / R / or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Giti

Front

Rear

R/Bal.

7

mm

R/Bal.

4

mm

L/Bal.

7

mm

L/Bal.

4

mm

D.O.A.

7/11/18

D.O.I.

8/11/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/EQI18020340/Kja3

Date: 09/11/2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

PRELIMINARY ADVICE OF VEHICLE NO.

SHD 882E

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 08/11/2018 at the premises of M/s Trans-cab Auto Services Pte Ltd - Ang Mo Kio have the following to report:-

Workshop Estimate Amount	: S\$	39,933.69
Revised Estimate Amount	: S\$	7,499.50
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	7,499.50
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3.0 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD 882E**AAD1811-047***Not Authored**Survey B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

SHD 882E

VF1ABL15AUC282624

RENAULT

LATITUDE

7.11.2018

EQ**PART****LIST**

- 1 1 BUMPER COVER REAR
- 2 1 BUMPER LOWER REAR
- 3 1 BUMPER BRACKET CTR REAR
- 4 1 BUMPER BRACKET SIDE RH REAR
- 5 1 BUMPER RETAINER RH REAR
- 6 1 BUMPER REFLECTOR RH
- 7 1 BUMPER BRACKET SIDE LH REAR
- 8 1 BUMPER RETAINER LH REAR
- 9 1 BUMPER REFLECTOR LH
- 10 1 BUMPER BEAM REAR
- 11 1 BUMPER BEAM BRACKET LH REAR
- 12 1 BUMPER BEAM BRACKET RH REAR
- 13 1 OUTER PANEL REAR (End Panel)
- 14 1 OUTER PANEL REAR (End Panel)TRIM
- 15 1 TAILLAMP RH
- 16 1 TAILLAMP PANEL RH
- 17 1 TAILLAMP LH
- 18 1 TAILLAMP PANEL LH
- 19 1 BOOT REAR
- 20 1 BOOT FINISHER
- 21 1 BOOT WHEATERSTRIP
- 22 1 BOOT REFLECTOR LAMP LH
- 23 1 BOOT REFLECTOR LAMP RH
- 24 1 BOOT BADGE 'RENAULT'
- 25 1 BOOT BADGE
- 26 1 BOOT STRUT LH
- 27 1 BOOT STRUT RH
- 28 1 BOOT HINGE LH
- 29 1 BOOT HINGE RH

- | | | | |
|----|---------------|----------|---|
| \$ | <i>Bu</i> | 1,108.46 | ✓ |
| \$ | <i>not in</i> | 768.84 | ✓ |
| \$ | <i>SL</i> | 113.47 | X |
| \$ | <i>SL</i> | 135.97 | X |
| \$ | <i>SL</i> | 44.99 | X |
| \$ | <i>SL</i> | 43.61 | X |
| \$ | <i>SL</i> | 135.97 | X |
| \$ | <i>SL</i> | 44.99 | X |
| \$ | <i>SL</i> | 43.61 | X |
| \$ | <i>Bu</i> | 777.52 | ✓ |
| \$ | <i>R</i> | 225.95 | X |
| \$ | <i>R</i> | 225.95 | X |
| \$ | <i>R</i> | 1,471.77 | X |
| \$ | <i>not in</i> | 404.56 | ✓ |
| \$ | <i>SL</i> | 552.55 | X |
| \$ | <i>R</i> | 986.70 | X |
| \$ | <i>SL</i> | 552.55 | X |
| \$ | <i>R</i> | 986.70 | X |
| \$ | <i>Bu</i> | 2,872.68 | ✓ |
| \$ | <i>SL</i> | 470.06 | X |
| \$ | <i>SL</i> | 323.05 | X |
| \$ | <i>SL</i> | 493.35 | X |
| \$ | <i>SL</i> | 493.35 | X |
| \$ | <i>not in</i> | 225.36 | ✓ |
| \$ | <i>not in</i> | 225.36 | ✓ |
| \$ | <i>SL</i> | 276.08 | X |
| \$ | <i>SL</i> | 276.08 | X |
| \$ | <i>R</i> | 367.84 | X |
| \$ | <i>R</i> | 367.84 | X |

Trans-cab Auto Services Pte Ltd

AAD1811-047

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 882E

30	1 BOOT INNER TRIM	\$	<i>Sh</i> 586.45 X
31	1 BOOT SWITCH	\$	<i>Sh</i> 168.13 X
32	1 BOOT LOCK	\$	<i>n</i> 202.67 X
33	1 BOOT LOCK CATCH	\$	<i>n</i> 74.40 X
		\$	16,046.87
		10% \$	7.44
		\$	<u>16,039.43</u>

Special Nett

1	1SET PARKING AID	\$	<i>Shot</i> 700.00 <i>600.00</i>
2	1SET REAR BUMPER CLIP	\$	<i>nn</i> 66.00 —
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>nn</i> 33.00 —
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>nn</i> 10.00 X
5	1SET BUMPR RETAINER RH CLIP RR	\$	<i>nn</i> 20.00 X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	<i>nn</i> 10.00 X
7	1SET BUMPR RETAINER CLIP LH RR	\$	<i>nn</i> 20.00 X
8	1SET BUMPER LOWER REAR RIVET	\$	<i>nn</i> 22.00 X
9	1SET BUMPER LOWER REAR CLIP	\$	<i>nn</i> 66.00 ✓
10	1 EXHAUST MOUNTING REAR	\$	<i>Sh</i> 17.82 X
11	2 REAR WINDSCREEN SELANT	\$	<i>nn</i> 80.00 X
12	1 WINDSCREEN MOULDING	\$	<i>nn</i> 100.00 X
13	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 100.00 X

TOTAL \$ 1,244.82

TOTAL PARTS \$ 17,284.25**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 <i>4400</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00 <i>4000</i>

Trans-cab Auto Services Pte Ltd**AAD1811-047**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 882E

To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	~ 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	↳ 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	↳ 170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	↳ 170.00	X
To check steering geometry and computer wheel alignment	\$	↳ 220.00	X
TOTAL	\$	6,610.00	

Over All Total \$ 39,933.69

22297.00

(LUMP SUM)**Repair Days****10 DAYS**27 days
03

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHD882E
Vehicle to be Exported:	Yes
Intended Deregistration Date:	07 Nov 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C003062
Chassis No.:	VF1ABL15AUC282624
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	22 Mar 2016
First Registration Date:	22 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Mar 2024
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	
COE Expiry Date:	21 Mar 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$39,633.00
COE Rebate Amount:	\$26,608.00
Total Rebate Amount:	\$41,606.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	
The information contained herein is correct as at 07 Nov 2018	

OK



A.S.Frost Pte Ltd
2 Woodlands Sector 1,
#03-24, Singapore 738068
Tel: (65) 6257 3468 Fax: (65) 6257 3469

11th October 2019

RE: Verification of Employment for Lu Shun

To Whom It May Concern:

This letter is to verify that Lu Shun has been employed with A.S.Frost Pte Ltd since 05th September 2018. Currently Lu Shun

- Hold title of Delivery Driver in our Logistic Department.
- His current basic salary is S\$2,000.00.
- Works on a full time basis of 5 days a week.

If you have any enquiries regarding his employment situation, please give me a call at (65) 6257 3468.

Yours Sincerely,

HR Manager
Rebecca Yoon



A.S.Frost Pte Ltd
2 Woodlands Sector 1,
#03-24, Singapore 738068
Tel: (65) 6257 3468 Fax: (65) 6257 3469

11th October 2019

Letter of Authorization

To Whom It May Concern:

I Rebecca Yoon would like to authorize Lu Shun, Fin G1441276Q to operate the vehicle number GBH 5021R from A.S. Frost Pte Ltd.

If you have any enquiries, please contact 6258 3468.

Thank you.

Yours Sincerely,

HR Manager
Rebecca Yoon

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Tuesday, 26 November 2019 5:03 PM
To: jaime tay
Cc: Joel Goh
Subject: RE: Direct Settlement - Accident Involving GBH5021R (OI : EQI - DM18HO03100-JT) AND SHD882E (TP : LKK REF - CC3/EQI18020340/Kja3) on 07/11/2018
Attachments: ADJUSTMENT REPORT.pdf; INSPECTION REPORT.pdf; LKK RESURVEY PHOTO.pdf; LKK SURVEY PHOTO.pdf; LOD AND OTHER DOCUMENTS.pdf

EQ ref : **DM18HO03100-JT**
LKK ref : CC3/EQI18020340/Kga3

Dear Sirs/Madam,

ACCIDENT INVOLVING GBH5021R(EQ-OI) AND SHD882E(TP) ON 07/11/2018

We refer to the above matter.

This is a head-to-rear collision.

A letter was sent out to the Insured to notify Third Party claim and NCD issues. No further feedback till to date.

We seek your approval to offer Third Party repairer "**TRANS-CAB AUTO SERVICES PTE LTD**" at **8,953.56(all-in)**.

The summary is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 22,297.00	\$ 7,499.50
2. Loss of Rental (6days x \$103.60)	\$ 621.60	\$ 621.60 (6days x \$103.60)
3. Loss of Income (6days x \$50.00)	\$ 300.00	\$ 300.00 (6days x \$50.00)
3. LTA/ GIA Search Fee	\$ 7.49	\$ 7.49
Total	\$ 23,226.09	<u>\$ 8,953.56</u>

**3days recommendation for repair + 1Sunday + 1PRS + 1Saturday = 6days

Market Value	: \$00,000.00 (est)
LTA Rebate	: <u>\$00,000.00 (est)</u>
Nett Value	: <u>\$00,000.00 (est)</u>

Enclosed here with all the relevant documents for your perusal.

Kindly let us have your approval/instruction.

Best Regards,
Cecilia Chong | Case Handler
LKK Auto Consultants Pte Ltd

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Wednesday, 4 December 2019 9:39 AM
To: Ng Wai Yin
Cc: 'Jasmine Tan'; claims@transcab.com.sg
Subject: YOUR REF: AAD1811-047 (OUR REF: CC3/EQ118020340/Kga3q2) *** ACCIDENT INVOLVING GBH 5021R & SHD 882E ON 07/11/2018 ***

WITHOUT PREJUDICE

Dear Wai Yin,

We are pleased to offer total amount of \$8953.56 (all-in) as per your LOD.

Please note that NO DV is required for this matter.

Thus, we shall proceed to submit and close off the case.

Thanks

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC3/EQ18020340/Kga3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 11-12-2019



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 5021R	Veh. Inspected	SHD 882E
Policy No.	DMCPHQ18-003647	Coverage (\$)	0.00
Claim No.	DM18HO03100-JT	Excess (\$)	0.00
Assign From		Assign Date	08/11/2018

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	VF1ABL15AUC282624	Colour	METALLIC WHITE / RED
Odometer	325445	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	7 mm
L/H Front Tyre	215/60 R16	GITI	7 mm
R/H Rear Tyre	215/60 R16	GITI	4 mm
L/H Rear Tyre	215/60 R16	GITI	4 mm

4. Description of DamagesTHE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.**5. General Information**

Accident Date	07/11/2018	Inspection Date	08/11/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. RemarksA)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 882E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER REAR	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR	DENTED / CUT	768.84	768.84
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	OUTER PANEL REAR (END PANEL)	TO REPAIR SEE LABOUR	1,471.77	-
1	OUTER PANEL REAR (END PANEL) TRIM	DENTED	404.56	404.56
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	BOOT REAR	BENT	2,872.68	2,872.68
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP	SERVICEABLE	323.05	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	BOOT BADGE "RENAULT"	NECESSARY	225.36	225.36
1	BOOT BADGE	NECESSARY	225.36	225.36
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-

Report Ref No. CC3/EQ118020340/Kga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-
	LESS 10% DISCOUNT		-1,604.68	-638.28
			14,442.18	5,744.50
	<u>SPECIAL NETT ITEMS</u>			
1	SET PARKING AID (SN)	SHORTED	700.00	600.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
			1,244.82	765.00
	<u>LABOUR</u>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	440.00

Report Ref No. CC3/EQ118020340/Kga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET LH REAR,BUMPER BEAM BRACKET RH REAR,OUTER PANEL REAR (END PANEL),TAILLAMP PANEL RH,TAILLAMP PANEL LH,BOOT HINGE LH,BOOT HINGE RH,BOOT LOCK AND BOOT LOCK CATCH.		2,200.00	400.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			6,610.00	990.00
GRAND TOTAL			22,297.00	7,499.50
RECOMMENDED COST OF REPAIRS				7,499.50

Report Ref No. CC3/EQ118020340/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.