

ASSIGNMENT

Adrian

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 1780088863Claims No. 138637023256Sum Insured: _____ Excess: 600 15/11/15

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 100K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 07 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLC1222L Yr Regn: 2017, DecType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Audi A3 c.c. 499Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 18867 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAU2228V751032826Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / 8Rim / STD A/Rim orTyre Size: F: 205/55R16R: 205/55R16BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 09/11/18Survey held at PremierDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>UD AIG</u>
	<u>SLC 1222L - C03 / AU118020341 / Adon2</u>
	<u>12/11/18 @ 3.15pm report to Victor via Message.</u>
	<u>14/11/18 @ 5pm Victor informed clm via Message</u>
	<u>15/11/18 @ 11.15am informed Tony CIA & Ex \$600 by email.</u>
	<u>04/10/19 @ 2.54pm confirmed with Carriane final fig \$9474.96, 7 days.</u>
	<u>(led \$6210.04, 41%)</u>

Date/Time, File Pass to?

Date/Time, File Return to?

1) 15/10 final

2)

3)

4)

5)

6)

Preli. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Basic & Add.

S + RS, Si

Photos

Others

TOTAL

Date:

20011211

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mohd Zawaye, Norsazani

Date: 21 Dec 2018

Preliminary Advice

Vehicle No	: SLC1222L	Accident Date	: 03/11/2018
Make	: AUDI A3	Policy No.	: 1700088863
Assignment Date	: 09/11/2018	Excess	: S\$600.00
Date of Inspection	: 09/11/2018	Est. Duration of Repair	: 7.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,960.00
Revised Amount	:S\$	9,974.96
Check Items (Estimated)	:S\$	0.00
Total	:S\$	9,974.96

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	100,000.00
COE / PARF Rebate	:S\$	50,112.00
Salvage Value	:S\$	
Margin for Repair	:S\$	49,888.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mohd Zawaye, Norsazani

Date: 12 Nov 2018

Preliminary Advice

Vehicle No	: SLC1222L	Accident Date	: 03/11/2018
Make	: AUDI A3	Policy No.	: 1700088863
Assignment Date	: 09/11/2018	Excess	: S\$0.00
Date of Inspection	: 09/11/2018	Est. Duration of Repair	: 6.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,885.00
Revised Amount	:S\$	7,938.00
Check Items (Estimated)	:S\$	5,646.00
Total	:S\$	13,584.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	100,000.00
COE / PARF Rebate	:S\$	50,112.00
Salvage Value	:S\$	
Margin for Repair	:S\$	49,888.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 4 October 2019 2:54 PM
To: Carrine Leong; SUR
Cc: jayee.yap@premiumauto.com.sg; 'Chang Chee Sing'
Subject: RE: FINAL REVISION - SLC1222L - OD AIG - SURVEYED 9 NOV 18

Dear Carrine,

WITHOUT PREJUDICE

Confirm final fig \$9,974.96 before excess \$600 & GST and 7 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carrine Leong <carrine.leong@premiumauto.com.sg>
Sent: Thursday, 29 August 2019 4:42 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: jayee.yap@premiumauto.com.sg; 'Chang Chee Sing' <claims@premiumauto.com.sg>
Subject: RE: FINAL REVISION - SLC1222L - OD AIG - SURVEYED 9 NOV 18

Hi Adrian,

Reminder

We have yet receive your confirmation of repair cost and days of repair for above vehicle.
Revised estimate was mailed to you on 17 Dec 2018, 21 Feb & 15 Jul 2019.
We sincerely appreciate your early closure.

Thanks & Best Regard
Carrine Leong
Claims Administrator

Premium Automobiles Pte Ltd (Reg No: 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183
e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	05 Nov 2018 12:04	Cim Veh Model Changed		[] Merimen Administrator
2	05 Nov 2018 12:04	Cim Created	Reg No: SLC1222L, Policy No: 1700088863, Acct Date: 2018/11/03, Claim Type: S C, Insurer: AIG Asia Pacific Insurance Pte. Ltd, (SG), Ins.Status => Notification. Created from SAS:MPA118142971	[I] Merimen Administrator
3	09 Nov 2018 17:04	Cim Registration Modified	Setl.Type:3->0, Claim Type:SC->OD,	[] CATHERINE CHONG KAI LING
4	09 Nov 2018 17:04	Adj Cim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CATHERINE CHONG KAI LING
5	09 Nov 2018 17:04	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CATHERINE CHONG KAI LING
6	09 Nov 2018 17:04	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/11/20	[A] CATHERINE CHONG KAI LING
7	09 Nov 2018 17:04	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] CATHERINE CHONG KAI LING
8	09 Nov 2018 17:04	Cim Registration Modified	Rep:1137->200611.	[A] CATHERINE CHONG KAI LING
9	09 Nov 2018 17:04	Cim Veh Model Changed	(205280) AUDI A3 999cc TFSI (A).	[A] CATHERINE CHONG KAI LING
10	09 Nov 2018 17:04	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CATHERINE CHONG KAI LING
11	12 Nov 2018 11:10	Cim Registration Modified	Init.Est.:->8,000 - 9,000.	[I] Mohd Zawaye, Norsazani
12	12 Nov 2018 14:48	Adj Rpt Initiated		[A] SHIAU CHAN
13	12 Nov 2018 14:48	Insured Phone No Updated	[None] -> [+6597505171]	[A] SHIAU CHAN
14	12 Nov 2018 14:48	Cim Dtl Modified	JPJ Reg. Date: -> 2017/12/19.	[A] SHIAU CHAN
15	12 Nov 2018 14:48	Cim Details Notified		[A] SHIAU CHAN
16	12 Nov 2018 15:13	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/11/20	[A] SHIAU CHAN
17	12 Nov 2018 15:14	Adj Mandate Request	Cur.Reg:13584.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
18	13 Nov 2018 13:19	Cim Registration Modified	Excess: -> 600.00, 2F Remarks: -> Not Applicable, GST: -> 7.00.	[I] Mohd Zawaye, Norsazani
19	13 Nov 2018 13:19	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
20	14 Nov 2018 17:00	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/11/20, Mandate Remarks: Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
21	14 Nov 2018 17:00	Adj Mandate Set	Approved:7938.00:Re-inspection to be done for damage check and supplementary items / labour.Reinsp:Yes.	[I] Koh, Victor-CK
22	21 Dec 2018 11:35	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/11/20	[A] SHIAU CHAN
23	21 Dec 2018 11:36	Adj Mandate Request	Cur.Reg:9974.96:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY APPROVE ON REPAIR COST OF \$9,974.96.	[A] SHIAU CHAN
24	31 Jan 2019 08:44	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2018/11/20, Mandate Remarks: Replacement of front lock carrier + R&R headlamp 2 days. Total labour 3 days at \$1500.00. To amend.	[I] Koh, Victor-CK
25	31 Jan 2019 08:44	Adj Mandate Set	Maintained:Replacement of front lock carrier + R&R headlamp 2 days. Total labour 3 days at \$1500.00. To amend.	[I] Koh, Victor-CK
26	31 Jan 2019 11:27	Adj Mandate Request	Cur.Reg:9974.96:Dear Victor, According to our surveyor, replacement for FRONT BUMPER (1 day), 2 HEADLAMP (1 day), LOCK CARRIER (2.5 days). Total labour at \$2,250.00. Hope above clarify.	[A] SHIAU CHAN
27	07 Feb 2019 08:22	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2018/11/20, Mandate Remarks: Replacement of front lock carrier + R&R headlamp 2 days. Total labour 3 days at \$1500.00. To amend. Justify why Lock Carrier needed 2.5 days?	[I] Koh, Victor-CK

AUDIT TRAIL				
No.	On	Audit	Remarks	By
28	07 Feb 2019 08:22	Adj Mandate Set	Maintained:Replacement of front lock carrier + R&R headlamp 2 days. Total labour 3 days at \$1500.00. To amend, Justify why Lock Carrier needed 2.5 days?	[I] Koh, Victor-CK
29	09 May 2019 15:08	Adj Mandate Request	Cur.Req:9974.96:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY APPROVE ON REPAIR COST OF \$9,974.96.	[A] SHIAU CHAN
30	27 May 2019 14:07	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2018/11/20. Mandate Remarks: Replacement of front lock carrier + R&R headlamp 2 days. Total labour 3 days at \$1500.00. To amend, Justify why Lock Carrier needed 2.5 days?	[I] Koh, Victor-CK
31	27 May 2019 14:07	Adj Mandate Set	Maintained:Replacement of front lock carrier + R&R headlamp 2 days. Total labour 3 days at \$1500.00. To amend, Justify why Lock Carrier needed 2.5 days?	[I] Koh, Victor-CK
32	23 Sep 2019 09:01	Adj Mandate Request	Cur.Req:9974.96:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY APPROVE ON REPAIR COST OF \$9,974.96.	[A] SHIAU CHAN
33	30 Sep 2019 14:42	Adj Mandate Set	Approved:9974.96.	[I] Koh, Victor-CK

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1971796	12 Nov 2018 14:48:11	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLC1222L		10.70

View Received Message

This mail is associated with :

***SLC1222L (2386370232SG)**

GD

Nov 3 2018 11:45PM

[TAN CHIEW BOO]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 07/02/2019 08:22 AM.

To LKK_HQ

Subject Alert - Adj Mandate Maintained - SLC1222L - Claim Handler: Mohd Zawaye, Norsazani

Maintained: Replacement of front lock carrier + R&R headlamp 2 days. Total labour 3 days at \$1500.00. To amend. Justify why Lock Carrier needed 2.5 days?

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SLC1222L (2386370232SG)**

OD

Nov 3 2018 11:45PM

[TAN CHIEW BOO]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 31/01/2019 08:44 AM.

To LKK_HQ

Subject Alert - Adj Mandate Maintained - SLC1222L - Claim Handler: Mohd Zawaye, Norsazani

Maintained: Replacement of front lock carrier + R&R headlamp 2 days. Total labour 3 days at \$1500.00. To amend,

DOCUMENTS SUMMARY

There are no documents.

Front Bumper : 1 Days
2 Headlamp : 1 Days
Lock Carrier : 2.5 Days

4.5 Days.

View Received Message

This mail is associated with :

***SGX9476S (2313987226SG)**

OD

Nov 10 2018 12:00AM

[LIM OI LENG]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 07/02/2019 08:21 AM.

To LKK_HQ

Subject Alert - Adj Mandate Maintained - SGX9476S - Claim Handler: Mohd Zawaye, Norsazani

Maintained: Replacement of front lock carrier additional of 1 days only. Total labour at \$2250.00. To amend. Justify why Lock Carrier needed 2.5 days?

DOCUMENTS SUMMARY

There are no documents.

Shiau Chan (LKKAUTO)

From: Koh, Victor-CK <Victor-CK.Koh@aig.com>
Sent: Thursday, 31 January 2019 2:52 PM
To: Shiau Chan (LKKAUTO)
Subject: RE: KINDLY ASSIST ON THE AUTHORISATION

Hi Shiau Chan,

Refer to below.

Thanks & Regards

Victor Koh
AIG
Claims Technical Controller
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120
Tel +65 6419 1785 | Fax +65 68357416
Victor-ck.koh@aig.com | www.aig.com

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Thursday, January 31, 2019 11:30 AM
To: Koh, Victor-CK
Subject: RE: KINDLY ASSIST ON THE AUTHORISATION

Dear Victor,

SGX 9476S - According to our surveyor, replacement for FRONT BUMPER + BONNET + FENDER (3 days), HEADLAMP (0.5 day), LOCK CARRIER (2.5 days). Total labour at \$3,000.00. – 1 day for one panel so lock carrier should be at 1 day as well why is it 2.5 days. No acceptable.

SLC 1222L - According to our surveyor, replacement for FRONT BUMPER (1 day), 2 HEADLAMP (1 day), LOCK CARRIER (2.5 days). Total labour at \$2,250.00. – same as above.

Hope above clarify.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Koh, Victor-CK <Victor-CK.Koh@aig.com>
Sent: Thursday, 31 January 2019 10:22 AM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: RE: KINDLY ASSIST ON THE AUTHORISATION

Hi Shiau Chan,

Refer to below.

View Received Message

This mail is associated with :

***SGX9476S (2313987226SG)**

OD

Nov 10 2018 12:00AM

[LIM OI LENG]

Premium Automobiles Pte Ltd

Reply Reply All Mark as Unread Print Message Delete Message Forward

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 31/01/2019 08:35 AM.

To LKK_HQ

Subject Alert - Adj Mandate Maintained - SGX9476S - Claim Handler: Mohd Zawaye, Norsazani

Maintained: Replacement of front lock carrier additional of 1 days only. Total labour at \$2250.00. To amend.

DOCUMENTS SUMMARY

There are no documents.

Front Bumper, Bonnet, Fender : 3 Days
 Headlamp : 0.5 Days.
 Lock Carrier : 2.5 Days.

 6 Days.
 6 x 500 = 3000.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 15 November 2018 11:15 AM
To: 'Claims'; SUR
Subject: RE: SLC 1222 L Own Damage Claims

Dear Tony,

As instructed by our client, please proceed to repair the insured vehicle **SLC 1222L (excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Thursday, 15 November 2018 10:20 AM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: RE: SLC 1222 L Own Damage Claims

Dear Shiau Chan,

Any update on repair approval?

Thank you.

Best Regards,

Tony Foong

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	05 Nov 2018 12:04	Cim Veh Model Changed		[I] Merimen Administrator
2	05 Nov 2018 12:04	Cim Created	Reg No: SLC1222L. Policy No: 1700088863. Acct Date: 2018/11/03. Claim Type: S C. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MPA118142971	[I] Merimen Administrator
3	09 Nov 2018 17:04	Cim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD:	[I] CATHERINE CHONG KAI LING
4	09 Nov 2018 17:04	Adj Cim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[I] CATHERINE CHONG KAI LING
5	09 Nov 2018 17:04	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CATHERINE CHONG KAI LING
6	09 Nov 2018 17:04	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/11/20	[A] CATHERINE CHONG KAI LING
7	09 Nov 2018 17:04	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] CATHERINE CHONG KAI LING
8	09 Nov 2018 17:04	Cim Registration Modified	Rep:1137->200611.	[A] CATHERINE CHONG KAI LING
9	09 Nov 2018 17:04	Cim Veh Model Changed	(205280) AUDI A3 999cc TFSI (A).	[A] CATHERINE CHONG KAI LING
10	09 Nov 2018 17:04	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CATHERINE CHONG KAI LING
11	12 Nov 2018 11:10	Cim Registration Modified	Init.Est.->8,000 - 9,000.	[I] Mohd Zawaye, Norsazani
12	12 Nov 2018 14:48	Adj Rpt Initiated		[A] SHIAU CHAN
13	12 Nov 2018 14:48	Insured Phone No Updated	[None] -> [+6597505171]	[A] SHIAU CHAN
14	12 Nov 2018 14:48	Cim Dtl Modified	JPJ Reg. Date: -> 2017/12/19.	[A] SHIAU CHAN
15	12 Nov 2018 14:48	Cim Details Notified		[A] SHIAU CHAN
16	12 Nov 2018 15:13	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/11/20	[A] SHIAU CHAN
17	12 Nov 2018 15:14	Adj Mandate Request	Cur.Reg:13584.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
18	13 Nov 2018 13:19	Cim Registration Modified	Excess: -> 600.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Mohd Zawaye, Norsazani
19	13 Nov 2018 13:19	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
20	14 Nov 2018 17:00	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/11/20. Mandate Remarks: Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
21	14 Nov 2018 17:00	Adj Mandate Set	Approved:7938.00:Re-inspection to be done for damage check and supplementary items / labour.Reinsp:Yes.	[I] Koh, Victor-CK

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1971796	12/11/2018 14:48	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLC1222L		10.70

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0734E
Vehicle Details	
Vehicle No.:	SLC1222L
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Nov 2018
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.0 TFSI S TRONIC (LED)
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	CHZ602908
Chassis No.:	WAUZZZ8V7J1032826
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$23,892.00
Original Registration Date:	19 Dec 2017
First Registration Date:	19 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$15,449.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Dec 2027
PARF Rebate Amount:	\$11,586.00
Intended COE Rebate Details	
COE Expiry Date:	18 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,339.00
COE Rebate Amount:	\$38,526.00
Total Rebate Amount:	\$50,112.00

The information contained herein is correct as at 12 Nov 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/11/2018 11:43
Date Of Accident	03/11/2018 23:45
Exact Location Of Accident	AYE (TUAS) TOWARDS CHECKPOINT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC1222L
Insured/Policyholder	
Name Of Registered Owner	TAN CHIEW BOO
NRIC No	S7040734E
Email Address	EDDYTAN12@YAHOO.COM
Mobile Phone No	(LOCAL) +65-97505171
Alternative Phone No	OTHERS-97505171

Vehicle Particulars

Manufacturer	AUDI
Model	A3 SEDAN 1.0 TFSI 8V
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700088863
Cover Note Number	

Driver

Name of Driver	GOH YANCHE
NRIC No	S9508978Z
Date Of Birth	13/03/1995
Occupation	INDOOR
Date Of Driving Pass	28/10/2014
Driving Experience	4 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91939323
Fax Number	
Contact Number	
Email Address	YAN_CHE95@HOTMAIL.COM

Address	BLK 485C CHOA CHU KANG AVENUE 5 #06-126
Postcode	683485
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	FRIEND
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT BY FALLEN TREE / OTHER OBJECTS
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (including Driver)	2
Passenger 1	NAME: : TAN YAN MING GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

DRIVING ON THE HIGHWAY, WHEN SPOTTED WOODEN PLANK, IT WAS TOO LATE TO AVOID. THE WOODEN PLANK FLEW INTO THE BUMPER.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	
Details Of Properties	WOODEN PLANK
Vehicle Category	NA/UNKNOWN
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/ran be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

07/11/18

1050 hrs

Reporting Centre Personnel's Signature
Name: Tommy Poon
NRIC/FIN No.: G2040197X



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Driving on the Highway when ~~first~~ spotted wooden plank,
was too late to avoid. ~~the plank~~ The wooden plank flew into
the bumper.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____

Date & Time:

Driver's Signature _____

(if driver is not the policyholder)

Date & Time: 05/11/18

1050 L.



Reporting Centre Personnel's Signature

Name: Tom Fears

NRIC/FIN No: 670401471

Accident Photo





CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : TAN CHIEW BOO
Period of Insurance : 19 Dec 2017 To 18 Dec 2019
Engine No. : CHZ602908
Chassis No. : WAUZZZ8V7J1032826

Vehicle No. : SLC1222L
Policy No. : 1700088863
Endorsement No. :
Issued Date : 27 Dec 2017

ABOUT THE COVER

Make/Model : AUDI A3 Sedan 1.0 TFSI S tronic
Engine Capacity/Tonnage : 999.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2017
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
 b) Any other person who is driving at the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods (other than samples in connection with any trade or business) or use for any purpose in connection with Motor Trade.

Limit of Use 1500cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 85 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

TAN CHIEW BOO - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

LAudi Customer Service Centre, Add: 36 Ulu Road 1 Singapore 408699 E3662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65-6138 8200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG Ulu Mobile App. Simply search and download AIG Ulu from iTunes or Google play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: OVERSEA-CHINESE BANKING CORPN LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125211

PREMIUM LEASING - NC
 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.



Manile

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

Shafiqul Islam

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1269/2018/JT
Date : 9-Nov-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Tan Chiew Boo
Address : Blk 101 Hillview Rise
#23-03
Singapore 667981
Telephone : HP +65 9750 5171
Type of Claim : Own Damage Claim
Policy No. : 1700088863
Vehicle No : **SLC 1222 L**
Model Code : Audi A3 1.0 TFSI
Model / Year : Dec-17
Engine No : CHZ 602908
Chassis No : WAUZZZ8V7J1032826
Mileage :
Date In :
Liability :
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 3-Nov-18
Place of Accident : AYE (Tuas) towards Checkpoint

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLC 1222 L

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓
2	To remove and renew aircond condenser, radiator, additional radiator, electrical fans and control unit. To carry out vacuum/regas and to pressurize cooling system.	S/N \$ 1,000.00 ✓
3	To dismantle and renew front bumper. Renew front lock carrier and align to position. Re-organize front crash management components. Reinstall all parts removed.	\$ 3,000.00 2790 500
4	To respray front bumper.	\$ 800.00 550
5	To carry out diagnostic checks.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ <u>5,352.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLC 1222 L.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>distorted</i>	S 1,739.00	✓ 1391.70
2	FRONT BUMPER FIXING PARTS <i>Not New</i>	S 161.00	? X
3	FRONT BUMPER GUIDE - LHS/RHS <i>New</i>	S 66.00	X
4	FRONT BUMPER LOWER GRILLE - CENTRE <i>Crashed</i>	S 140.00	✓ 112
5	FRONT BUMPER CLOSING ELEMENT <i>Crashed</i>	S 460.00	✓ 368
6	FRONT BUMPER INNER PIECE - LHS/RHS <i>Not New</i>	S 508.00	? X
7	FRONT BUMPER LOWER TRIM - LHS/RHS <i>2H Dgtd</i>	S 280.00	? 140 111.60
8	FRONT WHEEL HOUSE LINER ADAPTOR - LHS/RHS <i>Not New</i>	S 64.00	? X
9	RADIATOR GRILLE <i>Crashed</i>	S 1,239.00	✓ 991.70
10	RADIATOR GRILLE BACK PIECE <i>Not New</i>	S 167.00	? X
11	AIR GRILLE - LHS/RHS <i>LH Missing</i>	S 328.00	164 131.20
12	FOAM FILLER PIECE <i>Not New</i>	S 162.00	? X
13	FRONT REINFORCEMENT BEAM <i>Not New</i>	S 633.00	? X
14	FRONT BUMPER TOP COVER <i>New</i>	S 105.00	X
16	A/C & CAUTION SIGN STICKER <i>New</i>	S 19.00	X 14.16 ✓
17	NOISE INSULATION PAN <i>Not New</i>	S 226.00	? X
18	LOCK CARRIER <i>Crashed</i>	S 638.00	? 510 ✓
19	LOCK CARRIER AIR GUIDE - LHS/RHS <i>Deformed.</i>	S 40.00	? 31.84 ✓
20	COOLANT <i>New</i>	4 S 133.00	✓ 65.28
SUB-TOTAL SPARE PARTS		S 7,108.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLC 1222 L.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	A/C CONDENSER <i>Painted</i>	\$ 468.00	<i>✓ 374</i>
22	RADIATOR <i>Painted</i>	\$ 828.00	<i>✓ 662.40</i>
23	ADDITIONAL RADIATOR <i>Painted</i>	\$ 799.00	<i>✓ 639.20 ✓</i>
24	RADIATOR FAN <i>2H new</i>	\$ 1,425.00	<i>✓ X</i>
25	WATER WASHER RESEVOIR <i>2H new</i>	\$ 177.00	<i>✓ X</i>
26	WATER HOSE <i>new</i>	\$ 57.00	<i>✓</i>
27	HEADLIGHT WASHER - LHS/RHS <i>Not Nec.</i>	\$ 246.00	<i>✓ X</i>
28	FRONT NO. PLATE <i>new</i>	S/N \$ 25.00	<i>✓ 108</i>
29	SUNDRIES <i>Nec.</i>	\$ 400.00	<i>✓ 120.88 ✓</i>
TOTAL SPARE PARTS		:	\$ 11,533.00
TOTAL LABOUR CHARGES		:	\$ 5,352.00
GRAND TOTAL		:	\$ 16,885.00

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

16960

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 09/11/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1269/2018/JT
Date : 9-Nov-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

7 days - ok - jb - 17 Dec 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Tan Chiew Boo
Address : Blk 101 Hillview Rise
#23-03
Singapore 667981
Telephone : HP +65 9750 5171
Type of Claim : Own Damage Claim
Policy No. : 1700088863
Vehicle No : **SLC 1222 L**
Model Code : Audi A3 1.0 TFSI
Model / Year : Dec-17
Engine No : CHZ 602908
Chassis No : WAUZZZ8V7J1032826
Mileage :
Date In :
Liability :
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 3-Nov-18
Place of Accident : AYE (Tuas) towards Checkpoint

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLC 1222 L

S/N	Nature of Jobs	Estimated Charges			
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	360.00	\$	360.00
2	To remove and renew aircond condenser, radiator, additional radiator, electrical fans and control unit. To carry out vacuum/regas and to pressurize cooling system.	S/N \$	1,000.00	\$	1,000.00
3	To dismantle and renew front bumper. Renew front lock carrier and align to position. Re-organize front crash management components. Reinstall all parts removed. <i>(Lock carrier replacement with R/l front fittings)</i>	\$	3,000.00	\$	2,250.00
4	To respray front bumper,	\$	800.00	\$	550.00
5	To carry out diagnostic checks.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 5,352.00	\$	4,352.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLC 1222 L.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,739.00	\$ 1,391.20
2	FRONT BUMPER FIXING PARTS	\$ 161.00	
3	FRONT BUMPER GUIDE - LHS/RHS	\$ 66.00	
4	FRONT BUMPER LOWER GRILLE - CENTRE	\$ 140.00	\$ 112.00
5	FRONT BUMPER CLOSING ELEMENT	\$ 460.00	\$ 368.00
6	FRONT BUMPER INNER PIECE - LHS/RHS	\$ 508.00	
7	FRONT BUMPER LOWER TRIM - LHS/RHS	\$ 280.00	\$ 111.60
8	FRONT WHEEL HOUSE LINER ADAPTOR - LHS/RHS	\$ 64.00	
9	RADIATOR GRILLE	\$ 1,239.00	\$ 991.20
10	RADIATOR GRILLE BACK PIECE	\$ 167.00	
11	AIR GRILLE - LHS/RHS	\$ 328.00	\$ 131.20
12	FOAM FILLER PIECE	\$ 162.00	
13	FRONT REINFORCEMENT BEAM	\$ 633.00	
14	FRONT BUMPER TOP COVER	\$ 105.00	
16	A/C & CAUTION SIGN STICKER	\$ 19.00	\$ 14.16
17	NOISE INSULATION PAN	\$ 226.00	
18	LOCK CARRIER	\$ 638.00	\$ 510.00
19	LOCK CARRIER AIR GUIDE - LHS/RHS	\$ 40.00	\$ 31.84
20	COOLANT	4 \$ 133.00	\$ 65.28
SUB-TOTAL SPARE PARTS		\$ 7,108.00	\$ 3,726.48

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLC 1222 L.

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		<i>c/f</i>	\$	3,726.48
21	A/C CONDENSER		\$ 468.00	\$ 374.00
22	RADIATOR		\$ 828.00	\$ 662.40
23	ADDITIONAL RADIATOR		\$ 799.00	\$ 639.20
24	RADIATOR FAN		\$ 1,425.00	
25	WATER WASHER RESEVOIR		\$ 177.00	
26	WATER HOSE		\$ 57.00	
27	HEADLIGHT WASHER - LHS/RHS		\$ 246.00	
28	FRONT NO. PLATE	S/N	\$ 25.00	\$ 100.00
30	SUNDRIES		\$ 400.00	\$ 120.88
TOTAL SPARE PARTS		:	\$ 11,533.00	\$ 5,622.96
TOTAL LABOUR CHARGES		:	\$ 5,352.00	\$ 4,352.00
GRAND TOTAL		:	\$ 16,885.00	\$ 9,974.96

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLC 1222 L

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1269/2019/NH

9 October 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLC 1222 L, Audi A3 SEDAN 1.0 TFSI.

With reference to the above-mentioned vehicle, no. **SLC 1222 L**, claimant, **Mr. Tan Chew Boo**, please find the related document per attached.

1. A copy of the Original invoice no. 85014324 – S\$10,031.21.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SLC 1222 L

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6541 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

C

INS TAX INVOICE

Page 1 10:31

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014324 Date : 07/10/2019 Order : SLC1222L Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SLC1222L (V 36387)	Regn Date: 19/12/2017	Mileage: 34182	WIP No.: 30956
Model: A3 SEDAN 1.0 TFSI SVMANG	Chassis: WAUZZZ8V7J1032826	Engine: CHZ 602908	Dept: U
You have been assisted by :- UB-Tony Foong (33)			

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE(SPECIAL PLATES)	100.00	1.00	100.00
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO REMOVE AND RENEW AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. TO CARRY OUT VACUUM/REGAS AND TO PRESSURISE COOLING SYSTEM	1000.00	1.00	1,000.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER, RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. REORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	2250.00	1.00	2,250.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER	550.00	1.00	550.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8V0010515A	STICKER Less 020%	1.00	6.10	4.88
X	A5Q0816411AS	CONDENSER Less 020%	1.00	467.50	374.00
X	A5Q0121251GD	RADIATOR Less 020%	1.00	828.00	662.40
X	A5Q0121251GB	RADIATOR Less 020%	1.00	799.00	639.20
X	A8V5807233B	PLATE Less 020%	1.00	460.00	368.00
X	A8V0805588A	CARRIER Less 020%	1.00	637.50	510.00
X	AG A13040M2	PREMIX-COOLANT Less 020%	4.00	20.40	65.28
X	A8V5807065R GRU	COVER Less 020%	1.00	1739.00	1,391.20
X	A8K0010520A	PLATE Less 020%	1.00	11.60	9.28
X	A8V3853651AA3FZ	GRILLE Less 020%	1.00	1239.00	991.20
X	A8V0121285A	AIR DUCT Less 020%	1.00	9.60	7.68
X	A8K0837199	CLIP Less 020%	10.00	0.70	5.60

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6386 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

C

INS TAX INVOICE

Page 2 10:31

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014324 Date : 07/10/2019 Order : SLC1222L Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SLC1222L (V 36387) Regn Date: 19/12/2017 Mileage: 34182 WIP No.: 30956

Model: A3 SEDAN 1.0 TFSI 8VMANG Chassis: WAUZZZ8V7J1032826 Engine: CHZ 602908 Dept: U

You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
X	A8V5807533A	(S.K) COVERSTRIP	Less 020%	1.00	139.50
X	A8V0121230	SEAL	Less 020%	1.00	6.80
X	A8V0820536	BRACKET	Less 020%	1.00	15.60
X	A820820535A	TEMP.SENS.	Less 020%	1.00	51.50
X	A8V5807681AA9B9	GRILL	Less 020%	1.00	164.00
X	A4D0260749B	WASHER	Less 020%	1.00	2.90
X	A3D0260749C	WASHER	Less 020%	1.00	3.80
X	A8V5807647B 9B9	GRILLE	Less 020%	1.00	140.00
X	A000979940	CONNECTOR (WHITE)	Less 020%	2.00	9.00
X	A000979025EA	WIRES	Less 020%	1.00	27.80
X	A8K0973702	HOUSING	Less 020%	1.00	8.10
X	A8V0121284K	AIR DUCT	Less 020%	1.00	19.90
X	A8V0121283K	AIR DUCT	Less 020%	1.00	19.90

Parts 5,522.96
Labour 0.00
Sublet 4,452.00
Menus 0.00
Lubricant 0.00

Sub-Total 9,374.96

7% GST 656.25

Grand Total 10,031.21



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLC 1222 L

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1269/2018/TF
22 November 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 Sedan 1.0 TFSI 8V
Vehicle Chassis No. : WAUZZZ8V7J1032826
Vehicle Regn No. : **SLC 1222 L**
Vehicle Mileage : 18867 KM
Vehicle Owner : Mr. Tan Chiew Boo
Certificate No : 1700088863
Policy Excess : S\$642.00 (inclusive 7% GST)
Accident Date : 3 November 2018
Place : AYE (Tuas) towards Checkpoint
Repair Cost : \$ 10,031.21
WIP No. : 30956
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time :
Date : 24/11/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Nov 2018		09 Nov 2018 17:04 Edit Adj Rpt	\$99,974.96 Edit Estimates	\$99,974.96 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	TAN CHIEW BOO, ID: S7040734E, Tel: +6597505171								
Vehicle Reg. No.:	SLC1222L	Date of Loss:	03/11/2018 23:00 - :59 [10 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 2386370232SG	Policy/Cover Note No.:	1700088863 (Comprehensive)						
		Excess:	S\$600.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mohd Zawaye, Norsazani] Norsazani.Zawaye@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 20/11/2018]								
Driver/Custodian:	GOH YANCHE (23 / Male), NRIC: S9508978Z, Tel: +6591939323 Email: YAN_CHE95@HOTMAIL.COM								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (30/09/2019): Alert - Adj Mandate Approved (\$9974.96) - SLC1222L - Claim Handler: Mohd Zawaye... - AIG_SG (27/05/2019): Alert - Adj Mandate Maintained - SLC1222L - Claim Handler: Mohd Zawaye, Norsazan... - AIG_SG (07/02/2019): Alert - Adj Mandate Maintained - SLC1222L - Claim Handler: Mohd Zawaye, Norsazan... - AIG_SG (31/01/2019): Alert - Adj Mandate Maintained - SLC1222L - Claim Handler: Mohd Zawaye, Norsazan... - AIG_SG (14/11/2018): Alert - Adj Mandate Approved (\$7938.00) - SLC1222L - Claim Handler: Mohd Zawaye... - AIG_SG (13/11/2018): SLC1222L / OD / 03/11/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLC1222L (2386370232SG)
OD
Nov 3 2018 11:45PM
[TAN CHIEW BOO]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View	Use Viewer	
Assessment Reports											1 per page		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print	
1	12/11/18 15:13	Adjuster Immediate Advice									1 Load HTM		
2	21/12/18 11:35	Adjuster Immediate Advice									1 Load HTM		
Photos/Images											3 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print	
1	12/11/18 15:08	General View									1 Load JPG		
2	12/11/18 15:08	Chassis Number									1 Load JPG		
3	12/11/18 15:08	General View									1 Load JPG		
4	12/11/18 15:08	General View									1 Load JPG		
5	12/11/18 15:08	General View									1 Load JPG		
6	12/11/18 15:08	General View									1 Load JPG		
7	12/11/18 15:08	General View									1 Load JPG		
8	12/11/18 15:08	General View									1 Load JPG		
9	12/11/18 15:08	General View									1 Load JPG		
10	12/11/18 15:08	General View									1 Load JPG		
11	12/11/18 15:08	General View									1 Load JPG		
12	12/11/18 15:08	General View									1 Load JPG		
13	12/11/18 15:08	General View									1 Load JPG		
14	12/11/18 15:08	General View									1 Load JPG		
15	12/11/18 15:08	General View									1 Load JPG		
16	12/11/18 15:08	General View									1 Load JPG		
17	12/11/18 15:08	General View									1 Load JPG		
18	12/11/18 15:08	General View									1 Load JPG		
19	12/11/18 15:08	General View									1 Load JPG		
20	12/11/18 15:08	General View									1 Load JPG		
21	12/11/18 15:08	General View									1 Load JPG		
22	19/12/18 09:29	Reinspection Photo									1 Load JPG		
23	19/12/18 09:29	Reinspection Photo									1 Load JPG		
24	19/12/18 09:29	Reinspection Photo									1 Load JPG		
25	19/12/18 09:29	Reinspection Photo									1 Load JPG		
26	19/12/18 09:29	Reinspection Photo									1 Load JPG		
27	19/12/18 09:29	Reinspection Photo									1 Load JPG		
28	19/12/18 09:29	Reinspection Photo									1 Load JPG		
Documentation											1 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print	
1	12/11/18 15:07	Singapore Accident Statement									1 Load PDF		
2	12/11/18 15:07	Certificate of Insurance									1 Load PDF		
3	12/11/18 15:07	Driver's Driving License									1 Load PDF		
4	12/11/18 15:07	ESTIMATE									1 Load PDF		
5	13/11/18 11:53	UNDERTAKING FORM									1 Load PDF		
6	13/11/18 12:02	INTERVIEW FORM									1 Load PDF		
7	21/12/18 11:32	REVISED ESTIMATE									1 Load PDF		
8	18/10/19 10:21	WORKSHOP INVOICE									1 Load PDF		
9	18/10/19 10:21	DISCHARGE VOUCHER									1 Load PDF		

Linked Accident Report Documents

			View	Use Viewer	
Assessment Reports			1 per page		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	05/11/18 12:04	Accident Statement		Load HTM	
Photos/Images			3 per page		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	05/11/18 11:58	Accident Photo		Load JPG	
2	05/11/18 11:58	Accident Photo		Load JPG	
3	05/11/18 11:58	Accident Photo		Load JPG	
4	05/11/18 11:58	Accident Photo		Load JPG	
5	05/11/18 11:58	Accident Photo		Load JPG	
6	05/11/18 11:58	Accident Photo		Load JPG	
7	05/11/18 11:58	Accident Photo		Load JPG	
8	05/11/18 11:58	Accident Photo		Load JPG	
9	05/11/18 11:58	Accident Photo		Load JPG	
10	05/11/18 11:58	Accident Photo		Load JPG	
Documentation			1 per page		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	05/11/18 11:52	Sketch Plan		Load JPG	
2	05/11/18 11:52	Sketch Plan #2		Load JPG	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18020347/AQBN2

Date: 18/10/2019

REFERENCE

Insured/Claimant: TAN CHIEW BOO Policy No: 1700088863
Date of Loss: 03/11/2018 Nature of Claim: OD Claim No: 2386370232SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLC1222L
Make & Model: AUDI A3, 999cc TFSI (A) Engine No: CHZ602908
Reg. Date: 19/12/2017 (Man. Year: 2017) Chassis No: WAUZZZ8V7J1032826
Colour: Grey Odometer: 18867 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$100,000.00
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	11,608.00	5,622.96	5,985.04	51.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,352.00	4,352.00	1,000.00	18.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,960.00	9,974.96	6,985.04	41.19
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	16,360.00	9,374.96	6,985.04	42.70
+ GST 7.00/7.00% (\$\$)	1,145.20	656.25	488.95	42.70
Nett Amount (\$\$)	17,505.20	10,031.21	7,473.99	42.70

INSPECTION

Date of Assignment: 09/11/2018
Date Inspected: 09/11/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Distorted	1,739.00 FS	*1,391.20 FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	161.00 FS	*- FS
3	2	*FRONT BUMPER GUIDE-LHS/RHS	Not Necessary	66.00 FS	*- FS
4	1	*FRONT BUMPER LOWER GRILLE-CENTRE	Cracked	140.00 FS	*112.00 FS
5	1	*FRONT BUMPER CLOSING ELEMENT	Cracked	460.00 FS	*368.00 FS
6	2	*FRONT BUMPER INNER PIECE-LHS/RHS	Not Necessary	508.00 FS	*- FS
7	1	*FRONT BUMPER LOWER TRIM-LHS/RHS	N/s Damaged	280.00 FS	*111.60 FS
8	2	*FRONT WHEEL HOUSE LINER ADAPTOR-LHS/RHS	Not Necessary	64.00 FS	*- FS
9	1	*RADIATOR GRILLE	Cracked	1,239.00 FS	*991.20 FS
10	1	*RADIATOR GRILLE BACK PIECE	Not Necessary	167.00 FS	*- FS
11	1	*AIR GRILLE-LHS/RHS	N/s Missing	328.00 FS	*131.20 FS
12	1	*FOAM FILLER PIECE	Not Necessary	162.00 FS	*- FS
13	1	*FRONT REINFORCEMENT BEAM	Not Necessary	633.00 FS	*- FS
14	1	*FRONT BUMPER TOP COVER	Not Necessary	105.00 FS	*- FS
15	1	*A/C & CAUTION SIGN STICKER	Necessary	19.00 FS	*14.16 FS
16	1	*NOISE INSULATION PAN	Not Necessary	226.00 FS	*- FS
17	1	*LOCK CARRIER	Cracked	638.00 FS	*510.00 FS
18	2	*LOCK CARRIER AIR GUIDE-LHS/RHS	Deformed	40.00 FS	*31.84 FS
19	4	*COOLANT	Necessary	133.00 FS	*65.28 FS
20	1	*A/C CONDENSER	Dented	468.00 FS	*374.00 FS
21	1	*RADIATOR	Dented	828.00 FS	*662.40 FS
22	1	*ADDITIONAL RADIATOR	Dented	799.00 FS	*639.20 FS
23	1	*RADIATOR FAN	Not Necessary	1,425.00 FS	*- FS
24	1	*WATER WASHER RESERVOIR	Not Necessary	177.00 FS	*- FS
25	1	*WATER HOSE	Not Necessary	57.00 FS	*- FS
26	2	*HEADLIGHT WASHER-LHS/RHS	Not Necessary	246.00 FS	*- FS
27	1	*FRONT NO PLATE	Necessary	100.00 FS	*100.00 FS
28	1	*SUNDRIES	Necessary	400.00 FS	*120.88 FS

F=Franchise part. S=SpcNetl.

Total Parts (\$\$) 11,608.00 5,622.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND RENEW AIRCOND CONDENSER,RADIATOR,ADDITIONAL RADIATOR,ELECTRICAL FANS AND CONTROL UNIT.TO CARRY OUT VACUUM/REGAS AND TO PRESSURIZE COOLING SYSTEM	New	1,000.00	1,000.00
3	TO DISMANTLE AND RENEW FRONT BUMPER.RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.RE-ORGANIZE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	3,000.00	2,250.00
4	TO RESPRAY FRONT BUMPER	New	800.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (S\$)			5,352.00	4,352.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >