

Surveyor

ASSIGNMENT (Office)

From (Person): WS Karen Tan of FCI Date/Time: 09/11/2018 1:02pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKZ 3089H Insured: SHD 4806Aat Workshop n/s Chun's Customcraft Tel: 6271 7054of Blk 1010 Bukit Merah Lane 3 # 01-105Policy No: _____ Claim No: D18008010MTSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 03-11-2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time: 09-11-2018 1:28pm Person Contacted: Sharon Vehicle: IN / OUT

| Date/Time | Action/Instruction (✓) Estimate |
|-----------------|---|
| | <u>SKZ 3089H - X</u> |
| | <u>SHD 4806A - X</u> |
| <u>15/11/18</u> | <u>Email preli revised to FCI</u> |
| <u>27/11/18</u> | <u>@ 4:11pm Sharon said vehicle has not send in for repair,</u> <u>pending liability</u> |


DATE: Tue 12/12/18

REF:

FCI

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____
(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.
Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT



Veh No: SK73089H Yr Regn: 2016 Jan.
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Maya de B. C.C.: 2488
Colour: Blue A/C: Insured / Std / NI / NA
Sp. Reading: 50796 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: SM69J103260 229286
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 225/55R17
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: _____ Rear: _____
R/Bal: 6 mm R/Bal: 6 mm
L/Bal: 6 mm L/Bal: 6 mm
D.O.A.: _____ D.O.I.: 14/11/18 @ 1250
Survey held at: Charns Coopers
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
Frt N/S
The UIC / Chassis frame / Body Structure affected due to collision:

Date / Time Action / Instruction

12/12/18 final fig \$4910.08 (Red 380, 19) confirmed by email [Signature]
- RECEIVED 12 DEC 2018 12/12/2018

Date/Time: File Pass to? ☐ : Preli. Report
☐ : Final Report

1) _____
Date/Time: File Return to? 2) 12/12 - typist

Report Format: CWS
Lump Sum / I.B.I.: (\$) 4910.08

Days Of Repair: 4
Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$) ☐ : Interview (\$) ☐ : Tech. Invs (\$) ☐ : Weekend (\$)

Survey Fee: _____
Transportation: _____
S + PS: _____
Photos: _____
Others: _____
TOTAL: _____

| |
|-------|
| 140 |
| 50 |
| 50+50 |
| 49 |
| 339 |



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18008010MFSH

Our ref: CS/FCI18020354/T1vb

Date: 15/11/2018

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO SKZ 3089H


We thank you for your instruction on 9/11/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 14/11/2018 at the premises of M/s CHARN'S CUSTOMCRAFT and have the following to report:-

| | |
|--------------------------|---------------|
| Workshop Estimate Amount | : S\$5,151.76 |
| Revised Estimate Amount | : S\$2,204.32 |
| "Check" Items Amount | : S\$2,567.44 |
| Total | : S\$ |
| Market Value | : S\$ |
| LTA Reimbursement Value | : S\$ |
| Nett Value | : S\$ |

Description of Damage:

The vehicle sustained damages at the front n/s portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automobile Assessor

MOTOR SURVEY ASSIGNMENT

| | | |
|---------------------------|---------------------------------------|--------------------------------------|
| Date | 09-11-2018 | Our Ref No. D18008010MFSH |
| Accident Date | 03-11-2018 | Claim Type. Third Party |
| Insured Vehicle | SHD4806A | Third Party Vehicle. SKZ3089H |
| Survey Location | BLK 1010 BUKIT MERAH LANE 3 #01-105 | |
| Contact Person. | SHARON LEE | |
| Contact No. | 62717054/ 62733304 | Fax No. 62736676 |
| Survey Type | WITHOUT PREJUDICE: LIABILITY UNCLEAR: | |
| Appointed Surveyor | LKK AUTO CONSULTANTS PTE LTD | |
| Contact Person | NA | Fax No. 68416315 |
| Contact Number. | NA | |

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

| | | |
|--------------------------|------------------------|--------------------------------|
| Cc : Workshop | CHARN'S CUSTOMCRAFT | Attention. NIL |
| Cc : TP Solicitor | NA | TP Solicitor Fax No. NA |
| Officer Incharge | KARENT | |

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 15 November 2018 12:30 PM
To: 'CWS Motor Claims'
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008010MFSH/1, SKZ 3089H
Attachments: SKZ 3089H PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SKZ 3089H
Date of survey: 14/11/2018
Number of days : 4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 9 November 2018 4:31 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008010MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 9 November, 2018 4:02 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008010MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 12 December 2018 1:50 PM
To: 'Charn's Customcraft'; Taufikh (LKKAUTO)
Cc: SUR
Subject: RE: Finalization - SKZ 3089 H - Mazda 6

Sensitivity: Confidential

Dear Sharon,

WITHOUT PREJUDICE

Confirmed \$4910.08 (before GST) @ 4 working days.

Kindly send Final invoice and all supporting documents to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Charn's Customcraft <charns@singnet.com.sg>
Sent: Tuesday, 11 December 2018 5:01 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: Finalization - SKZ 3089 H - Mazda 6
Importance: High
Sensitivity: Confidential

Hi

Kindly find attached for finalization.

Parts: \$3920.08

Lab: \$990.00

Total: \$4910.08 (before GST)

Please confirm

Thanks & Regards,
Sharon Lee
Charn's Customcraft
Tel: 6272 5429 Fax: 6273 6676
Email: charns@singnet.com.sg

GST Reg. No: M90367863L
Company Reg No: 25151300M

Veron Chen (LKKAUTO)

From: Charn's Customcraft <charns@singnet.com.sg>
Sent: Wednesday, 12 December 2018 2:48 PM
To: Veron Chen (LKKAUTO)
Subject: RE: Finalization - SKZ 3089 H - Mazda 6

Sensitivity: Confidential

Hi

OK accepted

Regards,
Rina Chua
CHARN'S CUSTOMCRAFT

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Wednesday, December 12, 2018 1:50 PM
To: Charn's Customcraft; Taufikh (LKKAUTO)
Cc: SUR
Subject: RE: Finalization - SKZ 3089 H - Mazda 6
Sensitivity: Confidential

Dear Sharon,

WITHOUT PREJUDICE

Confirmed \$4910.08 (before GST) @ 4 working days.

Kindly send Final invoice and all supporting documents to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Charn's Customcraft <charns@singnet.com.sg>
Sent: Tuesday, 11 December 2018 5:01 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: Finalization - SKZ 3089 H - Mazda 6
Importance: High
Sensitivity: Confidential

Hi

Kindly find attached for finalization.

Parts: \$3920.08

Lab: \$990.00

Total: \$4910.08 (before GST)

Please confirm

Thanks & Regards,

Sharon Lee

Charn's Customcraft

Tel: 6272 5429 Fax: 6273 6676

Email: charns@singnet.com.sg

GST Reg. No: M90367863L

Company Reg No: 25151300M

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 3533G

Vehicle Details

Vehicle No.: SKZ3089H
Vehicle to be Exported: Yes
Intended Deregistration Date: 30 Nov 2018
Vehicle Make: MAZDA
Vehicle Model: MAZDA6 4-DOOR SEDAN 2.5L SP6EAT SR LED
Primary Colour: Blue
Manufacturing Year: 2015
Engine No.: PY20705085
Chassis No.: JM6GJ1032G0229286
Maximum Power Output: 141.0 kW (189 bhp)
Open Market Value: \$23,566.00
Original Registration Date: 18 Jan 2016
First Registration Date: 18 Jan 2016
Transfer Count: 0
Actual ARF Paid: \$24,993.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 17 Jan 2026
PARF Rebate Amount: \$18,744.00

Intended COE Rebate Details

COE Expiry Date: 17 Jan 2026
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$60,003.00
COE Rebate Amount: \$42,774.00
Total Rebate Amount: \$61,518.00

The information contained herein is correct as at 07 Nov 2018

OK

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) (Singapore) (the "Act")
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 (Singapore)
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

This document forms part of your contract with us and should be read together with your Policy Schedule and your Policy Details. Do let us know if any of the details shown here need to be amended or updated.

| | |
|--|---|
| Certificate No. | : MT/00438748 |
| Type of Coverage / Driver Plan | : Car Comprehensive (Value Plus Plan) |
| 1) Vehicle Registration No. | : SKZ3089H |
| Chassis No. | : JM6GJ1032G0229286 |
| 2) Name of Policy Holder | : Jauhari, Saurabh |
| 3) Effective Date / Time of Commencement of Insurance for the Purpose of the Act | : 18/01/2018 00:00 |
| 4) Date/Time of Expiry of Insurance | : 17/01/2019 23:59 |
| 5) Persons or Classes of Persons Entitled to Drive | |
| (a) The Insured (b) Any named person under the policy who is driving on the Insured's order or with his permission. (c) Any authorised person, provided such person is aged 30 and above and holds a valid driving licence of 2 years or more, who is driving on the Insured's order or with his permission The person driving must have a valid driving licence to drive in Singapore and must not be under suspension or disqualification from driving. | |
| 6) Limitations as to use* | |
| Use only for private purposes, in accordance with the declared car usage stated on your Policy Schedule. The policy does not cover use for hire or reward, tuition, driving test, racing, pace-making, reliability trials, speed tests, the carriage of goods for payment or for any purpose in connection with the motor trade business. *Limitations rendered inoperative by Section 8 of the Act and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under this heading. | |
| Sum Insured | : Market Value |
| Own Damage Excess | : S\$ 800.00 (before any applicable GST) |
| Windscreen Excess | : S\$ 100.00 (before any applicable GST) |
| Choice of workshop | : My Workshop/ My Authorised Distributor Workshop |
| Finance company / Hire Purchase | : HONG LEONG FINANCE LTD |
| Main driver | : Jauhari, Saurabh |
| Named driver | : None |
| Important Note: This policy does not cover drivers below the age of 30 and drivers who hold a valid driving licence of less than 2 years with the exception of the named drivers above. | |

I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and the Road Transport Act, 1987 (Malaysia).

Issued on: 28/12/2017

Direct Asia Insurance (Singapore) Pte. Ltd.



Edip Okur
Chief Underwriting Officer

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S7583533G**

Name: **SAURABH JAUHARI**

Birth Date: **05 Jun 1975**

Issue Date: **28 Jan 2012**

002037921B

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S7583533G**

Name: **SAURABH JAUHARI**

Race: **INDIAN**

Date of birth: **05-06-1975**

Sex: **M**

Country/Place of birth: **INDIA**

S7583533G

SKZ 30-89H
3/1/18

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

| Class | Motorcycles | Motor cars | Motor tractors/vehicles | EFFECTIVE DATE |
|----------|---------------------------------------|---|-------------------------|----------------|
| Class 2B | Motorcycles <= 200 CC | | | 06 Jan 2015 |
| Class 2A | Motorcycles between 201 CC and 400 CC | | | 15 Dec 2017 |
| Class J | | Motor cars <= 3000 kg with <= 7 passengers, exclusive of the driver, and motor tractors/vehicles <= 2500 kg | | 06 Nov 2004 |

S7583533G

S / No. 9000311831

NP 428A

License No: S7583533G

9356564

NRIC No: **S7583533G**

Nationality: **INDIAN**

Date of issue: **16-01-2015**

BLK 50 CHOA CHU KANG NORTH 6 #15-01
SINGAPORE 689574

NRIC No: **S7583533G** Date: **05/05/2017**



創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars

BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

DA/FC(SHD4806A)

DOA: 03/11/2018@1840

MS FIRST CAPITAL INSURANCE PTE LTD

08/11/2018

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SKZ 3089 H - MAZDA 6 4-DOOR SEDAN 2.5L SP.6EAT SR LED

CHASSIS NO: JM6GJ1032G0229286 (01/2016)

- 1 pc Front headlamp LH
- 1 pc Front fender LH
- 1 pc Front bumper
- 1 pc Front bumper retainer LH

| | | |
|----|----------|-------|
| \$ | 3,209.30 | ✓ cat |
| \$ | 339.30 | bt |
| \$ | 1,154.10 | de |
| \$ | 24.50 | use |
| \$ | 4,727.20 | |
| \$ | 945.44 | |
| \$ | 3,781.76 | |

LESS 20%

Repair and putty front rim LH

| | | |
|----|--------|-----|
| \$ | 100.00 | 80. |
| \$ | 70.00 | 60 |

Alignment

Remove necessary parts: jacking, panel beating, repair and straighten front bumper, front fender LH & front bonnet

| | | |
|----|--------|-----|
| \$ | 600.00 | 400 |
|----|--------|-----|

Putty and respray front bumper, front fender LH & front bonnet

| | | |
|----|----------|-----|
| \$ | 600.00 | 450 |
| \$ | 5,151.76 | |
| \$ | 360.62 | |
| \$ | 5,512.38 | |

ADD 7% GST

Note: The above is an estimate only. IF other parts required during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Tanfer 97775749
-wp
14/11/18 @ 1250
4 days.
sure lkhauto.com.
* Resurvey before paint



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62738676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

DA/FC(SHD4806A)
DOA: 03/11/2018@1840

MS FIRST CAPITAL INSURANCE PTE LTD

08/11/2018

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

~~SKZ 3089 H~~ MAZDA 6 4-DOOR SEDAN 2.5L SP.6EAT SR LED

CHASSIS NO: JM6GJ1032G0229286 (01/2016)

1 pc Front headlamp LH
1 pc Front fender LH
1 pc Front bumper
1 pc Front bumper retainer LH

\$ 3,209.30 *2nd*

\$ 339.30 *bt*

\$ 1,154.10 *de*

\$ 24.50 *ue*

\$ 4,727.20

\$ 945.44

\$ 3,781.76

LESS 20%

Repair and putty front rim LH

\$ 100.00 *80*

Alignment

\$ 70.00 *60*

Remove necessary parts: jacking, panel beating, repair and straighten front bumper, front fender LH & front bonnet

\$ 600.00 *400*

Putty and respray front bumper, front fender LH & front bonnet

\$ 600.00 *450*

\$ 5,151.76

\$ 360.62

\$ 5,512.38

ADD 7% GST

Note: The above is an estimate only. IF other parts required during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

.....

* Fender inner shield LH
- \$115 *de*

* bp rivet x4 @ \$8.70 x4

* inner shield cup
x6 @ 3.85
x6

* Tanfer 97475749
- WP

14/11/18 @ 1250

4 days.

sure@lkauto.com

* Resing before paint



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars

BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

DA/FC(SHD4806A)

DOA: 03/11/2018@1840

MS FIRST CAPITAL INSURANCE PTE LTD

08/11/2018

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SKZ 3089 H - MAZDA 6 4-DOOR SEDAN 2.5L SP.6EAT SR LED

CHASSIS NO: JM6GJ1032G0229286 (01/2016)

Supplementary

1 pc Front fender inner shield LH
4 pcs Front bumper rivets @ \$8.70
6 pcs Front fender inner shield clips @ \$3.85

\$ 115.00

\$ 34.80

\$ 23.10

\$ 172.90

LESS 20%

\$ 34.58

\$ 138.32

ADD 7% GST

\$ 9.68

\$ 148.00

CHARN'S CUSTOMCRAFT

.....




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|---|-----------------------------|------------|---|
| MS FIRST CAPITAL INSURANCE LTD | | Ref : CS/FCI18020354/T1vbn2 | | |
| 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877 | | Date : 14-12-2018 | |  |
| | | Code : FCI2 | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SHD 4806A | Veh. Inspected | SKZ 3089H | |
| Policy No. | | Coverage (\$) | 0.00 | |
| Claim No. | D18008010MFSH | Excess (\$) | 0.00 | |
| Assign From | KARENT | Assign Date | 09/11/2018 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | MAZDA 6 | c.c | 2488 | |
| Engine No. | HIDDEN | Year of Reg. | 2016 | |
| Chassis No. | JM6GJ1032G0229286 | Colour | BLUE | |
| Odometer | 50796 | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 225/55 R17 | BRIDGESTONE | 6 mm | |
| L/H Front Tyre | 225/55 R17 | BRIDGESTONE | 6 mm | |
| R/H Rear Tyre | 225/55 R17 | BRIDGESTONE | 6 mm | |
| L/H Rear Tyre | 225/55 R17 | BRIDGESTONE | 6 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 03/11/2018 | Inspection Date | 14/11/2018 | |
| Survey held at | CHARN'S CUSTOMCRAFT BLK 1010 BUKIT MERAH LANE 3 #01-105 SINGAPORE 159724 | | | |
| 5a. Remarks | | | | |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 4 Working Days | | |

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 3089H

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---|-----------|---------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | FRONT HEADLAMP LH | CUT | 3,209.30 | 3,209.30 |
| 1 | FRONT FENDER LH | BENT | 339.30 | 339.30 |
| 1 | FRONT BUMPER | DEFORMED | 1,154.10 | 1,154.10 |
| 1 | FRONT BUMPER RETAINER LH | NECESSARY | 24.50 | 24.50 |
| 1 | FRONT FENDER INNER SHIELD LH (ADDITIONAL) | DEFORMED | 115.00 | 115.00 |
| 4 | FRONT BUMPER RIVETS @\$8.70 (ADDITIONAL) | NECESSARY | 34.80 | 34.80 |
| 6 | FRONT FENDER INNER SHIELD CLIPS @\$3.85 (ADDITIONAL) | NECESSARY | 23.10 | 23.10 |
| | LESS 20% DISCOUNT | | -980.02 | -980.02 |
| | | | 3,920.08 | 3,920.08 |
| | LABOUR | | | |
| | REPAIR AND PUTTY FRONT RIM LH. | | 100.00 | 80.00 |
| | ALIGNMENT. | | 70.00 | 60.00 |
| | REMOVE NECESSARY PARTS; JACKING, PANEL BEATING, REPAIR AND STRAIGHTEN FRONT BUMPER, FRONT FENDER LH & FRONT BONNET. | | 600.00 | 400.00 |
| | PUTTY AND RESPRAY FRONT BUMPER, FRONT FENDER LH & FRONT BONNET. | | 600.00 | 450.00 |
| | | | 1,370.00 | 990.00 |
| | GRAND TOTAL | | 5,290.08 | 4,910.08 |
| RECOMMENDED COST OF REPAIRS | | | | 4,910.08 |

Report Ref No. CS/FC118020354/T1vbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.