OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel: +65 6472 1313 Fax: +65 6472 2112

Branch office: 9A Serangoon North Ave 5 Singapore 554500 Tel: +65 6484 9919 Fax: +65 6481 1011

Co. Reg. No. 201212455W

Date:

8 NOVEMBER 2018

Third Party Insurer:

AIG

Vehicle No: SME3886K

Third Party Veh No:

SU4862H

Model:

HONDA FIT HYBRID AUTO

Date of Accident:

8 NOVEMBER 2018

Chassis:

GP53415787 - 2018

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1		Bu \$828.90
2	REAR BUMPER CLIPS	10	\$4.00	Me \$40.00
3	REAR BUMPER SIDE RETAINER LH	1		0.7 \$37.90
4	REAR BUMPER SIDE INNER SHIELD LH	1		In \$59.20
5	REAR BUMPER SIDE INNER SHIELD CLIPS	4	\$4.50	un \$18.00
6	REAR END PANEL	1		\$370.10
7	REAR WELL SIDE PANEL LH	1		\$585.00
8	REAR FENDER INNER TRIM BOARD LH	1		Ne form \$355.50
9	REAR FENDER INNER TRIM BOARD CLIPS	8	\$5.80	Ma \$46.40
			SUB TOTAL	\$2,341.00
			LESS 20%	-\$468.20
			PARTS TOTAL	\$1,872.80

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION

\$1,000.00

TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION

\$800.00

TO TUFF KOTE / ANTI-RUST

\$60.00 -

TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR

100 \$220.00

\$2,080.00 LABOUR TOTAL

PEI TING

\$3,952.80

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 1

Not Notheries
Resury B4 pains
Eday,