

Surveyor:

Advan

DOI:

ASSIGNMENT
20/11/18

Date / Time:

12/11/2018

Registered in Meriton:

12/11/2018

Pre-assign / CCU / FTE



Insured Vehicle No. : SLV 577A
Name of Insured : _____
Insured Tel No. : _____ HP: _____
Excess Sec II : \$5 _____ D.O.A : 10.11.18
Is driver the owner? (YES) NO) Nature of Accident : _____
If NO, Driver Name / Age : _____
Driver Tel No. : _____ (V/L: YES / NO)

Claim No. : _____
Policy No. : _____
Make / Model : _____
Place of Accident : CIE ? AYE

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
Insured Liability : % Final ? Yes / No

LBX 3303B → SLV 577A → SLX 77846 → SLZ 8263B



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

07



INSRS:
WSP: Premium
Tel:
Liability:
RMKS:

7P



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

12/11
01/17

SLX 77846 - X;
SLV 577A - NA / A16180 20394.A, 10/11/18

13/11/18

4 vehcc. OI was 3rd car.
TP video in Meriton

2/12/18

File → Action + Finalize

9/4

Offer LOR @ \$11,351.68 to TP (w/o GST) - Pending VOI
7/5 - FV pays to RT type mandate
7/5 - SLX mandate \$12708.30 - Pending approval.

STAGE	DATE / PIC
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	<u>SLX 13/11/18</u>
After call ltr to OI:	
Documentation Check List:	Handler Typist
Notification ltr (if non-pickup)	
After call ltr to OI:	<input checked="" type="checkbox"/>
Authorisation To Act:	<input checked="" type="checkbox"/>
Release Voucher:	<input checked="" type="checkbox"/>
Final Repair Bill:	<input checked="" type="checkbox"/>
Car Rental Invoice:	
Towing Invoice:	
LTA / GIA:	<input checked="" type="checkbox"/>
Medical Bill:	
FIR:	
Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
LOD:	
Payment Breakdown Form:	
Post-Repair Photos:	
Others:	

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	\$5	(days) Reduction:	%
FINAL SETTLEMENT		Date/Time: 01-08-19	Confirm with: Terey
Final Liability:	%	(Agreed / Assessed) BOLA S/N No.:	<u>28946.013rd</u>
Repair Cost:	<u>(W/ST)</u> \$5	<u>12,146.30</u>	If NO or B 28, Ass. Lie: <u>07.</u>
Loss of Rental (LOR):	\$5	(days)	
Loss of Use (LOU):	\$5	<u>400.00</u> (\$ <u>80</u> x <u>6</u> days)	
Loss of Income (LOI):	\$5	(\$ x days)	
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]		
GIA/LTA Search	\$5	<u>2.00</u>	
Medical:	\$5		
Disbursement:	\$5	(e.g. Tow/Independent)	
Legal Cost:	\$5		
Total:	\$5	<u>12,628.30</u>	Global Sum \$5:
FINAL PAYMENT		Date/Time: 01-08-19	Confirm with: Terey
Payee 1:	\$5	<u>12,146.30</u>	Name 1: <u>PREMIUM ALLOCATIONS PTE LTD</u>
Payee 2: (Strike if N.A.)	\$5		Name 2:
Payee 3: (Strike if N.A.)	\$5		Name 3:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/1307/2018/GW
Date	:	16-Nov-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no. **SLV 5717 A**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Wong Hong Yang
Address	:	368 Upper East Coast Road# 02-03 Singapore 466473
Telephone	:	(HP) 85338208
Type of Claim	:	Third Party Claims
Policy No.	:	
Vehicle No	:	SLX 7784 G
Model Code	:	Audi A6 1.8 TFSI S- Tronic
Model / Year	:	Apr-18
Engine No	:	CYG 018829
Chassis No	:	WAUZZZ4G9HN092651
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	10-Nov-18
Place of Accident	:	CTE Heading Towards Town

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLX 7784 G

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓
2	To dismantle and renew front bumper. Re-organise crash management components. Reinstall all parts removed.	\$ 1,050.00 500 - L
3	To respray front bumper.	\$ 900.00 550 x
TOTAL LABOUR CHARGES - FRONT		: \$ 2,430.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 7784 G

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Repair</i>	\$	2,650.00 *
2	FRONT BUMPER FIXING PARTS	\$	464.00 *
3	FRONT BUMPER SECURING STRIPS	2 \$	12.00 *
4	FRONT BUMPER GRILLE	\$	112.00 *
5	FRONT BUMPER LOCKING CLIP	14 \$	48.00 *
6	FRONT BUMPER CLOSING ELEMENT	\$	188.00 *
7	FRONT BUMPER SPOILER	\$	817.00 *
8	FRONT BUMPER LOWER SPOILER	\$	216.00 *
9	RADIATOR GRILLE <i>cracked</i>	\$	1,697.00 ✓ 1357.60 P
10	RADIATOR GRILLE SENSOR SUPPORT-LH/RH <i>dyd.</i>	2 \$	118.00 ✓ 92.96 P
11	AIR GUIDE GRILLE-LH/RH	2 \$	868.00 *
12	FRONT BUMPER COVER-LH/RH	2 \$	88.00 *
13	FRONT BUMPER COVER CAP-LH/RH	2 \$	98.00 *
14	FRONT SENSOR INNER	2 \$	392.00 *
15	FRONT SENSOR SEAL RING	4 \$	5.00 *
16	FRONT NO. PLATE <i>Net</i>	S/N \$	25.00 ✓ <i>SN</i>
SUB-TOTAL SPARE PARTS CHARGES - FRONT		:	<u>\$ 7,798.00</u>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLX 7784 G

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid. Check function and renew according damage.	S/N \$ 360.00 ✓ L
2	To remove and transfer lid's convenience lock system and wire harness for tail lights.	S/N \$ 280.00 ✗ ✓ L
3	To dismantle and renew rear bumper and rear lid. Re-organize crash management components. Reinstall all parts removed.	\$ 2,100.00 500 1000 L
4	To respray rear bumper, rear lid and rear lid hinges.	\$ 1,900.00 550 1100 L
5	To carry out diagnostic check.	S/N \$ 192.00 ✓ L
SUB-TOTAL LABOUR CHARGES - (REAR)		: \$ 4,832.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 7784 G

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Deland</i>	\$	2,519.00 ✓ 2015-20 P
2	REAR BUMPER FIXING PARTS <i>new</i>	\$	234.00 ✓
3	REAR BUMPER SPOILER <i>lit</i>	\$	416.00 ✓ 333 SUP
4	REAR BUMPER SECURING <i>new</i>	\$	191.00 ✓
5	REAR BUMPER CLOSING ELEMENT-LH/RH <i>new</i>	2 \$	138.00 ✓
6	REAR BUMPER CABLE TERMINAL <i>new</i>	14 \$	84.00 ✓
7	REAR BUMPER CARREIR <i>2 MV</i>	\$	851.00 ✓
8	REAR BUMPER SEAL-LH/RH <i>new</i>	2 \$	24.00 X.
9	REAR BUMPER UPPER GUIDE SECTION-LH/RH <i>2</i>	2 \$	56.00 ✓
10	REAR BUMPER GUIDE SECTION-LH/RH	2 \$	92.00 ✓
11	REAR BUMPER CONNECTING PIECE	2 \$	21.00 ✓
12	REAR BUMPER GUIDE PROFILE-LH/RH	2 \$	114.00 ✓
13	REAR BUMPER SECURING ELEMENT	6 \$	9.00 ✓
14	REAR BUMPER GUIDE SECTION-CENTER	\$	91.00 ✓
15	REAR BUMPER HOLDING STRA-LH/RH	2 \$	108.00 ✓
16	REAR SENSOR	2 \$	421.00 ✓
17	REAR LID <i>Regis & dated</i>	\$	2,485.00 ✓ 1998 W P
18	REAR LID BRACKET <i>new</i>	\$	30.00 ✓
19	REAR LID ATTACHMENT PARTS <i>3 new</i>	\$	93.00 ✓
20	REAR LID HINGE-LH/RH	2 \$	400.00 X.
SUB-TOTAL SPARE PARTS		\$	8,377.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 7784 G

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	REAR LID STOP BUFFER	4 \$	57.00 ✓
22	REAR LID PUSH BUTTON FOR ELECTRIC	\$	1,181.00 ✓
23	REAR LID GASKET FOR FLAP	\$	181.00 ✓
24	REAR LID LOCK	\$	170.00 ✓
25	REAR LID LOCK COVER	\$	7.00 ✓
26	REAR LID PACKING ADHESIVE	\$	15.00 ✓ 11.60 SN
27	REAR LID AUDI EMBLEM	\$	108.00 ✓ 86.00 SN
28	REAR LID INSCRIPTION 'A6'	\$	83.00 ✓ 66.16 SN
29	REAR LID INSCRIPTION 'TFSI'	\$	83.00 ✓ 66.16 SN
30	REAR LID DECORATIVE TRIM	\$	317.00 ✓ 267.60 SN
40	REAR NO. PLATE	S/N \$	25.00 ✓ 25.00 SN
41	SUNDRIES	\$	600.00 ✓ 560 SN
MATERIALS FRONT/REAR		:	\$ 19,002.00
LABOUR CHARGES FRONT/REAR			\$ 7,262.00
GRAND TOTAL :			\$ 26,264.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/1307/2018/GW
Date	:	16-Nov-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no. **SLV 5717 A**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

6 days - ok - /b - 5 Jan 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Wong Hong Yang
Address	:	388 Upper East Coast Road# 02-03 Singapore 466473
Telephone	:	(HP) 85338208
Type of Claim	:	Third Party Claims
Policy No.	:	
Vehicle No	:	SLX 7784 G
Model Code	:	Audi A6 1.8 TFSI S- Tronic
Model / Year	:	Apr-18
Engine No	:	CYG 018829
Chassis No	:	WAUZZZ4G9HN092651
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	10-Nov-18
Place of Accident	:	CTE Heading Towards Town

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLX 7784 G

S/N	Nature of Jobs	Estimated Charges	
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	\$ 480.00
2	To dismantle and renew front bumper. Re-organise crash management components. Reinstall all parts removed.	\$ 1,050.00	\$ 500.00
3	Added job - by owner (Δ)	\$ 1,100.00	\$ 1,100.00
4	To respray front bumper.	\$ 900.00	
TOTAL LABOUR CHARGES - FRONT		\$ 3,530.00	\$ 2,080.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 7784 G

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 2,650.00	
2	FRONT BUMPER FIXING PARTS	\$ 464.00	
3	FRONT BUMPER SECURING STRIPS	2 \$ 12.00	
4	FRONT BUMPER GRILLE	\$ 112.00	
5	FRONT BUMPER LOCKING CLIP	14 \$ 48.00	
6	FRONT BUMPER CLOSING ELEMENT	\$ 188.00	
7	FRONT BUMPER SPOILER	\$ 817.00	
8	FRONT BUMPER LOWER SPOILER	\$ 216.00	
9	RADIATOR GRILLE	\$ 1,697.00	\$ 1,357.60 ✓
10	RADIATOR GRILLE SENSOR SUPPORT-LH/RH	2 \$ 118.00	\$ 92.96 ✓
11	AIR GUIDE GRILLE-LH/RH	2 \$ 868.00	
12	FRONT BUMPER COVER-LH/RH	2 \$ 88.00	
13	FRONT BUMPER COVER CAP-LH/RH	2 \$ 98.00	
14	FRONT SENSOR INNER	2 \$ 392.00	
15	FRONT SENSOR SEAL RING	4 \$ 5.00	
16	FRONT NO. PLATE	S/N \$ 25.00	\$ 25.00 ✓
SUB-TOTAL SPARE PARTS CHARGES - FRONT :		\$ 7,798.00	\$ 1,475.56

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLX 7784 G

S/N	Nature of Jobs	Estimated Charges	
	<i>Labour front c/f</i>	\$	2,080.00
1	To remove and transfer rear parking aid. Check function and renew according damage.	S/N \$ 360.00	\$ 360.00 ✓
2	To remove and transfer lid's convenience lock system and wire harness for tail lights.	S/N \$ 280.00	\$ 280.00 ✓
3	To dismantle and renew rear bumper and rear lid. Reorganize crash management components. Reinstall all parts removed. <i>(Rear lid replaced)</i>	\$ 2,100.00	\$ 1,000.00
4	To respray rear bumper, rear lid and rear lid hinges.	\$ 1,900.00	\$ 1,100.00
5	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00 ✓
SUB-TOTAL LABOUR CHARGES - (REAR)		\$ 4,832.00	\$ 5,012.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 7784 G

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
			\$ 1,475.56
1	REAR BUMPER	\$ 2,519.00	\$ 2,015.20
2	REAR BUMPER FIXING PARTS	\$ 234.00	
3	REAR BUMPER SPOILER	\$ 416.00	\$ 332.80
4	REAR BUMPER SECURING	\$ 191.00	
5	REAR BUMPER CLOSING ELEMENT-LH/RH	2 \$ 138.00	
6	REAR BUMPER CABLE TERMINAL	14 \$ 84.00	
7	REAR BUMPER CARREIR	\$ 851.00	
8	REAR BUMPER SEAL-LH/RH	2 \$ 24.00	
9	REAR BUMPER UPPER GUIDE SECTION-LH/RH	2 \$ 56.00	
10	REAR BUMPER GUIDE SECTION-LH/RH	2 \$ 92.00	
11	REAR BUMPER CONNECTING PIECE	2 \$ 21.00	
12	REAR BUMPER GUIDE PROFILE-LH/RH	2 \$ 114.00	
13	REAR BUMPER SECURING ELEMENT	6 \$ 9.00	
14	REAR BUMPER GUIDE SECTION-CENTER	\$ 91.00	
15	REAR BUMPER HOLDING STRA-LH/RH	2 \$ 108.00	
16	REAR SENSOR	2 \$ 421.00	
17	REAR LID	\$ 2,485.00	\$ 1,988.00
18	REAR LID BRACKET	\$ 30.00	
19	REAR LID ATTACHMENT PARTS	\$ 93.00	
20	REAR LID HINGE-LH/RH	2 \$ 400.00	
SUB-TOTAL SPARE PARTS		\$ 8,377.00	\$ 5,811.56

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 7784 G

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
			\$ 5,811.56
21	REAR LID STOP BUFFER	4 \$ 57.00	
22	REAR LID PUSH BUTTON FOR ELECTRIC	\$ 1,181.00	
23	REAR LID GASKET FOR FLAP	\$ 181.00	
24	REAR LID LOCK	\$ 170.00	
25	REAR LID LOCK COVER	\$ 7.00	
26	REAR LID PACKING ADHESIVE	\$ 15.00	\$ 11.60
27	REAR LID AUDI EMBLEM	\$ 108.00	\$ 86.00
28	REAR LID INSCRIPTION 'A6'	\$ 83.00	\$ 66.16
29	REAR LID INSCRIPTION 'TFSI'	\$ 83.00	\$ 66.16
30	REAR LID DECORATIVE TRIM	\$ 317.00	\$ 267.60
40	REAR NO. PLATE	S/N \$ 25.00	\$ 25.00
41	SUNDRIES	\$ 600.00	\$ 5.60
	MATERIALS FRONT/REAR	\$ 19,002.00	\$ 6,339.68
	LABOUR CHARGES FRONT/REAR	\$ 8,362.00	\$ 5,012.00
	GRAND TOTAL :	\$ 27,364.00	\$ 11,351.68

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315	Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/1307/2018/GW 26-Dec-18 Tony 1 SLX 7784 G Audi A6 1.8 TFSI S- Tronic
--	---	--

Quantity	Description	Unit Price	Amount
<u>LABORS</u>			
1	To reapply paint protection film (By owner)	\$ 1,100.00	\$ 1,100.00
TOTAL		\$ 1,100.00	\$ 1,100.00

For Premium Automobiles Pte Ltd



Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 20/11/18
Authorised Date :
Excess Cost :
Liability :
Remarks : not Authorised , 05 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 7784 G

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS

1	REAR BUMPER <i>Defect</i>	\$	2,519.00 ✓
2	REAR BUMPER FIXING PARTS <i>new</i>	\$	234.00 ✗
3	REAR BUMPER SPOILER <i>new</i>	\$	416.00 ✓
4	REAR BUMPER SECURING <i>new</i>	\$	191.00 ✗
5	REAR BUMPER CLOSING ELEMENT-LH/RH <i>new</i>	2 \$	138.00 ✗
6	REAR BUMPER CABLE TERMINAL <i>new</i>	14 \$	84.00 ✗
7	REAR BUMPER CARREIR	\$	851.00 ✗
8	REAR BUMPER SEAL-LH/RH <i>new</i>	2 \$	24.00 ✗
9	REAR BUMPER UPPER GUIDE SECTION-LH/RH	2 \$	56.00 ✗
10	REAR BUMPER GUIDE SECTION-LH/RH	2 \$	92.00 ✗
11	REAR BUMPER CONNECTING PIECE	2 \$	21.00 ✗
12	REAR BUMPER GUIDE PROFILE-LH/RH	2 \$	114.00 ✗
13	REAR BUMPER SECURING ELEMENT	6 \$	9.00 ✗
14	REAR BUMPER GUIDE SECTION-CENTER	\$	91.00 ✗
15	REAR BUMPER HOLDING STRA-LH/RH	2 \$	108.00 ✗
16	REAR SENSOR	2 \$	421.00 ✗
17	REAR LID <i>Repair</i>	\$	2,485.00 ✗ ✓
18	REAR LID BRACKET <i>new</i>	\$	30.00 ✗
19	REAR LID ATTACHMENT PARTS <i>new</i>	\$	93.00 ✗
20	REAR LID HINGE-LH/RH	2 \$	400.00 ✗
SUB-TOTAL SPARE PARTS		\$	8,377.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

20394/A3

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 7784 G

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	REAR LID STOP BUFFER	4 \$	57.00 ✓
22	REAR LID PUSH BUTTON FOR ELECTRIC	\$	1,181.00 ✓
23	REAR LID GASKET FOR FLAP	\$	181.00 ✓
24	REAR LID LOCK	\$	170.00 ✓
25	REAR LID LOCK COVER	\$	7.00 ✗
26	REAR LID PACKING ADHESIVE	\$	15.00 ✗
27	REAR LID AUDI EMBLEM <i>new</i>	\$	108.00 ✗
28	REAR LID INSCRIPTION 'A6' <i>new</i>	\$	83.00 ✗
29	REAR LID INSCRIPTION 'TFSI' <i>new</i>	\$	83.00 ✗
30	REAR LID DECORATIVE TRIM <i>new</i>	\$	317.00 ✗
40	REAR NO. PLATE <i>Bent</i>	S/N \$	25.00 ✓
41	SUNDRIES ?	\$	600.00 ✓
MATERIALS FRONT/REAR		:	\$ 19,002.00
LABOUR CHARGES FRONT/REAR			\$ 7,262.00
GRAND TOTAL :			\$ 26,264.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/TP/1307/2018/GW

26-Dec-18

Tony

1

SLX 7784 G

Audi A6 1.8 TFSI S- Tronic

Quantity	Description	Unit Price	Amount
LABORS			
1	To reapply paint protection film (By owner)	\$ 1,100.00	✓
TOTAL		\$ 1,100.00	

For Premium Automobiles Pte Ltd

Adrian Ling
SLX



Authorised Signature



GROOMERSLAB

None others Can

Client:

Mr Jeremy WONG
Make & Model: Audi A6
Colour: Brown
VRN: SLX 7784 M

Tel: +65 8533 8208

Email: NIL

Invoice No.

PPF201805085

Invoice Date:

08th May 2018, Tuesday

Treatment/Installation: 08th May 2018, Tuesday

Bill To:

Jeremy

Terms of Payment:

Nets

Mode of Payment:

Cash | Nets | Visa | Mastercard

Description**Amount**

Washing & Clayng of Exterior Bodywork

\$

4,500.00

Application of Coating on Entire Bodyworks Prior to Installation of Xpel Ultimate Plus

Installation of Xpel Ultimate Plus Self-Healing Paint Protection Film on the Following Areas:

1. Front Bonnet | Front Whole Bumper | Front Left & Right Fenders | Front Headlights

2. 4 Doors | Left & Rear Rear Fenders | Rear Whole Bumper | Rear Boot | Rear Brake Lights

Application of Coating on Entire Bodyworks Prior to Installation of Xpel Ultimate Plus

* 4 x Maintenance Program (as per vouchers) *

* Special Discounted Rate for Referral by Johnson *

Invoice Subtotal

\$

4,500.00

Discount (if applicable)

Deposit (if any)

TOTAL

\$

4,500.00

Disclaimer:

1. The above works had been carried out and all services have been satisfactorily completed and hereby absolve **Groomers Lab Pte Ltd** of any liability arising from use therefrom.
2. Deposit paid (if any) are not refundable should the job be cancelled for whatsoever reason(s). Postponement of job(s) are subject to be completed within a month from the deposit paid date.
3. All payments are C.O.D. Late interest of 2% shall be liable for all late payment. Invoice will only be valid with 2 signatories.
4. All payments are to be made to Groomers Lab Pte Ltd **DBS Current Account Number 0039 3986 70** for all E-transfers
5. **All Complimentary Services are not applicable for appointment(s) on weekends.**
6. All Complimentary Maintenance Program does not cover removal of Sandblast Grit, Harsh Defects Or Severe Water Marks
7. **All Goods | Merchandise Sold and | or Services Rendered | Offered | Completed are non-refundable or exchangeable**
8. All warranty are subject to terms & condition of Groomers Lab Pte Ltd.
9. **All payment[s] remain outstanding unless stamped PAID and signed by authorised personnel from Groomers Lab Pte Ltd**

Groomers Lab Pte. Ltd.

Customer's Signature

Thank You for Your Business & We Look Forward to Welcoming You Back

Groomers Lab Pte Ltd & Groomers Lab Concept Centre Pte Ltd is @

25 Kaki Bukit Road 4 #07-56 | #03-34 Synergy@KB Singapore 417800

Labline: +65 6610 0118 | +65 6969 6745 For Appointment: +65 9323 2333

www.groomerslab.com.sg

Facebook: Groomers Lab Pte Ltd | Groomers Lab Concept Centre Pte Ltd



GROOMERSLAB

— None others Can —

14th December 2018 | Friday

Our Ref : PPFR201812141 – Revised 1

Name of Client : Mr Jeremy WONG

Make & Model : Audi A6

Colour Of Vehicle : Brown

VRN : SLX 7784 M

Dear Mr Tan,

RE : INSTALLTION OF XPEL ULTIMATE PLUS SELF-HEALING PAINT PROTECTION FILM

Greetings from Groomers Lab.

Thank you for enquiring on our services for the installation of Xpel Ultimate Plus Self-Healing Paint Protection Film on the following panels:

🔧 Rear Whole Bumper @ SGD650 Nett

🔧 Rear Whole Boot Cover @ SGD450

The installation services will include the following scope:

1. Washing & claying of above mentioned panels.
2. Paint | Surface Correction & Enhanced Polishing on above mentioned panel

Please let us know if you would like to confirm our services so that we can block the slot for you. Meanwhile, please feel free to call me or send me an email should you require any further assistance or clarification, I shall be most glad to assist with no obligation.

Thank you

Regards,

Rendall Chee

Mobile: +65 9323 2333

- No signature is required for PDF transmission (if sent via E mode)

Groomers Lab Pte Ltd is located @ 25 Kaki Bukit Road 4 #07-56 Synergy@KB Singapore 417800

Groomers Lab Concept Centre is located @ 25 Kaki Bukit Road 4 #03-34 Synergy@KB Singapore 417800

Lab: +65 6610 0118 Concept Centre: +65 6969 6745 FB: Groomers Lab Pte Ltd / Groomers Lab Concept Centre

Hsiao Tong (LKKAuto)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Saturday, 5 January 2019 4:50 PM
To: Adrian Ling (LKKAuto); CS A Team; Admin A; Carrine Leong;
jiayee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: FINAL REVISION - SLX7784G - TP AIG - SURVEYED 20 NOV 18
Attachments: PA13072018 -SLX 7784 G - Audi A6 1.8 TFSI S - FRONT + REAR (AIG).xls

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$11,351.68 @ 6 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Thursday, 27 June 2019 5:58 PM
To: Chan, Kian-Meng
Subject: ACCIDENT ON 10/11/2018 INVOLVING SLV 5717A (OI) & SLX 7784G (TP)

Your ref : **2992829214SG**
Our ref : CC3/AIG18020394/Aea3

Dear Sirs,

ACCIDENT ON 10/11/2018 INVOLVING SLV 5717A (OI) & SLX 7784G (TP)

We refer to the above matter.

The said chain collision involved 4 vehicles whereby our insured was the 3rd vehicle.

In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer repairer " **PREMIUM AUTOMOBILES PTE LTD**" at **\$ 12,688.30 (all-in)**.

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repairs (with GST)	\$ 29,279.48	\$ 12,146.30
2. Loss of Use (6days x \$100)	\$ 600.00	\$ 540.00 (6days x \$90)
3. LTA Search Fee	\$ 2.00	\$ 2.00
Total	\$ 29,881.48	<u>\$ 12,688.30</u>

For your approval in merimen please.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Print Received Message

This mail is associated with :

***SLX7784G (2992829214SG)
[SLV5717A]**

TP

WONG HONG YANG

Nov 10 2018 12:00PM

[TENG YEN PING (DING YANPING)]

Premium Automobiles Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 22/07/2019 15:20 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$12628.30) - SLX7784G - Claim Handler: Chan, Kian-Meng

Approved:12628.30:COR: \$12,146.30 LOU: \$480 (6 days x \$80) as per LOD Search fee: \$2 Total: \$12,628.30 Kindly settle at best.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S15177791



Name

WONG HONG YANG

黄宏向

Race

CHINESE

Date of birth

23-08-1962

Sex

M

S15177791

Country/Place of birth

SINGAPORE



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S15177791

Name

WONG HONG YANG

Birth Date 23 Sep 1962

Issue Date 12 Nov 2003




000596423A

5991491



NAME No. S15177791



Date of issue

01-08-2018

Address

368 UPPER EAST COAST ROAD
#02-03
SINGAPORE 466473

YOU ARE PERMITTED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

PASS DATE

or Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms 30 Nov 1979



Licence No: S15177791

NP 001

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
 78 Shenton Way
 #07-16 AIG Building
 Singapore 079120
Attn: Motor Claims Dept
Yr Ref: CC3/AIG18020394/pa3

Norah Khai
 6768 9911
 6841 1183
 Nora.khai@premiumauto.com.sg
 Body & Paint Dept
 PA/TP/1307/2018/MAS

30 Apr 2019

from
 Telephone +65-
 Telefax +65-
 EMail
 Our department
 Our Ref
 Your Ref
 Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLX 7784 G, Audi A6 1.8 TFSI S-Tro

With reference to the above-mentioned vehicle, no. **SLX 7784 G**, claimant, **Mr. Wong Hong Yang**, please find the related document as per attached.

1. A copy of the Original invoice no. 85013708 – S\$12,146.30
2. A copy of Authorization to Act duly signed by client
3. A copy of the Release Voucher attached
4. A copy of Breakdown of Payment attached
5. Loss of Use – S\$480.00 (S\$80.00 x 6 working days)
6. GIA Search Fee – S\$2.00

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
 Claims Dept

Encls

AIG – SLX 7784 G

Premium Automobiles Pte Ltd
 Showroom
 9 Leng Kee Road
 Singapore 159090
 Telephone (65) 6566 1111
 Telefax (65) 6471 3733

Service & Parts Centres
 55 Ubi Rd 1
 Singapore 408699
 Telephone (65) 6336 2323
 Telefax (65) 684 11183

total pages



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18020394/pa3

19 NOV 2018

TENG YEN PING (DING YANPING)

BLK 106 ALJUNIED CRESCENT

#03-211

SINGAPORE 380106

Dear Sir/Madam,

ACCIDENT INVOLVING SLV 5717A/ SLX 7784G/ OTHERS ON 10/11/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SLX 7784G against your motor insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be withheld for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG

Case Handler

DID: 6742 3197

FAX: 6741 4108

Email: chewht@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORISATION TO ACT
(AIG Express Third Party Claim)

I, WONG HONG YANG (the third party claimant) of 368 UPPER EAST COAST ROAD
#02-03, SINGAPORE 466473 (address), owner of SLX7784G (vehicle no.)
hereby authorize PREMIUM AUTOMOBILES PTE LTD ("the workshop") to act for me
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle
no. SLX7784G that was damaged pursuant to the accident which occurred on 10/11/2018
(date) along CTE HEADING TOWARDS TOWN (location) involving vehicle no/s
SLV5717A ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 15 (day) of DEC (month) 2018 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Express Third Party Claim)

"We/I, PREMIUM AUTOMOBILES PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$12,146.30 (Repair Cost), S\$480.00 (Loss of rental/use), S\$2,000 (Disbursement), for vehicle no. SLX7784G that was damaged pursuant to the accident which occurred on 10/11/2018 (date) along CTE HEADING TOWARDS TOWN (location) involving vehicle no/s SLV5717A. This is pursuant to the inspection conducted on 20/11/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner WONG HONG YANG ("the third party claimant") of vehicle no. SLX7784G make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLX7784G (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 01 (day) of 07 (month) 2019 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159988
Main Telephone: 6836 2223
Main Telefax: 6471 3133

Alexandra Service Centre
281 Alexandra Road
Singapore 159988
Telephone: 6886 2223
Telefax: 6475 1033

Ubi Service Centre
55 Ubi Road 1
Singapore 408809
Telephone: 6386 2223

Customer Service
Service Appointment:
24 Hour Breakdown Service
customer.care@premiumauto.com.sg

6386 2223
6828 1233

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 1 17:11

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013708 Date : 24/04/2019 Order : SLX7784G Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLX7784G (V 33875)	Regn Date: 11/04/2018	Mileage: 14576	WIP No.: 31813
Model: A6 1.8 TFSI S tronic 460066 (N	Chassis: WAUZZZ469H092651	Engine: CYG 018829	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee (11)			

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE (FRONT & REAR)	50.00	1.00	50.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	480.00	1.00	480.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	500.00	1.00	500.00
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGES	360.00	1.00	360.00
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHT	280.00	1.00	280.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6896 2223
Mark Telefax: 6471 3333

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6896 2223
Telefax: 6475 1023

UBI Service Centre
35 Ubi Road 1
Singapore 408722
Telephone: 6886 2123

Customer Service
Service Appointment
281 Alexandra Road
Singapore 119938
customer.care@premiumauto.com.sg

6896 2223
6828 1233

INSURANCE TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 2 17:11

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013708 Date : 24/04/2019 Order : SLX7784G Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLX7784G (V 33075)	Regn Date: 11/04/2018	Mileage: 14576	WIP No.: 31813
Model: A6 1.8 TFSI S tronic 4G006G (N	Chassis: WAUZZZ4G9HN092651	Engine: CYG 018829	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee (11)			

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID, REORGANISE CRASH MANAGEMENT COMPONENTS, REINSTALL ALL PARTS REMOVED	1000.00	1.00	1,000.00
S	BODYWORK	M: TO RESPRAY REAR BUMPER AND REAR LID	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
Q	OTHERS	M: TO REAPPLY PAINT PROTECTION FILM (BY OWNER)	1100.00	1.00	1,100.00
X	A4G0053651AET94	GRILLE Less 020%	1.00	1697.00	1,357.60
X	A4G5827023C	LID Less 020%	1.00	2485.00	1,988.00
X	A4G0007521T 909	(A) (GER) SPOILER Less 020%	1.00	416.00	332.80
X	A4G5807067K GRU	(A) (GER) COVER Less 020%	1.00	2519.00	2,015.20
X	A4F0053741 222	INSCRIPTION 'A6' Less 020%	1.00	82.70	66.16
X	A8X0053737A 222	INSCRIPTION 'TFSI' Less 020%	1.00	82.70	66.16
X	A4G5853742 222	AUDI SIGN Less 020%	1.00	107.50	86.00
X	A8D0053419F	PACKING Less 020%	1.00	14.50	11.60
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119908
Main Telephone: 6848 2222
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 119908
Telephone: 6888 2222
Telefax: 6475 1022

Uli Service Centre
55 Uli Road 1
Singapore 119908
Telephone: 6888 2222

Customer Service
Service Appointment
Your Breakdown Service
Email: customer.care@premiumauto.com.sg

9366 2322
9828 1239

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 3 17:11

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013708
Date : 24/04/2019
Order : SLX7784G
Term : 30

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLX7784G (V 33075) Regn Date: 11/04/2018 Mileage: 14576 VIP No.: 31813
Model: A6 1.8 TFSI S tronic 4GC06G (N Chassis: WAUZZZ4G9HN092651 Engine: CY6 018829 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (11)

		Details		Qty	Unit Price	Amount
X	A4G0827310	CLIP	Less 020%	2.00	1.40	2.24
X	A8X0867189	CLIP	Less 020%	6.00	0.70	3.36
X	A4G0919268K	(A) (SK) MOUNTING	Less 020%	1.00	58.10	46.48
X	A4G0919267K	(A) (SK) MOUNTING	Less 020%	1.00	58.10	46.48
X	A4G5853927 222	MOLDING	Less 020%	1.00	334.50	267.60

Parts 6,289.68
Labour 1,100.00
Sublet 3,962.00
Menus 0.00
Lubricant 0.00

Sub-Total 11,351.68

7% GST 794.62

Grand Total 12,146.30



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-174237

Date of Request: 10/11/2018

Your Ref No:

Online Purchase

Premium Automobiles Pte Ltd
55 Ubi Road 1
Singapore 408699

Dear Sir/Madam,

Enquiry Date 10/11/2018
Enquiry By Jeffrey Tan Eng Su
TP Vehicle No. SLV5717A
Accident Date 10/11/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLV5717A	AIG Asia Pacific Insurance Pte. Ltd.	02/01/2018-01/01/2020	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-174237

Date of Request: 10/11/2018

Your Ref No:

Online Purchase

Premium Automobiles Pte Ltd
55 Ubi Road 1
Singapore 408699

Dear Sir/Madam,

Enquiry Date 10/11/2018
Enquiry By Jeffrey Tan Eng Su
TP Vehicle No. SLV5717A
Accident Date 10/11/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ [X] GIRO ☐ [] Cash ☐ [] Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Nov 2018 Edit Reg		20 Nov 2018 00:00 Edit Adj Rpt	S\$11,351.68 Edit Estimates	S\$11,351.68 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TENG YEN PING (DING YANPING) , ID: S7410073B								
Main Claimant:	WONG HONG YANG , ID: S15177791								
Vehicle Reg. No.:	SLX7784G	Date of Loss:	10/11/2018 12:00 - :59 [6 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2992829214SG	Policy/Cover Note No.:	1800006245 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLV5717A	Policy No. (Claimant):	-						
		Excess:							
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 21/11/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG_EXPRESS (22/07/2019): Alert - Adj Mandate Approved (S\$12628.30) - SLX7784G - Claim Handler: Chan, Kian... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLX7784G (2992829214SG)
[SLV5717A]
TP
WONG HONG YANG
Nov 10 2018 12:00PM
[TENG YEN PING (DING YANPING)]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Video															1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print		
1	13/11/18 17:45	Video - Accident (SLX7784G)												1	Load MP4			
Letters/Correspondences															1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown												1	Edit			
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	10/12/18 09:46	General View												1	Load JPG	<input checked="" type="checkbox"/>		
2	10/12/18 09:46	General View												1	Load JPG	<input checked="" type="checkbox"/>		
3	10/12/18 09:46	General View												1	Load JPG	<input checked="" type="checkbox"/>		
4	10/12/18 09:46	General View												1	Load JPG	<input checked="" type="checkbox"/>		
5	10/12/18 09:46	General View												1	Load JPG	<input checked="" type="checkbox"/>		
6	10/12/18 09:46	General View												1	Load JPG	<input checked="" type="checkbox"/>		
7	10/12/18 09:46	General View												1	Load JPG	<input checked="" type="checkbox"/>		
8	10/12/18 09:46	General View												1	Load JPG	<input checked="" type="checkbox"/>		
9	10/12/18 09:46	General View												1	Load JPG	<input checked="" type="checkbox"/>		
10	10/12/18 09:46	General View												1	Load JPG	<input checked="" type="checkbox"/>		
11	10/12/18 09:46	General View												1	Load JPG	<input checked="" type="checkbox"/>		
12	10/12/18 09:46	General View												1	Load JPG	<input checked="" type="checkbox"/>		
13	10/12/18 09:46	General View												1	Load JPG	<input checked="" type="checkbox"/>		
14	10/12/18 09:46	General View												1	Load JPG	<input checked="" type="checkbox"/>		
15	10/12/18 09:46	General View												1	Load JPG	<input checked="" type="checkbox"/>		
16	10/12/18 09:46	General View												1	Load JPG	<input checked="" type="checkbox"/>		
17	10/12/18 09:46	General View												1	Load JPG	<input checked="" type="checkbox"/>		
18	10/12/18 09:46	General View												1	Load JPG	<input checked="" type="checkbox"/>		
19	10/12/18 09:46	General View												1	Load JPG	<input checked="" type="checkbox"/>		
20	10/12/18 09:46	General View												1	Load JPG	<input checked="" type="checkbox"/>		
21	10/12/18 09:46	General View												1	Load JPG	<input checked="" type="checkbox"/>		
22	10/12/18 09:46	General View												1	Load JPG	<input checked="" type="checkbox"/>		
23	10/12/18 09:46	General View												1	Load JPG	<input checked="" type="checkbox"/>		
24	10/12/18 09:46	General View												1	Load JPG	<input checked="" type="checkbox"/>		
25	10/12/18 09:46	General View												1	Load JPG	<input checked="" type="checkbox"/>		
26	10/12/18 09:46	General View												1	Load JPG	<input checked="" type="checkbox"/>		
27	10/12/18 09:46	General View												1	Load JPG	<input checked="" type="checkbox"/>		
28	10/12/18 09:46	General View												1	Load JPG	<input checked="" type="checkbox"/>		
29	10/12/18 09:46	General View												1	Load JPG	<input checked="" type="checkbox"/>		
30	10/12/18 09:46	General View												1	Load JPG	<input checked="" type="checkbox"/>		

Video			1 per page		<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
31	10/12/18 09:46	General View	1	Load JPG	<input checked="" type="checkbox"/>
32	10/12/18 09:46	General View	1	Load JPG	<input checked="" type="checkbox"/>
33	21/03/19 19:11	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
34	21/03/19 19:11	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
35	21/03/19 19:11	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
36	21/03/19 19:11	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
37	21/03/19 19:11	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
38	21/03/19 19:11	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
39	21/03/19 19:11	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
40	21/03/19 19:11	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
41	21/03/19 19:11	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
42	21/03/19 19:11	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
43	21/03/19 19:11	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
44	21/03/19 19:11	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
45	21/03/19 19:11	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
46	21/03/19 19:11	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
47	21/03/19 19:11	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
48	21/03/19 19:11	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
49	21/03/19 19:11	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
50	21/03/19 19:11	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
51	21/03/19 19:11	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
52	21/03/19 19:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
53	21/03/19 19:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
54	21/03/19 19:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
55	21/03/19 19:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
56	21/03/19 19:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
57	21/03/19 19:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
58	21/03/19 19:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/11/18 09:11	TP GIA REPORT	1	Load PDF	
2	22/11/18 09:45	TP ESTIMATE - MARKED	1	Load PDF	
3	10/12/18 09:45	Photos from OI - SLV 5717A	1	Load PDF	
4	22/05/19 11:05	LETTER TO OI	1	Load PDF	
5	22/05/19 11:05	GIA SEARCH	1	Load PDF	
6	22/05/19 16:58	LOD AND OTHER DOCUMENTS	1	Load PDF	
7	15/08/19 10:50	WORKSHOP INVOICE	1	Load PDF	
8	15/08/19 10:50	AUTHORISATION TO ACT FORM	1	Load PDF	
9	15/08/19 10:50	Release Voucher	1	Load PDF	
10	15/08/19 10:50	GIA SEARCH	1	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	13/11/18 11:24	OI GIA REPORT	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLV5717A (Insd veh)	Model:	AUDI A6 1.8 TFSI ULTRA (PI)
	SLX7784G (TP veh)		(NAV) (A)
Date of Accident:	10/11/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	29,279.48
Final Repair Cost	:	\$	12,146.30
Loss of Use	:	\$	480.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	12,628.30

6.00 days at \$80.00 per day
days

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: 28

BOLA Liability: 100 (%) Assessed Liability (*): 0 (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Premium Automobiles Pte Ltd	:	\$ 12,628.30
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

15 Aug
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18020394/AEA3Q2

Date: 15/08/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800006245
Claimant Vehicle No : SLX7784G **Insured Vehicle No :** SLV5717A
Date of Loss: 10/11/2018 **Nature of Claim:** TP **Claim No:** 2992829214SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLX7784G
Make & Model: AUDI A6, 1.8 TFSI Ultra (PI) (NAV) (A) **Engine No:** CYG018829
Reg. Date: 11/04/2018 (Man. Year: 2017) **Chassis No:** WAUZZZ4G9HN092651
Colour: Bronze **Odometer:** 11074 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 225/55 R17 **Rear Tyre Size:** 225/55 R17
Front Left Side: Michelin 6 mm **Rear Left Side:** Michelin 6 mm
Front Right Side: Michelin 6 mm **Rear Right Side:** Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,002.00	6,339.68	12,662.32	66.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,362.00	5,012.00	3,350.00	40.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	27,364.00	11,351.68	16,012.32	58.52
+ GST 7.00/7.00% (S\$)	1,915.48	794.62	1,120.86	58.52
Nett Amount (S\$)	29,279.48	12,146.30	17,133.18	58.52
+ Loss of Use (6.0 x S\$80.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		12,628.30		

INSPECTION

Date of Assignment: 20/11/2018
Date Inspected: 20/11/2018 **Inspected At:** Premium Automobiles Pte Ltd (UBI)
 55 Ubi Road 1
 Singapore 408699
Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,650.00 FS	*-FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	464.00 FS	*-FS
3	2		*FRONT BUMPER SECURING STRIPS	Not Necessary	12.00 FS	*-FS
4	1		*FRONT BUMPER GRILLE	Not Necessary	112.00 FS	*-FS
5	14		*FRONT BUMPER LOCKING CLIP	Not Necessary	48.00 FS	*-FS
6	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	188.00 FS	*-FS
7	1		*FRONT BUMPER SPOILER	Not Necessary	817.00 FS	*-FS
8	1		*FRONT BUMPER LOWER SPOILER	Not Necessary	216.00 FS	*-FS
9	1		*RADIATOR GRILLE	Cracked	1,697.00 FS	*1,357.60 FS
10	2		*RADIATOR GRILLE SENSOR SUPPORT -LH/RH	Damaged	118.00 FS	*92.96 FS
11	2		*AIR GUIDE GRILLE -LH/RH	Not Necessary	868.00 FS	*-FS
12	2		*FRONT BUMPER COVER-LH/RH	Not Necessary	88.00 FS	*-FS
13	2		*FRONT BUMPER COVER CAP -LH/RH	Not Necessary	98.00 FS	*-FS
14	2		*FRONT SENSOR INNER	Not Necessary	392.00 FS	*-FS
15	4		*FRONT SENSOR SEAL RING	Not Necessary	5.00 FS	*-FS
16	1		*FRONT NO.PLATE	Necessary	25.00 FS	*25.00 FS
17	1		*REAR BUMPER	Deformed	2,519.00 FS	*2,015.20 FS
18	1		*REAR BUMPER FIXING PARTS	Not Necessary	234.00 FS	*-FS
19	1		*REAR BUMPER SPOILER	Cut	416.00 FS	*332.80 FS
20	1		*REAR BUMPER SECURING	Not Necessary	191.00 FS	*-FS
21	2		*REAR BUMPER CLOSING ELEMENT -LH/RH	Not Necessary	138.00 FS	*-FS
22	14		*REAR BUMPER CABLE TERMINAL	Not Necessary	84.00 FS	*-FS
23	1		*REAR BUMPER CARRIER	Not Necessary	851.00 FS	*-FS
24	2		*?REAR BUMPER SEAL -LH/RH	Not Necessary	24.00 FS	*-FS
25	2		*REAR BUMPER UPPER GUIDE SECTION -LH/RH	Not Necessary	56.00 FS	*-FS
26	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	92.00 FS	*-FS
27	2		*REAR BUMPER CONNECTING PIECE	Not Necessary	21.00 FS	*-FS
28	2		*REAR BUMPER GUIDE PROFILE -LH/RH	Not Necessary	114.00 FS	*-FS
29	6		*REAR BUMPER SECURING ELEMENT	Not Necessary	9.00 FS	*-FS
30	1		*REAR BUMPER GUIDE SECTION -CENTER	Not Necessary	91.00 FS	*-FS
31	2		*REAR BUMPER HOLDING STRA-LH/RH	Not Necessary	108.00 FS	*-FS
32	2		*REAR SENSOR	Not Necessary	421.00 FS	*-FS
33	1		*REAR LID	Dented	2,485.00 FS	*1,988.00 FS
34	1		*REAR LID BRACKET	Not Necessary	30.00 FS	*-FS
35	1		*REAR LID ATTACHMENT PARTS	Not Necessary	93.00 FS	*-FS
36	2		*REAR LID HINGE -LH/RH	Not Necessary	400.00 FS	*-FS
37	4		*REAR LID STOP BUFFER	Not Necessary	57.00 FS	*-FS
38	1		*REAR LID BUSH BUTTON FOR ELECTRIC	Not Necessary	1,181.00 FS	*-FS
39	1		*REAR LID GASKET FOR FLAP	Not Necessary	181.00 FS	*-FS
40	1		*REAR LID LOCK	Not Necessary	170.00 FS	*-FS
41	1		*REAR LID LOCK COVER	Not Necessary	7.00 FS	*-FS
42	1		*REAR LID PACKING ADHESIVE	Necessary	15.00 FS	*11.60 FS
43	1		*REAR LID AUDI EMBLEM	Necessary	108.00 FS	*86.00 FS
44	1		*REAR LID INSCRIPTION A6	Necessary	83.00 FS	*66.16 FS
45	1		*REAR LID INSCRIPTION TFSI	Necessary	83.00 FS	*66.16 FS
46	1		*REAR LID DECORATIVE TRIM	Necessary	317.00 FS	*267.60 FS
47	1		*REAR NO.PLATE	Bent	25.00 FS	*25.00 FS
48	1		*SUNDRIES	Necessary	600.00 FS	*5.60 FS

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Total Parts (S\$)	19,002.00	6,339.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANAFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,FOG LAMPS, OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER .RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY FRONT BUMPER	New	900.00	0.00
4	TO REMOVE AND TRANSFER REAR PARKING AID .CHECK FUNCTION AND RENEW ACCORDING DAMAGE	New	360.00	360.00
5	TO REMOVE AND TRANSFER LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	280.00	280.00
6	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
7	TO RESPRAY REAR BUMPER ,REAR LID AND REAR LID HINGES	New	1,900.00	1,100.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
9	ADDED JOB -BY OWER	New	1,100.00	1,100.00
Gross Labour Cost (S\$)			8,362.00	5,012.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >