

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHA 7977K

DATE 9/11/2018

MAKE :

MODEL : HYUNDAI IONIQ

EQ - CP/P)

TS

LKK - Kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 459.40
	Rear Bumper Reinforcement ?			\$ 294.80
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 138.10	\$ 276.20
	Rear Bumper Centre Moulding Assy ✓			\$ 451.25
	Rear Bumper Lower Centre Moulding Assy ?			\$ 270.10
	Rear Bumper Side Bracket (LH/RH) ?		\$ 33.10	\$ 66.20
	Rear Bumper Under Centre			\$ 53.85
	Rear Bumper Cover Clips ?			\$ 22.00
	<i>Rear Tail gate -</i>			
	<i>Tailgate LH lamp -</i>			
	<b>SUB TOTAL</b>			<b>\$ 1,893.80</b>
	<b>LESS 20%</b>			<b>\$ 378.76</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 1,515.04</b>
	Rear No. Plate ✓			\$ 25.00
	<b>Labour Charge</b>			
	Panel Beating			\$ 300
	Spray Painting Charge			\$ 400.00
	Wiring Charge			\$ 300.00
	Remove/Refix Reverse Sensor			\$ 300.00
	<b>TOTAL LABOUR</b>			<b>\$ 850.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,390.04</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Any modification is allowed
- Suppliers must be approved and approved by the Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kalvin LKK

9/11/18 1250hrs

3 Pys

P/P

Define Part photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.