

REPAIR ESTIMATE*

MAKE :

MODEL : HYUNDAI i40

EQ-45

DATE 9/11/2018

TS

LKK-kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 553.00
	Rear Bumper Clip 10 pcs			\$ 22.00
	SUB TOTAL			\$ 575.00
	LESS 20%			\$ 115.00
	DISCOUNTED TOTAL			\$ 460.00
	Rear Bumper Rubber Mat			\$ 50.00
				\$ 50.00
	Labour Charge			200
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 300.00
	Wiring Charge			\$ 30.00
	Remove/Refix Reverse Sensor			\$ 80.00
	TOTAL LABOUR			\$ 810.00
	ESTIMATE TOTAL			\$ 1,320.00

Nett

200

200

X

20

Ka Lin LKK

9/11/18 1030 hr.

20yrs

4/3

After Repair p LK

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.