

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)Block 6 Woodlands Road 399F, Yew Tee Industrial Estate
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : AXA INSURANCE SINGAPORE PTE LTD

PARTICULARS OF CLAIM

Claim Type:	TP	Ref. No:	YTHQ/TP/1810/013
Policy No:	5082810781-02	Date of Loss:	19/10/2018
Vehicle Reg. No.:	SJS3418R	Driveable?	no
Driver Age:	25/06/1972	Third Party Vehicle No.:	SGD3625Z
Any Injuries?	no	Contact No:	97903075
Insured/Claimant:	CAROLINE BAY HWEE PHING	Driver:	CAROLINE BAY HWEE PHING

Make/Model:	Honda, Fit / Jazz - GE6	Vehicle Reg. Date:	12/08/2009
Vehicle Colour:	YELLOW	Engine Number:	L13A4122381
Chassis No:	GE61110475	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss COLLISION - HEAD TO REAR
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

COST OF CLAIMS

	Amount
Parts	1,768.80
Miscellaneous Items	1,000.00
Labour	1,070.00
Paintwork Labour	750.00
Towing	0.00
Gross Total(S\$):	4,588.80
GST 7.00%(S\$):	321.22
Nett Amount(S\$):	4,910.02

This claim is handled by: Sky Toh T C

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*Not allocated
for
12/11/18
L/S S
Hdy.
subject to the repair*

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER <i>Torn</i>	160.00	160.00	+10.00	176.00
2	1	REAR BUMPER SIDE RETAINER LH <i>set</i>	11.00	11.00	+10.00	12.10
3	1	REAR BUMPER SIDE RETAINER RH <i>set</i>	11.00	11.00	+10.00	12.10
4	1	REAR BUMPER TOWING COVER <i>72.7</i>	10.00	10.00	+10.00	11.00
5	1	REAR TAILGATE <i>no/346</i>	276.00	276.00	+10.00	303.60
6	1	REAR TAILGATE LOCK <i>11</i>	60.00	60.00	+10.00	66.00
7	1	REAR TAILGATE LOCK CATCH <i>11</i>	28.00	28.00	+10.00	30.80
8	1	REAR TAILGATE FIT EMBLEM <i>11</i>	25.00	25.00	+10.00	27.50
9	1	REAR EXHAUST SILENCER <i>1</i>	556.00	556.00	+10.00	611.60
10	1	REAR EXHAUST HEAT SHIELD <i>11</i>	26.00	26.00	+10.00	28.60
11	2	REAR EXHAUST PIPE MOUNTING <i>11</i>	15.00	30.00	+10.00	33.00
12	1	REAR END PANEL	157.00	157.00	+10.00	172.70
13	1	REAR END PANEL INNER GARNISH	48.00	48.00	+10.00	52.80
14	1	REAR TAILLAMP LH <i>11</i>	105.00	105.00	+10.00	115.50
15	1	REAR TAILLAMP RH <i>1</i>	105.00	105.00	+10.00	115.50
16	1	REAR TAILLAMP PANEL LH <i>1</i>	0.00	0.00	+10.00	0.00
17	1	REAR TAILLAMP PANEL RH <i>1</i>	0.00	0.00	+10.00	0.00
Total Parts (\$\$)						1,768.80

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER CLIPS <i>11</i>	35.00	35.00	0.00	35.00
2	1	REAR BUMPER SENSORS (SET) <i>short</i>	220.00	220.00	0.00	220.00
3	1	REAR BUMPER LOWER SPOILER <i>11</i>	650.00	650.00	0.00	650.00
4	1	REAR WINDSCREEN SEALANT <i>11</i>	60.00	60.00	0.00	60.00
5	1	REAR NUMBER PLATE <i>11</i>	35.00	35.00	0.00	35.00
Sub Total (\$\$)						1,000.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	80.00	0.00	80.00
3	1	To Transfer Rear Tailgate.	80.00	80.00	0.00	80.00
4	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	100.00	0.00	100.00
5	1	To Remove and Refit, Straighten and Re-adjust Exhaust Pipe and Rear Exhaust Silencer and Mountings.	180.00	180.00	0.00	180.00
6	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	600.00	600.00	0.00	600.00

Gross Labour Cost (\$\$) **1,070.00**

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	750.00	750.00	0.00	750.00

600

Gross Labour Cost (\$) 750.00

< END OF ESTIMATES >