

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Block 6 Woodlands Road 399F, Yew Tee Industrial Estate
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : AXA INSURANCE SINGAPORE PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTHQ/TP/1810/013
Policy No:	5082810781-02	Date of Loss:	19/10/2018
Vehicle Reg. No.:	SJS3418R	Driveable?	no
Driver Age:	25/06/1972	Third Party Vehicle No.:	SGD3625Z
Any Injuries?	no	Contact No:	97903075
Insured/Claimant:	CAROLINE BAY HWEE PHING	Driver:	CAROLINE BAY HWEE PHING

Make/Model:	Honda, Fit / Jazz - GE6	Vehicle Reg. Date:	12/08/2009
Vehicle Colour:	YELLOW	Engine Number:	L13A4122381
Chassis No:	GE61110475	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss COLLISION - HEAD TO REAR
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

COST OF CLAIMS

	Amount
Parts	1,768.80
Miscellaneous Items	1,000.00
Labour	1,070.00
Paintwork Labour	750.00
Towing	0.00
Gross Total(S\$):	4,588.80
GST 7.00%(S\$):	321.22
Nett Amount(S\$):	4,910.02

This claim is handled by: Sky Toh T C

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER	160.00	160.00	+10.00	176.00
2	1	REAR BUMPER SIDE RETAINER LH	11.00	11.00	+10.00	12.10
3	1	REAR BUMPER SIDE RETAINER RH	11.00	11.00	+10.00	12.10
4	1	REAR BUMPER TOWING COVER	10.00	10.00	+10.00	11.00
5	1	REAR TAILGATE	276.00	276.00	+10.00	303.60
6	1	REAR TAILGATE LOCK	60.00	60.00	+10.00	66.00
7	1	REAR TAILGATE LOCK CATCH	28.00	28.00	+10.00	30.80
8	1	REAR TAILGATE FIT EMBLEM	25.00	25.00	+10.00	27.50
9	1	REAR EXHAUST SILENCER	556.00	556.00	+10.00	611.60
10	1	REAR EXHAUST HEAT SHIELD	26.00	26.00	+10.00	28.60
11	2	REAR EXHAUST PIPE MOUNTING	15.00	30.00	+10.00	33.00
12	1	REAR END PANEL	157.00	157.00	+10.00	172.70
13	1	REAR END PANEL INNER GARNISH	48.00	48.00	+10.00	52.80
14	1	REAR TAILLAMP LH	105.00	105.00	+10.00	115.50
15	1	REAR TAILLAMP RH	105.00	105.00	+10.00	115.50
16	1	REAR TAILLAMP PANEL LH	0.00	0.00	+10.00	0.00
17	1	REAR TAILLAMP PANEL RH	0.00	0.00	+10.00	0.00
Total Parts (\$\$)						1,768.80

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER CLIPS	35.00	35.00	0.00	35.00
2	1	REAR BUMPER SENSORS (SET)	220.00	220.00	0.00	220.00
3	1	REAR BUMPER LOWER SPOILER	650.00	650.00	0.00	650.00
4	1	REAR WINDSCREEN SEALANT	60.00	60.00	0.00	60.00
5	1	REAR NUMBER PLATE	35.00	35.00	0.00	35.00
Sub Total (\$\$)						1,000.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	80.00	0.00	80.00
3	1	To Transfer Rear Tailgate.	80.00	80.00	0.00	80.00
4	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	100.00	0.00	100.00
5	1	To Remove and Refit, Straighten and Re-adjust Exhaust Pipe and Rear Exhaust Silencer and Mountings.	180.00	180.00	0.00	180.00
6	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	600.00	600.00	0.00	600.00
Gross Labour Cost (\$\$)						1,070.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	750.00	750.00	0.00	750.00

Gross Labour Cost (\$) 750.00

< END OF ESTIMATES >