

Trans-cah Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 315B**AAD1811-051**

Not Authorized
Presumy B4 part

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 315B

VF1ABL15AUC282361

RENAULT

LATITUDE

8.11.2018

CHINA TAIPING**PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>Bu/um</i>	1,259.42	✓
2	1	BUMPER SPOILER FRT	\$	<i>Sn</i>	181.75	X
3	1	BUMPER ABSORBER FRT	\$	<i>Tn</i>	394.68	✓
4	1	BUMPER RETAINER FRT LH	\$	<i>Sn</i>	151.41	X
5	1	BUMPER SUPPORT FRT	\$	<i>Sn</i>	123.88	X
6	1	BUMPER RETAINER FRT RH	\$	<i>DIT</i>	150.77	✓
7	1	BUMPER SUPPORT FRT	\$	<i>DIT</i>	123.88	✓
8	1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i>	472.83	X
9	1	BUMPER GRILLE LOWER FRT	\$	<i>DIT</i>	266.80	✓
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sn</i>	207.21	X
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>DIT</i>	207.21	✓
12	1	BUMPER BEAM FRT	\$	<i>Bz</i>	914.08	✓
13	1	TOW COVER FRT	\$	<i>Sn</i>	28.61	X
14	1	RADIATOR GRILLE	\$	<i>Sn</i>	1,707.78	} X
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>na</i>	225.36	
16	1	RADIATOR GRILLE FRAME	\$	<i>Sn</i>	1,353.75	
17	1	FRAME FULL SUPPORT PANEL	\$	<i>Sn</i>	615.90	
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i>	89.79	
19	1	FRONT BRACE PANEL	\$	<i>R</i>	177.22	
20	1	HORN	\$	<i>Sn</i>	314.17	
21	1	HORN BRACKET	\$	<i>R</i>	40.45	
22	1	HEADLAMP LH	\$	<i>Sn</i>	1,184.43	} X
22	1	HEADLAMP HARNESS	\$	<i>Sn</i>	928.29	
22	1	HEADLAMP RH	\$	<i>CM</i>	1,184.43	✓
22	1	HEADLAMP HARNESS	\$	<i>Sn</i>	928.29	X
22	1	HEADLAMP PANEL FRT LH	\$	<i>R</i>	152.15	X
25	1	HEADLAMP PANEL FRT RH	\$	<i>R</i>	152.15	X
26	1	BONNET	\$	<i>Bz</i>	1,941.63	✓

Trans-cab Auto Services Pte Ltd**AAD1811-051**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 315B

27	1	BONNET INSULATOR	\$	SL	405.73	
28	1	BONNET STRUT LH	\$	SL	88.61	
29	1	BONNET STRUT RH	\$	SL	88.61	
30	1	BONNET HINGE LH	\$	N	348.31	
31	1	BONNET HINGE RH	\$	N	348.31	
32	1	BONNET LOCK	\$	N	305.48	
33	1	BONNET CABLE	\$	SL	119.19	
34	1	BONNET CABLE COVER	\$	SL	161.03	
35	1	BONNET SEAL OUTER	\$	SL	92.36	
36	1	BONNET SEAL INNER	\$	SL	157.28	
37	1	FENDER PANEL FRT LH	\$	N	783.83	X
38	1	WHEELARCH FRT LH	\$	SL	278.84	X
39	1	FENDER BRACKET LOWER LH	\$	SL	15.79	X
40	1	FENDER INSULATOR LH	\$	SL	130.84	X
41	1	FENDER PANEL FRT RH	\$	N	783.83	
42	1	WHEELARCH FRT RH	\$	CNS	278.84	
43	1	FENDER BRACKET LOWER RH	\$	SL	15.79	X
44	1	FENDER INSULATOR RH	\$	SL	130.84	X
45	1	WIPER RESERVOIR	\$	N	348.25	
46	1	WIPER RESERVOIR NECK	\$	SL	136.11	
47	1	WIPER RESERVOIR MOTOR	\$	SL	270.06	
48	1	AIR CLEANER LOWER	\$	SL	271.26	
49	1	AIR CLEANER HOSE	\$	SL	76.14	
50	1	AIR CLEANER BOX	\$	SL	464.20	
51	1	TURBO DUCT	\$	SL	1,027.80	
52	1	A/C HEATER VALVE	\$	SL	484.50	
53	1	SUBFRAME OUTER FRT	\$	SL	2,652.45	
54	1	SUBFRAME BRACKET OUTER LH	\$	N	92.36	
55	1	SUBFRAME BRACKET OUTER RH	\$	N	92.36	
56	1	ENGINE UNDERTRAY	\$	SL	564.98	
57	1	A/C CONDENSER	\$	SL	2,020.37	
58	1	A/C CONDENSER GARNISH LH UPPER	\$	SL	39.67	
59	1	A/C CONDENSER GARNISH RH UPPER	\$	SL	39.67	
60	1	A/C CONDENSER GARNISH LH	\$	SL	58.81	
61	1	A/C CONDENSER GARNISH RH	\$	SL	59.60	
62	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	SL	208.39	
63	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	SL	658.72	
74	1	A/C PIPE COMPRESSOR	\$	SL	334.29	

Trans-cab Auto Services Pte Ltd**AAD1811-051**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 315B

75	1	A/C PIPE	\$	658.72
76	1	A/C COMPRESSOR	\$	2,684.61
77	1	AIR COOLER	\$	792.60
78	1	AIR INTERCOOLER HOSE (LONG)	\$	1,014.13
79	1	AIR INTERCOOLER HOSE (Short)	\$	375.14
80	1	TRANSMISSION COOLER	\$	1,219.30
81	1	TRANSMISSION COOLER PAD	\$	17.96
82	1	RADIATOR	\$	1,202.20
83	2	RADIATOR STUD UPPER	\$	14.41
84	2	RADIATOR BUSH UPPER	\$	50.12
85	2	RADIATOR MTG LOWER	\$	55.85
86	1	RADIATOR FAN COWLING	\$	820.54
87	1	RADIATOR FAN MOTOR LH	\$	967.36
88	1	RADIATOR FAN MOTOR RH	\$	1,479.46
89	1	RADIATOR TANK	\$	324.62
90	1	RADIATOR HOSE UPPER	\$	240.56
91	1	RADIATOR HOSE LOWER	\$	491.18
92	1	RADIATOR TANK HOSE	\$	61.18
93	1	AUTO COMPUTER	\$	5,032.17
94	1	INJECTION COMPUTER	\$	4,706.30
95	1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	5,154.52
96	1	STEERING PUMP ELECTRIC	\$	2,306.90
97	1	STEERING PINION RACK	\$	4,413.11

TOTAL	\$	63,994.74
10%	\$	6,399.47
	\$	57,595.27

Special Nett

1	1SET RADIATOR GRILLE FRAME CLIP	\$	52.00 X
2	1SET BUMPER CLIP FRT	\$	66.00 ✓

Trans-cab Auto Services Pte Ltd**AAD1811-051**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 315B

3	1	BUMPER BRACKET CLIP FRT LH	\$	nn	12.00	}
4	1	BUMPER SUPPORT CLIP FRT LH	\$	nn	10.50	
5	1	BUMPER BRACKET CLIP FRT RH	\$	nn	12.00	
6	1	BUMPER SUPPORT CLIP FRT RH	\$	nn	10.50	
7	1	TOW COVER FRT	\$	sn	14.50	
8	1SET	RADAIOR GRILLE SCREW	\$	sn	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	nn	69.00	
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT	\$	sn	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	sn	30.00	
21	1	Windscreen moulding	\$	nn	100.00	}
22	1SET	Front licence plate with holder	\$	sn	80.00	

TOTAL	\$	562.50
TOTAL PARTS	\$	58,157.77

Panel beating, knocking and straightening the
necessary portion, remove and renewal of parts,
adjust and realign the same

\$ 5,400.00 *500*

Towing Fees.

\$ 120.00 *50*

To apply paint protection system (PPS) maintain
and enhancement

\$ nn 380.00 *X*

Putty and spray painting of the affected portion.

\$ 5,000.00 *660*

To rust-proofing of the affected areas.

\$ 170.00 *80*

To remove and refit interior fittings, trimings,
garnish, fittings and other, to enable repair.

\$ nn 380.00 *X*

To check steering geometry and computer wheel
alignment

\$ nn 220.00 *X*

Trans-cab Auto Services Pte Ltd**AAD1811-051**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 315B

To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	nn 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	4 380.00	X
To lift-up engine with gear box and refit.	\$	4 440.00	X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	7 440.00	X
To remove and refit air bag system and reset.	\$	4 480.00	X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	4 380.00	X
To vacuum, replace, refix and recharge air condenser	\$	4 380.00	X
To replace, refix and top up coolant for radiator	\$	4 170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	4 170.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	nn 170.00	X

TOTAL \$ 15,400.00**Over All Total \$ 73,557.77****Repair Days (LUMP SUM) 20 DAYS***3 days*