



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

AXA Insured's Veh No : SHD9476K

Date of Accident : 08 November 2018

agree with Mr. Tan
confirm with main

\$12100.00

Miss Tan Yee Siang (Chen Yichang)

Not Allowed
Lhr
H/S \$12100
12/11/18
12 day.

Date : 08 November 2018

Lhr - Marcus
09/11/18 0950h

Estimate To Repair SLQ8507X - Audi A3 SB 1.4 TFSI AMBIENTE

Chassis No : WAUZZZ8P5DA033673

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	bonnet	\$ 1,982.50
02	2 pc	bonnet hinge @ \$43.00	\$ 86.00
03	1 pc	bonnet lock	\$ 210.00
04	1 pc	bonnet underseal weahterstrip garnish	\$ 19.00
05	1 pc	bonnet opening level top	\$ 44.25
06	2 pc	bonnet lock bottom @ \$132.50	\$ 265.00
07	2 pc	bonnet lock latch top @ \$77.75	\$ 155.50
08	1 pc	bonnet insulator	\$ 156.75
09	2 pc	bonnet insulator clip @ \$4.50	\$ 9.00
10	1 pc	radiator assy	\$ 880.00
11	1 pc	radiator grille with emblem badge	\$ 455.00
12	1 pc	radiator fan assy	\$ 1,352.50
13	1 pc	front support panel	\$ 650.00
14	1 pc	front support air baffle	\$ 53.75
15	1 pc	front bumper	\$ 1,450.00
16	2 pc	front bumper side retainer @ \$43.00	\$ 86.00
17	1 pc	front bumper reinforcement	\$ 496.25
18	2 ps	front bumper spot lamp @ \$451.00	\$ 902.00
19	2 ps	front bumper spot lamp garnish @ \$75.75	\$ 151.50
20	1 pc	front bumper absorber form	\$ 57.00
21	1 pc	front bumper reinforcement cover/garnish	\$ 38.00
22	2 pc	front bumper air guide @ \$21.75	\$ 43.50
23	2 pc	front bumper reinforcement stay @ \$185.00	\$ 370.00
24	1 pc	front bumper lower splashshield cover	\$ 108.50
25	2 pc	head lamp @ \$1620.00	\$ 3,240.00
26	1 pc	headlamp "Auto bend " control module	\$ 442.50
27	1 pc	head lamp side bracket	\$ 103.75
28	1 pc	headlamp washer nozzle	\$ 151.75
29	1 pc	headlamp washer nozzle hose	\$ 184.25
30	1 pc	headlamp washer nozzle cover	\$ 39.00
31	1 pc	headlamp washer nozzle holder	\$ 22.00
32	1 pc	headlamp washer nozzle hose "T" joint	\$ 23.25
33	1 pc	front support panel top air intake chamber	\$ 38.00
34	1 pc	aircon condenser	\$ 565.00
35	1 pc	n/s front fender	\$ 750.00
36	1 pc	front fender inner cowl	\$ 119.25
37	1 pc	front fender top bracket front	\$ 33.00
38	5 pc	front fender top bracket rivet @ \$2.50	\$ 12.50
39	1 pc	front fender top bracket rear	\$ 19.00



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AXA Insured's Veh No : SHD9476K
Date of Accident : 08 November 2018

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Miss Tan Yee Siang (Chen Yichang)

Date : 08 November 2018

Estimate To Repair SLQ8507X - Audi A3 SB 1.4 TFSI AMBIENTE
Chassis No : WAUZZZ8P5DA033673

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
40	1 pc	front fender top foam 11	\$ 23.50
41	1 pc	front fender air guide 11	\$ 22.75
42	1 pc	windshield washer tank 11	\$ 155.00
43	1 pc	windshield washer tank motor front 11	\$ 132.00
44	1 pc	windshield washer tank filter hose 11	\$ 32.00
45	1 pc	bootlid assy 10/3ul	\$ 1,800.00
46	1 pc	bootlid TFSI badge 11	\$ 135.00
47	1 pc	bootlid audi badge 11	\$ 110.00
48	1 pc	bootlid A3 badge 11	\$ 72.30
49	1 pc	bootlid weathertrip 11 188	\$ 320.00
50	1 pc	bootlid lock 11	\$ 320.00
51	1 pc	rear bumper 11	\$ 1,204.00
52	1 pc	rear bumper lower diffuser 11	\$ 418.60
53	2 ps	rear bumper parking sensor @ \$350.00 NF	\$ 700.00
54	1 pc	rear bumper reinforcement 11	\$ 550.00
55	1 pc	rear bumper absorber foam NF	\$ 380.00
56	1 pc	rear bumper inner frame 11	\$ 42.90
57	2 pc	rear bumper bracket @ \$47.45 11	\$ 94.90
58	2 pc	rear bumper side retainer @ \$47.45 11	\$ 94.90
59	1 pc	rear end panel 11	\$ 680.00
60	1 pc	rear end panel trimboard garnish 11	\$ 320.00
61	1 pc	rear exhaust box 11	\$ 1,366.00
62	2 ps	rear exhaust box chrome @ \$201.00 11	\$ 402.00
63	2 ps	front bumper parking sensor @ \$350.00 NF	\$ 700.00
Less 10% 50%			\$ 25,841.10
			\$ 2,584.11
			\$ 23,256.99
<u>SPECIAL NETT ITEMS</u>			
64	1 pc	radiator coolant 11	\$ 35.75
65	1 pc	front license plate 11	\$ 80.00
66	1 pc	rear windscreen sealant glass 11	\$ 50.00
67	1 pc	rear reverse camera 11	\$ 450.00
			\$ 615.75
<u>LABOUR & MISC. CHARGES</u>			
01		Towing with king dolly charges	\$ 150.00
02		To check electrical lighting concerned.	\$ 100.00
03		To rust-proofing of the affected areas.	\$ 450.00

18007.55

9003.77

35

20

40

2

95

100

30

100



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AXA Insured's Veh No : SHD9476K
Date of Accident : 08 November 2018

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Miss Tan Yee Siang (Chen Yichang)

Date : 08 November 2018

Estimate To Repair SLQ8507X - Audi A3 SB 1.4 TFSI AMBIENTE
Chassis No : WAUZZZ8P5DA033673

S/No	Quantity	Description	Amount
LABOUR & MISC. CHARGES			
04		To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas.	\$ 120.00
05		To transfer of bootlid fittings, attachments and perform water seepage test.	\$ 100.00
06		To reinstall of rear <i>reverse camera</i>	\$ 200.00
07		To drop rear exhaust box and renew the same.	\$ 11 100.00
08		Using onboard scan tool (OBD) perform full engine diagnostic check, to configure and clear, reset SRS service light.	\$ 11 450.00
09		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,800.00
10		Putty and spray painting of the affected portion.	\$ 1,600.00
			\$ 5,070.00
Total			\$ 28,942.74

100
60
50
X
X
1200
1400
3040

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AXA Insured's Veh No : SHD9476K
Date of Accident : 08 November 2018

Miss Tan Yee Siang (Chen Yichang)

Date : 14 November 2018

Supplementary To Repair SLQ8507X - Audi A3 SB 1.4 TFSI AMBIENTE
Chassis No : WAUZZZ8P5DA033673

S/No	Quantity	Description	Amount
01	1 pc	<u>LIST ITEMS</u>	
		left tail lamp	\$ 430.00
			\$ 430.00
		Less 10 %	\$ 43.00
		Total	\$ 387.00