



Lim Tan Motor Pte Ltd

Block 176 Sin Ming Drive # 03-09/10/06 Sin Ming Autocare Singapore 575721

Tel : 65-64520893 Fax : 65-64589127 Email : sales@ltm.sg

Website : www.ltm.sg

Co.Reg No. : 199307277D GST Reg No. : M2-0119086-0

TP INSURER: India International Insurance Pte Ltd (HQ)

COMFORT TRANSPORTATION PTE LTD

Singapore

Claimant Insurer: NTUC Income Insurance Co-operative Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	06/11/2018
Vehicle Reg. No.:	SJF9037K	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	CHEONG KAI HUP, BING	Driver (Insured):	TAN CHOON HWA

Make/Model:	DAIHATSU COPEN, 660CC (A)	Vehicle Reg. Date:	13/06/2008
Vehicle Colour:	YELLOW		
Engine No:	JB0372956	Chassis No:	L880K0042525
Odometer:	0 KM		

Paint Type:	
List Item Discount:	15.00 %
Total Loss?	NO
Est. Duration of Repair (day)	<i>5 & 4 days</i>

*Not with claim
claim 87
insurance after repair*

Description of Accident/Loss	COLLISION - HEAD TO REAR
Remarks:	VEHICLE NOT IN WORKSHOP, PLEASE CALL TO ARRANGE FOR SURVEY
Present Location:	LIM TAN MOTOR PTE LTD (HQ)

COST OF CLAIMS	Amount
Parts	1,963.80
Miscellaneous Items	10.00
Labour	550.00
Paintwork Labour	700.00
Towing	0.00
Gross Total (S\$)	3,223.80
+ GST 7.00% (S\$)	225.67
Nett Amount (S\$)	3,449.47

This claim is handled by: ANG WEI GUANG, RICHARD

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Nov 2018)

Parts: M1-COUPE DAIHATSU COPEN 660cc (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Lim Tan Motor Pte Ltd/SJF9037K/12/11/2018 16:29

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	15.00	0.00	<i>Am</i> *650.00 FL ✓
2	2		*REAR BUMPER BRACKET	15.00	0.00	*110.00 FL ✓
3	1		*REAR BUMPER LAMP	15.00	0.00	<i>PL</i> *380.00 FL ✓
4	1		*REAR BOOT LID	15.00	0.00	<i>n</i> *820.00 FL ✓
5	1		*REAR BOOT EMBLEM	15.00	0.00	<i>m</i> *68.00 FL ✓
6	1		*REAR BUMPER SENSOR	0	0.00	<i>na</i> *200.00 FS ✓
7	1		*REAR NUMBER PLATE	0	0.00	<i>CM</i> *40.00 FS ✓

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,268.00
- List Item Discount on L Items (S\$)	304.20
Total Parts (S\$)	1,963.80

Lim Tan Motor Pte Ltd/SJF9037K/12/11/2018 16:29. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	TO PUTTY AND SPRAY PAINTING	New	<i>500</i> 700.00
Labour Items			
2	TO ANTI RUST	New	<i>nn</i> 50.00 <i>λ</i>
3	LABOUR CHARGES	New	<i>400</i> 500.00
Gross Labour Cost (S\$)			1,250.00

Lim Tan Motor Pte Ltd/SJF9037K/12/11/2018 16:29. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >