

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKP 9950 J

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
21	BONNET MICRO SWITCH	\$	128.00 +	}
22	BONNET BOWDEN CABLE	\$	50.00 +	
23	BONNET LOCK CABLE COVER	\$	9.00 +	
24	LED HEADLIGHT-LH/RH <i>the new</i>	2 \$	5,806.00 +	
25	FRONT NO. PLATE <i>also</i>	S/N \$	25.00 ✓	
26	SUNDRIES <i>the new</i>	\$	300.00 ? X	
TOTAL SPARE PARTS CHARGES		:	\$ 17,631.00	
TOTAL LABOUR CHARGES			\$ 5,372.00	
GRAND TOTAL			\$ 23,003.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 13/11/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 05 Days

<p>Consultants hence notify</p> <p>of the following:</p> <ul style="list-style-type: none">• Resurvey before other spray painting• To apply damaged parts during resurvey• Parts prices are subject to confirmation• Third party survey is on a "Without Prejudice" basis• No illegal modifications allowed• Supplementary items must be resurveyed and is subject to final approval from Insurance Company. <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p>
--

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1272/2018/GW
Date : 9-Nov-18

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

5 days - ok - jb - 26 Dec 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. K Ramasamy
Address : 560 Upper East Coast Road
#04-07
Singapore 466580
Telephone : HP +65 94750871
Type of Claim : Own Damage Claims
Policy No. : 21003970763-04
Vehicle No : **SKP 9950 J**
Model Code : Audi A6 C7 2.0 TFSI Mu
Model / Year : Oct-14
Engine No : CDN 409447
Chassis No : WAUZZZ4G7EN146332
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 3-Nov-18
Place of Accident : PIE Towards TPE

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKP 9950 J

<u>S/n</u>	<u>Nature of Jobs</u>		<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove and transfer front wire harness for headlight, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$	480.00	\$ 480.00
2	To dismantle and renew front bumper, bonnet and both headlight. Re-organise crash management components. Reinstall all parts removed.	S/N \$	2,800.00	\$ 1,000.00
3	To respray front bumper, hinges and bonnet.	\$	1,900.00	\$ 1,100.00
4	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
SUB-TOTAL LABOUR CHARGES		:	\$ 5,372.00	\$ 2,772.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKP 9950 J.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 2,326.00	\$ 1,860.80
2	FRONT BUMPER FIXING PARTS	\$ 236.00	
3	FRONT BUMPER SPOILER	\$ 216.00	
4	RADIATOR GRILLE	\$ 1,174.00	\$ 939.20
5	RADIATOR GRILLE COVER	\$ 32.00	
6	FOAM FILLER PIECE	\$ 85.00	
7	FRONT BUMPER SIDE REINFORCEMENT	\$ 702.00	
8	FRONT BUMPER GUIDE PIEC-LH/RH	2 \$ 64.00	
9	FRONT BUMPER COVER	\$ 105.00	\$ 84.00
10	FRONT BUMPER CAP -LH/RH	2 \$ 98.00	
11	SIGN " CAUTION "	\$ 12.00	\$ 9.28
12	AIR CONDITIONER STICKER	\$ 17.00	\$ 13.44
13	REAR SENSOR	2 \$ 392.00	
14	BONNET	\$ 4,771.00	\$ 3,816.80
15	BONNET ATTACHMEN PARTS	\$ 123.00	
16	BONNET HINGE - LH/RH	2 \$ 282.00	
17	BONNET STOP BUFFER	4 \$ 93.00	
18	BONNET CATCH HOOK	\$ 122.00	
19	BONNET LOCK BAR	2 \$ 87.00	
20	BONNET LID LOCK	2 \$ 376.00	
SUB-TOTAL SPARE PARTS CHARGES		\$ 11,313.00	\$ 6,723.52

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKP 9950 J

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
			\$ 6,723.52
	<i>c/f</i>		
21	BONNET MICRO SWITCH	\$ 128.00	
22	BONNET BOWDEN CABLE	\$ 50.00	
23	BONNET LOCK CABLE COVER	\$ 9.00	
24	LED HEADLIGHT-LH/RH	2 \$ 5,806.00	
25	FRONT NO . PLATE	S/N \$ 25.00	\$ 25.00
26	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS CHARGES		\$ 17,631.00	\$ 6,748.52
TOTAL LABOUR CHARGES		\$ 5,372.00	\$ 2,772.00
GRAND TOTAL		\$ 23,003.00	\$ 9,520.52

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SKP 9950 J

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1272/2018/MAS

28 March 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SKP 9950 J, Audi A6 C7 2.0 TFSI Mu

With reference to the above-mentioned vehicle, no. **SKP 9950 J**, claimant, **Mr. K Ramasamy**, please find the related document per attached.

1. A copy of the Original invoice no. 85013601 – S\$9,330.96
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SKP 9950 J

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SKP 9950 J

Norah Khai
6768 9828
6841 1183
Body Repair
from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

PA/OD/1272/2018/JT
December 2018

1 total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A6 C7 2.0 TFSI Mu
Vehicle Chassis No. : WAUZZZ4G7EN146332
Vehicle Regn No. : **SKP 9950 J**
Vehicle Mileage : 90852 km
Vehicle Owner : Mr. K Ramasamy
Certificate No : 2100390763-04
Own Damage Excess : **SS856.00 (inclusive of 7% GST)**
Accident Date : 03rd November 2018
Place : PIE towards TPE
Repair Cost : \$ 9,330.96
WIP No. : 31008
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : _____
Date : 16/12/2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Nov 2018		13 Nov 2018 13:35 Edit Adj Rpt	\$9,520.52 Edit Estimates	\$9,520.52 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	K RAMASAMY , ID: S1842723J, Tel: +6594750871, Email: RAMASASCO@YAHOO.COM.SG	
Vehicle Reg. No.:	SKP9950J	Date of Loss: 03/11/2018 16:00 - :59 [48 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 9624165539SG	Policy/Cover Note No.: 2100390763-04 (Comprehensive) Coverage: 28/10/2018 - 27/10/2019
		Excess: S\$800.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911	
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 22/11/2018]	
Driver/Custodian:	K RAMASAMY (54 / Male) , NRIC: S1842723J, Tel: +6594750871 Email: RAMASASCO@YAHOO.COM.SG	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
<ul style="list-style-type: none"> AIG_SG (19/03/2019): Alert - Adj Mandate Approved (\$9520.52) - SKP9950J - Claim Handler: Loo, Tong S... AIG_SG (18/03/2019): Alert - Adj Mandate Maintained - SKP9950J - Claim Handler: Loo, Tong Shing AIG_SG (15/11/2018): Alert - Adj Mandate Approved (\$8876.00) - SKP9950J - Claim Handler: Loo, Tong S... AIG_SG (14/11/2018): Alert - Adj Mandate Maintained - SKP9950J - Claim Handler: Loo, Tong Shing AIG_SG (14/11/2018): SKP9950J / OD / 03/11/2018 / Coverage & Excess update 		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*SKP9950J (9624165539SG)
 OD
 Nov 3 2018 4:00PM
 [K RAMASAMY]
 Premium Automobiles Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)
View [View in Browser](#) ▼

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/11/18 08:17	Adjuster Immediate Advice	Load HTM	
2	13/02/19 14:36	Adjuster Immediate Advice	Load HTM	

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/11/18 17:18	General View	Load JPG	<input checked="" type="checkbox"/>
2	14/11/18 17:18	General View	Load JPG	<input checked="" type="checkbox"/>
3	14/11/18 17:18	General View	Load JPG	<input checked="" type="checkbox"/>
4	14/11/18 17:18	General View	Load JPG	<input checked="" type="checkbox"/>
5	14/11/18 17:18	General View	Load JPG	<input checked="" type="checkbox"/>
6	14/11/18 17:18	General View	Load JPG	<input checked="" type="checkbox"/>
7	14/11/18 17:18	General View	Load JPG	<input checked="" type="checkbox"/>
8	14/11/18 17:18	General View	Load JPG	<input checked="" type="checkbox"/>
9	14/11/18 17:18	General View	Load JPG	<input checked="" type="checkbox"/>
10	14/11/18 17:18	General View	Load JPG	<input checked="" type="checkbox"/>
11	14/11/18 17:18	General View	Load JPG	<input checked="" type="checkbox"/>
12	14/11/18 17:18	General View	Load JPG	<input checked="" type="checkbox"/>
13	14/11/18 17:18	General View	Load JPG	<input checked="" type="checkbox"/>
14	14/11/18 17:18	General View	Load JPG	<input checked="" type="checkbox"/>
15	14/11/18 17:18	General View	Load JPG	<input checked="" type="checkbox"/>
16	14/11/18 17:18	General View	Load JPG	<input checked="" type="checkbox"/>
17	14/11/18 17:18	General View	Load JPG	<input checked="" type="checkbox"/>
18	14/11/18 17:18	General View	Load JPG	<input checked="" type="checkbox"/>
19	14/11/18 17:18	General View	Load JPG	<input checked="" type="checkbox"/>
20	14/11/18 17:18	General View	Load JPG	<input checked="" type="checkbox"/>
21	14/11/18 17:18	General View	Load JPG	<input checked="" type="checkbox"/>
22	14/11/18 17:18	General View	Load JPG	<input checked="" type="checkbox"/>
23	14/11/18 17:18	General View	Load JPG	<input checked="" type="checkbox"/>
24	14/11/18 17:18	General View	Load JPG	<input checked="" type="checkbox"/>
25	14/11/18 17:18	General View	Load JPG	<input checked="" type="checkbox"/>
26	14/11/18 17:18	General View	Load JPG	<input checked="" type="checkbox"/>
27	14/11/18 17:18	General View	Load JPG	<input checked="" type="checkbox"/>
28	14/11/18 17:18	General View	Load JPG	<input checked="" type="checkbox"/>
29	19/03/19 10:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
30	19/03/19 10:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
31	19/03/19 10:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
32	19/03/19 10:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	19/03/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	19/03/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	19/03/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	19/03/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	19/03/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	19/03/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	19/03/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	19/03/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	19/03/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	19/03/19 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/11/18 14:26	Certificate of Insurance	 Load PDF	
2	13/11/18 14:26	ESTIMATE	 Load PDF	
3	13/11/18 14:27	Singapore Accident Statement	 Load PDF	
4	14/11/18 12:11	Driver's Driving License and NIRC	 Load PDF	
5	13/02/19 14:31	ESTIMATE MARKING	 Load PDF	
6	01/04/19 09:00	WORKSHOP INVOICE	 Load PDF	
7	01/04/19 09:00	DISCHARGE VOUCHER	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	05/11/18 12:50	Accident Statement	 Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	05/11/18 12:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	05/11/18 12:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	05/11/18 12:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	05/11/18 12:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	05/11/18 12:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	05/11/18 12:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	05/11/18 12:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	05/11/18 12:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	05/11/18 12:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	05/11/18 12:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	05/11/18 12:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	05/11/18 12:42	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	05/11/18 12:42	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18020497/ATBS2
Date: 01/04/2019

REFERENCE

Insured/Claimant: K RAMASAMY Policy No: 2100390763-04
Date of Loss: 03/11/2018 Nature of Claim: OD Claim No: 9624165539SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKP9950J**
Make & Model: AUDI A6, 2.0 TFSI MU (A) Engine No: CDN409447
Reg. Date: 28/10/2014 (Man. Year: 2014) Chassis No: WAUZZZ4G7EN146332
Colour: Black Odometer: 89578 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$98,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55R17 Rear Tyre Size: 225/55R17
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,631.00	6,748.52	10,882.48	61.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,372.00	2,772.00	2,600.00	48.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,003.00	9,520.52	13,482.48	58.61
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	22,203.00	8,720.52	13,482.48	60.72
+ GST 7.00/7.00% (S\$)	1,554.21	610.44	943.77	60.72
Nett Amount (S\$)	23,757.21	9,330.96	14,426.25	60.72

INSPECTION

Date of Assignment: 13/11/2018
Date Inspected: 13/11/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,326.00 FS	*1,860.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	236.00 FS	*- FS
3	1		*FRONT BUMPER SPOILER	Not Necessary	216.00 FS	*- FS
4	1		*RADIATOR GRILLE	Cracked	1,174.00 FS	*939.20 FS
5	1		*RADIATOR GRILLE COVER	Not Necessary	32.00 FS	*- FS
6	1		*FOAM FILLER PIECE	Not Necessary	85.00 FS	*- FS
7	1		*FRONT BUMPER SIDE REINFORCEMENT	Not Necessary	702.00 FS	*- FS
8	2		*FRONT BUMPER GUIDE PIEC - LH/RH	Not Necessary	64.00 FS	*- FS
9	1		*FRONT BUMPER COVER	Deformed	105.00 FS	*84.00 FS
10	2		*FRONT BUMPER CAP - LH/RH	Not Necessary	98.00 FS	*- FS
11	1		*SIGN CAUTION	Necessary	12.00 FS	*9.28 FS
12	1		*AIR CONDITION STICKER	Necessary	17.00 FS	*13.44 FS
13	2		*REAR SENSOR	Not Necessary	392.00 FS	*- FS
14	1		*BONNET	Dented	4,771.00 FS	*3,816.80 FS
15	1		*BONNET ATTACHMENT PARTS	Not Necessary	123.00 FS	*- FS
16	2		*BONNET HINGE - LH/RH	Not Necessary	282.00 FS	*- FS
17	4		*BONNET STOP BUFFER	Not Necessary	93.00 FS	*- FS
18	1		*BONNET CATCH HOOK	Not Necessary	122.00 FS	*- FS
19	2		*BONNET LOCK BAR	Not Necessary	87.00 FS	*- FS
20	2		*BONNET LID LOCK	Not Necessary	376.00 FS	*- FS
21	1		*BONNET MICRO SWITCH	Not Necessary	128.00 FS	*- FS
22	1		*BONNET BOWDEN CABLE	Not Necessary	50.00 FS	*- FS
23	1		*BONNET LOCK CABLE COVER	Not Necessary	9.00 FS	*- FS
24	2		*LED HEADLIGHT - LH/RH	Not Necessary	5,806.00 FS	*- FS
25	1		*FRONT NO. PLATE	Necessary	25.00 FS	*25.00 FS
26	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett,

Total Parts (S\$)	17,631.00	6,748.52
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	2,800.00	1,000.00
3	TO RESPRAY FRONT BUMPER, HINGES AND BONNET.	New	1,900.00	1,100.00
4	TO CARRY DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (S\$)			5,372.00	2,772.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >