

ASSESSMENT FOR REPAIR :FBC919K HONDA CBR600RR

1. Windscreen CR ✓	\$350
2. Head Cowling SC ✓	\$680
3. Left Side Mirror X	\$180
4. Right Side Mirror SC ✓	\$180
5. Headlight Unit Right Side CR ✓	\$600
6. Headlight Cover Right Side MS ✓	\$38
7. Stay Mirror Bracket CR ✓	\$280
8. Right Side Hander Bar PT ✓	\$265
9. Right Side Barend Shaft MS ✓	\$125
10. Throttle Cable Assy SC ✓	\$140
11. Throttle Cone DE ✓	\$60
12. Brake lever SC ✓	\$110
13. Left Barend X	\$75
14. Right Barend MS ✓	\$75
15. Right Side Top Cowling SC ✓	\$830
16. Right Center Cowling DE ✓	\$590
17. Right Signa Light Front SC ✓	\$165
18. Right Body Salaiter SC ✓	\$85
19. Rear Brake Padel PT ✓	\$185
20. Right Front Footrest SC ✓	\$110
21. Right Front Footrest Bracket SC ✓	\$90
22. Right Rear Footrest Bracket SC ✓	\$135
23. Right Rear Footrest SC ✓	\$110
24. Rear Tyre Shaft PT ✓	\$135
25. Rear Tyre Nut SC ✓	\$28
26. Rear seat cut ✓	\$265
27. Rear Tail Cover SC ✓	\$810
28. Right Rear Signa Light SC ✓	\$165
29. Rear Fander SC ✓	\$350
30. Tail Light Lamp ?	\$455
31. Left Side Top Cowling SC ✓	\$835
32. Left Center Cowling SC ✓	\$570
33. Left Body Salaiter SC ✓	\$85
34. Left Front Signa Light X	\$165
35. Headlight Cover Left Side X	\$38
36. Steering race Bearing X	\$150
37. Hander Grips cut ✓	\$25
38. Front No Plate SC ✓	\$15
39. Rear No Plate PT ✓	\$25
40. Towing	\$45 35
41. Labour Repair	\$450 300
42. workmanship	\$250 200

Repair 15/11/18
HP 90010068

5 days

4/5

14/11/18 @ 1220

Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Suppiementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total \$10,319