

## CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

Co Reg No : 199405410K ESTIMATE

GST Reg No : MR-8500111-X

o key No . 13	9405410K					GST Reg	No: MR-8500111
Invoice Name & Address				Owner Name & Vehicle Info			
Mr	Chin We	ei Liang Joel (Chen		Cust No/Name	LCV04764/Mr	Chin Wei Liang	Joel (Chen We
Weiliang) Blk 310 Bukit Batok Street 32				Reg No/Reg Date			
				Date In/Mileage	/	/ 0	
#04-01 Singapore 650310				Chassis No	KNAFZ411MJ5760991 G4FGHH690873		
			Engine No				
Contact No Mobile: 82013629				Make/Model KIA/CERATO K3 1.6 A SX SR			
				Colour ATHAMO Co	SWPLSNOWOWH	ETELINEAR / WK S	ATURN BLACK
				a the repairer	of the following store/after spray pa	1"	
Account No	Terms	Date/Time Printed	CSE	Operatoro display dan	naged part(s) during	WIP No	
CSM00081	Cash	08/11/2018/ 20:17		261 / Edwinnicaria	sabject to confirm	nati38591	
70,202,000		Description of Good	s / Services	e No illegal med	ification(s) is allowed	Unit Price Disc%	Amount
RENEW RH	R DOOR	ACCIDENT DAMAGED POR	RTION:	Supplementar is subject to fire	y item(s) must be re nal approval from in	DSUProvord and	1/00 2200.00
E PNT98000 RESPRAY F	RR BUMPER	R , RHR DOOR , RHF DO		Acknowledged b Signature: NDER , Date:	y Repairer		2520.00
E PNT88000		HR DOOR COMPONENTS	ווא וטכ				X 120.00
M SUNDRY		RIM & TRANSFER TYRE	пП		п		50.00
E PNT88000							X 120.00
REMOVE & REFIT RR FLR BOARD, TRIM. & CARPET [ ] A 54900099							30 80 00
CHECK WIRING ELECTRICAL SYSTEM							30.00
A 10028901							200.00
		GNOSTIC CHECK USING H	HI-SCAN PRO	TEST			
USING HI- WHEELALIGN		) IEST					9 120 00
		terize Full Wheel Ali	gnment				120.00
1 SUNDRY	1 000000	AU AFFEATER AREA	•				80, 120.00
APPLY ANI  SUNDRY	1 CORROS	SION ON AFFECTED AREA	ıS				
Sundries							20, 30.00
MHEEL ASS					1.00	926.00 00.00	at 926.00
M PANEL ASSY-REAR DOOR, RH					1.00	1309.00 00.00	
M BLACK TAPE-RR DR FRAME UPR,RH M TAPE-RR DR FRAME BLACK RR,RH					1.00	11.00 00.00 8.00 00.00	× 11.00
		PEARL SWP			1.00	1177.00 00.00	8.00 R 1177.00
		SURVEYOR NAME: _	Tay	m 9749574	1		, , ,
Confirm & ac	cepted by	y		3000			
		REMARKS:	1100	repair.	7% GST on	Nett 8991.00	8,991.00 629.37
		TEITH WATER	04 days	. 1		al Payable	9,620.37
Authorized s	ignatorv	and company stamp	_ ()				
		is 14 days from date of	musta This is	a computer concurt	I decument ==	elematume to use to	

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.