



PORSCHE

STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS

EUROKARS GROUP

INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04-06 IOB BUILDING
SINGAPORE 049711

ATTN.: MOTOR CLAIMS
FAX:

NAME: Dr Wong Nan-Yaw

ADDRESS: 43 Sunrise Walk
Singapore 806319

TEL:

WIP: 39498

EXCESS:

DATE: 12.11.2018

VEH NO:	SLS2904L	DATE IN:		CONTACT PERSON:	EVA	63310683
CHASSIS NO:	WP0ZZZ99ZJ5110939	MILEAGE:		TYPE OF CLAIM:	TP AGAINST SHA7765E	
MODEL:	911 Carrera S	DATE REG.:	19.09.2017	POLICY NO.:		

NATURE OF WORKS

Parts Description

		QTY		REVISED	PRICES
1	REAR BUMPER DE ✓	1	P991-505-022-35-		\$ 2,305.40
2	REAR BUMPER LOWER TRIM COVER DE ✓	1	P991-505-811-04-OK1		\$ 550.60
3	REAR BUMPER TAIL PIPE TRIM COVER SEA ✓	1	P991-505-651-04-OK1		\$ 200.10
4	REAR BUMPER BLIND RIVET SEA ✓	3	P999-190-191-30-		\$ 15.60
5	SENSOR PARKASSIST X	2	P5Q0-919-275-B -G2X		\$ 455.20
6	SENSOR GASKET SEA ✓	2	P5Q0-919-133- -9B9		\$ 5.00
7	REAR BUMPER SUPPORT ?	1	P991-505-639-03-		\$ 62.10
8	REAR BUMPER HEAT PROTECTION ?	1	P991-505-475-04-		\$ 372.90
9	LOGO PORSCHE GALVANO SILVER SEA ✓	1	P991-559-235-00-		\$ 191.10
10	LOGO CARRERA GALVANO SILVER SEA ✓	1	P991-559-237-01-		\$ 131.60
11	LOGO S GALVANO SILVER 991 SEA ✓	1	P991-559-243-01-		\$ 95.20
12	LOGO "911" SMALL SEA ✓	1	P991-559-231-02-		\$ 130.00
13	TAIL PIPE SPORT SET GTS ?	1	P991-044-200-25-		\$ 1,935.50
14	MUFFLER CLAMP SEA ✓	2	P9P1-253-145- -		\$ 142.20
15	MUFFLER CLAMP ?	2	P997-111-230-80-		\$ 169.00
16	MUFFLER RETAINING STRIPE ?	2	P9P1-251-571- -		\$ 204.80
17	MUFFLER HEXAGON NUT ?	8	PPAF-007-634- -		\$ 124.00
18	EXHAUST GASKET ?	2	P9A2-111-215-00-		\$ 67.20
19	MAIN MUFFLER ?	1	P9P1-251-053-B -		\$ 8,956.00

TOTAL PARTS

LESS 10%

TOTAL PARTS COST

\$ 16,113.50

\$ 1,611.35

\$ 14,502.15

Labour Description

1	TO REMOVE / REPLACE REAR BUMPER & OTHER DAMAGED PARTS & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	2340	\$ 3,120.00
2	TO RESPRAY REAR BUMPER & EMBLEM ("PORSCHE, 911, CARRERA, S" GUN METAL COLOR).	1300	\$ 1,500.00
3	TO REMOVE & REPLACE THE REAR EXHAUST ASSY.	NETT 780?	\$ 1,560.00
4	TO SUPPLY 1 PC NUMBER PLATE WITH CASING.	NETT 144	\$ 70.00
5	TO APPLY SPECIAL COATING.	NETT	TBA

6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	NETT 550	\$ 600.00
8	SUNDRIES.	NETT 30	\$ 50.00
		TOTAL LABOUR	\$ - \$ 7,150.00
		TOTAL PARTS	\$ - \$ 14,502.15
		TOTAL	\$ - \$ 21,652.15
		LESS EXCESS	\$ - \$ -
		TOTAL AFTER EXCESS	\$ - \$ -
		GST 7%	\$ - \$ -
		GRAND TOTAL	\$ - \$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Form
Hp 90010068
4 days
15/11/18 @ 1145
Resuy by part