

ASS./REC. BY:

REF:

CS/SM018020510 / Uqbnz

Special Instruction:

SURVEYOR:

ASSIGNMENT (Office)

Mulligan

From (Person):

Agnes Chan

of

SMO

Date/Time: 14/12/01 11:28am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKQ 3106P

Insured:

SKM 6438H

at Workshop m/s

Fostech Auto

Tel:

of

Blk 1 Kaki Bukit Ave 6 #01-46

Policy No:

D18MTPV0101492

Claim No:

CMTD1804983

Sum Insured:

Excess:

Make of Vch:

D.O.A.

13-112018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKQ 3106P - X

SKM 6438H - X

14/11/18 @ 2.40pm Informed Agnes Chan, we are pending estimate from repairer

24/11/18 @ 11.29am revised to Agnes Chan via MEXIMART.

08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

LTA 48995

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

6 yrs.

Radiator X 10 + 1 13005

26/11/18 4/5 @ 13.000 confirmed with Alu. (Red 849201.03, 79%)

RECEIVED 27 NOV 2018

Veh No:

SKP 31067

Yr Regn:

20/11/14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CAI

Make:

Toyota corolla Altis

c.c

1598

Colour

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

208655

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MRO53REH10.4519595

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

215/45 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

13/11/18

D.O.I.

13/11/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s & Lf.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

11/11/18

Date/Time, File Return to?

2)

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

12

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

___ S + RS ___ SI

Photos

Others

TOTAL

Report Format :

MEK-TP

Lump Sum / I.B.I: (\$

13000

450

10

460

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 27 Nov 2018

Preliminary Advice

Insured Vehicle No	: SKM6438H	Accident Date	: 13/11/2018
TP Vehicle No	: SKQ3106P	Assignment Date	: 14/11/2018
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 12.00
Date of Inspection	: 13/11/2018		
Inspection At	: FASTECH AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s & front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	62,201.03
Revised Amount	:S\$	18,798.99
Check Items (Estimated)	:S\$	0.00
Total	:S\$	18,798.99
Lump Sum Repair	:S\$	13,000.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Nov 2018		14 Nov 2018 11:28 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

TEO SENG CHAI, ID: S1711944C

Main Claimant:

LOUIS TAN, ID: S1623555E

Vehicle Reg. No.:

SKQ3106P

Date of Loss:

13/11/2018 08:00 - :59

Claim Type:

TP / CMTD1804983

Policy/Cover Note No.:

D18MTPV01014922 (Comprehensive)

Vehicle Reg. No. (Insured):

SKM6438H

Policy No. (Claimant):

Excess:

Repairer:

Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405

Handling Insurer:

Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/11/2018]

Driver/Custodian (Insured):

TEO SHU LIN (), NRIC: S8946872H, Tel: +6582807112

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Wednesday, 14 November 2018 2:40 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: VEHICLE SKQ 3106P (YOUR REF: CMTD1804983)

This mail is associated with :

***SKQ3106P (CMTD1804983)**

[SKM6438H]

TP

FASTLANE TRANSPORT SERVICES

Nov 13 2018 8:00AM

[TEO SENG CHAI]

Fastech Auto Pte Ltd

Dear Agnes,

Please be informed that we have inspected the vehicle SKQ 3106P on 13/11/2018.

We are pending estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



This email has been checked for viruses by AVG antivirus software.
www.avg.com



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more



toyota altis

Price Range

Depreciation

2014

Vehicle Type



Submit

Advanced Search

Home » Used Cars » Direct Owners » Toyota Corolla Altis 1.6A Elegance

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Tyres



Toyota Corolla Altis 1.6A Elegance

Overview

Financial

Accessories

Similar

Research

Photos

Map

DIRECT OWNER

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price \$64,000**Depreciation** \$9,330 /yr

View models with similar depreciation

Reg Date 18-Dec-2014

(6yrs 1mth 4days COE left)

Manufactured 2014**Mileage** 61,800 km (15.8k /yr)**Transmission** Auto**Engine Cap** 1,598 cc**Road Tax** \$742 /yr**Power** 90.0 kW (120 bhp)

View specs of the Toyota Corolla Altis (2014)

Curb Weight 1,205 kg**Features** 1.6L 4 Cylinders Inline 16 Valves DOHC Dual VVT-i Engine, 7 Speed Auto Transmission, Climate Control Aircon, Multi Function Steering, Auto Headlights.**Accessories** Factory Fitted Audio With Navigation, Full Leather Interior/Upholstery, Sports Rims, Parking Sensor With Reverse Camera, Keyless Entry, Push Start.**Description** Only 2.28% Loan Interest! Borneo Motors Warranty Till Dec 2019 With Unlimited Mileage, Full Agent Service, Both Front & Rear Installed With Blackvue Camera, Accident Free, Extremely Well Maintain Ed By One Owner, Smooth Running Engine & Gearbox, Spacious Boot And Fuel Efficient Car, All Tyres In Good Condition, Drive With Peace Of Mind, Trade In/Loan Available, Door Step Viewing Provided, Call Now**COE** \$63,990**OMV** \$19,143**ARF** \$14,143**Dereg Value** \$49,632 as of today (change)**No. of Owners** 1**Type of Veh** Mid-Sized Sedan**Category** PARF Car, Direct Owner Sale**Availability** Available

DIRECT OWNER

Add to Shortlist

Add to Compare

Add a Note

Posted on: 02-Nov-2018 | Last Updated on: 13-Nov-2018

100% FREE
PAPERWORK
SUPPORT FOR
BOTH BUYER
& SELLER

Price Analysis

Seller Information

Contact Person(s) Mr Peh**Contact No.** 96926486**Enquiry** Contact Seller

USEFUL FORMS

- » Indemnity form
- » Receipt
- » M01
- » Sales agreement
- » Hand-over form

Instructions on how to complete a seller to end-consumer deal

Regardless of buying or selling, we'll handle your paperwork, loans & insurance for FREE.



Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Compare

Save up to
\$629 on your car insurance!
We help you compare from 10 insurers!

Get your
cheaper
quote now!

**+\$150 Petrol
Voucher!**

toyota altis

Price Range

Depreciation

2014

Vehicle Type



Submit

Advanced
Search

Home » Used Cars » Prime Motor & Leasing » Toyota Corolla Altis 1.6A Elegance

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Toyota Corolla Altis 1.6A Elegance

Overview

Financial

Accessories

Similar

Research

Photos

Map



PRIME MOTOR & LEASING



[CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES]

• PRIME CAR RENTAL & TAXI SERVICES PTE LTD • SECTION CREDIT & MOTOR LEASING PTE LTD • BEST PETROL AND DIESEL SUPPLY PTE LTD • BEST ELECTRICITY SUPPLY PTE LTD

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price **\$59,800**Depreciation **\$9,440 /yr**

View models with similar depreciation

Reg Date **25-Jun-2014**
(5yrs 7mths 11days COE left)Manufactured **2014**Mileage **26,000 km (5.9k /yr)**Transmission **Auto**Engine Cap **1,598 cc**Road Tax **\$742 /yr**Power **90.0 kW (120 bhp)**
View specs of the Toyota Corolla Altis (2014)Curb Weight **1,205 kg**Features **Airbags, ABS, Reliable And Fuel Efficient 1.6L 4
Cylinders Inline Dual VVTI Engine, Super CVT Gearbox,
Keyless Start/Stop, Navigation System.**Accessories **Leather Seats, Sport Rims, Touch Screen Audio
System, Bluetooth, Reverse Camera, Steering Controls.**Description **One Owner Only, Very Low Mileage Done, Elegance
Model With Fitted In Navigation System And Reverse
Camera, Serviced By Agent, Accident Free, Low
Maintenance Cost, Very Well Maintained, Agent
Warranty Till June 2019, Drive Away With Minimum
Down Payment, Flexible In-House Loan Packages
Available.**COE **\$61,899**OMV **\$18,544**ARF **\$13,544**Dereg Value **\$44,923 as of today (change)**No. of Owners **1**Type of Veh **Mid-Sized Sedan**Category **PARF Car, Low Mileage Car**Availability **Available**

Seller Information

Company

Prime Motor & Leasing

• dealer's pricelist

• 91 vehs sold | 169 vehs available

Address

61 Ubi Avenue 2 #02-01/02/03

Search cars nearby this location

Location

Automobile Megamart

Office No

64440088

Contact Person(s)

Dennis	91182773
Mark	84995146
Pauline	97810269

Compare

[➤ Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	8747A
Vehicle Details	
Vehicle No.:	SKQ3106P
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA COROLLA ALTIS 1.6L CVT
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	1ZRY117289
Chassis No.:	MR053REH104519595
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,144.00
Original Registration Date:	20 Nov 2014
First Registration Date:	20 Nov 2014
Transfer Count:	1
Actual ARF Paid:	\$14,144.00 7072
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Nov 2024
PARF Rebate Amount:	\$10,608.00
Intended COE Rebate Details	
COE Expiry Date:	19 Nov 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$63,990.00
COE Rebate Amount:	\$38,387.00
Total Rebate Amount:	\$48,995.00

The information contained herein is correct as at 14 Nov 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/11/2018 15:08
Date Of Accident	13/11/2018 08:25
Exact Location Of Accident	PIE(TWRDS CHANGI BEFORE LORNIE EXIT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKQ3106P
Insured/Policyholder	
Name Of Registered Owner	FASTLANE TRANSPORT SERVICES
Co Reg No	53348747A
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91460700

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5091664466
Cover Note Number	

Driver

Name of Driver	TAN HONG CHYE
NRIC No	S1623555E
Date Of Birth	27/08/1963
Occupation	OUTDOOR
Date Of Driving Pass	13/03/1984
Driving Experience	34 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91460700
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 681A #03-92 JURONG WEST CENTRAL 1
Postcode	641681
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - SOLE-PROPIETOR
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	4
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKM6438H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SBV318U
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SJH8220T
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TAN HONG CHYE
Approximate Age
Injuries Sustain
Injured person in which vehicle? SKQ3106P
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address BLK 681A #03-92 JURONG WEST CENTRAL 1
Postcode 641681

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

13 NOV 2018


IDAC KAKI BUKIT(VAC)

Reporting Officer's Signature
Name: Singapore 415933
NRIC/FIN No.: Tel: 67416697
Fax: 67492305
Email: vackb@singnet.com.sg

Accident Sketch Plan Pg. 1

SKETCH PLAN

Vehicle A SKQ3106P
 Vehicle B SKM6438H
 Vehicle C SBV318U
 Vehicle D: ~~SBV318U~~
 SJH8220T



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date & time, I was driving on the stated venue. The front vehicle stopped & I follow suit. I stopped for a few seconds, vehicle B SKM6438H hit onto my vehicle SKQ3106P. The great impact pushes my car ^{to move} forward and hit onto the front vehicle SJH8220T.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

13 NOV 2018
 IDAC KAKI BUKIT(VAC)
 23 KAKI BUKIT AVE 4
 Singapore 415933
 Tel: 67416697
 Reporting Centre Person's Signature
 Name: Email: vackb@singnet.com.sg
 NRIC/FIN No.:

Date of Accident : 13 Nov 2018 Accident Time: 8:25am (24-HR-Format)
Accident Place : PIE Towards Changi before ^{Lorrie} Changi Exit
Vehicle No. (Car Plate No.) : 8KQ3104P Make/Model: Toyota Altis
Insurance Company : NTUC Policy No: 5091664466
Owner or Company Name / IC No. : Fastlane Transport Services / 53348747A
Owner or Company Contact No. : Owner's Hp 91460700 Company Tel
DRIVER'S Name / IC No. : Tan Hong Chye S1623555E
DRIVER'S Date Of Birth : 27/8/1963 DRIVER'S License Pass Date 13th Mar 1984
Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: owner
DRIVER'S Address : B1K681A Jurong West Central 1 #03-92 (S) 641681
DRIVER'S Contact No / Alt No. : 1) 91460700 2)
DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)
Email Address :
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance
Number of Passengers (Including Driver): 2
Was there any video Captured by car camera: YES \ NO
Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose
Any Injury (If YES, Pls state): yes

Other Party Driver's Particular (if any)

Vehicle No: B 8KM6438H	Vehicle No: C: SBV318U
Vehicle Make/Model:	Vehicle Make/Model:
Name Driver:	Name Driver:
IC No. Driver/Contact:	IC No. Driver/Contact:

* NEW - Passenger's name & gender:

Vehicle D: SJH8220T

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

Vehicle A SKQ 3106P

Vehicle B SKM 6438H

Vehicle C SBV 318U

Vehicle D: ~~SBV 318U~~
SJH 8220T



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date & time, I was driving on the stated venue. The front vehicle stopped & I follow suit. I stopped for a few seconds, vehicle B SKM 6438H hit onto my vehicle SKQ 3106P. The great impact pushes ~~to~~ move my car forward and hit onto the front vehicle SJH 8220T.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]

Reporting Centre Personnel's Signature
Name:
NBIC/CI/MLA:

Fastech Auto Pte Ltd

1 Kaki Bukit Avenue 6, #01-46/48/50, Autobay, Singapore 417883

H/P: 9487 7074 Tel: 6741 7244, 6746 5405

Fax: 6745 8520, 6746 5786

Email: general@fastechauto.com.sg

Vehicle No.: SKQ 3106P

Model: TOYOTA ALTIS

not allowed
here
d/s 13000
12th
13/11/18

QTY	List Price:		Prices \$
1	Rear boot lid	Bent/buc	733.80
1	Rear boot logo	ner	68.50
1	Rear boot emblem "COROLLA"	ner	42.50
1	Rear boot emblem "ALTIS"	ner	42.50
2	Rear boot lamps- R/L @ 328.10	285.10 M/Sen	656.20
1	Rear boot chrome moulding	11	281.65
2	Rear boot licence lamps @ 81.50	11	163.00
1	Rear boot inner trim	11	261.60
10	Rear boot inner trim clips @ 5.50	11	55.00
1	Rear boot inner lock	292.30 11	481.65
1	Rear boot lock striker	11	105.00
1	Rear boot lock cable	11	126.20
1	Rear boot w/strip	11	211.95
2	Rear boot hinges- R/L @ 110.60	Suc	221.20
2	Rear boot stopper @ 18.60	11	37.20
1	Rear bumper	D/S	681.60
2	Rear bumper reflector- R/L @ 95.50	M/Sen	191.00
2	Rear bumper PDC sensor @ 383.65	11	767.30
1	Rear bumper reinforcement	11	580.60
2	Rear bumper side brackets- R/L @ 105.00	M/Sen	210.00
2	Rear bumper side retainers- R/L @ 112.60	65.10 x 2 = 130.20 Buc	225.20
6	Rear bumper clips @ 5.50	ner	33.00
2	Rear bumper mudflap- R/L @ 115.00	11	230.00
2	Rear bumper reinforcement stays- R/L @ 155.00	M/Sen	310.00
1	Rear end panel	Bent/buc	962.60
1	Rear end panel trim	11	252.60
3	Rear end panel trim clips @ 5.50	11	16.50
1	Rear exhaust silencer	11	931.90
3	Rear exhaust mountings @ 48.60	11	97.20
1	Rear exhaust insulator	11	120.60
1	Rear centre exhaust pipe	11	1150.60

25%

1	Rear floor board	Torn	480.60	✓
1	Rear floor panel	n	744.15	α
2	Rear floor panel side member- R/L @ 285.00	n	570.00	α
1	Rear floor panel crossmember- CTR	n	441.50	α
2	Rear fenders- R/L @ 1257.60	n/s	2515.20	IPC
2	Rear fender inner trims- R/L @ 361.60	MSD's	723.20	IPC
10	Rear fender inner trim clips @ 6.50	n	65.00	X
2	Rear fender inner shields @ 110.45	MSD's	220.90	IPC
6	Rear fender inner shield clips @ 8.50	n	51.00	α
1	Rear fender air vent	Cra	114.65	✓
2	Rear fender inner panels- R/L @ 881.50	n	1763.00	α
2	Rear fender wheel housing- R/L @ 950.50	n	1901.00	α
2	Rear fender wheel housing extension- R/L @ 415.00	n	830.00	α
1	Rear fuel lid	n	141.20	X
1	Rear fuel opener	n	126.50	X
1	Rear fuel lock cable	n	110.80	X
1	Rear fuel filler pipe	n	281.90	X
1	Rear fuel tank assy	n	1285.60	X
1	Rear fuel tank float	n	935.50	X
1	Rear smart key less sensor	n	215.60	X
1	Rear spare wheel retainer lock	n	48.95	X
1	Rear speaker panel	n	1055.90	α
1	Rear speaker board	n	861.50	α
2	Rear shock absorber- R/L @ 481.60	n	963.20	X
2	Rear wheel hub with bearing- R/L @ 761.50	n	1523.00	X
1	Rear axle beam assy	n	2210.80	X
2	Rear door- R/L @ 1260.50	R	2521.00	α
2	Rear door inner lock- R/L @ 581.60	n	1163.20	X
2	Rear door inner boards- R/L @ 891.50	n	1783.00	α
2	Rear door glass outer mouldings @ 142.60	n	285.20	α
2	Rear door glass run channel @ 181.90	n	363.80	α
2	Rear door w/strip @ 161.20	n	322.40	α
2	Rear door checker- R/L @ 105.00	n	210.00	X
2	Rear door top hinges- R/L @ 115.00	n	230.00	α
2	Rear door lower hinges- R/L @ 115.00	n	230.00	α
2	Rear door lower step garnish @ 121.50	n	243.00	α
2	Rear passenger seat side cover- R/L @ 141.20	n	282.40	α
2	Rear taillamps- R/L @ 421.60	MSD's	843.20	IPC

2	Rear taillamp panels- R/L @ 448.55	MSD	897.10	lpc
2	Rear taillamp clips- R/L @ 12.60	11	25.20	
2	Rear taillamp lower brackets- R/L @ 18.60	11	37.20	X
1	Rear windscreen moulding	11	120.60	/
2	Rear side chassis member- R/L @ 560.90	11	1121.80	X
1	Front bonnet	ms/ 11	1426.95	/
1	Front bonnet seal	11	81.90	/
1	Front bonnet insulator	11	280.62	X
10	Front bonnet insulator clips @ 5.50	11	55.00	X
1	Front bonnet lock	11	135.60	/
1	Front bonnet lock cable	11	110.60	X
2	Front bonnet hinges- R/L @ 115.00	11	230.00	X
1	Front bonnet stand	11	110.20	X
1	Front bonnet stand clip	11	12.60	X
1	Front bumper	20/De	681.60	/
1	Front bumper CTR grille	11	140.65	/
2	Front bumper fog lamps- R/L @ 361.50	11	723.00	X
2	Front bumper fog lamp cover- R/L @ 126.50	11	253.00	X
1	Front bumper sponge	11	140.63	/
1	Front bumper reinforcement	11	561.60	/
2	Front bumper reinforcement stay- R/L @ 135.00	11	270.00	Xnn
2	Front bumper side retainers- R/L @ 89.95	11	179.90	/
10	Front bumper clips @ 5.50	11	55.00	/
2	Front fenders- R/L @ 761.50	11	1523.00	X
2	Front fender emblem " VVT-I " @ 58.50	11	117.00	X
2	Front fender inner shields- R/L @ 161.30	11	322.60	X
30	Front fender inner shield clips @ 5.50	11	165.00	X
1	Front grille assy	11	381.95	/
1	Front grille logo	11	89.95	/
4	Front grille clips @ 5.50	11	22.00	X
1	Front grille top garnish	11	130.60	X
10	Front grille top garnish clips @ 5.50	11	55.00	X
2	Front headlamps- R/L @ 3500.00	11	7000.00	/
4	Front headlamp lower brackets- R/L @ 89.95	11	179.90	X
2	Front headlamp side garnish- R/L @ 58.60	11	117.20	X
1	Front brace panel	11	130.95	/

1	Front support panel assy	675.11	1160.90	
2	Horn @ 105.00		210.00	X
1	Air con condenser	1418.30	1613.50	
1	Air con discharge pipe		481.90	X
1	Air con suction pipe		426.50	X
1	Air con liquid pipe		411.50	X
1	Air con compressor		1151.30	X
1	Air cleaner intake hose		186.20	X
1	Air cleaner box		455.60	X
1	Radiator assy		2101.50	X
1	Radiator top frame bracket		182.60	X
2	Radiator top mount @ 18.60		37.20	X
1	Radiator top hose		58.80	X
1	Radiator lower hose		62.40	X
1	Radiator fan cowl		291.66	X
1	Radiator fan blade		116.55	X
1	Radiator fan motor		581.80	X
1	Radiator spare tank		142.60	X
1	Radiator spare tank hose		120.10	X
1	Inlet manifold		1210.50	X
1	Engine mounting- RH		341.50	X
1	Engine mounting- FRT		281.90	X
1	Engine mounting- Rear		281.90	X
1	Engine mounting- LH		320.60	X
1	Engine undercover		211.60	X
1	Rear floor panel- inner		1460.50	X
2	Rear shock absorber top mount- R/L @ 180.60		361.20	X
			66354.71	
			Less 25%	(16588.68)
			Subtotal	49766.03

19371.99
14528.99

Special Nett Items:

1 Set	Rear windscreen sealant	80.00	40
1 Set	Rear no plate	60.00	X
2	Rear tyre- R/L @ 240.00	480.00	X
1	Rear reverse camera	450.00	X
1 Set	Front no plate	60.00	40
1 bot	A/C oil	65.00	X
1 bot	Radiator coolant	60.00	X
1 Set	Rear passenger leather seat assy- (use)	1500.00	X
		Subtotal	2755.00

Labour Charges:

Towing- use king roller	300.00	50
To checking F/R electrical wiring	120.00	30
To remove, refix R/windscreen	180.00	120
To remove, refix R/interior trims to assist repair	150.00	80
To remove, refix R/undercarriage	11 350.00	x
To reinstall rear fuel tank to assist repair	180.00	60
To remove, refix A/C condenser and refill A/C gas	180.00	100
To respray undercoating	200.00	150
To remove, refix engine parts	11 300.00	x
To respray painting and etc	2600.00	1800
Panel beating, cut, weld, remove and replacing above parts	5000.00	1800
To check wheel alignment	11 120.00	x
Subtotal	9680.00	

65726.03

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

62201.03

4270

1679899

16039

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18020510/UQBN2
Date: 04/12/2018

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01014922
Claimant Vehicle No :	SKQ3106P	Insured Vehicle No :	SKM6438H
Date of Loss:	13/11/2018	Nature of Claim:	TP
		Claim No:	CMTD1804983

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKQ3106P	Engine No:	1ZRY117289
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053REH104519595
Reg. Date:	20/11/2014 (Man. Year: 2014)	Odometer:	209655 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	56,046.03	14,608.99	41,437.04	73.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,680.00	4,190.00	5,490.00	56.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	65,726.03	18,798.99	46,927.04	71.40
Approved Total (Overridden) (\$\$)		13,000.00		
(\$\$)	65,726.03	13,000.00	52,726.03	80.22
+ GST 7.00/7.00% (\$\$)	4,600.82	910.00	3,690.82	80.22
Nett Amount (\$\$)	70,326.85	13,910.00	56,416.85	80.22

INSPECTION

Date of Assignment:	14/11/2018	
Date Inspected:	13/11/2018 Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	12.0 days	

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Dec 2018)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKQ3106P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent/Buckled	733.80 FL	*733.80 FL
2	1		*REAR BOOT LOGO	Necessary	68.50 FL	*68.50 FL
3	1		*REAR BOOT EMBLEM COROLLA	Necessary	42.50 FL	*42.50 FL
4	1		*REAR BOOT EMBLEM ALTIS	Necessary	42.50 FL	*42.50 FL
5	1		*REAR BOOT LAMPS-R/L	N/s Cracked	656.20 FL	*285.10 FL
6	1		*REAR BOOT CHROME MOULDING	Not Necessary	281.65 FL	*- FL
7	2		*REAR BOOT LICENCE LAMPS	Not Necessary	163.00 FL	*- FL
8	1		*REAR BOOT INNER TRIM	Not Necessary	261.60 FL	*- FL
9	10		*REAR BOOT INNER TRIM CLIPS	Not Necessary	55.00 FL	*- FL
10	1		*REAR BOOT INNER LOCK	Twisted	481.65 FL	*292.30 FL
11	1		*REAR BOOT LOCK STRIKER	Not Necessary	105.00 FL	*- FL
12	1		*REAR BOOT LOCK CABLE	Not Necessary	126.20 FL	*- FL
13	1		*REAR BOOT W/STRIP	Twisted	211.95 FL	*211.95 FL
14	2		*REAR BOOT HINGES-R/L	Serviceable	221.20 FL	*- FL
15	2		*REAR BOOT STOPPER	Not Necessary	37.20 FL	*- FL
16	1		*REAR BUMPER	Distorted	681.60 FL	*681.60 FL
17	1		*REAR BUMPER REFLECTOR-R/L	N/s Broken	191.00 FL	*95.50 FL
18	2		*REAR BUMPER PDC SENSOR	Not Necessary	767.30 FL	*- FL
19	1		*REAR BUMPER REINFORCEMENT	Dented	580.60 FL	*580.60 FL
20	1		*REAR BUMPER SIDE BRACKETS-R/L	N/s Bent	210.00 FL	*105.00 FL
21	2		*REAR BUMPER SIDE RETAINERS-R/L	Bent	225.20 FL	*130.20 FL
22	6		*REAR BUMPER CLIPS	Necessary	33.00 FL	*33.00 FL
23	2		*REAR BUMPER MUDFLAP-R/L	Not Necessary	230.00 FL	*- FL
24	1		*REAR BUMPER REINFORCEMENT STAYS-R/L	N/s Bent	310.00 FL	*155.00 FL
25	1		*REAR END PANEL	Badly Dented	962.60 FL	*962.60 FL
26	1		*REAR END PANEL TRIM	Twisted	252.60 FL	*252.60 FL
27	3		*REAR END PANEL TRIM CLIPS	Not Necessary	16.50 FL	*- FL
28	1		*REAR EXHAUST SILENCER	Not Necessary	931.90 FL	*- FL
29	3		*REAR EXHAUST MOUNTINGS	Not Necessary	97.20 FL	*- FL
30	1		*REAR EXHAUST INSULATOR	Not Necessary	120.60 FL	*- FL
31	1		*REAR CENTRE EXHAUST PIPE	Not Necessary	1,150.60 FL	*- FL
32	1		*REAR FLOOR BOARD	Torn	480.60 FL	*480.60 FL
33	1		*REAR FLOOR PANEL	Repair	744.15 FL	*- FL
34	2		*REAR FLOOR PANEL SIDE MEMBER-R/L	Repair	570.00 FL	*- FL
35	1		*REAR FLOOR PANEL CROSSMEMBER-CTR	Repair	441.50 FL	*- FL
36	1		*REAR FENDERS-R/L	N/s Buckled/O/s Repair	2,515.20 FL	*971.10 FL
37	1		*REAR FENDER INNER TRIMS-R/L	N/s Distorted	723.20 FL	*361.60 FL
38	10		*REAR FENDER INNER TRIM CLIPS	Not Necessary	65.00 FL	*- FL
39	1		*REAR FENDER INNER SHIELDS	N/s Torn	220.90 FL	*110.45 FL
40	6		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	51.00 FL	*- FL
41	1		*REAR FENDER AIR VENT	Cracked	114.65 FL	*114.65 FL
42	2		*REAR FENDER INNER PANELS-R/L	Repair	1,763.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	2		*REAR FENDER WHEEL HOUSING-R/L	Repair	1,901.00 FL	*- FL
44	2		*REAR FENDER WHEEL HOUSING EXTENSION-R/L	Repair	830.00 FL	*- FL
45	1		*REAR FUEL LID	Not Necessary	141.20 FL	*- FL
46	1		*REAR FUEL OPENER	Not Necessary	126.50 FL	*- FL
47	1		*REAR FUEL LOCK CABLE	Not Necessary	110.80 FL	*- FL
48	1		*REAR FUEL FILLER PIPE	Not Necessary	281.90 FL	*- FL
49	1		*REAR FUEL TANK ASSY	Not Necessary	1,285.60 FL	*- FL
50	1		*REAR FUEL TANK FLOAT	Not Necessary	935.50 FL	*- FL
51	1		*REAR SMART KEY LESS SENSOR	Not Necessary	215.60 FL	*- FL
52	1		*REAR SPARE WHEEL RETAINER LOCK	Not Necessary	48.95 FL	*- FL
53	1		*REAR SPEAKER PANEL	Not Necessary	1,055.90 FL	*- FL
54	1		*REAR SPEAKER BOARD	Not Necessary	861.50 FL	*- FL
55	2		*REAR SHOCK ABSORBER-R/L	Not Necessary	963.20 FL	*- FL
56	2		*REAR WHEEL HUB WITH BEARING-R/L	Not Necessary	1,523.00 FL	*- FL
57	1		*REAR AXLE BEAM ASSY	Not Necessary	2,210.80 FL	*- FL
58	2		*REAR DOOR-R/L	Repair	2,521.00 FL	*- FL
59	2		*REAR DOOR INNER LOCK-R/L	Not Necessary	1,163.20 FL	*- FL
60	2		*REAR DOOR INNER BOARDS-R/L	Not Necessary	1,783.00 FL	*- FL
61	2		*REAR DOOR GLASS OUTER MOULDINGS	Not Necessary	285.20 FL	*- FL
62	2		*REAR DOOR GLASS RUN CHANNEL	Not Necessary	363.80 FL	*- FL
63	2		*REAR DOOR W/STRIP	Not Necessary	322.40 FL	*- FL
64	2		*REAR DOOR CHECKER-R/L	Not Necessary	210.00 FL	*- FL
65	2		*REAR DOOR TOP HINGES-R/L	Not Necessary	230.00 FL	*- FL
66	2		*REAR DOOR LOWER HINGES-R/L	Not Necessary	230.00 FL	*- FL
67	2		*REAR DOOR LOWER STEP GARNISH	Not Necessary	243.00 FL	*- FL
68	2		*REAR PASSENGER SEAT SIDE COVER-R/L	Not Necessary	282.40 FL	*- FL
69	1		*REAR TAILLAMPS-R/L	N/s Broken	843.20 FL	*421.60 FL
70	1		*REAR TAILLAMP PANELS-R/L	N/s Dented	897.10 FL	*448.55 FL
71	2		*REAR TAILLAMP CLIPS-R/L	Not Necessary	25.20 FL	*- FL
72	2		*REAR TAILLAMP LOWER BRACKETS-R/L	Not Necessary	37.20 FL	*- FL
73	1		*REAR WINDSCREEN MOULDING	Necessary	120.60 FL	*120.60 FL
74	2		*REAR SIDE CHASSIS MEMBER-R/L	Repair	1,121.80 FL	*- FL
75	1		*FRONT BONNET	Dented/Buckled	1,426.95 FL	*1,426.95 FL
76	1		*FRONT BONNET SEAL	Necessary	81.90 FL	*81.90 FL
77	1		*FRONT BONNET INSULATOR	Not Necessary	280.62 FL	*- FL
78	10		*FRONT BONNET INSULATOR CLIPS	Not Necessary	55.00 FL	*- FL
79	1		*FRONT BONNET LOCK	Twisted	135.60 FL	*135.60 FL
80	1		*FRONT BONNET LOCK CABLE	Not Necessary	110.60 FL	*- FL
81	2		*FRONT BONNET HINGES-R/L	Not Necessary	230.00 FL	*- FL
82	1		*FRONT BONNET STAND	Not Necessary	110.20 FL	*- FL
83	1		*FRONT BONNET STAND CLIP	Not Necessary	12.60 FL	*- FL
84	1		*FRONT BUMPER	Dented/Deformed	681.60 FL	*681.60 FL
85	1		*FRONT BUMPER CTR GRILLE	Torn	140.65 FL	*140.65 FL
86	2		*FRONT BUMPER FOG LAMPS-R/L	Not Necessary	723.00 FL	*- FL
87	2		*FRONT BUMPER FOG LAMP COVER-R/L	Not Necessary	253.00 FL	*- FL
88	1		*FRONT BUMPER SPONGE	Torn	140.63 FL	*140.63 FL
89	1		*FRONT BUMPER REINFORCEMENT	Bent	561.60 FL	*561.60 FL
90	2		*FRONT BUMPER REINFORCEMENT STAY-R/L	Not Necessary	270.00 FL	*- FL
91	2		*FRONT BUMPER SIDE RETAINERS-R/L	Bent	179.90 FL	*179.90 FL
92	10		*FRONT BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
93	2		*FRONT FENDERS-R/L	Repair	1,523.00 FL	*- FL
94	2		*FRONT FENDER EMBLEM VVT-I	Not Necessary	117.00 FL	*- FL
95	2		*FRONT FENDER INNER SHIELDS-R/L	Not Necessary	322.60 FL	*- FL
96	1		*FRONT FENDER INNER SHIELD CLIPS (30 Pcs)	Not Necessary	165.00 FL	*- FL
97	1		*FRONT GRILLE ASSY	Cracked	381.95 FL	*381.95 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
98	1		*FRONT GRILLE LOGO	Necessary	89.95 FL	*89.95 FL
99	4		*FRONT GRILLE CLIPS	Not Necessary	22.00 FL	*- FL
100	1		*FRONT GRILLE TOP GARNISH	Not Necessary	130.60 FL	*- FL
101	10		*FRONT GRILLE TOP GARNISH CLIPS	Not Necessary	55.00 FL	*- FL
102	2		*FRONT HEADLAMPS-R/L	Cracked	7,000.00 FL	*5,570.00 FL
103	4		*FRONT HEADLAMP LOWER BRACKETS-R/L	Not Necessary	179.90 FL	*- FL
104	2		*FRONT HEADLAMP SIDE GARNISH-R/L	Not Necessary	117.20 FL	*- FL
105	1		*FRONT BRACE PANEL	Twisted	130.95 FL	*130.95 FL
106	1		*FRONT SUPPORT PANEL ASSY	Bent	1,160.90 FL	*675.11 FL
107	2		*HORN	Not Necessary	210.00 FL	*- FL
108	1		*AIR CON CONDENSER	Bent/Punctured	1,613.50 FL	*1,418.30 FL
109	1		*AIR CON DISCHARGE PIPE	Not Necessary	481.90 FL	*- FL
110	1		*AIR CON SUCTION PIPE	Not Necessary	426.50 FL	*- FL
111	1		*AIR CON LIQUID PIPE	Not Necessary	411.50 FL	*- FL
112	1		*AIR CON COMPRESSOR	Not Necessary	1,151.30 FL	*- FL
113	1		*AIR CLEANER INTAKE HOSE	Not Necessary	186.20 FL	*- FL
114	1		*AIR CLEANER BOX	Not Necessary	455.60 FL	*- FL
115	1		*RADIATOR ASSY	Not Necessary	2,101.50 FL	*- FL
116	1		*RADIATOR TOP FRAME BRACKET	Not Necessary	182.60 FL	*- FL
117	2		*RADIATOR TOP MOUNT	Not Necessary	37.20 FL	*- FL
118	1		*RADIATOR TOP HOSE	Not Necessary	58.80 FL	*- FL
119	1		*RADIATOR LOWER HOSE	Not Necessary	62.40 FL	*- FL
120	1		*RADIATOR FAN COWLING	Not Necessary	291.66 FL	*- FL
121	1		*RADIATOR FAN BLADE	Not Necessary	116.55 FL	*- FL
122	1		*RADIATOR FAN MOTOR	Not Necessary	581.80 FL	*- FL
123	1		*RADIATOR SPARE TANK	Not Necessary	142.60 FL	*- FL
124	1		*RADIATOR SPARE TANK HOSE	Not Necessary	120.10 FL	*- FL
125	1		*INLET MANIFOLD	Not Necessary	1,210.50 FL	*- FL
126	1		*ENGINE MOUNTING-RH	Not Necessary	341.50 FL	*- FL
127	1		*ENGINE MOUNTING-FRT	Not Necessary	281.90 FL	*- FL
128	1		*ENGINE MOUNTING-REAR	Not Necessary	281.90 FL	*- FL
129	1		*ENGINE MOUNTING-LH	Not Necessary	320.60 FL	*- FL
130	1		*ENGINE UNDERCOVER	Not Necessary	211.60 FL	*- FL
131	1		*REAR FLOOR PANEL-INNER	Repair	1,460.50 FL	*- FL
132	2		*REAR SHOCK ABSORBER TOP MOUNT-R/L	Not Necessary	361.20 FL	*- FL
133	1		*SET REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
134	1		*SET REAR NO PLATE	Not Necessary	60.00 FS	*- FS
135	2		*REAR TYRE-R/L	Not Necessary	480.00 FS	*- FS
136	1		*REAR REVERSE CAMERA	Not Necessary	450.00 FS	*- FS
137	1		*SET FRONT NO PLATE	Bent	60.00 FS	*40.00 FS
138	1		*BOT A/C OIL	Not Necessary	65.00 FS	*- FS
139	1		*BOT RADIATOR COOLANT	Not Necessary	60.00 FS	*- FS
140	1		*SET REAR PASSENGER LEATHER SEAT ASSY-(USE)	Not Necessary	1,500.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 73,809.71 19,451.99
 - List Item Discount on L Items 25.00/25.00% (\$\$) 17,763.68 4,843.00

Total Parts (\$\$) 56,046.03 14,608.99

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING-USE KING ROLLER	New	300.00	50.00
2	TO CHECKING F/R ELECTRICAL WIRING	New	120.00	30.00
3	TO RMEOVE,REFIX R/WINDSCREEN	New	180.00	120.00
4	TO RMEOVE,REFIX R/INTERIOR TRIMS TO ASSIST REPAIR	New	150.00	80.00
5	TO RMEOVE,REFIX R/UNDERCARRIAGE	New	350.00	-
6	TO REINSTALL REAR FUEL TANK TO ASSIST REPAIR	New	180.00	60.00
7	TO REMOVE,REFIX A/C CONDENSER AND REFILL A/C GAS	New	180.00	100.00
8	TO RESPRAY UNDERCOATING	New	200.00	150.00
9	TO REMOVE,REFIX ENGINE PARTS	New	300.00	-
10	TO RESPRAY PAINTING AND ETC	New	2,600.00	1,800.00
11	PANEL BEATING,CUT,WELD,REMOVE AND REPLACING ABOVE PARTS	New	5,000.00	1,800.00
12	TO CHECK WHEEL ALIGNMENT	New	120.00	-
Gross Labour Cost (S\$)			9,680.00	4,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >