

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 8549X

DATE 12/11/2018 9:41

MAKE :

DOA: 08.11.2018

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover /			\$ 544.50
	Front Bumper Bracket Top (LH) ?			\$ 22.40
	Front Bumper Bracket (LH) /			\$ 24.60
	Frt Wheel Hub Cap, LH /			\$ 107.10
	SUB TOTAL			\$ 698.60
	LESS 20%			\$ 139.72
	DISCOUNTED TOTAL			\$ 558.88
	Labour Charge			200
	Panel Beating-Repair Fender			\$ 400.00
	Spray Painting Charge		400	\$ 600.00
	Tuff Kote			\$ 50.00
	Frt Wheel Alignment			\$ 80.00
	TOTAL LABOUR			\$ 1,130.00
	ESTIMATE TOTAL			\$ 1,688.88

Kalin LKK

12/11/18 1505hrs

2 days

P/P

Before Paint photo

Lorry Ng

LKK Auto Consultants hence notify the Repaired of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.