

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

(SUPPLEMENTARY)**INSURER: EQ Insurance Company Ltd (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPPHQ18-003284	Date of Loss:	09/11/2018
Vehicle Reg. No.:	SGH1948J	Driveable?	
Driver Age/Info:	35 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TAN LAN CHENG	Contact No:	+6596319497
Driver:	TAN LAN CHENG		
Make/Model:	TOYOTA VIOS, 1.5 E (M)	Vehicle Reg. Date:	01/06/2006
Vehicle Colour:	GOLD		
Engine No:	1NZX432738	Chassis No:	MR053HY4204188105
Odometer:	5 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	AS PER POLICE REPORT NO.T/20181109/2132.		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

COST OF CLAIMS

	Amount
Parts	1,412.30
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	1,412.30
+ GST 7.00% (S\$)	98.86
Nett Amount (S\$)	1,511.16
+ Previous Estimates (S\$)	6,012.33
Claim Total (S\$)	7,523.49

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 03 Jan 2019)**Parts:** 143 TOYOTA VIOS 1.5 E (M) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Sng Ah Tee Motor & Panel Service Pte Ltd/SGH1948J/03/01/2019 16:06**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*AIRCON COMPRESSOR <i>PA</i> ✓	0.00	0.00	*850.00 F
2	1		*ENGINE OIL SUMP <i>PA</i> ✓	0.00	0.00	*75.00 F
3	1		*OIL SUMP GASKET <i>neu</i> ✓	0.00	0.00	*15.00 F
4	1		*OIL SUMP SILICON <i>neu</i> ✓	0	0.00	*20.00 FS
5	1		*OIL SUMP DRAIN NUT <i>neu</i> ✓	0.00	0.00	*10.00 F
6	1		*OIL SUMP DRAIN PLUG WASHER <i>neu</i> ✓	0.00	0.00	*3.00 F
7	1		*ENGINE OIL (4LITRE) <i>neu</i> ✓	0	0.00	*80.00 FS
8	1		*ENGINE MOUNTING REAR <i>PA</i> ✓	0.00	0.00	*45.00 F
9	1		*ENGINE MOUNTING LH <i>PA</i> ✓	0.00	0.00	*50.00 F
10	1		*ENGINE MOUNTING RH <i>PA</i> ✓	0.00	0.00	*75.00 F
11	2		*FRT BUMPER REINFORCEMENT ARM <i>PA</i> ✓	0.00	0.00	*70.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	1,293.00
+ Margin on L,N Items 10.00% (S\$)	119.30
Total Parts (S\$)	1,412.30

Sng Ah Tee Motor & Panel Service Pte Ltd/SGH1948J/03/01/2019 16:06. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Sng Ah Tee Motor & Panel Service Pte Ltd/SGH1948J/03/01/2019 16:06. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >