

1552111

INS. CASE OWNER:

CC 4 / AXA1802 0575, Fpbh⁵²LKK:
IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(VL: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28. Ass. Lia:

Repair Cost:

S\$

2884.00

Loss of Rental (LOR):

S\$

720.00

(6 days)

x \$120.00

Loss of Use (LOU):

S\$

-

(5 x days)

Loss of Income (LOI):

S\$

-

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

S\$

2.00

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

Total:

S\$

3611.00

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

3611.00

Name 1:

Accord Auto Services Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

250.00

250.00

REF:

ASM

ASSIGNMENT

From

Date: 13/11

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SGS 1673T

at Workshop m/s Accord Auto

of 10 AMC #03-11

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$67k

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

11/26

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SGS 1673T Yr Regn: 01 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

M. E 200

C.C.

1788

Colour:

M.D. Brown

A/C.

Insured / Std / NI / NA

Sp. Reading:

222 743

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WOB 2110412B 074784

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F:

225/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal.

7

mm

R/Bal.

5

mm

L/Bal.

7

mm

L/Bal.

5

mm

D.O.A.

9/11/18

D.O.I.

13/11/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

14/11

File pass to Corham

45 \$ 270 CRE + 6159.70 / 700

4 + 1 PRS + 1 Sum. - 2

Date/Time. File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time. File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ - RS. SI

) Photos

) Others

TOTAL

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Not Withheld ESTIMATE

AXA Insurance Singapore Pte Ltd

8 Shenton Way,

#27-01/02 AXA Tower

Singapore 068811

Attn: Motor Claims Department

11 Lp 827001
Penny Ate Rain

Date : 10/11/2018

Vehicle No : SGS1673T

Veh Make/Model : Mercedes Benz E200K

YOM : 2006

Chassis No : WDB2110412B074784

Date of Accident : 09/11/2018

4 days

No	Qty	Description	Amount S
<u>List Items:-</u>			
1	1	Rear bootlid	\$ <i>R</i> 2,210.00 <i>X</i>
2	1	Rear bootlid logo	\$ <i>re</i> 47.00 <i>—</i>
3	1	Rear bootlid "E200" emblem	\$ <i>re</i> 76.00 <i>—</i>
4	1	Rear bootlid "KOMPRESSOR" emblem	\$ <i>re</i> 106.00 <i>—</i>
5	1	Rear bootlid lock	\$ <i>R</i> 176.00 <i>X</i>
6	1	LH tail lamp	\$ <i>re</i> 472.00 <i>X</i>
7	1	RH tail lamp	\$ <i>re</i> 472.00 <i>X</i>
8	1	Rear bumper	\$ <i>re</i> 1,372.00 <i>—</i>
9	1	Rear bumper trim moulding w chrome strip (center)	\$ <i>re</i> 187.00 <i>—</i>
10	1	Rear bumper trim moulding w chrome strip (RH)	\$ <i>re</i> 132.00 <i>—</i>
11	1	Rear bumper trim moulding w chrome strip (LH)	\$ <i>re</i> 132.00 <i>—</i>
12	2	Rear bumper side bracket	\$ <i>CM</i> 48.00 <i>—</i>
13	2	Rear bumper side attachemnt	\$ <i>re</i> 84.00 <i>X</i>
14	1	Rear bumper reinforcement	\$ <i>re</i> 578.00 <i>X</i>
15	1	End panel	\$ <i>R</i> 741.00 <i>X</i>
Total - List Item			\$ 6,833.00
Less 10%			\$ <i>SGS</i> 683.30
Total			\$ 6,149.70
<u>Special Nett Items:-</u>			
1	10	Rear bumper clip	\$ <i>re</i> 90.00 <i>—</i>
2	1 Set	Rear bumper reverse sensor	\$ <i>short</i> 380.00 <i>2001N</i>
Total - SN Item			\$ 470.00
Balance b/f			\$ 6,619.70

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

AXA Insurance Singapore Pte Ltd
8 Shenton Way,
#27-01/02 AXA Tower
Singapore 068811
Attn: Motor Claims Department

Date : 10/11/2018
Vehicle No : SGS1673T
Veh Make/Model : Mercedes Benz E200K
YOM : 2006
Chassis No : WDB2110412B074784
Date of Accident : 09/11/2018

[illegible]

9037.90

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

SUPPLEMENTARY

AXA Insurance Singapore Pte Ltd
8 Shenton Way,
#27-01/02 AXA Tower
Singapore 068811
Attn: Motor Claims Department

Date : 13/11/2018
Vehicle No : SGS1673T
Veh Make/Model : Mercedes Benz E200K
YOM : 2006
Chassis No : WDB2110412B074784
Date of Accident : 09/11/2018

[illegible]

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Not Withheld

ESTIMATE

AXA Insurance Singapore Pte Ltd

8 Shenton Way,

#27-01/02 AXA Tower

Singapore 068811

Attn: Motor Claims Department

11 Sep 07
Punary After Paint
4 day

Date : 10/11/2018
Vehicle No : SGS1673T
Veh Make/Model : Mercedes Benz E200K
YOM : 2006
Chassis No : WDB2110412B074784
Date of Accident : 09/11/2018

No	Qty	Description	Amount \$
		List Items:-	
1	1	Rear bootlid	\$ <i>R</i> 2,210.00 <i>X</i>
2	1	Rear bootlid logo	\$ <i>m</i> 47.00 <i>—</i>
3	1	Rear bootlid "E200" emblem	\$ <i>m</i> 76.00 <i>—</i>
4	1	Rear bootlid "KOMPRESSOR" emblem	\$ <i>m</i> 106.00 <i>—</i>
5	1	Rear bootlid lock	\$ <i>R</i> 176.00 <i>X</i>
6	1	LH tail lamp	\$ 472.00 <i>?</i>
7	1	RH tail lamp	\$ 472.00 <i>?</i>
8	1	Rear bumper	\$ <i>Bu</i> 1,372.00 <i>—</i>
9	1	Rear bumper trim moulding w chrome strip (center)	\$ <i>m</i> 187.00 <i>—</i>
10	1	Rear bumper trim moulding w chrome strip (RH)	\$ <i>m</i> 132.00 <i>—</i>
11	1	Rear bumper trim moulding w chrome strip (LH)	\$ <i>m</i> 132.00 <i>—</i>
12	2	Rear bumper side bracket	\$ <i>CM</i> 48.00 <i>4</i>
13	2	Rear bumper side attachemnt	\$ 84.00 <i>?</i>
14	1	Rear bumper reinforcement	\$ 578.00 <i>?</i>
15	1	End panel	\$ <i>R</i> 741.00 <i>X</i>
		Total - List Item	\$ 6,833.00
		Less 10%	<i>\$500</i> 683.30
		Total	\$ 6,149.70
		Special Nett Items:-	
1	10	Rear bumper clip	\$ <i>m</i> 90.00 <i>—</i>
2	1 Set	Rear bumper reverse sensor	\$ 380.00 <i>?</i>
		Total - SN Item	\$ 470.00
		Balance b/f	\$ 6,619.70

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by:
Signature:
Date:

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

AXA Insurance Singapore Pte Ltd
8 Shenton Way,
#27-01/02 AXA Tower
Singapore 068811
Attn: Motor Claims Department

Date :	10/11/2018
Vehicle No :	SGS1673T
Veh Make/Model :	Mercedes Benz E200K
YOM :	2006
Chassis No :	WDB2110412B074784
Date of Accident :	09/11/2018

No	Qty	Description	Amount \$
		Balance c/f	\$ 6,619.70
		<u>Labour Charges:-</u>	
1		Spray painting on all affected area.	\$ 700.00
2		Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	\$ 800.00
3		To apply anti rust treatment.	\$ <i>rr</i> 120.00
4		To check wiring system & light.	\$ 80.00
5		Upholstery details cleaning.	\$ <i>rr</i> 220.00
6		To remove and replace reverse sensor.	\$ 120.00
7		To remove/replace/reinstall boot lid inner compartment, mechanism & assy to new boot lid	\$ <i>rr</i> 200.00
		Total - L/C	\$ 2,240.00
Sub-Total			\$ 8,859.70
7% GST			\$ 620.18
Total			\$ 9,479.88

Service Request Details

Claim

S8M012GX

Reference

None 

Loss Date

November 9, 2018

Request Date

November 12, 2018

Due Date

November 19, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Vehicle Information

Incident Vehicle Registration

SGS1673T

Make

TPVD MERCEDES-BENS

Model

E200K

Service Address

Handwritten note: *Passy - Accord
@ 11:43 - Veh. in, can arrange survey.*

Primary Contact/Insured

HO CHUN MENG

BLK 533 HOUGANG AVENUE 6, #12-313, 530533, Singapore

ERICH08822@GMAIL.COM

Claim Handler

LOH Cynthia

6568804843

cynthia.loh@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

TYPE



SENT

11/12/18 11:34 AM

FROM

LOH Cynthia

SUBJECT

PROCEED DS

BODY





<MANDATE IA> - S8M012GX [ACCIDENT INVOLVING SLH 8061L(OI) & SGS 1673T(TP) ON 09/11/2018]

Type

Question

Message

Liability: 100%. Insured rear-ended third party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$3,611.00(all-in). Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 18 March 2019

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 18/03/2019

Survey Details:

Date of loss	9-Nov-18
Date of appointment	13-Nov-18
Date of survey	13-Nov-18
Location of survey	ACCORD AUTO SERVICES PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SGS 1673T
Make and Model	MERCEES BENZ E200K
Date of registration	24/1/2007
Excess	
Market Value	\$67,000
Parf Rebate	\$45,091
Nett Loss	\$21,909

Repair details:

Initial Estimate	\$ 8,859.70
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 1,795.20	(part less 50%)
Check items (estimate)	NIL	
Labour	\$ 920.00	
Total	\$ 2,715.20	
Lump Sum(if applicable)	\$ 2,700.00	

Number of days for repair	4
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

--

Mandate:

Liability(TP)		100%
Proposed repair cost (w/GST)	\$	2,889.00
Loss of use		NIL no. of days
Loss of rental	\$	720.00 (6days x \$120.00)
Loss of income		NIL no. of days
LTA search fees	\$	2.00
Others		NIL
Proposed Total	\$	3,611.00



Re:<MANDATE IA> - S8M012GX [ACCIDENT INVOLVING SLH 8061L(OI) & SGS 1673T(TP) ON 09/11/2018]

Type

🔗 Question

Message

APPROVED

Reply

Hsiao Tong (LKKAUTO)

From: Accord Claims(AV) <avclaims@mycarworkshop.com.sg>
Sent: Saturday, 23 March 2019 2:23 PM
To: Hsiao Tong (LKKAUTO)
Cc: Admin A
Subject: Re: Your ref: SGS 1673T *Our ref: CC4/ASM18020515/Kpb3 [ACCIDENT INVOLVING SLH 8061L(AXA) & SGS 1673T ON 09/11/2018]

Dear Hsiao Tong,

Accept your offer. Kindly let us have your DV.

Thank you.

Kind regards,
Celia Lai

Accord Auto Services Pte Ltd
Blk 1009 Bukit Merah Lane 3
#01-80
Singapore 159723

Mobile: (65) 9274 0999
Tel : (65) 6271 7433
Fax : (65) 6274 5715

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.

On Sat, Mar 23, 2019 at 1:24 PM Hsiao Tong (LKKAUTO) <chewht@lkkauto.com> wrote:

Your ref: **SGS 1673T** **Without Prejudice**

Our ref: CC4/ASM18020515/Kpb3

Dear Sir/Mdm,

ACCIDENT INVOLVING SLH 8061L(AXA) & SGS 1673T ON 09/11/2018

We refer to the above matter.

We have our principal instruction to offer as follows: -

1. Cost of Repair (w/GST)	\$ 2,889.00
2. Loss of Rental (6days x \$120.00)	\$ 720.00
4. LTA/ GIA Search Fee	\$ 2.00
TOTAL	<u>\$ 3,611.00</u>

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLH 8061L (Insd veh)	Model:	MERCEDES BENZ E200K (A)
	SGS 1673T (TP veh)		
Date of Accident:	09/11/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	9,670.55
Final Repair Cost	:	\$	2,889.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	720.00 6 days
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	3,611.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability ____100____(%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____(%)	Assessed Liability (*): _____(%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____ _____	

Payment Instruction: Payee's Breakdown			
1)	ACCORD AUTO SERVICES PTE LTD	:	\$ 3,611.00

NUR SHAQILAH BTE ABDOL
WAHAB

27/05/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18020515/Kpb3s2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CYNTHIA LOH		Date : 27-05-2019		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLH 8061L	Veh. Inspected	SGS 1673T	
Policy No.	GA139488	Coverage (\$)	0.00	
Claim No.	S8M012GX	Excess (\$)	0.00	
Assign From	CYNTHIA LOH	Assign Date	13/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E200K (A)	c.c	1796	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	WDB2110412B074784	Colour	METALLIC DARK BROWN	
Odometer	222743	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55R16	FALKEN	7 mm	
L/H Front Tyre	225/55R16	FALKEN	7 mm	
R/H Rear Tyre	225/55R16	FALKEN	5 mm	
L/H Rear Tyre	225/55R16	FALKEN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/11/2018	Inspection Date	13/11/2018	
Survey held at	ACCORD AUTO SERVICES PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTO POINT #03-11 SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGS 1673T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOTLID (CONSISTENT)	TO REPAIR SEE LABOUR	2,210.00	-
1	REAR BOOTLID LOGO (CONSISTENT)	NECESSARY	47.00	47.00
1	REAR BOOTLID "E200" EMBLEM (CONSISTENT)	NECESSARY	76.00	76.00
1	REAR BOOTLID "KOMPRESSOR" EMBLEM (CONSISTENT)	NECESSARY	106.00	106.00
1	REAR BOOTLID LOCK (CONSISTENT)	TO REPAIR SEE LABOUR	176.00	-
1	LH TAIL LAMP (CONSISTENT)	SERVICEABLE	472.00	-
1	RH TAIL LAMP (CONSISTENT)	SERVICEABLE	472.00	-
1	REAR BUMPER (CONSISTENT)	BUCKLED	1,372.00	1,372.00
1	REAR BUMPER TRIM MOULDING W CHROME STRIP (CENTER) (CONSISTENT)	NECESSARY	187.00	187.00
1	REAR BUMPER TRIM MOULDING W CHORME STRIP (RH) (CONSISTENT)	NECESSARY	132.00	132.00
1	REAR BUMPER TRIM MOULDING W CHROME STRIP (LH) (CONSISTENT)	NECESSARY	132.00	132.00
2	REAR BUMPER SIDE BRACKET (CONSISTENT)	CRACKED 1PC ONLY	48.00	24.00
2	REAR BUMPER SIDE ATTACHMENT (CONSISTENT)	SERVICEABLE	84.00	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	578.00	578.00
1	END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	741.00	-
	LESS 10% DISCOUNT		-683.30	-
	LESS 50% DISCOUNT		-	-1,327.00
			6,149.70	1,327.00
SPECIAL NETT ITEMS				
10	REAR BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	90.00	90.00
1	SET REAR BUMPER REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	380.00	200.00
1	REAR BUMPER CENTER BRACKET (@ \$356.40.00 DISC 50%) (SN) (CONSISTENT) (ADDITIONAL)	CRACKED	178.20	178.20
			648.20	468.20

Report Ref No. CC4/ASM18020515/Kpb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	SPRAY PAINTING ON ALL AFFECTED AREA.		700.00	440.00
	LABOUR REMOVE / REFIX ACCIDENT DAMAGES PARTS TO KNOCK, JACK, CUT, WELD AND REALIGN ACCIDENT AFFECTED AREA. INCLUSIVE OF THE REPAIR OF REAR BOOTLID, REAR BOOTLID LOCK AND END PANEL.		800.00	400.00
	TO APPLY ABTI RUST TREATMENT.	NOT NECESSARY	120.00	-
	TO CHECK WIRING SYSTEM & LIGHT.		80.00	20.00
	UPHOLSTERY DETAILS CLEANING.	NOT NECESSARY	220.00	-
	TO REMOVE AND REPLACE REVERSE SENSOR.		120.00	60.00
	TO REMOVE / REPLACE / REINSTALL BOOT LID INNER COMPARTMENT, MECHANISM & ASSY TO NEW BOOT LID.	NOT NECESSARY	200.00	-
			2,240.00	920.00
	GRAND TOTAL		9,037.90	2,715.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,700.00

Report Ref No. CC4/ASM18020515/Kpb3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.