

# ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

*Not Authorised*

## ESTIMATE

AXA Insurance Singapore Pte Ltd

8 Shenton Way,

#27-01/02 AXA Tower

Singapore 068811

Attn: Motor Claims Department

*11 Sep 2018*  
*Penny Ate Lim*  
*4 days*

Date : 10/11/2018

Vehicle No : SGS1673T

Veh Make/Model : Mercedes Benz E200K

YOM : 2006

Chassis No : WDB2110412B074784

Date of Accident : 09/11/2018

| No                          | Qty   | Description                                       | Amount \$     |
|-----------------------------|-------|---------------------------------------------------|---------------|
| <b>List Items:-</b>         |       |                                                   |               |
| 1                           | 1     | Rear bootlid                                      | \$ R 2,210.00 |
| 2                           | 1     | Rear bootlid logo                                 | \$ R 47.00    |
| 3                           | 1     | Rear bootlid "E200" emblem                        | \$ R 76.00    |
| 4                           | 1     | Rear bootlid "KOMPRESSOR" emblem                  | \$ R 106.00   |
| 5                           | 1     | Rear bootlid lock                                 | \$ R 176.00   |
| 6                           | 1     | LH tail lamp                                      | \$ 472.00     |
| 7                           | 1     | RH tail lamp                                      | \$ 472.00     |
| 8                           | 1     | Rear bumper                                       | \$ R 1,372.00 |
| 9                           | 1     | Rear bumper trim moulding w chrome strip (center) | \$ R 187.00   |
| 10                          | 1     | Rear bumper trim moulding w chrome strip (RH)     | \$ R 132.00   |
| 11                          | 1     | Rear bumper trim moulding w chrome strip (LH)     | \$ R 132.00   |
| 12                          | 2     | Rear bumper side bracket                          | \$ CM 48.00   |
| 13                          | 2     | Rear bumper side attachemnt                       | \$ 84.00      |
| 14                          | 1     | Rear bumper reinforcement                         | \$ 578.00     |
| 15                          | 1     | End panel                                         | \$ R 741.00   |
| <b>Total - List Item</b>    |       |                                                   | \$ 6,833.00   |
| <b>Less 10%</b>             |       |                                                   | \$ 501 683.30 |
| <b>Total</b>                |       |                                                   | \$ 6,149.70   |
| <b>Special Nett Items:-</b> |       |                                                   |               |
| 1                           | 10    | Rear bumper clip                                  | \$ R 90.00    |
| 2                           | 1 Set | Rear bumper reverse sensor                        | \$ 380.00     |
| <b>Total - SN Item</b>      |       |                                                   | \$ 470.00     |
| <b>Balance b/f</b>          |       |                                                   | \$ 6,619.70   |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

