

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

12-Nov-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8837 U

1 pc	Rear bumper <i>X repair</i>	\$	696.00
1 pc	Rear bumper lower cover <i>✓</i>	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>✓</i>	\$	58.00
1 pc	Rear bumper inner sponge <i>X</i>	\$	114.00
1 pc	Rear bumper reinforcement <i>X</i>	\$	607.00
1 pc	Rear bumper stay - o/s & n/s @ \$53.00 <i>X</i>	\$	106.00
1 pc	Rear bumper reinforcement lower bracket - o/s & n/s <i>X</i> @\$18.00	\$	36.00
1 pc	Rear bumper reinforcement upper bracket - o/s & n/s @ <i>X</i> \$18.00	\$	36.00
1 pc	Rear bumper reflector - o/s & n/s @ \$46.00 <i>X</i>	\$	92.00

\$ 1,951.00

Less 10%

\$ 195.10

\$ 1,755.90

S/NETT

1 set	Rear bumper clips <i>X</i>	\$	48.00
1 set	Reverse sensor <i>✓</i>	\$	280.00 200
1 pc	Rear bumper top protector <i>✓</i>	\$	80.00 50
	Sundry	\$	50.00 X
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00 X
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs	\$	180.00
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel	\$	550.00 200
	To putty and spray painting on rear bumper, end panel	\$	500.00 180
	To apply rustproofing on the repaired and replaced panels.	\$	120.00 X
		\$	3,683.90

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.