

ASS. REC. BY:

REF: 02/CTU18020522 / Dvbnz

Special Instruction:

Surveyor: Byron

**ASSIGNMENT (Office)**

From (Person): Chong Soon Sen

of CTL

Date/Time: 13.11.2018 3:50pm

Estimated Cost:

Bill to:

**OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS**

To Inspect Vehicle No:

SHC 8919L

Insured:

YK 8654G

at Workshop m/s

Soon Hock motor

Tel:

of

Bik 10 AMK Ind Park 2A #01-05

Policy No:

DMLVSN 3000 291803

Claim No:

SNM18D05320C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11-11-2018

CA / REV / REP. / REV 24 HRS api

H.O.D. Endorsement:

Date/Time:

13-11-2018 4pm

Person Contacted:

Lynn

Vehicle IN / OUT

Date/Time

Action/Instruction (  ) Estimate

SHC 8919L - CS3 / FC116001165 / mighsc2

DOA: 15/11/2016

YK 8654G - X



**...CLAIM SUBFOLDER...(New Assignment)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Nov 2018		13 Nov 2018 15:50 Assign				<b>New Assignment</b> Cancel Case

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<b>Show All</b>
-------------	------------------	----------------------	------------------	-----------------

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

Insured:

Main Claimant: **COMFORT TRANSPORTATION PTE LTD**

Vehicle Reg. No.: **SHC8919L**      Date of Loss: 11/11/2018 00:00 - :59

Claim Type: **TP / SNM18D05320C02**      Policy/Cover Note No.: DMCVSN3000291803

Vehicle Reg. No. (Insured): **YK8654G**      Policy No. (Claimant):

Excess: S\$0.00

Repairer: **Soon Hock Motor Pte Ltd (HQ)** Blk 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016

Handling Insurer: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: 6389 6111 ... [Handled by **Chong Boon Sen**]

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Final Rpt due 22/11/2018]

---

**ASSOCIATED MAIL RECEIVED** View All    Compose Case Mail

There are no mail for this case.

---

**ALL ASSOCIATED TASKS** View All    Search Tasks    Create New Task    Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MCD618145891 / ComfortDelGro Engineering Pte Ltd - Layang  
 ENTRY DATE & TIME: 12/11/2018 10:41  
 SUBMITTED BY: Janet Lim Siang Gek

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	12/11/2018 10:41
Date Of Accident	11/11/2018 14:20
Exact Location Of Accident	SLIP RD OF LORNIE RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC8919L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
<b>Vehicle Particulars</b>	
Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	
<b>Driver</b>	
Name of Driver	LEAU TAT SIONG
NRIC No	S1690603D
Date Of Birth	28/11/1965
Occupation	OUTDOOR
Date Of Driving Pass	18/01/1985
Driving Experience	33 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93229976
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address BLK 146 SIMEI STREET 2  
#10-28  
Postcode 520146  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER  
Vehicle Registration Number of Driver's Own Vehicle -  
Vehicle -  
Insurance Company of Driver's Own Vehicle -

**General Information of the Accident**

Type Of Accident CHAIN COLLISION  
Weather Conditions RAINING  
Road Surface WET

**Other Information**

Was any foreign vehicle involved in this accident? NO  
Number of vehicles involved in the accident 3  
Was any body injured in the Accident? NO  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 2  
Passenger 1 NAME: : -  
GENDER: : FEMALE

**Details of Police Action**

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

**Circumstances of Accident**

REFER ATTACHED

**Attachment(s)**

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? YES  
Remarks/ Reasons: -  
Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number YK8654G  
Vehicle Make/Model/Colour NISSAN  
Details Of Properties  
Vehicle Category COMMERCIAL VEHICLE  
Name of Driver LIU JINLONG  
NRIC/Passport Number G2233877W  
Contact Number 83196037  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage FRONT

No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number	FBM4610X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	MUHAMMAD SUFYAN BIN M.SUHAIMI
NRIC/Passport Number	S9109864D
Contact Number	84487413
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REAR
No. Of Passenger (Including Driver)	

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time: 12.10.2018 @ 09:45 Hrs

Reporting Centre Personnel's Signature  
Name: *Rubini*  
NRIC/FIN No.:

**SKETCH PLAN**



Along Slip Road of Lornie Road.

**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

On 11.11.2018 at about 14:20 hrs, I was travelling along slip road of Lornie Rd with one female passenger on board.

I was travelling on the extreme right lane. I saw in front of my vehicles slowing down and stopped, So I follow too. Out of sudden, there was a loud impact coming from the rear portion and caused my taxi (A), to lose control and surge forward, and colliding onto veh (C) (FBM 4610X) rear portion. My taxi (A) front and rear portion were damaged.

I assessed the damages to my taxi (A) and come to know that there were 3 vehicles involved in the chain accident.

No one was conveyed by the ambulance.

The parties involved in the accident are:

A - SHC 8919L.  
 B - YK 8654G. Mr. Liu JinLong. Fin No : G 2233877W. Hp : 8319 6037.  
 C - FBM 4610X. Mr. Muhammad Sufyan Bin M. Suhaimi. NRIC : S 9109864D. Hp : 8448 7413.


No injury in this accident.

**DECLARATION**

I/We declare the foregoing particulars are true in every respect.

**MFORT TRANSPORTATION PTE LTD**  
 CO. REG. NO. 199303821R

Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time: 12.10.2018 @ 09:45 Hrs

  
 Reporting Centre Personnel's Signature  
 Name: Rubbini  
 NRIC/FIN No.:





SHC 8919L

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	<b>Labour Charge</b>			
	Panel Beating			S 1,800.00 800/-
	Spray Painting Charge			S 1,500.00 700/-
	Wiring Charge			S 50.00 30/-
	Tuff Kote			S 100.00 40/-
	Remove/Refix Cushion & Upholstery Rear			S 150.00 80/-
	Remove/Refix Rear Windscreen Glass			S 120.00 80/-
	Remove/Refix Reverse Sensor			S 120.00 40/-
	Remove/Refix Exhaust Pipe			S 300.00 60/-
			1830.00	
	<b>TOTAL LABOUR</b>			<b>S 4,140.00</b>
	<b>ESTIMATE TOTAL</b>			<b>S 30,832.74</b>
	<p>14/11/18 14/11/2018 20930w                      167 Antenn                      2 Panel 10                      8 dys                      ngn                      LKK Auto</p>		24918.98 4/3 19000/-	

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18020522/DVBN2

Date: 17/12/2018

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3000291803
Claimant Vehicle No :	SHC8919L	Insured Vehicle No :	YK8654G
Date of Loss:	11/11/2018	Nature of Claim:	TP
		Claim No:	SNM18D05320C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC8919L	Engine No:	D4FDGU613578
Make & Model:	HYUNDAI I40, 1.7 D (A)	Chassis No:	KMHLB41UMGU087814
Reg. Date:	21/04/2016 (Man. Year: 2016)	Odometer:	470505 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	24,112.74	21,948.98	2,163.76	8.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,720.00	2,970.00	3,750.00	55.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>30,832.74</b>	<b>24,918.98</b>	<b>5,913.76</b>	<b>19.18</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>19,000.00</b>		
(S\$)	30,832.74	19,000.00	11,832.74	38.38
+ GST 7.00/7.00% (S\$)	2,158.29	1,330.00	828.29	38.38
<b>Nett Amount (S\$)</b>	<b>32,991.03</b>	<b>20,330.00</b>	<b>12,661.03</b>	<b>38.38</b>

### INSPECTION

Date of Assignment:	13/11/2018	
Date Inspected:	14/11/2018	Inspected At: CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047

Estimated Period of Repair: 10.0 days

Adjuster: BRYAN TANI

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 17 Dec 2018)
<b>Parts:</b> 143	HYUNDAI I40 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SHC8919L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	2,265.90 FL	*2,265.90 FL
2	1		*RADIATOR GRILLE	Cracked	1,110.10 FL	*1,110.10 FL
3	1		*RADIATOR GRILLE H EMBLEM	Necessary	39.50 FL	*39.50 FL
4	1		*FRONT BUMPER COVER	Distorted	1,052.20 FL	*1,052.20 FL
5	1		*FRONT BUMPER SPONGE	Torn	99.20 FL	*99.20 FL
6	1		*FRONT BUMPER REINFORCEMENT	Bent	402.10 FL	*402.10 FL
7	1		*FRONT BUMPER GRILLE LH	Serviceable	93.60 FL	*- FL
8	1		*FRONT BUMPER GRILLE AIRDUCT (LH)	Not Necessary	26.20 FL	*- FL
9	1		*FRONT BUMPER BRACKET TOP (LH)	Serviceable	22.40 FL	*- FL
10	1		*FRONT BUMPER BRACKET (LH)	Cracked	24.60 FL	*24.60 FL
11	1		*HEADLAMP SUPPORT TOP COVER	Serviceable	222.60 FL	*- FL
12	1		*HEADLAMP SUPPORT PANEL ASSY	Cracked	907.40 FL	*907.40 FL
13	2		*HEADLAMP (LH/RH)	Ns Broken/Os Mounting Cracked	2,776.00 FL	*2,776.00 FL
14	1		*RADIATOR	Bent	698.30 FL	*698.30 FL
15	1		*RADIATOR FAN BLADE,COWLING,MOTOR ASSY	Not Necessary	792.95 FL	*- FL
16	2		*RADIATOR BRACKET (LH/RH)	Not Necessary	13.00 FL	*- FL
17	2		*RADIATOR GUARD	Not Necessary	40.00 FL	*- FL
18	1		*FRONT FENDER (LH)	Dented	566.30 FL	*566.30 FL
19	1		*FRONT FENDER SHIELD (LH)	Serviceable	174.90 FL	*- FL
20	1		*AIRCON CONDENSER	Bent	927.50 FL	*927.50 FL
21	1		*INTER COOLER	Bent	1,032.50 FL	*1,032.50 FL
22	1		*INTER COOLER MOUNTING (2 PCS)	Not Necessary	25.90 FL	*- FL
23	1		*BOOT LID	Buckled	2,174.90 FL	*2,174.90 FL
24	1		*BOOT LID RUBBER	Deformed	96.50 FL	*96.50 FL
25	2		*BOOT LID HINGE (LH/RH)	Repair	284.60 FL	*- FL
26	1		*BOOT LID LOCK UPPER	Bent	102.60 FL	*102.60 FL
27	1		*BOOT LID LOCK LOWER	Repair	31.70 FL	*- FL
28	1		*BOOT LID H EMBLEM	Necessary	28.70 FL	*28.70 FL
29	1		*BOOT LID CRDI PLATE	Necessary	27.90 FL	*27.90 FL
30	2		*FRONT BUMPER LAMP (LH/RH)	Cracked	1,131.20 FL	*1,131.20 FL
31	1		*LICENCE LAMP (LH/RH)	O/s Cracked/N/s Not Necessary	67.90 FL	*33.95 FL
32	1		*BOOT LID TRIMBOARD	Not Necessary	116.40 FL	*- FL
33	10		*BOOT LID TRIMBOARD CLIPS	Not Necessary	11.00 FL	*- FL
34	1		*BOOTLID MOULDING	Serviceable	85.00 FL	*- FL
35	1		*BOOTLID I40 EMBLEM	Serviceable	27.90 FL	*- FL
36	1		*BOOTLID LOWER GARNISH	Serviceable	227.90 FL	*- FL
37	1		*REAR BUMPER	Distorted	553.00 FL	*553.00 FL
38	1		*REAR BUMPER REINFORCEMENT	Cracked	428.40 FL	*428.40 FL
39	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Dented	160.60 FL	*160.60 FL
40	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	2		*REAR BUMPER BRACKET	Not Necessary	71.20 FL	*- FL
42	1		*REAR BUMPER SPONGE	Torn	118.40 FL	*118.40 FL
43	1		*REAR BUMPER UNDER COVER	Distorted	228.00 FL	*228.00 FL
44	2		*TAIL LAMP (LH/RH)	Cracked	1,395.60 FL	*1,395.60 FL
45	1		*TAIL LAMP QUARTER PANEL (LH)	Dented	226.50 FL	*226.50 FL
46	1		*REAR PANEL	Dented	526.70 FL	*526.70 FL
47	1		*REAR PANEL GARNISH	Deformed	57.70 FL	*57.70 FL
48	1		*REAR PANEL LOWER PANEL	Dented	495.50 FL	*495.50 FL
49	2		*EXHAUST PIPE INSULATOR	Not Necessary	117.10 FL	*- FL
50	2		*EXHAUST SILENCER	Bent	1,935.40 FL	*1,935.40 FL
51	2		*EXHAUST PIPE HANGER	Not Necessary	117.10 FL	*- FL
52	1		*EXHAUST PIPE CENTRE	Bent	730.10 FL	*730.10 FL
53	1		*REAR FENDER WITH HOUSING (LH)	Dented	4,736.80 FL	*4,736.80 FL
54	1		*REAR FENDER INNER LINING (LH)	Not Necessary	169.30 FL	*- FL
55	1		*REAR WINDSCREEN MOULDING	Necessary	28.30 FL	*28.30 FL
56	1		*BOOT LID COMFORT LOGO & TEL NO STICKER	Necessary	30.00 FS	*30.00 FS
57	1		*REAR NO PLATE	Cracked	25.00 FS	*25.00 FS
58	1		*REAR BUMPER REVERSE SENSOR	Damaged	135.70 FS	*135.70 FS
59	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc

<b>Sub Total (\$)</b>	<b>30,081.75</b>	<b>27,377.05</b>
- List Item Discount on L Items 20.00/20.00% (\$)	5,969.01	5,428.07
<b>Total Parts (\$)</b>	<b>24,112.74</b>	<b>21,948.98</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	2,800.00	1,300.00
2	SPRAY PAINTING CHARGE	New	2,250.00	1,200.00
3	WIRING CHARGE	New	100.00	60.00
4	TUFF KOTE	New	200.00	70.00
5	TOWING CHARGE	New	50.00	-
6	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	80.00
7	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	480.00	-
8	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
9	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
10	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
11	REMOVE/REFIX EXHAUST PIPE	New	300.00	60.00
<b>Gross Labour Cost (S\$)</b>			<b>6,720.00</b>	<b>2,970.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >