VEING	
12/11/18	tra
ed in Merimen: 1311	11/8
115-5 15 110-5-1-	
HOL 18110210	
AIRPORT BLVD	1
/NO ; TP GIA REPORT: FEB / NO % Final ? Yes / No	5)
2	
DNSRS: WSP: Tel: Liability: RMKS:	
DATE / P porting ltr (1st)	IC
porting Its (2nd):	_
porting ltr (Final):	
tion itr (if non-pickup):	
If ht to OI:	
entation Check List: Handler Typ	ist
tion itr (if non-pickup)	
II its to OI:	
Voucher:	-
pair Bill:	
tal Invoice:	
Invitios	
EA:	
80	\vdash
eReject Instruction:	
Por man detton;	
it Breskdown Form:	
pair Photos:	
n by	
Email Call	
T B 28, Ass. Lin :	
COD RETHE-ENOUS -	(a)
	*)
DOOM SELLI	
20 X19	
Dertion.	
n status: Norm VReject/Private Senie	
n status: Norm l/Reject/Private Senio at Format:	1
ey fee: \$350.00	
Cutt	
ALMICED LAR PLD	

Weekend (\$

TOTAL

PREMIER AUTOMOT¥VE-SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

12-Nov-18

1 pc	Rear bumper Patrol	s	696.00
	Rear bumper lower cover		
1 pc	Rear bumper side bracket o/s & n/s @ \$29.00 *	S	206.00
2 pcs	Rear bumper side bracker dis & his to \$29.007	5	58.00
1 pc	Rear bumper inner sponge	\$	114.00
1 pc	Rear bumper reinforcement \$\mathcal{K}\$ Rear bumper n/s & o/s stay @ \$53.00 \$\mathcal{X}\$	5	607.00
2 pcs	7 03	5	106.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	5	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	5	36.00
1 pc	Rear bumper o/s reflector @ \$46.00 🔀	5	46.00
		\$	1,905.00
	Less 10%	\$	190.50
	100	\$	1,714.50
S/NETT	we'c wants hence noticy		
1 set	Rear bumper clips	\$	48.00
1 set	Reverse sensor	s	289:00 2
1 pc	Dear humans ton analysts 200001	\$	8000
	- Tend 100 1 30 11 11 11 11 11 11 11 11 11 11 11 11 11		
	Sundry To dismantle / replace reverse sensor to hew humperland	\$	5000大分
	To dismantle / replace reverse sensor to new bumper and reset to the same	s	120.00 30
	To dismantle / refit the inner garnishes, inner linings, thner trims, cushion seat, carpet, etc to facilitate repairs.	\$	50.00 × 27
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair,		200
	reshape and adjust of the end panel, etc	\$	650.00
			180
	To putty and spray painting on rear bumper, end panel	s	400.00
	To apply rustproofing on the repaired and replaced panels.	\$	120:00 大ツ
		\$	3,642.50
	(ALL THE REPAIR COSTS ARE SUBJECTED TO GST) Kale	111	164
	THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.	12/1	1/18 1705m
	21/11/1 Us \$1350/ 2/2,		//
	Aller	Ry	rept
	//		

1/2/40

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

12-Nov-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6856 Y

1 pc	Rear bumper	\$	696.00
1 pc	Rear bumper lower cover	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 -	\$	58.00
1 pc	Rear bumper inner sponge .*	S	114.00
1 pc	Rear bumper reinforcement .*	5	607.00
2 pcs	Rear bumper n/s & o/s stay @ \$53.00	\$	106.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 -	5	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 2	\$	36.00
1 pc	Rear bumper o/s reflector @ \$46.00 🔀	S	46.00
		5	1,905.00
	Less_10%	\$	190.50
S/NETT	Rear bumper clips	\$	1,714.50
1 set	Rear bumper clips Reverse sensor	\$	48.00
1 set	Rear bumper clips Reverse sensor	\$	280.00 200
1 pc	Rear bumper top protector	\$	80.00 50
	Sundry	\$	50.00 ×
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00 30
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	s	180.00 上
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair,		200
	reshape and adjust of the end panel, etc	\$	650.00
	×		180
	To putty and spray painting on rear bumper, end panel	\$	400.00
	To apply rustproofing on the repaired and replaced panels.	S	120.00 >
		\$	3,642.50
	(ALL THE REPAIR COSTS ARE SUBJECTED TO GST) Kale	110	My

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Affer Ry or pht

Page I of 2

Text size + -

Enquire Transaction History

Transaction History Details

Log Date/Time:

02 Sep 2015 / 08:05:01

Receipt No.:

AACCK001-AX239-150902-000021

Asset Type:

Vehicle

Transaction Amount:

\$69,132.00

Asset ID:

SHC6856Y

Channel:

AA Counterless - CYCLE & CARRIAGE KIA PTE LTD

Transaction Type:

01.02 Register New Vehicle (AA)

Business Transaction

Reference No.:

20150902080501867408

Vehicle No.:

SHC6856Y

Vehicle Type:

H10 - Public Transport Taxi (Motor Car)

Vehicle Attachment 1:

Air-Con (Taxi)

Vehicle Attachment 2:

Vehicle Attachment 3:

Vehicle Scheme:

Taxi (Company)

First Registration Date: 02 Sep 2015

Original Registration

02 Sep 2015

KIA

Vehicle Make: Vehicle Model:

OPTIMA 1.7(A) DIESEL

Chassis No.:

KNAGM414MF5519948

Engine No.:

D4FDEH313527

Motor No.:

Propellant

Diesel

Passenger Capacity:

Trailer Chassis No.:

4 Engine Capacity: 1685

Power Rating:

Unladen Weight:

1584

Maximum Laden

2050

Weight:

Primary Color:

Silver

Secondary Color:

2015

Manufacturing Year: Open Market Value:

\$21,156.00

Minimum PARF Benefit: \$12,971.00

PARF Eligibility

Y.

No of Transfer.

Effective Ownership Date/Time.

02 Sep 2015 08:05:01

COE No:

2015090201003474G

COE Expiry Date:

01 Sep 2023

COE Bid Category:

Actual OP/PQP Paid

Amount

\$47,373.00

Lifespan Expiry Date:

01 Sep 2023

Print Received Message

This mail is associated with:

*SHC6856Y (MCT18110310) [SHA7231D] TP PREMIER TAXIS PTE LTD

Nov 11 2018 11:00PM [COMFORT TRANSPORTATION PTE LTD] Premier Automotive Services Pte Ltd

From

India International Insurance Pte Ltd (HQ) (III_SG), sent on 11/07/2019 10:19 AM.

To

LKK HQ

Subject

Alert - Adj Mandate Approved (S\$1752.66) - SHC6856Y - Claim Handler: Zuhaidah Bte Samsuri

Approved:1752.66:Please ensure TP repair bill addressed to III.

Premier Automotive Services Pte Ltd

23 Changi South Avenue 2 #04-02

Singapore 486443 GST: 200707743D ROC: 200707743D

Fax:

Phone: (65) 6214 8880 (65) 6214 4498

Tax Invoice



Date Page Jul 12, 2019 1 Invoice Number IV1907010879

Sold To:


INDIA INTERNATIONAL INSURANCE PTE LTD 64 Cecil Street #04/#05


IOB Building Singapore 049711 049711


Ship To:

INDIA INTERNATIONAL INSURANCE PTE LTD 64 Cecil Street #04/#05 IOB Building Singapore 049711 049711

	Shipment / DO No. SM1907013896	Order Date	Vehicle No. SHC6856Y	Case TP/181111/S		PO Numbe	r Terms
S/N	ltem Number Description				Unit Price	Total Discount	Total Amount
1 2	ICGST1 ICGST2	Cost of Repair (subject to Loss of Rental (subject to				0.00	1.350.0 288.0
Ac	cident involving SHA723	1D on 11/11/18			Subtotal Less discou Total amou	1	1,638.0 0.0 1,638.0 114.6
	Motor				Grand total		1,752.6











MOHAMED SALAHUDDIN BIN ABDUL AZIZ

MALAY 02-02-1970 SINGAPORE





VOCATIONAL LICENCE Licence No. S7002445D

Name MOHAMED SALAHUDDIN BIN ABOUL AZIZ

Date: 23/11/2012

Please visit www.lta.gov.sg to check the status of this vocational licence

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIE

PASS DATE

Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

20 Oct 1997



APT BLK 311 JURONG EAST STREET 32 #12-335

SINGAPORE 600311

MRIC No: \$70024450

Date: 08-01-2001 No: 3871227

NP 428A

This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrendered to the LTA on request. If found, please return to LTA, 10 Sin Ming Drive, Singapore 575701.

Type Description

02 TAXI VL Issue Date

23/11/2012



Text size + -

Enquire Transaction History

Transaction History Details

Log Date/Time:

02 Sep 2015 / 08:05:01

Receipt No.:

AACCK001-AX239-150902-000021

Asset Type:

Vehicle

Transaction Amount:

\$69,132.00

Asset ID:

SHC6856Y

Channel:

AA Counterless - CYCLE & CARRIAGE KIA PTE LTD

Transaction Type:

Business Transaction Reference No.:

01.02 Register New Vehicle (AA)

20150902080501887408

Vehicle No.:

SHC6856Y

Vehicle Type:

H10 - Public Transport Taxi (Motor Car)

Vehicle Attachment 1:

Air-Con (Taxi)

Vehicle Attachment 2:

Vehicle Attachment 3:

Vehicle Scheme:

Taxi (Company)

First Registration Date: 02 Sep 2015

Original Registration

02 Sep 2015

Date: Vehicle Make:

Vehicle Model:

OPTIMA 1.7(A) DIESEL

Chassis No.:

KNAGM414MF5619948

Engine No.:

D4FDEH313527

Motor No.:

Trailer Chassis No.:

Diesel

Propellant: Passenger Capacity:

4

Engine Capacity:

1685

Power Rating:

Unladen Weight: Maximum Laden 1584

Weight:

2050

Primary Color:

Silver

Secondary Color:

2015

Manufacturing Year:

Open Market Value:

\$21,156.00 Minimum PARF Benefit: \$12,971.00

PARF Eligibility:

Y

No of Transfer:

Effective Ownership

Date/Time:

02 Sep 2015 08:05:01

COE No:

2015090201003474G

COE Expiry Date:

01 Sep 2023

COE Bid Category:

Actual QP/PQP Paid

Lifespan Expiry Date:

\$47,373.00

Amount

01 Sep 2023



Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189) MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5095103893

Cover : Third Party

1. Index mark and Registration Number of Vehicle

: SHC685GY

Chassis Number

: KNAGM414MF5619948

: PREMIER TAXIS PTE. LTD.

Name of Policyholder
 Effective Date of Insurance

: 20 Oct 2017

4. Explry Date of Insurance

: 31 Jan 2019

5. Persons or Classes of Persons entitled to drive*

(a) The Policyholder.

(b) Any licensed taxi driver driving on the Policyholder's order or with his/her permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

- Limitations as to Use*
 - (a) Use as a Taxi.
 - (b) Use for social domestic and pleasure purposes.

This Policy does not cover

(a) Use for racing, pace-making, reliability trial or speed-testing.

- (b) Use whilst drawing a trailer except the towing (Other than for reward) of any one disabled mechanically propelled vehicle.
 - * Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION I)

: N/A

EXCESS (SECTION II)

: \$\$3,500

INSURE WITH COE

N/A

HIRE PURCHASE COMPANY

: N/A

SUM INSURED

: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency

: HL SUNTEK INSURANCE BROKERS PTE LTD (00000690672)

Date of Issue

: 16 Oct 2017 17:13 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

Authorised Officer

Chief Executive

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVE 2 #01-02 SINGAPORE 486443 TEL:65446671 FAX:62141511 CO. REG:200707743D GST REG:200707743D

Our Ref: SHC6856Y/GS

WITHOUT PREJUDICE

5th January 2019

(By Email Only)

Attn: The Motor Claims Department
India International Insurance Pte Ltd
64 Cecil Street #04/#05
IOB Building
Singapore 049711

Dear Sir/Madam

ACCIDENT INVOLVING SHC6856Y & SHA7231D ALONG AIRPORT BOULEVARD ON 11.11.18

We have been authorized by Premier Taxis Pte Ltd, the owner of Taxi vehicle number: SHC6856Y, to claim against the party/parties responsible for the damages arising from the above-mentioned accident.

Our records show that you are the insurers of vehicle number: SHA7231D at the material time of the accident with the driver of our client's vehicle, Mr Mohamed Salahuddin Bin Abdul Aziz

As a result of the accident caused by your Insured Driver's negligent driving and/or management of your insured's Vehicle Number: SHA7231D, our client's vehicle was damaged and we have been put to loss and damage as follows:

(1) Cost of repair

\$ 1444.50 (Incl. GST)

(2) Loss of Rental - 3Days @\$102.72per day

\$ 308.16 \$ 1752.66

A copy of each of the following supporting documents is enclosed:

- (1) Final Repair Bill, GIA report & sketch plan of SHC6856Y
- (2) Driver's I/C and Driving Licence
- (3) Vehicle Registration card, Certificate of Insurance
- (4) Check In/Out Voucher

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVE 2 #01-02 SINGAPORE 486443 TEL:65446671 FAX:62141511 CO. REG:200707743D GST REG:200707743D

Our Ref: SHC6856Y/GS

We would appreciate if you could look into the subject matter and let us have your favorable offer within 14 days. If you are agreeable to the settlement of the above said claims, please forward us your discharge voucher as for our client's signature and payment made to "Premier Automotive Services Pte Ltd".

Please note that if we do not hear from you within the stipulated 14 days, we will have no alternative but to appoint our solicitor to act on our behalf to commence proceedings against you without further notice to you.

Yours faithfully,

Claims Department - Gary Shi

Email: gary.shi@premiertaxi.com

NB: We encourage all parties to liaise with us via email to expedite all matters

PS: Please quote our reference no when replying

c.c. Client - Premier Taxis Pte Ltd

AUTHORISATION TO ACT

I/We, PREMIER TAXIS PTE LTD ("the third party claimant") of 23 CHANGI SOUTH AVENUE 2 #03-02 SINGAPORE 486443 (address), owner of SHC 6856Y (vehicle no.) hereby authorize PREMIER AUTOMOTIVE SERVICES PTE LTD ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SHC 6856Y that was damaged pursuant to the accident which occurred on 11/11/2018 (date) along AIRPORT BLVD (location) involving vehicle no/s SHA 7231D ("the accident").

I/We further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of "the workshop".

I/We further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this _____ (day) of _____ (month) 2019 (year)

Signed by "the third party claimant" (with chop if applicable) Signed by "the workshop" (with chop)



INDIA INTERNATIONAL INSURANCE PTE LTD

Co. Reg. No. 190703792h ; GS7 Reg. No. M2 40/70000-8 64 | Cecil Street | #04 | #05 | #06-02 | 109 Building | Singapore 049711

Critice (65) 63476-100 Email insure@rit.cam.og Fax (65) 62234174 Website sewschit.com.og

EXPRESS SETTLEMENT his Settlement excludes any bodily injuries arising out of : 'c DISCHARGE VOUCHER III-Direct Settlement (PODS) above said accident and post

to and party dank

India Ref: MCT18110310

India Ref: MCT18 Claimant Ref: Sh	1C6856Y/GS	120 2	J. J
We/LPREMIER AU	TOMOTIVE SERVICES PTE LTP the work	shop") hereby confirm that we	// have reached an agreement TANTS PTE LTD (name
of Surveyor) with in	Surveyor of India International Insurance Pt espect to the amount claimed for S\$	1,444.50 (repair cost). Yithat was damaged pursuant	S\$ 308.16 (loss of to the accident which occurred
	AIRCORTBEVO	110000000000000000000000000000000000000	vehicle no SHA7231 Dhaured
vehicle). This is purs	uant to the inspection conducted on 1211		
	we/l are/am authorized by the owner le noSHC685616 make the claim as set		
the matter on his/	te noSHC685616 make the claim as set ther behalf in a manner that we/I deem fit.	We/I enclose herein the lette	r of authority given by the third
party claimant*			
they will or have	m that we/l will indemnify India Internation already incurred in the event that "the trust the former for any loss and expenses the damage to SHC6856Y(vehicle no.) is	suffered pertaining to cost of	
pursuant to the a basis.	the agreement reached above is in full accident and that further this settlement is	eached on a window project	
dispute arising ou			
We/lauthorize	you to pay the total amount of S\$ 1,752	66 to PREMIER AUTOM	OTIVE SERVICES PTE LTD
Dated this 16	day of Jucy 20 19	WITNESS:	(44)
CLAIMANT:	(E) ARC) MAN	Signature	Signed by appointed Surveyor
Signature:	Signed by "the bookshop" (with chop)		LKK AUTO CONSULTANTS PTE LTD
Name.	SHAFAWATI MO RABU	Name:	199607198R
NRIC	S83093J4B	NRIC	51 UBI AVENUE 1 #01-25
Address:		Address:	PAYA UBI INDUSTRIAL PARK (S) 408933
TEN APPROXIMATION	Swanforen	Nationality:	
Nationality:	CUTIMS SETTLEMENT	Occupation:	
Occupation:	Centilis at the the test	an KG/mikirywww.k	



PREMIER AUTOMOTIVE SERVICES PTE LTD

OFFICE: 23 Changi South Avenue 2 #01-02 S(486443) TEL: 65438676 / 65436689 FAX: 62141511

CO. REG NO.: 200707743D GST. REG. NO.: 200707743D

TAX INVOICE

DATE

16-Jul-2019

PAGE

1 OF 1

INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street #04/#05

OB Building

Singapore 049711

ITEM	Description	QTY	U.PRICE	A	MOUNT
	FINAL REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6856 Y			\$	1,350.00
	TOTAL LUMPSUM REPAIR COSTS AS RECOMMENDED BY SURVEYOR GST @ 7% GRAND TOTAL		\$	1,350.00 94.50 1,444.50	

for Premier Automotive Services Pte Ltd

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)



14 November 2018

To Whom It May Concern

Dear Sir/Madam

CERTIFICATION LETTER

This letter serves to inform that Mohamed Salahuddin Bin Abdul Aziz of NRIC Number S7002445D is a registered driver of SHC6856Y. Mohamed Salahuddin Bin Abdul Aziz is paying daily rental rate of \$102.72 (Inclusive of GST).

Should you require further information, please contact us at 6214 8880.

Thank you.

Yours sincerely

Kellie Poh

Administration Manager

Prepared By: 5Y

PREMIER TANIS PTE LTD 23 Changi South Avenue 2 #03-02 Singapore 486443 Telephone: +65 6214 8880 Fnx: +65 6214 0330 www.premiertaxl.com Co. Reg. No. 20030497511

REPLACEMENT	VEH	GIVEN	YES /	NO
-------------	-----	-------	-------	----

PREMIER

VEH NO. __

JOB NO.

CHECK IN / OUT VOUCHER

DRIVER'S NAME M	OHD SALAH	PPIN		INDICATE AREA OF	DAMAGE HERE:
	2445D	HANDPHONE 4	450416	REA	В
	H C 6 8 5 6 Y	MAKE / MODEL	K02		一一
DATE IN	TIME IN	PA PAR	H 6 M S	mÆ	\exists m
3 3 4 9 5 4	FUEL IN E 1/4 1/2 3/4 F	KILOMETRES OUT	FUEL OUT E 1/4 1/2 3/4 F		
YES	NO	DATE / TIME TOWERING DO DOM M Y Y DATE / TIME CALL TO DE DO DO M M Y Y	H H M M M		
THAT THE SAME IS TOGETHER WITH T CONJUNCTION WIT	7	MOHAVA E DRIVERS NAME	S VOUCHER IS USED IN	O O O FRIC	
2	n 8_	CHECKED OUT BY	~8	BODY MARKINGS 1 Light Dent 2 Serious Dent 3 Light Scratch	5 – Damaged 6 – Chip 7 – Crack*
(PREMIER'S AUTHO	DRISED WORKSHOP)	(PREMIER'S AUTH	IORISED WORKSHOP)	4 - Serious Scratch	8 - Peeling
SERVICE / REPAIR	IS DONE		DRIVER'S REMARKS		
SERVICING T/BELT AIRCON SYSTE TURBO BRAKE SYSTE CLUTCH SYSTE BULB UNDER CARRU	M P P N IN IN A	46			

...CLAIM SUBFOLDER...(Pending for Survey Report) Direct Settlement

Case	Notified	Est Submitted	Ad) Assigned	Adj Rp		Adj Submit	ted	Ins Auth'ed	1 3	Status		
Main	16 Nov 2018 Edit Reg		12 Nov 2018 00:00 Edit Adj Rpt		50.00 Estimates	\$\$1,350.0 View Rpt	-			Pending for Report Cancel Case	manaan.	
	Main	R	eference		Claim Deta	ails		Docume	ents	1	Show All	
CLAIM SU	BFOLDER DE	ETAILS				[Crea	ated b	y adjuster)				
Insured:	COMFORT	TRANSPORTAT	ION PTE LTD, Co.	Reg. No.	19930382	18.						
Main Claimant:	PREMIER	PREMIER TAXIS PTE LTD, Co. Reg. No.: 200304975H										
Vehicle Reg. No.:	SHC685	6Y			Date of L			23:00 - :59 and 9 Days F	rom LTA	Reg Date (1	dan Yr)]	
Claim Type:	TP / MC	T18110310			Policy/Co Note No.		10015					
Vehicle Reg. No. (Insured):	SHA7231	D			Policy No (Claiman		5095103893					
					Excess:							
Repairer: Handling	Premier /	Automotive Serv	ices Pte Ltd (HQ)	23 Changi	South Ave	2, #01-02,	48644	3 Changi - Te	1: 62148	880		
Insurer:	India Int	ernational Insur	ance Pte Ltd (HQ)	- Tel: 63	476100 I	Handled by	Zuhai	dah Bte San	nsuri - 6	347 6070]		
Claimant's Insurer:	NTUC Inc	ome Insurance	Co-operative Ltd (HQ) - Tel	1							
Adjuster:	22/11/20		Ltd (HQ) - Tel: 62	56-3561	[Handled	by KALVIN	ANG	WEI KUN]	[Fina	I Rpt due		
ASSOCIAT	ED MAIL RE	CEIVED							View All	Compos	e Case Mai	
 III_SG () 	10/07/2019):	Alert - Adj Mand	Sate Approved (S\$ Sate Maintained - S Sate Approved (S\$	HC6856	Y - Claim H	landler: Zu	haida	h Bte Samsu	ıri			
ALL ASSO	CIATED TAS	KS =				View All	Se	earch Tasks	Create	New Task	Complete	
Due Date	Priority	Type Task	Group Subjec	t Han	dler A	ssigned By	9	Completed (On	Created On	Done	

Claim Documents

*SHC6856Y (MCT18110310)

[SHA7231D]

TP

PREMIER TAXIS PTE LTD

Nov 11 2018 11:00PM

[COMFORT TRANSPORTATION PTE LTD]

Premier Automotive Services Pte Ltd

	otos/Images		3 per p	age 💙	1
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	-
1	13/11/18 16:41	General View	0	Load 3PG	V
2	13/11/18 16:41	General View	0	Load JPG	~
3	13/11/18 16:41	General View	0	Load JPG	V
4	13/11/18 16:41	General View	0	Load JPG	V
5	13/11/18 16:41	General View	0	Load JPG	V
5	13/11/18 16:41	General View	0	Load JPG	V
7	13/11/18 16:41	General View	0	Load JPG	V
В	13/11/18 16:41	General View	0	Load JPG	V
9	13/11/18 16:41	General View	0	Load 3PG	V
10	13/11/18 16:41	General View	0	Load JPG	V
1.1	13/11/18 16:41	General View	0	Load JPG	V
12	13/11/18 16:41	General View	0	Load JPG	A
13	13/11/18 16:41	General View	0	Load JPG	(Z)
14	13/11/18 16:41	General View	0	Load JPG	₩.
15	13/11/18 16:41	General View	0		₹.
	Para Carlos de la Compania de la Carlos de l	AND CONTRACTOR OF THE PROPERTY		Load JPG	+
16	13/11/18 16:41	General View	0	Load JPG	<u>N</u>
17	13/11/18 16:41	General View	0	Load JPG	₩.
18	13/11/18 16:41	General View	0	Load JPG	8
19	13/11/18 16:41	General View	0	Load JPG	V
20	13/11/18 16:41	General View	0	Load JPG	V
2.1	13/11/18 16:41	General View	0	Load JPG	X
22	21/11/18 09:04	Reinspection Photo	0	Load 3PG	V
23	21/11/18 09:04	Reinspection Photo	0	Load 3PG	3
24	21/11/18 09:04	Reinspection Photo	0	Load JPG	~
25	21/11/18 09:04	Reinspection Photo	0	Load JPG	1
26	21/11/18 09:04	Reinspection Photo	0	Load JPG	V
27	21/11/18 09:04	Reinspection Photo	0	Load JPG	20
28	21/11/18 09:04	Reinspection Photo	0	Load JPG	50
29	21/11/18 09:04	Reinspection Photo	0	Load JPG	V
30	21/11/18 09:04	Reinspection Photo	0	Load JPG	V
Doc	cumentation		1 per p	age 🔽	
Vo	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnall	Print
	19/11/18 13:27	TP ESTIMATE - MARKED	0	Load PDF	
2	19/11/18 13:27	TP GIA REPORT	0	Load PDF	
3	11/07/19 09:49	LETTER OF DEMAND	0	Load PDF	
5	30/07/19 10:37	AUTHORISATION TO ACT FORM	0	Load PDF	

Pho	hotos/Images		3 per page 💟		
Νo	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
6	30/07/19 10:37	DISCHARGE VOUCHER	0	Load PDF	
7	30/07/19 10:37	RENTAL RECEIPT	0	Load PDF	
8	30/07/19 10:37	RENTAL MILEAGE	0	Load PDF	
9	30/07/19 10:37	LOD	0	Load PDF	
No.	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	14/11/18 09:06	Singapore Accident Statement	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/III18020524/K1HA3Q2

Date:

30/07/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle SHC6856Y

Insured Vehicle No:

SHA7231D

No: Date of Loss:

11/11/2018

Nature of Claim:

TP

Claim No: MCT18110310

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHC6856Y

Make & Model:

KIA OPTIMA, 1.7 D (A)

Engine No:

D4FDEH313527

Reg. Date:

02/09/2015 (Man. Year: 2015)

Chassis No: Odometer:

KNAGM414MF5619948

Colour:

334954 km

Engine Capacity: Market Value/New Car Price: N/A

1685 cc

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Handbrake (Serviceable):

Yes Engine Modification:

No Pre-accident Condition:

Yes

CONDITION OF TYRES

Front Tyre Size: Front Left Side:

205/65 R16

Rear Tyre Size:

205/65 R16

Front Right Side:

Maxxis 7 mm

Rear Left Side: Rear Right Side: Maxxis 7 mm Maxxis 7 mm

Maxxis 7 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,172.50	1,277.20	895.30	41.21
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,470.00 410.00 1,00		1,060.00	72.11
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	3,642.50	1,687.20	1,955.30	53.68
,	Approved Total (Overridden) (S\$)		1,350.00		
	(S\$)	3,642.50	1,350.00	2,292.50	62.94
	+ GST 7.00/7.00% (S\$)	254.98	94.50	160.48	62.94
	Nett Amount (S\$)	3,897.48	1,444.50	2,452.98	62.94
	+ Car Rental (3.0 x S\$10	02.72/day) (S\$)	308.16		
	Ne	tt Liability (S\$)	1,752.66		

INSPECTION

Date of Assignment:

12/11/2018

Date Inspected:

12/11/2018 Inspected At:

Premier Automotive Services Pte Ltd (HQ)

23 Changi South Ave 2, #01-02

Singapore 486443

Estimated Period of Repair:

2.0 days

Adjuster Report Page 2 of 4

Adjuster: KALVIN ANG WEI KUN Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other illability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 10 Dec 2018)

Parts:

143

KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC6856Y)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	696.00 FL	*696.00 FL
2	1		*REAR BUMPER LOWER COVER	Cut	206.00 FL	*206.00 FL
3	2		*REAR BUMPER SIDE BRACKET O/S & N/S	Serviceable	58.00 FL	*-FL
4	1		*REAR BUMPER INNER SPONGE	Tom	114.00 FL	*114.00 FL
5	1		*REAR BUMPER REINFORCEMENT	Serviceable	607.00 FL	*-FL
6	2		*REAR BUMPER N/S & O/S STAY	Serviceable	106.00 FL	*-FL
7	2		*REAR BUMPER REINFORCEMENT LOWER BRACKET	Cracked	36.00 FL	*36.00 FL
8	2		*REAR BUMPER REINFORCEMENT UPPER BRACKET	Cracked	36.00 FL	*36.00 FL
9	1		*REAR BUMPER O/S REFLECTOR	Serviceable	46.00 FL	*-FL
10	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
11	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
12	1		*REAR BUMPER TOP PROTECTOR	Necessary	80.00FS	*50.00 FS
13	1		*SUNDRY	Not Necessary	50.00 FS	*-FS
F=Fm	inchise	part. S=Spc	Nett L=ListttemDisc		National Control of	via in Expensional Lin
				Sub Total (S\$)	2,363.00	1,386.00
			- List Item Discount on L Items 1	0.00/10.00% (S\$)	190.50	108.80
				Total Parts (S\$)	2,172.50	1,277.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO DISMANTLE /REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME	New	New 120.00	
2	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	0.00
3	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE END PANEL ,ETC	New	650.00	200.00
4	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER ,END PANEL	New	400.00	180.00
5	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	120.00	0.00
	Gross Labor	ır Cost (S\$)	1,470.00	410.00
	Report was unsubmitted during	this print-out.		

< END OF ESTIMATES >