

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

12-Nov-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6856 Y

1 pc	Rear bumper	\$	696.00
1 pc	Rear bumper lower cover	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00
1 pc	Rear bumper inner sponge	\$	114.00
1 pc	Rear bumper reinforcement	\$	607.00
2 pcs	Rear bumper n/s & o/s stay @ \$53.00	\$	106.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00
1 pc	Rear bumper o/s reflector @ \$46.00	\$	46.00
			\$ 1,905.00
			\$ 190.50
			\$ 1,714.50

S/NETT

1 set	Rear bumper clips	\$	48.00
1 set	Reverse sensor	\$	280.00 200
1 pc	Rear bumper top protector	\$	80.00 0
	Sundry	\$	50.00 X
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00 30
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 X
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc	\$	650.00 200
	To putty and spray painting on rear bumper, end panel	\$	400.00 180
	To apply rustproofing on the repaired and replaced panels.	\$	120.00 X
			\$ 3,642.50

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Ka/11/11/18
12/11/18 1705hr
2 Qty.
L/S
After Rep or photo