

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

9-Nov-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHB 8367 J

1 pc	Tailgate lower garnish	\$	362.61 <i>car</i>
1 pc	Tailgate weatherstrip	\$	276.98 <i>act</i>
1 pc	Emblem I30	\$	27.80 <i>re</i>
1 pc	Emblem CRDI	\$	29.40 <i>re</i>
1 pc	Emblem Hyundai	\$	29.40 <i>re</i>
1 pc	Rear bumper	\$	811.11 <i>de</i>
1 pc	Rear bumper sponge	\$	79.20 <i>?</i>
1 pc	Rear bumper reinforcement	\$	815.64 <i>?</i>
1 pc	Rear bumper reinforcement centre	\$	79.20 <i>?</i>
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	\$	104.40 <i>X</i>

\$ 2,615.74

Less 20%

\$ 523.15

\$ 2,092.59

S/NETT

1 set	Rear bumper clips
1 set	Reverse sensor
1 set	Tailgate stickers
1 set	Tailgate lower garnish clips

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sundry

Towing Fee

To dismantle and replace reverse sensor and test system

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the end panel, etc

To putty and spray painting on the rear bumper, tailgate lower garnish, end panel

To apply rustproofing on the repaired and replaced panels

\$ 48.00 *re*

\$ 280.00 *200 \$'s*

\$ 100.00 *re*

\$ 38.00 *re*

\$ 50.00 *20.*

\$ 50.00 *? towing receipt?*

\$ 80.00 *30.*

\$ 180.00 *40.*

\$ 850.00 *400*

\$ 600.00 *400*

\$ 120.00 *X*

Total

\$ 4,488.59

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Taufik 97495749
WP
09/11/18 @ 215pm
Resurvey before paint
sure lkk auto.com.
Today