

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

12-Nov-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30(M) WAGON REGN NO: SHD 1801 H

1 pc	Front o/s fender	\$	434.40
1 pc	Front o/s fender inner shield	\$	120.00
1 pc	Front o/s door	\$	1,038.80
1 pc	Front o/s door hinges @\$34.00 <i>X repl</i>	\$	68.00
1 pc	Wheel cover <i>X</i>	\$	114.80
1 pc	Front o/s lower arm <i>X</i>	\$	279.80
1 pc	Front o/s shock absorber <i>X</i>	\$	191.70
1 pc	Front o/s tie rod <i>X</i>	\$	53.10
		\$	2,300.60
Less 20%		\$	460.12
		\$	1,840.48

S/NETT

1 set	Front o/s fender inner shield clips <i>X</i>	\$	28.00
1 set	o/s sticker	\$	100.00
1 pc	Front o/s fender sticker	\$	30.00
Sundry		\$	50.00 <i>20</i>
To do alignment check		\$	80.00 <i>X</i>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 <i>X</i>
To dismantle and replace the front o/s undercarriage		\$	250.00 <i>X</i>
To dismantle and refit the inner component of the front o/s door into new shell door		\$	150.00 <i>50</i>
To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the front o/s windscreen pillar		\$	650.00 <i>400</i>
To putty and spray painting on the front o/s fender, front o/s door, front o/s windscreen pillar <i>Bumper</i>		\$	600.00 <i>50</i>
To apply rustproofing on repaired panels		\$	120.00 <i>50</i>
Total		\$	4,078.48

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Ka/uh 16/11/18
12/11/18 1720 hrs
3 Days
After Repair