

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 351X**AAD1811-062***Not Authorized
Resumy B4 paint*

Vehicle No.:	SHD 351X
Chassis No.:	VF1ABL15AUC282620
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	8.11.2018
Third Party Insurer :	AIG

PART		LIST	
1	BUMPER COVER FRT	\$	<i>n</i> 1,259.42
1	BUMPER SPOILER FRT	\$	<i>sn</i> 181.75
1	BUMPER ABSORBER FRT	\$	<i>sn</i> 394.68
1	BUMPER RETAINER FRT LH	\$	<i>sn</i> 151.41
1	BUMPER SUPPORT FRT	\$	<i>sn</i> 123.88
1	BUMPER RETAINER FRT RH	\$	<i>sn</i> 150.77
1	BUMPER SUPPORT FRT	\$	<i>sn</i> 123.88
1	BUMPER UNDERTRAY FRT	\$	<i>sn</i> 472.83
1	BUMPER GRILLE LOWER FRT	\$	<i>sn</i> 266.80
1	BUMPER FOG LAMP GRILLE LH	\$	<i>sn</i> 207.21
1	BUMPER BEAM FRT	\$	<i>n</i> 914.08
1	HEADLAMP LH	\$	<i>sn</i> 1,184.43
1	HEADLAMP PANEL FRT LH	\$	<i>n</i> 152.15
1	FENDER PANEL FRT LH	\$	<i>n</i> 783.83
1	WHEELARCH FRT LH	\$	<i>sn</i> 278.84
1	FENDER BRACKET LOWER LH	\$	<i>sn</i> 15.79
1	FENDER INSULATOR LH	\$	<i>sn</i> 130.84
1	DOOR PANEL FRT LH	\$	<i>n</i> 2,844.66
TOTAL		\$	9,637.26
10%		\$	963.73
		\$	8,673.54

Special Nett

1SET	BUMPER CLIP FRT	\$	<i>nn</i> 66.00	X
1	BUMPER BRACKET CLIP FRT LH	\$	<i>nn</i> 12.00	X
1	BUMPER SUPPORT CLIP FRT LH	\$	<i>nn</i> 10.50	X
1SET	BUMPER GRILLE LOWER CLIP	\$	<i>nn</i> 69.00	X

Trans-cab Auto Services Pte Ltd

AAD1811-062

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 351X

	\$	157.50
TOTAL PARTS	\$	8,831.04

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,100.00	150
Putty and spray painting of the affected portion.	\$	2,100.00	440
To rust-proofing of the affected areas.	\$	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	380.00	X

TOTAL	\$	6,070.00
Over All Total	\$	14,901.04

LUMP SUM (REPAIR DAY)

7 DAYS

1 1/2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____