

ASS. REC. BY:

REF: CS/CTL18020534 / A/bc2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Irene Tay of CTL Date/Time: 13/11/2018 4:21pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMD4748A Insured: XD 6877Sat Workshop m/s 1st Autoworks Tel: 6844 1985 / 9189 2617of 23 Kaki Bukit Ave 4 #04-01Policy No: _____ Claim No: SNM18D05203C02

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 02/11/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

14-11-2018

H.O.D. Endorsement: _____

Date/Time: 13-11-2018 4:27pm Person Contacted: Suhaimi Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SMD 4748A - x</u>
	<u>XD 6877S - x</u>
<u>7/3/19</u>	<u>Adrian confirmed \$46,950.00 (Red 23,113.95, 33%)</u>

ASSIGNMENT

Veh No: 5MD4748A Yr Regn: 2018 / August.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Opel Insignia. c.c 1598

Colour Silver A/C: Insured / Std / NI / NA

Sp. Reading 5947. T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: W0VZM6EFOJH43210

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/45 R18

R: 245/45R18

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 86. mm R/Bal. 86. mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 74/11/18

Survey held at 1st Antwerp

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Downloaded from <http://ajphaphysocpharm.sagepub.com> at 10:06 11 September 2014

MV: 136k
PV: 47.7k
Nett: 88.3k

RECEIVED 0 8 MAR 2019

Date:

226

$$S + RS_2 \rightleftharpoons S_3$$

Photos

Others

TOTAL

Catherine Chong (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Tuesday, 13 November, 2018 4:21 PM
To: ronnie.tan@firstautoworks.com.sg
Cc: suhaimi@firstautoworks.com.sg; assignments@lkkauto.com
Subject: CTP REF NO. SNM18D05203C02 FA REF NO. SMD4748A - ACCIDENT INVOLVING XD6877S AND SMA4748A ON 02 NOVEMBER 2018
Attachments: 13112018161559.pdf

WITHOUT PREJUDICE

Dear Sir/Mdm (Ronnie),

We refer to the above matter.

As spoken, you have requested for Lkk.

Aside to LKK:

Please liaise with 1st Autoworks.

Thank you.

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6192
Fax (65) 62247478/62247175
Email: claimsdept@sg.cntaiping.com
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/11/2018 14:04
Date Of Accident	02/11/2018 17:50
Exact Location Of Accident	KPE TUNNEL TOWARDS CITY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMD4748A
Insured/Policyholder	
Name Of Registered Owner	ALPINE CAR RENTAL PTE LTD
Co Reg No	199003483E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-65113023

Vehicle Particulars

Manufacturer	OPEL
Model	INSIGNIA-1.6 TURBO (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5093613878-01
Cover Note Number	

Driver

Name of Driver	CANDICE CHUA
NRIC No	S9017002C
Date Of Birth	01/05/1990
Occupation	INDOOR
Date Of Driving Pass	01/07/2010
Driving Experience	8 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	+65-91136622
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Injuries Sustain

Injured person in which vehicle?

SMD4748A

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 3/11/18


Reporting Centre Personnel's Signature
Name: ✓
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3483E
Vehicle Details	
Vehicle No.:	SMD4748A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	14 Nov 2018
Vehicle Make:	OPEL
Vehicle Model:	INSIGNIA GRANDSPORT B16DTH
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	A2180998GKCX0187
Chassis No.:	W0VZM6EF0J1143270
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$26,319.00
Original Registration Date:	21 Aug 2018
First Registration Date:	21 Aug 2018
Transfer Count:	0
Actual ARF Paid:	\$28,847.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Aug 2028
PARF Rebate Amount:	\$21,635.00
Intended COE Rebate Details	
COE Expiry Date:	20 Aug 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$32,809.00
COE Rebate Amount:	\$26,040.00
Total Rebate Amount:	\$47,675.00

The information contained herein is correct as at 14 Nov 2018

OK





SEARCH

Min Price to No Max
Depreciation
Vehicle Type
Category

Home » New Cars » Insignia Search Results

Insignia Search Results (2 vehicles)

Sort by Model (Ascending)

Car Model	Price	Dealer	Built in	User Rating
Opel Insignia Grandsport				
 <input type="checkbox"/> 1.5 Turbo Innovation (A)	\$149,777	Auto Germany	Germany	★★★★☆ 5 User Reviews
<input type="checkbox"/> 1.5 Turbo Innovation Premium Edition (A)	\$156,777	• 16.3km/l 162bhp 6-speed (A)		<input type="button" value="Editor's Review"/>
<input type="checkbox"/> 2.0 Turbo AWD Innovation Premium Edition (A)	\$189,777	• 16.3km/l 162bhp 6-speed (A)		
★ COTY 2018 NOMINEE <input type="button" value="Vote for me!"/>				
Opel Insignia Grandsport Diesel				
 <input type="checkbox"/> 1.6 Turbo Enjoy (A)	\$139,777	Auto Germany	Germany	No Ratings yet
	\$12,500 /yr	• 19.6km/l 134bhp 6-speed (A)		<input type="button" value="Rate it!"/>

Car Model	Price	Dealer	Built in	User Rating
<input type="button" value="15 results/page"/>				

3 result(s) for **insignia** models no longer being sold by local distributors
[View all past Opel cars](#)



Opel Insignia
(2015-2017)



Opel Insignia Diesel
(2016-2017)



Opel Insignia
(2010-2014)

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5093613878-01

Cover : drive PREMIUM

1. Index mark and Registration Number of Vehicle : **SMD4748A**
Chassis Number : **W0VZM6EF0J1143270**
2. Name of Policyholder : **ALPINE CAR RENTAL PTE LTD**
3. Effective Date of Insurance : **01 Sep 2018**
4. Expiry Date of Insurance : **31 Aug 2019**
5. Persons or Classes of Persons entitled to drive#
(a) The Policyholder.
(b) Any other person who is driving on the Policyholder's order or with his/her permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to Use#
(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business.

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
 - (b) Use for the carriage of goods (other than samples) in connection with any trade or business.
 - (c) Use for any purpose in connection with the Motor Trade.
- # Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$1,400
EXCESS (SECTION 2)	: S\$1,400
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: YES
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: N/A
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: UNITED OVERSEAS BANK LIMITED
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : ALPINE CREDIT PTE LTD (00000615424)
Date of Issue : 28 Aug 2018 08:52 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED




Countersigned By:

Authorised Officer



Chief Executive

1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 13/11/2018

Reference: SMD4748A

OPEL INSIGNIA
GRANDSPORT
Make: B16DTH

TP Chime
Version

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SMD4748A
CHASSIS NO.:W0VZM6EF0J1143270
ENGINE NO.:A2180998GKCX0187

Name of insured :Alpine Car Rental Pte Ltd
Date of accident.: 02/11/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	RR FENDER LH	\$ 2,072.50
2	1	RR FENDER WHEELHOUSE PANEL LH	\$ 1,717.50
3	1	RR FENDER GUTTER PANEL LH	\$ 172.50
4	1	RR TAILLAMP PANEL LH	\$ 195.00
5	1	RR FENDER LOW EXTENSION PANEL LH	\$ 417.50
6	1	RR FENDER AIR DUCT	\$ 90.00
7	1	RR FENDER INNERSHIELD LH	\$ 320.00
8	1	RR FENDER INNER TRIM LH	\$ 370.00
9	1	RR FENDER INNER TRIM UPP LH	\$ 265.00
10	1	RR FENDER INNER GARNISH LH	\$ 186.00
11	1	RR FENDER RH	\$ 2,072.50
12	1	RR FENDER WHEELHOUSE PANEL RH	\$ 1,717.50
13	1	RR FENDER GUTTER PANEL RH	\$ 172.50
14	1	RR TAILLAMP PANEL RH	\$ 195.00

<u>15</u>	1	RR FENDER LOW EXTENSION PANEL RH	Distorted	\$ 417.50
<u>16</u>	1	RR FENDER AIR DUCT	Del'd.	\$ 90.00
<u>17</u>	1	RR FENDER INNERSHIELD RH	new	\$ 320.00
<u>18</u>	1	RR FENDER INNER TRIM RH	del'd	\$ 370.00
<u>19</u>	1	RR FENDER INNER TRIM UPP RH	new	\$ 265.00
<u>20</u>	1	RR FENDER INNER GARNISH RH	Del'd	\$ 186.00
<u>21</u>	1	RR BUMPER	Distorted	\$ 2,230.00
<u>22</u>	1	RR BUMPER TOW COVER	Missing	\$ 185.00
<u>23</u>	1	RR BUMPER SIDE RETAINER RH(inner) - Guide	new	\$ 162.50
<u>24</u>	1	RR BUMPER SIDE RETAINER RH(outer) - Bracket	new	\$ 62.50
<u>25</u>	1	RR BUMPER CENTER RETAINER	Cracked	\$ 75.00
<u>26</u>	1	RR BUMPER SIDE RETAINER LH(inner) - Guide	new	\$ 162.50
<u>27</u>	1	RR BUMPER SIDE RETAINER LH(outer) - Bracket	new	\$ 62.50
<u>28</u>	1	RR BUMPER REINFORCEMENT	Best.	\$ 865.00
<u>29</u>	1	RR BUMPER LOW GARNISH	Del'd	\$ 610.00
<u>30</u>	1	RR BUMPER REVERSE SENSOR	new	\$ 467.50
<u>31</u>	4	RR BUMPER REVERSE SENSOR RUBBER SEAL	new	\$ 40.00
<u>32</u>	1	RR BUMPER REVERSE SENSOR WIRE HARNESS	cut	\$ 512.50
<u>33</u>	1	RR BUMPER REFLECTOR RH	cut.	\$ 67.00
<u>34</u>	1	RR BUMPER REFLECTOR LH	new	\$ 67.00
<u>35</u>	2	RR BUMPER NUMBER PLATE LAMP	cracked.	\$ 120.00
<u>36</u>	1	RR REVERSE CAMERA	new	\$ 885.00
<u>37</u>	1	RR TAILGATE	Distorted	\$ 3,940.00
<u>38</u>	1	Rr Tailgate Lock-Push, Button (Less Emblem)	new	\$ 472.50
<u>39</u>	1	Rr Tailgate Opel Emblem	new	\$ 192.50

40	1	RR TAILGATE INSIGNIA EMBLEM	Ne	\$ 167.50
41	1	RR TAILGATE TURBO EMBLEM	Ne	\$ 150.00
42	1	RR TAILGATE LOCK	Jammed	\$ 590.00
43	1	RR TAILGATE LOCK CATCHER - Striker	Best	\$ 97.50
44	1	RR TAILGATE LOCK KEYLESS RECEIVER SENSOR	Changed	\$ 167.50
45	1	RR TAILGATE HINGE RH	Ne	\$ 67.50
46	1	RR TAILGATE HINGE LH	Ne	\$ 67.50
47	1	RR TAILGATE STOPPED	Ne	\$ 50.00
48	1	RR TAILGATE DAMPER	Best	\$ 312.50
49	1	RR TAILGATE INNER TRIM BOARD	Crushed	\$ 435.00
50	1	RR TAILGATE LAMP RH	3 crushed	\$ 745.00
51	1	RR TAILGATE LAMP LH		\$ 745.00
52	1	RR TAILGATE GLASS	Shattered	\$ 1,202.50
53	1	RR TAILLAMP RH	Smashed	\$ 1,212.50
54	1	RR TAILLAMP LH	Crushed	\$ 1,212.50
55	1	RR END PANEL	Distorted	\$ 972.50
56	1	RR END PANEL AIR DUCT	Ne	\$ 150.00
57	1	RR END PANEL TOP GARNISH	Crushed	\$ 330.00
58	1	RR BATTERY TRAY PANEL	Ne	\$ 180.00
59	1	RR SPARE TYRE PANEL	Ne	\$ 2,495.00
60	1	RR SPARE TYRE PANEL BOARD	Crushed	\$ 1,072.50
61	1	AIR BAG IMPACT SENSOR - Rear End	Activated	\$ 202.50
62	1	AIR BAG CONTROL UNIT	Activated	\$ 1,437.50
63	1	FRT DRIVER SEAT BELT	Activated	\$ 1,137.50
64	1	FRT DRIVER SEAT BELT BUCKLE	Ne	\$ 550.00
65	1	FRT DRIVER SEAT BELT PRETENSIONER	Ne	\$ 250.00
66	1	FRT PASSENGER SEAT BELT	Activated	\$ 1,137.50
67	1	FRT PASSENGER SEAT BELT BUCKLE	Ne	\$ 550.00
68	1	FRT PASSENGER SEAT BELT PRETENSIONER	Ne	\$ 250.00
69	1	RR PASSENGER SEAT BELT RH	3 Activated	\$ 1,445.00
70	1	RR PASSENGER SEAT BELT LH		\$ 1,445.00

71	1	REAR SEATBELT WIRING HARNESS	<i>2nd Lt</i>	\$ 2,309.00	?
72	1	RR EXHAUST SILENCER BOX	<i>RR RR</i>	\$ 2,580.00	*

33972
30574.80

Parts Total: \$ 48,507.50
Less 10%: \$ 4,850.75
Total: \$ 43,656.75

about

No. Labour Description Price (SGD)

<u>Rear portion</u>			
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$650 PER DAY)	\$ 9,750.00	<i>5200</i>
2	Carry out spray painting on accident affected area (\$550 PER PANEL)	\$ 5,500.00	<i>3850</i>
3	To conduct anti rust of under carriage tuff coat	\$ 65.00	
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 325.00	<i>80</i>
5	Remove and refix seat cushion/upholstery & roof lining to facilitate repairs	\$ 325.00	<i>250</i>
6	To remove and refix reverse sensor and conduct test	\$ 130.00	<i>100</i>
7	To remove and refix reverse camera and conduct test	\$ 130.00	<i>100</i>
8	Conduct chasis alignment of vehicle	\$ 700.00	<i>700</i>
9	To conduct transfer of parts from old tailgate to new tailgate	\$ 325.00	
10	To conduct water leakage test after repairs of vehicle	\$ 130.00	<i>x</i>
11	To remove and replace exhaust pipe	\$ 650.00	<i>x</i>
12	To conduct 4 wheel alignment	\$ 180.00	<i>x</i>
13	To conduct reset of air bag light on. SRS reset	\$ 520.00	<i>400</i>
14	To remove and refit audio system	\$ 130.00	<i>70</i>
15	To remove and refit fuel tank to facilitate accident repair	\$ 325.00	
16	To remove and replace rear tail gate windscreen	\$ 325.00	<i>720</i>

10815

Labour Total: \$ 19,510.00

thers

Other Description

<u>No.</u>	<u>Qty</u>		<u>Price (SGD)</u>	
<u>Rear portion</u>				
1	1	Rear number plate <i>could</i>	\$ 60.00	<i>✓</i>
2	10	Rear bumper clip <i>RR</i>	\$ 65.00	<i>50</i>
3	6	Tail lamp clip <i>RR</i>	\$ 39.00	<i>20</i>
4	10	Tailgate insulator clip <i>RR</i>	\$ 65.00	<i>40</i>
5	2	Tailgate/Boot lid stopper(Upper) <i>RR</i>	\$ 13.00	<i>✓</i>
6	2	Tailgate/Boot lid stopper(Lower)	\$ 13.00	<i>✓</i>

7	6	Rear fender liner clips <i>per m</i>	\$ 39.00	+
8	10	Rear end panel trim clip <i>per</i>	\$ 65.00	30
9	1	Reverse sensor (1 set) <i>Per m</i>	\$ 800.00	500.
10	1	Rear reverse camera <i>per m</i>	\$ 230.00	+
11	1	Rear end panel insulation seal <i>per</i>	\$ 120.00	60
12	1	Rear floor panel insulation seal <i>A 7/12</i>	\$ 220.00	7-120
13	26	Rear fender inner trim clip <i>per</i>	\$ 169.00	80
14	10	Tail gate inner trim board clip <i>per</i>	\$ 65.00	30
15	2	Rear exhaust mounting <i>per m</i>	\$ 160.00	+
16	1	Tailgate windscreen sealant <i>per</i>	\$ 120.00	60
17	1	Tailgate windscreen solar film <i>per</i>	\$ 220.00	✓
18	1	Rear quarter glass sealant <i>per</i>	\$ 60.00	40
19	1	Rear quarter glass solar film <i>per m</i>	\$ 150.00	+

1336

Other Total: \$ 2,673.00

(S) 4224-40

GRAND TOTAL: \$ 65,839.75 70,064.15

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully



Suhaimi Ong

Service Executive
Suhaimi Ong
HP : 8298 8933 Fax: 6844 5185

Supplementary SW- 250

Supplementary: 39740

Total 46950.20

Adrian Lim
P/P 12/11/18.

18 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Per: Pernier

VEHICLE NO:

SMD 4748H

[illegible]

Finalisation

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

TAX INVOICE

CHINA TAIPING INSURANCE(SINGAPORE)PTE LTD

3 Anson Road, #16-00

Singapore 069542

Springleaf Tower

SINGAPORE 079909

GST Ref. No: 20-0000274-Z

Vehicle No: SMD4748A

Invoice No:

Chasis No : W0VZM6EF0J1143270

Engine No: A2180998GKCX0187

Invoice Date:

DESCRIPTION	AMOUNT	SGD
-------------	--------	-----

Parts

No.	Qty.	Description	Price (SGD)
<u>1</u>	1	RR TAILLAMP PANEL LH	\$ 195.00
<u>2</u>	1	RR FENDER INNER TRIM LH	\$ 370.00
<u>3</u>	1	RR FENDER INNER TRIM UPP LH	\$ 265.00
<u>4</u>	1	RR FENDER RH	\$ 2,072.50
<u>5</u>	1	RR FENDER GUTTER PANEL RH	\$ 172.50
<u>6</u>	1	RR TAILLAMP PANEL RH	\$ 195.00
<u>7</u>	1	RR FENDER LOW EXTENSION PANEL RH	\$ 417.50
<u>8</u>	1	RR FENDER AIR DUCT	\$ 90.00
<u>9</u>	1	RR FENDER INNER TRIM RH	\$ 370.00
<u>10</u>	1	RR FENDER INNER GARNISH RH	\$ 186.00
<u>11</u>	1	RR BUMPER	\$ 2,230.00
<u>12</u>	1	RR BUMPER TOW COVER	\$ 185.00
<u>13</u>	1	RR BUMPER SIDE RETAINER RH(inner) - Guide	\$ 162.50
<u>14</u>	1	RR BUMPER SIDE RETAINER RH(outer) - Bracket	\$ 62.50

<u>15</u>	1	RR BUMPER CENTER RETAINER		\$ 75.00
<u>16</u>	1	RR BUMPER SIDE RETAINER LH(inner) - Guide		\$ 162.50
<u>17</u>	1	RR BUMPER SIDE RETAINER LH(outer) - Bracket		\$ 62.50
<u>18</u>	1	RR BUMPER REINFORCEMENT		\$ 865.00
<u>19</u>	1	RR BUMPER LOW GARNISH		\$ 610.00
<u>20</u>	1	RR BUMPER REVERSE SENSOR		\$ 467.50
<u>21</u>	4	RR BUMPER REVERSE SENSOR RUBBER SEAL		\$ 40.00
<u>22</u>	1	RR BUMPER REVERSE SENSOR WIRE HARNESS		\$ 512.50
<u>23</u>	1	RR BUMPER REFLECTOR RH		\$ 67.00
<u>24</u>	2	RR BUMPER NUMBER PLATE LAMP		\$ 120.00
<u>25</u>	1	RR REVERSE CAMERA		\$ 885.00
<u>26</u>	1	RR TAILGATE		\$ 3,940.00
<u>27</u>	1	Rr Tailgate Lock-Push, Button (Less Emblem)		\$ 472.50
<u>28</u>	1	Rr Tailgate Opel Emblem		\$ 192.50
<u>29</u>	1	RR TAILGATE INSIGNIA EMBLEM		\$ 167.50
<u>30</u>	1	RR TAILGATE TURBO EMBLEM		\$ 150.00
<u>31</u>	1	RR TAILGATE LOCK		\$ 590.00
<u>32</u>	1	RR TAILGATE LOCK CATCHER - Striker		\$ 97.50
<u>33</u>	1	RR TAILGATE LOCK KEYLESS RECEIVER SENSOR		\$ 167.50
<u>34</u>	1	RR TAILGATE DAMPER		\$ 312.50
<u>35</u>	1	RR TAILGATE INNER TRIM BOARD		\$ 435.00
<u>36</u>	1	RR TAILGATE LAMP RH		\$ 745.00
<u>37</u>	1	RR TAILGATE LAMP LH		\$ 745.00

<u>38</u>	1	RR TAILGATE GLASS		\$ 1,202.50
<u>39</u>	1	RR TAILLAMP RH		\$ 1,212.50
<u>40</u>	1	RR TAILLAMP LH		\$ 1,212.50
<u>41</u>	1	RR END PANEL		\$ 972.50
<u>42</u>	1	RR END PANEL TOP GARNISH		\$ 330.00
<u>43</u>	1	RR SPARE TYRE PANEL BOARD		\$ 1,072.50
<u>44</u>	1	AIR BAG IMPART SENSOR - Rear End		\$ 202.50
<u>45</u>	1	AIR BAG CONTROL UNIT		\$ 1,437.50
<u>46</u>	1	FRT DRIVER SEAT BELT		\$ 1,137.50
<u>47</u>	1	FRT PASSENGER SEAT BELT		\$ 1,137.50
<u>48</u>	1	RR PASSENGER SEAT BELT RH		\$ 1,445.00
<u>49</u>	1	RR PASSENGER SEAT BELT LH		\$ 1,445.00
<u>50</u>	1	REAR SEATBELT WIRING HARNESS		\$ 2,309.00

Supplementary Items

<u>51</u>	1	RR TAILGATE WEATHER STRIP	<i>ut</i>	\$ 198.00	✓
<u>52</u>	1	RR LOAD COMAPRTMENT BOARD	<i>ut</i>	\$ 660.00	✓
<u>53</u>	1	RR BLIND SPOT CONTROL UNIT RH	<i>Range</i>	\$ 792.00	✓
<u>54</u>	1	RR BLIND SPOT CONTROL UNIT BRACKET RH	<i>new</i>	\$ 135.00	✓
<u>55</u>	1	RR BLIND SPOT CONTROL UNIT LH	<i>Range</i>	\$ 792.00	✓
<u>56</u>	1	RR BLIND SPOT CONTROL UNIT BRACKET LH	<i>new</i>	\$ 135.00	✓
<u>57</u>	1	RR SEAT SIDE CUSHION RH	<i>ut</i>	\$ 546.00	✓
<u>58</u>	1	RR SEAT SIDE CUSHION LH	<i>ut</i>	\$ 546.00	✓
<u>59</u>	1	CENTRAL LOCKING RECEIVER	<i>Range</i>	\$ 101.00	✓

60	1	RR PARKING SENSOR CONTROL UNIT	<i>Ref</i>	\$ 311.00	✓
61	1	RR SPARE TYRE PANEL FOAM RH	<i>Ref</i>	\$ 84.00	✓
62	1	RR TOOL BOX FOAM	<i>Ref</i>	\$ 116.00	✓

4416
3974.40

Total: \$ 38,388.00
Less 10%: \$ 3,838.80
Parts Total : \$ 34,549.20

Labour

No.	Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$650 PER DAY)	\$ 5,200.00
2	Carry out spray painting on accident affected area (\$550 PER PANEL)	\$ 3,850.00
3	To conduct anti rust of under carriage tuff coat	\$ 65.00
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 80.00
5	Remove and refix seat cushion/upholstery & roof lining to facilitate repairs	\$ 250.00
6	To remove and refix reverse sensor and conduct test	\$ 100.00
7	To remove and refix reverse camera and conduct test	\$ 100.00
8	To conduct transfer of parts from old tailgate to new tailgate	\$ 325.00
9	To conduct reset of air bag light on. SRS reset	\$ 400.00
10	To remove and refit fuel tank to facilitate accident repair	\$ 325.00
11	To remove and replace rear tail gate windscreen	\$ 120.00

Labour Total : \$ 10,815.00

Other

No.	Other Description	Price (SGD)
1	1 Rear number plate	\$ 60.00
2	10 Rear bumper clip	\$ 50.00
3	6 Tail lamp clip	\$ 20.00
4	10 Tailgate insulator clip	\$ 40.00
5	2 Tailgate/Boot lid stopper(Upper)	\$ 13.00
6	2 Tailgate/Boot lid stopper(Lower)	\$ 13.00
7	10 Rear end panel trim clip	\$ 30.00
8	1 Reverse sensor (1 set)	\$ 500.00
9	1 Rear end panel insulation seal	\$ 60.00
10	1 Rear floor panel insulation seal	\$ 120.00
11	26 Rear fender inner trim clip	\$ 80.00
12	10 Tail gate inner trim board clip	\$ 30.00

13	1	Tailgate windscreen sealant	\$	60.00
14	1	Tailgate windscreen solar film	\$	220.00
15	1	Rear quarter glass sealant	\$	40.00
16	1	RR Recorder Camera <i>Dangd</i>	\$	250.00

Other Total : \$ 1,586.00

Total : \$ 46,950.20

GST (7%) \$ 3,286.51

Grand Total: \$ 50,236.71

Yours Faithfully,

Suhaimi Ong

Suhaimi Ong

Service Advisor

Tel: 68441985 Fax:68445185

E & O E

- ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "IST Autoworks Pte Ltd".
- PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.

Please check and finalize with me this invoice

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

TAX INVOICE

CHINA TAIPING INSURANCE(SINGAPORE)PTE LTD

3 Anson Road, #16-00

Singapore 069542

Springleaf Tower

SINGAPORE 079909

GST Ref. No: 20-0000274-Z

Vehicle No: SMD4748A

Invoice No:

Chasis No: W0VZM6EF0J1143270

Engine No: A2180998GKCX0187

Invoice Date:

DESCRIPTION	AMOUNT	SGD
-------------	--------	-----

Parts

No.	Qty.	Description	Price (SGD)
<u>1</u>	1	RR TAILLAMP PANEL LH	\$ 195.00
<u>2</u>	1	RR FENDER INNER TRIM LH	\$ 370.00
<u>3</u>	1	RR FENDER INNER TRIM UPP LH	\$ 265.00
<u>4</u>	1	RR FENDER RH	\$ 2,072.50
<u>5</u>	1	RR FENDER GUTTER PANEL RH	\$ 172.50
<u>6</u>	1	RR TAILLAMP PANEL RH	\$ 195.00
<u>7</u>	1	RR FENDER LOW EXTENSION PANEL RH	\$ 417.50
<u>8</u>	1	RR FENDER AIR DUCT	\$ 90.00
<u>9</u>	1	RR FENDER INNER TRIM RH	\$ 370.00
<u>10</u>	1	RR FENDER INNER GARNISH RH	\$ 186.00
<u>11</u>	1	RR BUMPER	\$ 2,230.00
<u>12</u>	1	RR BUMPER TOW COVER	\$ 185.00
<u>13</u>	1	RR BUMPER SIDE RETAINER RH(inner) - Guide	\$ 162.50
<u>14</u>	1	RR BUMPER SIDE RETAINER RH(outer) - Bracket	\$ 62.50