

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 10 NOVEMBER 2018

Third Party Insurer: AIG

Vehicle No: SLN2501S

Third Party Veh No: SGQ9D

Model: MERCEDES E200

Date of Accident: 8 NOVEMBER 2018

Chassis: WDD2130422A121483 – 2017

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT RH HEADLAMP	1		<i>SL</i> \$3,052.50
2	FRONT BUMPER SIDE RETAINER RH	1		<i>SL</i> \$35.00
3	FRONT BUMPER PARKING SENSOR RH	1		<i>SL</i> \$170.20
4	FRONT BUMPER PARKING SENSOR RUBBER SEAL RH	1		<i>SL</i> \$12.00
5	FRONT BUMPER PARKING SENSOR BRACKET RH	1		<i>SL</i> \$15.00
6	FRONT RH FENDER	1		<i>R1</i> \$925.00
7	FRONT RH DOOR	1		<i>R1</i> \$1,757.50
8	FRONT RH DOOR WEATHER STRIP	1		<i>SL</i> \$259.00
9	REAR RH DOOR	1		<i>R</i> \$2,035.00
10	REAR RH DOOR WEATHER STRIP	1		<i>SL</i> \$259.00
11	17 INCH RH RIM FRONT	1		<i>Net</i> \$912.00
12	FRONT RH KNUCKLE ARM	1		\$1,443.00
13	FRONT RH KNUCKLE ARM BEARING	1		\$518.00
14	FRONT RH UPPER ARM	1		\$740.00
SUB TOTAL				\$12,133.20
LESS 10%				-\$1,213.32
PARTS TOTAL				\$10,919.88

*Not Withheld
Resurvey B4 paint
6 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 10 NOVEMBER 2018

Third Party Insurer:

AIG

Vehicle No: SLN2501S

Third Party Veh No:

SGQ9D

Model: MERCEDES E200

Date of Accident:

8 NOVEMBER 2018

Chassis: WDD2130422A121483 – 2017

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION

700
\$1,200.00

TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION

1000
\$1,200.00

TO TUFF KOTE / ANTI-RUST

600
\$100.00

TO CHECK WIRING, REPLACED WITH FOCUS HEADLAMP

\$80.00 *200*

TO DISMANTLE & REPLACED FRONT BUMPER PARKING SENSOR

na \$80.00 *X*

TO DISMANTLE & REPLACED FRONT RH DOOR & REAR RH DOOR INNER COMPONENT
MECHANISM TO FACILITATE REPAIR WITH CHECK FOR FUNCTION

800
\$360.00

TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD

\$150.00 *?*

TO DISMANTLE & CHECK/REPLACED FRONT RH UNDER CARRIAGE COMPONENT IN ORDER TO
FACILITATE REPAIR

\$220.00 *?*

TO SEND VEHICLE FOR 3D COMPUTERISED ALIGNMENT IN ORDER TO CHECK & ADJUST
WHEEL ALIGNMENT

\$80.00 *600*

LABOUR TOTAL \$3,470.00

AZMAN

TOTAL \$14,389.88