

INSURANCE

INS. CASE OWNER

HL

CC

AIG1802

0538, U. #639

LKK

IDAC

Surveyor:

Arrows

DOI:

ASSIGNMENT

13

Date / Time:

12/11/18

Registered in Merimen:

12/11/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLQ 57522

Name of Insured:

LR

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

10/11/18

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

GERH 580W 46799

Driver Tel No.:

(V/L-YES / NO)

Claim No.:

077677467559

Policy No.:

0000000000

Make / Model:

MINI

Place of Accident:

LA20WHW K4 1 SCOTTS K4

OI GIA REPORT:

YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

Merim



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

12/11/18

SLQ 57522

STAGE

DATE / PIC

Non-Reporting Ir (1st):

Non-Reporting Ir (2nd):

Non-Reporting Ir (Final):

Notification Ir (if non-pickup):

Call CR:

After call Ir to CR:

Documentation Check List:

Handler

Typist

Notification Ir (if non-pickup):

After call Ir to CR:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If No or B 28. Ass. Lia:

Repair Cost:

SS

4462.44

Loss of Rental (LOR):

SS

( days)

Loss of Use (LOU):

SS

350.00

(5

70

x 5

days)

Loss of Income (LOI):

SS

( \$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOU

[Tick only one]

GIA/LTA Search

SS

7.45

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost:

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

4819.89

Global Sum SS:

4800.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

4800.00

Name 1:

Abir Service Ple Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/LCR18020538/Upb3

78 SHENTON WAY #08-16  
CHARTIS BUILDINGS SINGAPORE 079120

Date : 13-11-2018



Code : LCR

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLQ 5752Z	Veh. Inspected	SLS 7909R
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	13/11/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	10/11/2018	Inspection Date	13/11/2018
Survey held at	ABWIN SERVICE PTE LTD No. 8 KAKI BUKIT AVENUE 4 #07-48 PREMIER@KAKI BUKIT GATE 2 SINGAPORE 415875		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

Please arrange to survey vehicle at  
8 KAKI BUKIT AVENUE 4 - GATE 2  
#07-48 PREMIER @ KAKI BUKIT  
SINGAPORE 415875

**ABWIN** 詢問

Date : 13/11/2018  
TP Vehicle No. : SLQ-5752-Z  
To : AIG ASIA PACIFIC INSURANCE PTE LTD  
Attn : Motor Claim Department

LINDA LIAO  
ABWIN SERVICE PTE LTD  
DID: 67139417  
Fax: 67139415  
HP: 97519596

Owner : XB CHAUFFER SERVICES  
NTUC INCOME INSURANCE CO-OPERATIVE LTD

Certificate No. : 5094824884-01  
Vehicle No. : SL5-7909-R  
Make & Model : HONDA VEZEL-1.5 HYBRID (A)

Accident Date: 10/11/2018

# ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

## List Item

1	TAILGATE	Body ID \$1,200.90	X
1	TAILGATE WEATHERSTRIP	11 \$106.80	X
1	TAIL GATE EMBLEM" HYBRID"	RM \$95.50	/
1	TAILGATE VEZEL EMBLEM	RM \$45.80	/
1	TAILGATE LOCK	11 \$106.60	X
1	TAILGATE REFLECTOR RH	RM \$280.60	/
1	TAILLAMP RH	RM \$460.50	/
1	REAR BUMPER	PD \$762.70	/
1	REAR BUMPER RELECTOR RH	RM \$148.30	/
1	REAR BUMPER RELECTOR LH	11 \$148.30	X
1	REAR BUMPER RETAINER RH	RM \$35.60	/
1	REAR BUMPER RETAINER LH	11 \$45.60	X
1	REAR BUMPER BRACKET RH	11 \$45.60	X
10	REAR BUMPER CLIPS	RM \$60.00	/
1	REAR END PANEL	R \$456.90	X
1	REAR END PANEL TOP GARNISH	11 \$126.00	X
10	REAR END PANEL TOP GARNISH CLIPS	11 \$60.00	X
1	RH REAR FENDER ARCH GARNISH	11 \$206.50	X
1	RH REAR FENDER	11 \$615.40	X
1	REAR WINDSCREEN MOULDING	RM \$185.60	/
10	RH REAR FENDER INNER SHIELD CLIPS	11 \$60.00	X
1	EXHAUST MUFFLER	R \$726.00	X
	Sub Total	\$5,979.20	
	Discount 20% on Parts	(\$1,195.84)	
	near bumper side o/s 185.50	\$4,783.36	

## Special Net

1	REAR NUMBER PLATE & CASEING	11 \$65.00	X
1	REAR BUMPER REVERSE SENSOR	shock \$350.00	200
1	REAR WINDSCREEN SEALANT	RM \$65.00	40

Date : 13/11/2018  
 TP Vehicle No. : SLQ-5752-Z  
 To : AIG ASIA PACIFIC INSURANCE PTE LTD  
 Attn : Motor Claim Department

LINDA LIAO  
 ABWIN SERVICE PTE LTD  
 DID: 67139417  
 Fax: 67139415  
 HP: 97519596

Owner : XB CHAUFFER SERVICES  
 NTUC INCOME INSURANCE CO-OPERATIVE LTD  
 Certificate No. : 5094824884-01  
 Vehicle No. : SLS-7909-R  
 Make & Model : HONDA VEZEL-1.5 HYBRID (A)

Accident Date: 10/11/2018

## ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
	Sub Total	\$480.00	

### Labour & Misc

TO STAIGHTEN AND PANEL BEAT ACCIDENT AREAS  
 TO SPRAY PAINT ON AFFECTED AREAS  
 TO APPLY UNDERCOATING FOR RUST ROOFING  
 TO CHECK LIGHTING AND FOCUS TAILLAMP  
 TO INSTALL EXHAUST PIPE SYSTEM  
 TO INSTALL REVERSE SENSOR & CHECK FUNCTIONALITY  
 TO TRANSFER REAR & INSTALL WINDSCREEN FITTING  
 TO TRANSFER & INSTALL TAILGATE FITTING  
 Sub Total

\$1,800.00 480  
 \$1,800.00 600  
 \$150.00 30  
 \$150.00 20  
 ✓ 1 \$350.00 x  
 \$150.00 50  
 \$150.00 120  
 \$250.00 60  
 \$4,800.00

Sub Total \$10,063.36

GST 7% \$704.44

Total \$10,767.80

LOK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p - 2570.56  
 5.2 + 240  
 1.6m + 1360  
 4170.56

Please arrange to survey vehicle at  
8 KAKI BUKIT AVENUE 4 - GATE 2  
#07-48 PREMIER @ KAKI BUKIT  
SINGAPORE 415875

**ABWIN** 論輝

Date : 13/11/2018  
TP Vehicle No. : SLQ-5752-Z  
To : AIG ASIA PACIFIC INSURANCE PTE LTD  
Attn : Motor Claim Department

LINDA LIAO  
ABWIN SERVICE PTE LTD  
DID: 67139417  
Fax: 67139415  
HP: 97519596

Owner : XB CHAUFFER SERVICES  
NTUC INCOME INSURANCE CO-OPERATIVE LTD  
Certificate No. : 5094824884-01  
Vehicle No. : SLS-7909-R  
Make & Model : HONDA VEZEL-1.5 HYBRID (A)

Accident Date: 10/11/2018

### ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

#### List Item

1	TAILGATE	953	Bodily ID \$1,200.90	✓
1	TAILGATE WEATHERSTRIP		11 \$106.80	X
1	TAIL GATE EMBLEM" HYBRID"		ner \$95.50	✓
1	TAILGATE VEZEL EMBLEM		ner \$45.80	✓
1	TAILGATE LOCK		11 \$106.60	X
1	TAILGATE REFLECTOR RH		ner \$280.60	✓
1	TAILLAMP RH		ner \$460.50	✓
1	REAR BUMPER		PD \$762.70	✓
1	REAR BUMPER RELECTOR RH		ner \$148.30	✓
1	REAR BUMPER RELECTOR LH		11 \$148.30	X
1	REAR BUMPER RETAINER RH		ner \$35.60	✓
1	REAR BUMPER RETAINER LH		11 \$45.60	X
1	REAR BUMPER BRACKET RH		11 \$45.60	X
10	REAR BUMPER CLIPS		ner \$60.00	✓
1	REAR END PANEL		R \$456.90	X
1	REAR END PANEL TOP GARNISH		11 \$126.00	X
10	REAR END PANEL TOP GARNISH CLIPS		11 \$60.00	X
1	RH REAR FENDER ARCH GARNISH		11 \$206.50	X
1	RH REAR FENDER		11 \$615.40	X
1	REAR WINDSCREEN MOULDING		ner \$185.60	✓
10	RH REAR FENDER INNER SHIELD CLIPS		11 \$60.00	X
1	EXHAUST MUFFLER		R \$726.00	X
Sub Total			\$5,979.20	
Discount 20% on Parts			(\$1,195.84)	
			\$4,783.36	

#### Special Nett

1	REAR NUMBER PLATE & CASEING	11	\$65.00	X
1	REAR BUMPER REVERSE SENSOR	shock	\$350.00	200
1	REAR WINDSCREEN SEALANT	ner	\$65.00	40

Date : 13/11/2018  
 TP Vehicle No. : SLQ-5752-Z  
 To : AIG ASIA PACIFIC INSURANCE PTE LTD  
 Attn : Motor Claim Department

LINDA LIAO  
 ABWIN SERVICE PTE LTD  
 DID: 67139417  
 Fax: 67139415  
 HP: 97519596

Owner : XB CHAUFFER SERVICES  
 NTUC INCOME INSURANCE CO-OPERATIVE LTD  
 Certificate No. : 5094824884-01  
 Vehicle No. : SLS-7909-R  
 Make & Model : HONDA VEZEL-1.5 HYBRID (A)

Accident Date: 10/11/2018

## ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
	Sub Total	\$480.00	

### Labour & Misc

TO STAIGHTEN AND PANEL BEAT ACCIDENT AREAS	\$1,800.00
TO SPRAY PAINT ON AFFECTED AREAS	\$1,800.00
TO APPLY UNDERCOATING FOR RUST ROOFING	\$150.00
TO CHECK LIGHTING AND FOCUS TAILLAMP	\$150.00
TO INSTALL EXHAUST PIPE SYSTEM	\$350.00
TO INSTALL REVERSE SENSOR & CHECK FUNCTIONALITY	\$150.00
TO TRANSFER REAR & INSTALL WINDSCREEN FITTING	\$150.00
TO TRANSFER & INSTALL TAILGATE FITTING	\$250.00
Sub Total	\$4,800.00

480  
600  
30  
20  
11  
50  
120  
60

Sub Total \$10,063.36  
 GST 7% \$704.44  
**Total \$10,767.80**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**> Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Business

Owner ID: 5723C

### Vehicle Details

Vehicle No.: SLS7909R

Vehicle to be Exported: No

Intended Deregistration Date: 13 Nov 2018

Vehicle Make: HONDA

Vehicle Model: VEZEL HYBRID 1.5X AUTO

Primary Colour: White

Manufacturing Year: 2017

Engine No.: LEB5961780

Chassis No.: RU31261763

Maximum Power Output: 112.0 kW (150 bhp)

Open Market Value: \$29,983.00

Original Registration Date: 05 Oct 2017

First Registration Date: 05 Oct 2017

Transfer Count: 0

Actual ARF Paid: \$5,000.00

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 04 Oct 2027

PARF Rebate Amount: \$3,750.00

### Intended COE Rebate Details

COE Expiry Date: 04 Oct 2027

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$51,000.00

COE Rebate Amount: \$45,345.00

**Total Rebate Amount: \$49,095.00**

The information contained herein is correct as at 13 Nov 2018

OK



## Hsiao Tong (LKKAUTO)

---

**From:** Hsiao Tong (LKKAUTO)  
**Sent:** Tuesday, 20 November 2018 11:29 AM  
**To:** Linda Liao  
**Cc:** Admin A; Poh Kin (LKKAUTO)  
**Subject:** RE: SLS7909R Against SLQ5752Z Date of accident : 10/11/2018 \*\*\*LKK  
REF:CC6/LCR18020538/Ufb3

### Without Prejudice

Dear Sirs/ Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shu Pei (LKKAUTO)  
**Sent:** Wednesday, 14 November 2018 9:44 AM  
**To:** Linda Liao <lindaliao@abwin.com.sg>  
**Cc:** Admin A <admin-a@lkkauto.com>; Poh Kin (LKKAUTO) <pohkin@lkkauto.com>  
**Subject:** RE: SLS7909R Against SLQ5752Z Date of accident : 10/11/2018 \*\*\*LKK REF:CC6/AIG18020538/Ufb3

Dear Linda,

We refer to the below email.

Please be informed that we are currently pending for our insured's report.

Our case handler in-charge should be is Poh Kin and he can be contacted at 6841 2132.

Our respective case handler will look into the matter and revert to you in due course.

Thank you

*To check availability of the case handler, you may contact the undersigned.*

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Linda Liao <[lindaliao@abwin.com.sg](mailto:lindaliao@abwin.com.sg)>

**Sent:** Tuesday, 13 November 2018 1:53 PM

**To:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** Re: SLS7909R Against SLQ5752Z Date of accident : 10/11/2018

Dear All

Please advise the liability as soon as possible.

Thank you

Regards

**ABWIN** 詒輝

Abwin Service Pte Ltd

No. 8 Kaki Bukit Avenue 4

#07-48 Premier@Kaki Bukit Gate 2

Singapore 415875

**Linda Liao**

Motor Claim Executive

DID +65 6713 9417 HP:9751 9596

T +65 6713 9400 | F +65 6713 9415

[Website](#) | [Facebook](#) | [LinkedIn](#)

Looking to start a new business soon? Find out how we can provide you with a complete vehicle ownership solution and much more!

Click [here](#) to view our listing >>



Your Ref:  
Our Ref: AC18110005

04/12/2018

AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120  
Attn: Motor Claims Department

Dear Sirs,

**ACCIDENT ON 10/11/2018 INVOLVING SLS-7909-R & SLQ-5752-Z NO.28 SCOTTS RD**

We are authorised repair workshop for the owner of vehicle, SLS-7909-R, which was involved in the captioned accident with your insured's vehicle. The vehicle owner has requested and authorised us to assist him/her in presenting his claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured, SLQ-5752-Z, we are submitting these claims for your consideration on behalf of the owner/driver/claimant.

1. Cost of Repair	\$4,462.44	✓
2. 0 days Car Rental x \$0.00	-	
3. Loss of Use (4 x \$200.00) <sup>160</sup>	\$800.00	8 20x5: 250
4. Survey Fees	-	
5. LTA Fees	\$7.45	
6. TP/GIA Fees	-	
7. Medical Fees	-	
8. Others	-	
<b>(E&amp;OE)</b>		<b>\$5,269.89</b>

We enclose the following documents to support the claims:-

<input checked="" type="checkbox"/> Repair/Excess Bill	<input type="checkbox"/> GIA/Police Report(s)	<input type="checkbox"/> Power of Attorney	<input type="checkbox"/> Medical Bill
<input type="checkbox"/> Surveyor Report	<input checked="" type="checkbox"/> GIA/TP Search	<input type="checkbox"/> Car Rental Bill	<input type="checkbox"/> Witness Statement
<input type="checkbox"/> Coloured Photographs	<input type="checkbox"/> Insurance Certificate	<input type="checkbox"/> Others: _____	

Kindly look into the matter and let us hear from you on the settlement of our client's claim as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/driver/claimant.

Yours faithfully,  
**ABWIN SERVICE PTE LTD**LINDA LIAO  
Claims Department  
E-mail: lindaliao@abwin.com.sg  
DID: 67139417

Date: 04/12/18From: XB CHAUFFER SERVICES (Name of Policyholder)My Vehicle No.: SLS-7909-ROther Vehicles: SLQ-5752-ZAccident Date: 10/11/2018Location: NO.28 SCOTTS RD**LETTER OF AUTHORISATION**To: AIG ASIA PACIFIC INSURANCE PTE LTD (Third Party and/or Third Party Insurer)

I have authorised ABWIN SERVICE PTE LTD to proceed with the repairs to my accident damaged vehicle and to proceed with 3rd Party Insurance Claims against Third Party and / or its Insurer on my behalf for property damages, costs, and expenses, including loss of use, loss of rental, medical fees and legal costs.

To have absolute discretion to agree to any settlement of compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).

As ABWIN SERVICE PTE LTD will be handling the entire 3rd Party Claims, which includes signing / submission of all relevant documents and negotiation of my claims on my behalf, kindly forward and make payable all proceeds of my claims to **ABWIN SERVICE PTE LTD**.

I confirm that the payment of any negotiated settlement with and accepted by ABWIN SERVICE PTE LTD will serve as an effectual discharge of my claims against the Third Party and / or its Insurer for the damage caused.



Policyholder's Signature / Company's Stamp (if applicable)

Name: SLH XinboNRIC No./ROC No.: S27171324

Designation: \_\_\_\_\_



Witness's Signature

Name: Linda LiaoNRIC No.: S8188387D

## Hsiao Tong (LKKAUTO)

---

**From:** Hsiao Tong (LKKAUTO)  
**Sent:** Saturday, 15 December 2018 1:41 PM  
**To:** 'Linda Liao'  
**Cc:** Admin A; Poh Kin (LKKAUTO)  
**Subject:** RE: SLS7909R Against SLQ5752Z Date of accident : 10/11/2018 \*\*\*LKK  
REF:CC6/LCR18020538/Upb3

### Without Prejudice

Hi Linda,

We refer to the above matter.

We propose settlement at a global sum of \$4,700.00(all-in).

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Linda Liao <[lindaliao@abwin.com.sg](mailto:lindaliao@abwin.com.sg)>  
**Sent:** Tuesday, 4 December 2018 3:07 PM  
**To:** Hsiao Tong (LKKAUTO) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>  
**Cc:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Poh Kin (LKKAUTO) <[pohkin@lkkauto.com](mailto:pohkin@lkkauto.com)>  
**Subject:** RE: SLS7909R Against SLQ5752Z Date of accident : 10/11/2018 \*\*\*LKK REF:CC6/LCR18020538/Upb3

Dear Hsiao Tong

Please refer to attached document for your action.

Thank you  
Regards

## Hsiao Tong (LKKAUTO)

---

**From:** Linda Liao <lindaliao@abwin.com.sg>  
**Sent:** Tuesday, 18 December 2018 10:00 AM  
**To:** Hsiao Tong (LKKAUTO)  
**Cc:** Admin A; Poh Kin (LKKAUTO)  
**Subject:** RE: SLS7909R Against SLQ5752Z Date of accident : 10/11/2018 \*\*\*LKK REF:CC6/LCR18020538/Upb3

Dear Hsiao Tong

Please negotiation propose settlement at a global sum of 4800.00.

✓ ac 19/12/18

Thank you  
Regards

**ABWIN** 詒輝

Abwin Service Pte Ltd  
No. 8 Kaki Bukit Avenue 4  
#07-48 Premier@Kaki Bukit Gate 2  
Singapore 415875

**Linda Liao**

Motor Claim Executive

**DID +65 6713 9417 HP:9751 9596**

**T +65 6713 9400 | F +65 6713 9415**

[Website](#) | [Facebook](#) | [LinkedIn](#)

Looking to start a new business soon? Find out how we can provide you with a complete vehicle ownership solution and much more!

Click [here](#) to view our listing >>



Sales & Purchase of Pre-owned Commercial & Private Vehicles | Vehicle Service Centre | Vehicle Hire Purchase | Motor Insurance | C

---

**From:** Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]  
**Sent:** Saturday, 15 December, 2018 1:41 PM  
**To:** Linda Liao <lindaliao@abwin.com.sg>  
**Cc:** Admin A <admin-a@lkkauto.com>; Poh Kin (LKKAUTO) <pohkin@lkkauto.com>  
**Subject:** RE: SLS7909R Against SLQ5752Z Date of accident : 10/11/2018 \*\*\*LKK REF:CC6/LCR18020538/Upb3

**Without Prejudice**

Hi Linda,

We refer to the above matter.

We propose settlement at a global sum of **\$4,700.00(all-in)**.

## Hsiao Tong (LKKAuto)

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Tuesday, 20 November 2018 11:27 AM  
**To:** insurance@lioncityrentals.com.sg; 'Eileen, May Hwee Yap'  
**Subject:** ACCIDENT INVOLVING SLQ 5752Z(AIG) & SLS 7909R ALONG/AT CAIRNHILL ROAD & SCOTTS ROAD ON 10/11/2018

Your Ref: **SLQ 5752Z**  
Our Ref: CC6/LCR18020538/Upb3

Dear Sirs/Madam,

**ACCIDENT INVOLVING SLQ 5752Z(AIG) & SLS 7909R ALONG/AT CAIRNHILL ROAD & SCOTTS ROAD ON 10/11/2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from SLS 7909R against your insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**AUTHORIZATION TO ACT**  
**(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)**

I, XB chauffer services ("the third party claimant")  
of 8/A Palm Drive Singapore 456484 (address),  
owner of SLS7909R (vehicle no.) hereby authorize  
ABWIN SERVICE PTE LTD  
("the workshop") to act for me with respect to my claim for repair costs and/or  
rental and/or loss of use ("claim") for my vehicle no. SLS7909R that was  
damaged pursuant to the accident which occurred on 10/11/18 (date) along  
NO. 28 SCOTT'S Rd (location)  
involving vehicle no/s SLO 57522 ("the accident").

I further authorize the workshop to settle the above mentioned claim in a  
manner that they deem fit and the workshop is further authorized to receive  
payment further to settlement of my claim with payment cheque/s being made in  
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my  
behalf is on a without prejudice and without admission of liability basis insofar  
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 4<sup>th</sup> day of December (month) 20 18 (year)


Signed by "the third party claimant"


Signed by "the workshop"



**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, **ABWIN SERVICE PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$4,800.00** (Global Sum) for vehicle no. **SLS 7909R** that was damaged pursuant to the accident which occurred on **10/11/2018** (date) along **NO.28 SCOTTS ROAD** involving vehicle no/s **SLQ 5752Z**.

This is pursuant to the inspection conducted on **13/11/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **XB CHAUFFER SERVICES** ("the third party claimant") of vehicle no. **SLS 7909R** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SLS 7909R** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 19<sup>th</sup> (day) of Decemr (month) 2018 (year)



CICS.

Signed by appointed surveyor



Signed by "the workshop" (with chop)

**TAX INVOICE****INV18120003****To:** AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120**Date:** 04/12/2018  
**Vehicle No.:** SLS-7909-R  
**Make:** HONDA  
**Model:** VEZEL-1.5 HYBRID (A)**Attention:****Date of Accident:** 10/11/2018

S/N	DESCRIPTION	QTY	AMOUNT (S\$)
1	BEING SUCCESSFUL CLAIM FOR VEHICLE NO. SLS-7909-R ACCIDENT ON 10/11/2018 AS FOLLOWS :-		
2	REPAIR COSTS	1.000	\$4,170.50

**SUB TOTAL** \$4,170.50**7% GST** \$291.94**TOTAL** \$4,462.44

Remarks:

Payment by cheque should be crossed and made payable to **ABWIN SERVICE PTE LTD.**

For ABWIN SERVICE PTE LTD

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Nov 2018 <a href="#">Edit Reg</a>		13 Nov 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$4,170.50</b> <a href="#">Edit Estimates</a>	<b>S\$4,170.50</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K								
Main Claimant:	XB CHAUFFER SERVICES, Co. Reg. No.: 53335723C								
Vehicle Reg. No.:	SLS7909R	Date of Loss:	10/11/2018 12:00 - :59 [13 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0336334067SG	Policy/Cover Note No.:	0999994807 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLQ5752Z	Policy No. (Claimant):	5094824884-01						
		Excess:							
Repairer:	Abwin Service Pte Ltd (HQ) No. 8 Kaki Bukit Avenue 4, #07-48 Premier@Kaki Bukit Gate 2, 415875 Kaki Bukit - Tel: 6713 9400								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ng, Hai-Chuan] Hai-Chuan.Ng@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 22/11/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SLS7909R (0336334067SG)  
[SLQ5752Z]**




































**TP**















**XB CHAUFFER SERVICES**

**Nov 10 2018 12:00PM**

**[LCRF PTE LTD]**

**Abwin Service Pte Ltd**

<a href="#">Upload Documents</a>			<a href="#">Upload Photos</a>			<a href="#">Compose New Letter</a>			<a href="#">Upload Video</a>			<a href="#">Upload Audio</a>			<b>View</b>			<a href="#">View in Browser</a>		
<b>Letters/Correspondences</b>															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print		
1	(Draft)		Third Party Express Settlement – Payment Breakdown														Edit			
															3 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print		
1	13/11/18 18:04		Odometer Reading														Load JPG	<input checked="" type="checkbox"/>		
2	13/11/18 18:04		Chassis Number														Load JPG	<input checked="" type="checkbox"/>		
3	13/11/18 18:04		General View														Load JPG	<input checked="" type="checkbox"/>		
4	13/11/18 18:04		General View														Load JPG	<input checked="" type="checkbox"/>		
5	13/11/18 18:04		General View														Load JPG	<input checked="" type="checkbox"/>		
6	13/11/18 18:04		General View														Load JPG	<input checked="" type="checkbox"/>		
7	13/11/18 18:04		General View														Load JPG	<input checked="" type="checkbox"/>		
8	13/11/18 18:04		General View														Load JPG	<input checked="" type="checkbox"/>		
9	13/11/18 18:04		General View														Load JPG	<input checked="" type="checkbox"/>		
10	13/11/18 18:05		General View														Load JPG	<input checked="" type="checkbox"/>		
11	13/11/18 18:05		General View														Load JPG	<input checked="" type="checkbox"/>		
12	13/11/18 18:05		General View														Load JPG	<input checked="" type="checkbox"/>		
13	13/11/18 18:05		General View														Load JPG	<input checked="" type="checkbox"/>		
14	13/11/18 18:05		General View														Load JPG	<input checked="" type="checkbox"/>		
15	13/11/18 18:05		General View														Load JPG	<input checked="" type="checkbox"/>		
16	13/11/18 18:05		General View														Load JPG	<input checked="" type="checkbox"/>		
17	13/11/18 18:05		General View														Load JPG	<input checked="" type="checkbox"/>		
18	13/11/18 18:05		General View														Load JPG	<input checked="" type="checkbox"/>		
19	13/11/18 18:05		General View														Load JPG	<input checked="" type="checkbox"/>		
20	13/11/18 18:05		General View														Load JPG	<input checked="" type="checkbox"/>		
21	13/11/18 18:05		General View														Load JPG	<input checked="" type="checkbox"/>		
22	13/11/18 18:05		General View														Load JPG	<input checked="" type="checkbox"/>		
23	13/11/18 18:05		General View														Load JPG	<input checked="" type="checkbox"/>		
24	13/11/18 18:05		General View														Load JPG	<input checked="" type="checkbox"/>		
25	13/11/18 18:05		General View														Load JPG	<input checked="" type="checkbox"/>		
26	13/11/18 18:05		General View														Load JPG	<input checked="" type="checkbox"/>		
27	13/11/18 18:05		General View														Load JPG	<input checked="" type="checkbox"/>		
28	13/11/18 18:05		General View														Load JPG	<input checked="" type="checkbox"/>		
29	13/11/18 18:05		General View														Load JPG	<input checked="" type="checkbox"/>		
30	13/11/18 18:05		General View														Load JPG	<input checked="" type="checkbox"/>		
31	13/11/18 18:05		General View														Load JPG	<input checked="" type="checkbox"/>		
32	13/11/18 18:05		General View														Load JPG	<input checked="" type="checkbox"/>		
33	13/11/18 18:05		General View														Load JPG	<input checked="" type="checkbox"/>		
34	13/11/18 18:05		General View														Load JPG	<input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	04/12/18 09:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	04/12/18 09:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	04/12/18 09:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	04/12/18 09:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	04/12/18 09:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/11/18 17:16	TP ESTIMATE- MARKED	 Load PDF	
2	13/11/18 17:16	TP GIA REPORT	 Load PDF	
3	14/11/18 16:25	TP ESTIMATE- MARKED	 Load PDF	
4	26/12/18 07:59	WORKSHOP INVOICE	 Load PDF	
5	26/12/18 07:59	AUTHORISATION TO ACT FORM	 Load PDF	
6	26/12/18 07:59	Release Voucher	 Load PDF	
7	26/12/18 07:59	LTA SEARCH	 Load PDF	
8	26/12/18 07:59	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	14/11/18 09:34	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLQ5752Z (Insd veh)	Model:	HONDA VEZEL 1.5 G (A)
	SLS7909R (TP veh)		
Date of Accident:	10/11/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> [ X ] Yes	<input type="checkbox"/> [ ] No	
Repair Estimate	:	\$		10,926.60
Final Repair Cost	:	\$		4,800.00
Loss of Use	:	\$		5.00 days at \$70.00 per day
Rental (if any)	:	\$		days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (Global Sum)	:	\$		4,800.00

**Is Third Party Workshop GIA Registered?** ☐ [ ] YES ☒ [ X ] NO (Kindly indicate below)

**A) For Non GIA Registered Workshop:** Agreed Liability \_\_\_\_ 100 \_\_\_\_ (%)

**B) For GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_

BOLA Liability: \_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_ (%)

*\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Abwin Service Pte Ltd	: \$	4,800.00
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

26 Dec  
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR18020538/UPB3Q2

Date: 26/12/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 09999994807

Claimant Vehicle  
No: SLS7909R

Insured Vehicle No: SLQ5752Z

Date of Loss: 10/11/2018

Nature of Claim: TP

Claim No: 0336334067SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLS7909R

Make &amp; Model: HONDA VEZEL, 1.5 G (A)

Engine No: LEB5961780

Reg. Date: 05/10/2017 (Man. Year: 2017)

Chassis No: RU31261763

Colour: White

Odometer: 74707 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 8 mm

Rear Left Side: Dunlop 8 mm

Front Right Side: Dunlop 8 mm

Rear Right Side: Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,411.78	2,810.50	2,601.28	48.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,800.00	1,360.00	3,440.00	71.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>10,211.78</b>	<b>4,170.50</b>	<b>6,041.28</b>	<b>59.16</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>714.82</b>	<b>291.94</b>	<b>422.88</b>	<b>59.16</b>
<b>Nett Amount (S\$)</b>	<b>10,926.60</b>	<b>4,462.44</b>	<b>6,464.16</b>	<b>59.16</b>
<b>+ Loss of Use (5.0 x S\$70.00/day) (S\$)</b>		<b>350.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		<b>7.45</b>		
<b>Nett Liability (S\$)</b>		<b>4,819.89</b>		
<b>Global Sum Settlement (S\$)</b>		<b>4,800.00</b>		

## INSPECTION

Date of Assignment: 13/11/2018

Date Inspected: 13/11/2018 Inspected At:

Abwin Service Pte Ltd (HQ)  
No. 8 Kaki Bukit Avenue 4, #07-48  
Premier@Kaki Bukit Gate 2  
Singapore 415875

Estimated Period of Repair: 4.0 days

---

**Adjuster:** MARCUS CHUA

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	1,200.90 FL	*953.00 FL
2	1		*TAILGATE WEATHERSTRIP	Not Necessary	106.80 FL	*- FL
3	1		*TAILGATE EMBLEM HYBRID	Necessary	95.50 FL	*95.50 FL
4	1		*TAILGATE VEZEL EMBLEM	Necessary	45.80 FL	*45.80 FL
5	1		*TAILGATE LOCK	Not Necessary	106.60 FL	*- FL
6	1		*TAILGATE REFLECTOR RH	Cracked	280.60 FL	*280.60 FL
7	1		*TAILLAMP RH	Cracked	460.50 FL	*460.50 FL
8	1		*REAR BUMPER	Dented	762.70 FL	*762.70 FL
9	1		*REAR BUMPER REFLECTOR RH	Cracked	148.30 FL	*148.30 FL
10	1		*REAR BUMPER REFLECTOR LH	Not Necessary	148.30 FL	*- FL
11	1		*REAR BUMPER RETAINER RH	Bent	35.60 FL	*35.60 FL
12	1		*REAR BUMPER RETAINER LH	Not Necessary	45.60 FL	*- FL
13	1		*REAR BUMPER BRACKET RH	Not Necessary	45.60 FL	*- FL
14	10		*REAR BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
15	1		*REAR END PANEL	Repair	456.90 FL	*- FL
16	1		*REAR END PANEL TOP GARNISH	Not Necessary	126.00 FL	*- FL
17	10		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
18	1		*RH REAR FENDER ARCH GARNISH	Not Necessary	206.50 FL	*- FL
19	1		*RH REAR FENDER	Not Necessary	615.40 FL	*- FL
20	1		*REAR WINDSCREEN MOULDING	Necessary	185.60 FL	*185.60 FL
21	10		*RH REAR FENDER INNER SHIELD CLIPS	Not Necessary	60.00 FL	*- FL
22	1		*EXHAUST MUFFLER	Repair	726.00 FL	*- FL
23	1		*REAR BUMPER SIDE O/S	Deformed	185.53 FL	*185.53 FL
24	1		*REAR NUMBER PLATE & CASING	Not Necessary	65.00 FS	*- FS
25	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS
26	1		*REAR WINDSCREEN SEALANT	Necessary	65.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,644.73</b>	<b>3,453.13</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>1,232.95</b>	<b>642.63</b>
<b>Total Parts (\$\$)</b>	<b>5,411.78</b>	<b>2,810.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	New	1,800.00	480.00
2	TO SPRAY PAINT ON AFFECTED AREAS	New	1,800.00	600.00
3	TO APPLY UNDERCOATING FOR RUST PROOFING	New	150.00	30.00
4	TO CHECK LIGHTING AND FOCUS HEADLAMP	New	150.00	20.00
5	TO INSTALL EXHAUST PIPE SYSTEM	New	350.00	0.00
6	TO INSTALL REVERSE SENSOR & CHECK FUNCTIONALITY	New	150.00	50.00
7	TO TRANSFER REAR & INSTALL WINDSCREEN FITTING	New	150.00	120.00
8	TO TRANSFER & INSTALL TAILGATE FITTING	New	250.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,800.00</b>	<b>1,360.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >