

Please arrange to survey vehicle at  
8 KAKI BUKIT AVENUE 4 - GATE 2  
#07-48 PREMIER @ KAKI BUKIT  
SINGAPORE 415875

**ABWIN** 諭輝

Date : 13/11/2018  
TP Vehicle No. : SLQ-5752-Z  
To : AIG ASIA PACIFIC INSURANCE PTE LTD  
Attn : Motor Claim Department

LINDA LIAO  
ABWIN SERVICE PTE LTD  
DID: 67139417  
Fax: 67139415  
HP: 97519596

Owner : XB CHAUFFER SERVICES  
NTUC INCOME INSURANCE CO-OPERATIVE LTD  
Certificate No. : 5094824884-01  
Vehicle No. : SLS-7909-R  
Make & Model : HONDA VEZEL-1.5 HYBRID (A)

Accident Date: 10/11/2018

### ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

#### List Item

1	TAILGATE	953	Body rd \$1,200.90	✓
1	TAILGATE WEATHERSTRIP		11 \$106.80	X
1	TAIL GATE EMBLEM" HYBRID"		RM \$95.50	✓
1	TAILGATE VEZEL EMBLEM		RM \$45.80	✓
1	TAILGATE LOCK		11 \$106.60	X
1	TAILGATE REFLECTOR RH		RM \$280.60	✓
1	TAILLAMP RH		RM \$460.50	✓
1	REAR BUMPER		PD \$762.70	✓
1	REAR BUMPER RELECTOR RH		RM \$148.30	✓
1	REAR BUMPER RELECTOR LH		11 \$148.30	X
1	REAR BUMPER RETAINER RH		Set \$35.60	✓
1	REAR BUMPER RETAINER LH		11 \$45.60	X
1	REAR BUMPER BRACKET RH		11 \$45.60	X
10	REAR BUMPER CLIPS		RM \$60.00	✓
1	REAR END PANEL		R \$456.90	X
1	REAR END PANEL TOP GARNISH		11 \$126.00	X
10	REAR END PANEL TOP GARNISH CLIPS		11 \$60.00	X
1	RH REAR FENDER ARCH GARNISH		11 \$206.50	X
1	RH REAR FENDER		11 \$615.40	X
1	REAR WINDSCREEN MOULDING		RM \$185.60	✓
10	RH REAR FENDER INNER SHIELD CLIPS		11 \$60.00	X
1	EXHAUST MUFFLER		R \$726.00	X
Sub Total			\$5,979.20	
Discount 20% on Parts			(\$1,195.84)	
			\$4,783.36	

#### Special Nett

1	REAR NUMBER PLATE & CASEING	11	\$65.00	X
1 set	REAR BUMPER REVERSE SENSOR	shock	\$350.00	200
1	REAR WINDSCREEN SEALANT	RM	\$65.00	40

Date : 13/11/2018  
 TP Vehicle No. : SLQ-5752-Z  
 To : AIG ASIA PACIFIC INSURANCE PTE LTD  
 Attn : Motor Claim Department

LINDA LIAO  
 ABWIN SERVICE PTE LTD  
 DID: 67139417  
 Fax: 67139415  
 HP: 97519596

Owner : XB CHAUFFER SERVICES  
 NTUC INCOME INSURANCE CO-OPERATIVE LTD  
 Certificate No. : 5094824884-01  
 Vehicle No. : SLS-7909-R  
 Make & Model : HONDA VEZEL-1.5 HYBRID (A)

Accident Date: 10/11/2018

## ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
	Sub Total	\$480.00	

### Labour & Misc

TO STAIGHTEN AND PANEL BEAT ACCIDENT AREAS	\$1,800.00	400
TO SPRAY PAINT ON AFFECTED AREAS	\$1,800.00	600
TO APPLY UNDERCOATING FOR RUST ROOFING	\$150.00	30
TO CHECK LIGHTING AND FOCUS TAILLAMP	\$150.00	20
TO INSTALL EXHAUST PIPE SYSTEM	11 \$350.00	2
TO INSTALL REVERSE SENSOR & CHECK FUNCTIONALITY	\$150.00	50
TO TRANSFER REAR & INSTALL WINDSCREEN FITTING	\$150.00	120
TO TRANSFER & INSTALL TAILGATE FITTING	\$250.00	60
Sub Total	\$4,800.00	

Sub Total \$10,063.36  
 GST 7% \$704.44  
 Total \$10,767.80