

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

12 NOV 2018

Estimate No.	: b1 49083	Page No. : 1 of 5
Date Estimated	: 12/11/2018	
Prepared By	: Chua Kee Sin	

- ESTIMATE REPAIR FOR - Ng Kee Hong Blk 289E Bukit Batok Street 25 #12-150 Singapore 654289	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDE1397A	BJ20151	18/06/2018	520i	0

DESCRIPTION	VALUE
Replace rear bumper, rear boot lid and remove attachment etc include repair on accident damage area	1700 2,550.00
Spray painting rear boot lid, rear bumper and tail end pan	1868 2,819.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
To remove and install boot compartment carpet and garnish to facilitate repairs.	243 271.00
To carry out body cavity preservation. (Per panel).	100 118.00
Sundries.	? 150.00
Total Labour 1:	6,085.00

DESCRIPTION	QTY	PRIC	VALUE
TAILGATE ALUMINIUM	1	1,741.00	bt 1,741.00
LH TRUNK LID HINGE	1	116.50	Rx 116.50
RH TRUNK LID HINGE	1	116.50	Rx 116.50
LEFT PROTECT	1	15.55	? 15.55
RIGHT PROTEC	1	15.55	? 15.55
Carrier, bum	1	596.75	? 596.75
REAR BUMPER BOTTOM REINFORCEMENT	1	82.25	? 82.25
REAR BUMPER CENTRE GUIDE	1	61.55	? 61.55
REAR BUMPER LH SIDE GUIDE	1	58.50	? 58.50
REAR BUMPER RH SIDE GUIDE	1	58.50	? 58.50
REAR BUMPER TRIM STRIP	1	103.40	ant 103.40
REAR BUMPER PANEL PRIMED (PDC/PMA)	1	1,518.95	de 1,518.95
SET MOUNTING PMA SENSOR	1	69.00	? 69.00
BREAKTHROUGH BUFFER	2	8.45	? 16.90
PLAQUE 82MM	1	71.25	ner 71.25
GROMMET	2	0.75	ner 1.50
BOOT LID/TAILGATE PUSH BOTTON (RFK)	1	24.60	X 24.60

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 49083**
Date Estimated : **12/11/2018**
Prepared By : **Chua Kee Sin**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDE1397A	BJ20151	18/06/2018	520i	0

DESCRIPTION	QTY	PRIC	VALUE
LOCK TRUNK LID	1	228.00	228.00
RH SPINDLE DRIVE	1	547.55	547.55
WARNING SIGNALLER	1	38.95	38.95
TRUNK LID GASKET	1	127.95	127.95
(S/L) CLIP	2	5.20	10.40
REAR LH LIGHT IN TRUNK LID	1	353.35	353.35
REAR RH LIGHT IN TRUNK LID	1	353.35	353.35
LH TAIL LIGHT FINISHER TRUNK LID	1	32.00	32.00
RH TAIL LIGHT FINISHER TRUNK LID	1	32.00	32.00
Gasket, rear	1	13.45	13.45
Gasket, rear	1	13.45	13.45
DECOUPING RING PDC TORQUE CONVERTER	4	5.05	20.20
Ultrasonic s	4	380.65	1,522.60
Total Parts :			7,961.50

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 26/11/18 4:25pm Excess S\$ _____

Surveyor's Name Tan Jia Sign [Signature]

Surveyor's Tel 97495749 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail tan.jia@pml.com

No. of Working Days Recommend 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	6,085.00
Parts	:	7,961.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	983.26
Grand Total	:	15,029.76

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **