

**CHUNNI MOTOR WORK PTE LTD****REPAIR ESTIMATE\***

VEHICLE NO : SHA 7635Y (Supplementary)

DATE : 12.11.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Headlamp Panel Top Cover Rubber <i>trip</i>			\$ 68.00 ✓
	Actuator - Swirl Control <i>valve</i>			\$ 814.60 ✓
	SUB TOTAL			\$ 882.60
	LESS 20%			\$ 176.52
	DISCOUNTED TOTAL			\$ 706.08
<p>13/11/2018 @ 1330m</p> <p><i>[Signature]</i></p> <p>2 KK Auto</p> <p><i>[Signature]</i></p>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				